



GTE/6

INTERNATIONAL CIVIL AVIATION ORGANIZATION

FINAL REPORT

SIXTH MEETING/WORKSHOP OF THE SCRUTINY WORKING GROUP

(GTE/6)

The designations employed and the presentation of material in this publication do not imply the expression of any opinion whatsoever on the part of ICAO concerning the legal status of any country, territory, city or area or of its authorities, or concerning the delimitation of its frontiers or boundaries.

HISTORY OF THE MEETING

ii-1 PLACE AND DURATION OF THE MEETING

The Sixth Meeting/Workshop of the Scrutiny Working Group (GTE/6) was held at the ICAO Regional Office, in Mexico City, Mexico, 8-12 December 2008.

ii-2 OPENING CEREMONY AND OTHER MATTERS

Mr. Victor Hernandez, of the ICAO North American, Central American and Caribbean Office, greeted the participants, and highlighted the importance of the issues to be dealt with as well as notable adverse trends that have been identified within the Regions. Mr. Hernandez specifically noted facility-to-facility coordination issues and urged the Group to consider this trend when evaluating reports of large height deviations and determining proposed remedial actions. Mrs. Loretta Martin, Regional Director, also welcomed the participants highlighting the importance of the matters to be dealt with at a regional level.

ii-3 SCHEDULE, ORGANIZATION, WORKING METHODS, OFFICERS AND SECRETARIAT

The Meeting agreed to hold its sessions from 0830 to 1600 hours, with appropriate breaks. The work was done with the Meeting as a Single Committee, Working Groups and Ad-hoc Groups. Mr. Victor Hernandez served as Chairman of the Meeting and Mr. Madison Walton, delegate from United States served as Rapporteur of the Scrutiny Working Group.

ii-4 WORKING LANGUAGES

The working languages of the Meeting were Spanish and English and its relevant documentation was presented in both languages.

ii-5 AGENDA

The following agenda was adopted:

Agenda Item 1: ICAO provisions related to ATS Safety Management and Safety Assessment Programmes

Agenda Item 2: History of RVSM, Regional Monitoring Agencies and Scrutiny Groups

- Roles and responsibilities
- Overview of Target Levels of Safety

- Agenda Item 3: GTE Overview
- Review of Terms of Reference
 - Background
 - Composition
 - Objectives
 - Methodology
 - Reporting
- Agenda Item 4: Large Height Deviation (LHD) Analysis
- Application of GTE methodology to LHD events
 - Summarize parameter values
 - Identify operational trends
- Agenda Item 5: Other Business.

ii-6 ATTENDANCE

The meeting was attended by 27 participants representing 3 State of the CAR Region and 1 State of the SAM Region. Representatives of COCESNA, IFALPA, and IFATCA were also present. The list of participants is included in Appendix A.

Agenda Item 1: ICAO provisions related to ATS Safety Management and Safety Assessment Programmes

1.1 Victor Hernandez highlighted the importance of the ICAO safety management system (SMS) and discussed the role and contribution of the GTE with respect to the SMS.

Agenda Item 2: History of RVSM, Regional Monitoring Agencies and Scrutiny Groups

- a) Roles and responsibilities**
- b) Overview of Target Levels of Safety**

2.1 The Meeting recalled that GREPECAS established the Caribbean and South American Monitoring Agency (CARSAMMA) as a safety oversight function to support RVSM implementation and continued safe use in the Caribbean and South American Region, acting as a regional monitoring (RMA).

2.2 Along with maintaining a registry of State RVSM approvals of operators and aircraft operating in RVSM airspace, CARSAMMA is responsible for collecting and maintaining reports of large height deviations 90m (300ft) or greater.

2.3 CARSAMMA has applied the internationally accepted safety assessment process to safety analyses of the Reduced Vertical Separation Minima (RVSM) in CAR/SAM airspace. The basic collision risk model (CRM) is used to estimate the overall system risk attributable to all causes. In order to estimate the system risk, the CRM requires many parameters which are derived from data sources supplied to CARSAMMA. One of the required parameters for the CRM is the total number of annual flying hours spent at incorrect flight levels. As a means to accurately estimate risk, CARSAMMA, in conjunction with the GTE, analyzes monthly reports of any altitude variation of 90m (300ft) or greater from the assigned or planned altitude within CAR/SAM RVSM airspace.

Agenda Item 3: GTE Overview

- a) Review of Terms of Reference**
- b) Background**
- c) Composition**
- d) Objectives**
- e) Methodology**
- f) Reporting**

3.1 Under this agenda item, the meeting reviewed the work programme and terms of reference of the Scrutiny Group (SG) (See Appendix B to this part of the report).

3.2 The delegation from United States presented a reference guide to the meeting, describing the composition, objectives, and methodology employed by the GTE. The

reference guide serves as consultation material by interested parties in the activities being carried out by this Working Group. The Reference Guide is included in Appendix B to this report.

3.3 In general terms, the guide presents the role and responsibilities of a Regional Monitoring Agency, the establishment of the Grupo de Trabajo de Escrutinio (GTE), its composition, objectives, data collection process and methodology to carry out LHD analyses.

Agenda Item 4: Large Height Deviation (LHD) Analysis

a) Application of GTE methodology to LHD events

b) Summarize parameter values

c) Identify operational trends

4.1 Under this agenda item, the meeting reviewed all 90 m (300 ft) large-height deviations (LHD) occurrences submitted to and provided by CARSAMMA for the six-month period of January 2008 to June 2008. The summary of such reports is included in Appendix C of this report.

4.2 Under this task, the meeting estimated the flight times spent at incorrect flight level, the magnitude of each event, flight levels crossed, and reviewed the causes of each one of them. These values shall contribute to the estimate of operational risk in RVSM airspace within the CARSAM Regions. The task of estimating operational risk is the responsibility of CARSAMMA.

4.3 CARSAMMA reported that the Aircraft Registration Number field of a large portion of LHD reports is blank. It was noted that this information is important and the Group was advised to encourage the inclusion of the aircraft registration number for all LHD reports. It was suggested that the LHD reporting form should be revised for simplicity purposes so that the reporter can efficiently and thoroughly complete the form. CARSAMMA noted that any revisions to the LHD form would require approval through other organizations. The Group agreed to maintain the LHD form as it exists and provide more details for completing the form accurately. It was also suggested that CARSAMMA include a Frequently Asked Questions (FAQ) section clarifying how to accurately complete the LHD form. CARSAMMA agreed to post frequently asked questions on their web site.

4.4 Additionally, CARSAMMA recommended a change to the title of the existing LHD form to another one that would not limit its use only to large height deviations. The Meeting recalled that although category type "N" events contribute to LHD analyses, a physical large height deviation does not occur. The Group accepted that CARSAMMA will present this change of concept during the next RMA Special Meeting as well as other alterations such as field #6: "Radar- yes/no-if yes, which FL was seen".

4.5 CARSAMMA and the Group supported the suggestion of Curacao to create a new simpler LHD form to be completed by the controller immediately after the LHD event occurs. This form would be completed in addition to the existing LHD reporting form.

4.6 The Group noted that the event time recorded in the LHD report does not always correlate to the event. The Group will provide detailed instructions for completion of this field.

4.7 Reports concerning radar mechanical failure in the Bogota FIR were submitted. The failure resulted in an erroneous altitude display of about 500ft. The Group recorded these events as Technical LHDs; the events will contribute to the technical portion of the collision risk analysis. CARSAMMA will further investigate these events.

4.8 The Group identified an adverse trend involving ATC-to-ATC coordination errors between the Curacao and Santo (St.) Domingo FIRs specifically over the VESKA reporting point. The situation also involves the Haiti FIR. Aircraft transitioning through the Port au Prince FIR to the Curacao FIR also transition through the St. Domingo FIR for a short period of time. In many cases, Haiti provided a revised boundary crossing time estimate for a particular aircraft over VESKA to St. Domingo, by the time St. Domingo coordinates the revised estimate to Curacao the aircraft has already entered Curacao's airspace. This results in a significant variation between the time of the boundary crossing and the time expected into the Curacao FIR. It was noted that Haiti typically provides multiple time estimate revisions passing through St. Domingo to Curacao. This could be a workload issue. This issue will, through CARSAMMA and ICAO, be investigated further. Remedial action, if necessary, will be recommended upon the conclusion of the investigation.




Figure 1 Port Au Prince, Santo Domingo and Curacao FIRs

4.9 The Group also noted a large number of code “M” reports involving the St. Domingo and Curacao FIRs. It was agreed that these events require further investigation.

4.10 Several reports of ATC-to-ATC coordination errors involved the Maiquetia and Piarco FIRs. The Group noted that the majority of these reports involved communication errors linked specifically to the PELMA reporting point which is approximately 40nm east of the shared boundary. CARSAMMA reported that they informed ICAO of this issue.

4.11 In reference to items 4.8, 4.9 and 4.10, the Group agreed to submit a recommendation to ICAO that a meeting including CARSAMMA and the involved FIRs should be held to discuss methods to remediate these issues. The Group determines this meeting to be of such importance that a representative of GREPECAS participates. The Group noted the possibility that policies and procedures developed during this meeting might not be applicable to all regions.

4.12 It was noted that some States exercise the 5-minute reporting requirement prior to a boundary crossing more so than others. The Group recommends generating a NOTAM to advise operators of this 5-minute reporting requirement, further the

Group requests the assistance of IFALPA promulgating this requirement.

4.13 The Group reviewed several events involving a negative transfer where the pilot reported a boundary crossing estimate several minutes prior to entering the adjacent FIR. Typically this type of event would not be included in the LHD analysis. Some group members noted that although the accepting FIR received notification prior to the aircraft crossing the boundary, there is a period of time where the controller is unable to remediate the event prior to the error occurring and suggested there should be an agreed “buffer” duration to account for controller reaction time. In other words, if the boundary crossing estimate is provided before the agreed “buffer” duration then the event is not considered to be an LHD; if the estimate is received equal to or less than the established buffer estimate than the event is an LHD. The Group agreed that a “buffer” value should be considered and agreed to the duration value of 3 minutes. The buffer value should be used as a guideline and each event should be evaluated individually. Figure 2 illustrates the “buffer” concept.




Figure 2 Three-minute Buffer Illustration

4.14 The majority of LHDs are attributed to ATC-to-ATC coordination errors. It was suggested that the Group should determine whether the transfer was conducted orally or automatically and include this information in the analysis. The Group agreed and will collect this information. Example of this item will be presented to the next meeting of the GTE. Additionally, CARSAMMA will present this to the All RMA meeting.

4.15 Previously the GTE agreed that coordination errors identified in areas where radar is available and the controller is able to see the aircraft arriving several minutes prior to the boundary crossing that these events were not LHDs. CARSAMMA advocates that these events are LHDs primarily because the Group can not assume that even though the aircraft was displayed on the radar, that the controller identified the potential coordination error. For example if an arriving aircraft has not been coordinated by the adjacent FIR, there is the possibility that the controller will not be aware of the aircraft since he/she is not expecting the aircraft's arrival.

4.15.1 Further more, the Group agreed, when analyzing events of this type that it is essential to determine whether communication took place either from the pilot or the

controller. If no communication took place, then the event must be considered an LHD. If communication took place, we refer to item 4.13.

4.15.2 This is counter to current GTE policy and the Group agreed it should be further discussed at the next meeting.

4.15.3 The Group urges full completion of the LHD form with special attention to field number 6 to assist to the determination whether radar is available.

4.16 Considering the large portion of events involving ATC-to-ATC coordination errors, based on reports of CARSAMMA seminars to Brazil ACCs, the Group suggested CARSAMMA visit ACCs within the region promoting ATC-to-ATC coordination error awareness and recommended/required policies and procedures. It was also suggested that regional meetings, including participation of all adjacent FIRs, should be scheduled to address this issue. Participation should also include directors, supervisors and controllers.

4.16.1 The Group agreed to submit the recommendation that a formal letter with an accompanying white paper describing LHD analysis and how to accurately complete the form be distributed to directors and supervisors of all ACCs in the region.

4.16.2 The Group also agreed to recommend that the LHD reporting form be completed by the supervisors.

4.16.3 The Group urges that this process be expedited.

4.17 During discussion of two LHD events, it was noted that there is an issue concerning flights transferring through the Mexico FIR in RVSM airspace with the transponder turned off. It was also noted that some military aircraft operate in this airspace at flight levels other than cleared resulting in violation of separation with other aircraft. The Group expressed its concern for civil aviation safety in the applicable regions and suggests a review of procedures used by investigative authorities in their missions with a view to improve aviation safety.

Agenda Item 5: Other business

5.1 The Meeting concurred with a proposal by CARSAMMA in the sense that, in view of the complex technical background of the items included in the terms of reference and work programme of the GTE, member States should make every effort to keep continuity in the designated participating individuals to this contributory body.

5.2 In order to detect points of conflict and consequently communicate the issues to ICAO within a timely manner, CARSAMMA requested to the Group permission to complete a preliminary scrutiny of the received LHD events every month. Otherwise, ICAO will be only notified of those points of conflict after regular GTE meetings.

5.3 CARSAMMA explained and proposed to the Group that a three-day air traffic movement sample be collected every four months in order to monitor RVSM airspace and the approval status of aircraft flying in the Regions.

Appendix A



**INTERNATIONAL CIVIL AVIATION ORGANIZATION
ORGANIZACIÓN DE AVIACIÓN CIVIL INTERNACIONAL**

**CAR/SAM GRUPO DE TRABAJO DE ESCRUTINIO (GTE)
TRAINING SEMINAR/MEETING
SEMINARIO/REUNIÓN DEL GRUPO DE TRABAJO DE ESCRUTINIO (GTE) CAR/SAM**

**(Mexico City, Mexico, 8-12 December 2008)/
(Ciudad de México, México, 8-12 de diciembre de 2008)**

List of Participants / Participants List

Brazil/Brasil

Ricardo Luiz Dantas de Brito
Artur Flávio
Ricardo Dantas Rocha
Reinaldo Brandao Taveira
Thaís Santarém de Assumpcao

COCESNA

Jesús Rodríguez
Jorge Corrales

IFALPA

Mexico/México

José Inés Gil
Marco Antonio Coria
Manuel Rodríguez
Luis Manuel Flores
Quetzalcóatl Aguirre Pérez
Ana Luisa Espinosa
Nancy Medina
Oscar Callejas
Sergio González

Fernando Álvarez

IFATCA

Rodrigo Bruce Magallón

Netherlands Antilles/Antillas Neerlandesas

Ezzard Ignacio
Enrique Kroon

Saint Lucia/Santa Lucía

Errol Cherubin

United States/Estados Unidos

Madison Walton
Jose Perez
Lauren Martin
Stephanie Beritsky
Latonia Sewell

CAR/SAM GRUPO DE TRABAJO DE ESCRUTINIO (GTE)
TRAINING SEMINAR/MEETING
SEMINARIO/REUNIÓN DEL GRUPO DE TRABAJO DE ESCRUTINIO (GTE) CAR/SAM
 List of Participants / Lista de Participantes

LIST OF PARTICIPANTS / LISTA DE PARTICIPANTES
GENERAL INFORMATION / INFORMACIÓN GENERAL

Name / Nombre Position / Cargo	Address / Dirección Telephone / Teléfono Fax, E-mail
<i>Brazil / Brasil</i>	
Ricardo Luiz Dantas de Brito Chief of CARSAMMA (Major Aviator)	CARSAMMA Praça Salgado Filho S/N Complexo Santos Dumont – Centro Rio de Janeiro RJ CEP: 20021-370 Brasil Tel.: +55 21 2101 6375 Fax: +55 21 2101 6358 E-mail: ricardo@cgna.gov.br Web page: www.cgna.gov.br
Artur Flávio Dias <i>Safety Assessment</i>	CARSAMMA Av. Dr. Nelson D'Avila HZ5, Bl. D., Apto. 108 CEP 12245-030 Sao José dos Campos, SP, Brasil Tel. +5512 9134 5538 / 3947 5477 / 3923 4033 E-mail arturf@ieav.com.br
Ricardo Dantas Rocha Air Traffic Controller	CARSAMMA Praça Salgado Filho S/N Complexo Santos Dumont – Centro Rio de Janeiro RJ CEP: 20021-370 Brasil Tel.: +55 21 2101 6358 Fax: +55 21 2101 6490 E-mail: ricardodr@gmail.com Web page: www.cgna.gov.br
Reinaldo Brandao Taveira Air Traffic Controller	CARSAMMA Praça Salgado Filho S/N Complexo Santos Dumont – Centro Rio de Janeiro RJ CEP: 20021-370 Brasil Tel.: +55 21 2101 6358 Fax: +55 21 2101 6490 E-mail: taveira@cgna.gov.br Web page: www.cgna.gov.br
Thaís Santarém de Assumpção Air Traffic Controller	CARSAMMA Praça Salgado Filho S/N Complexo Santos Dumont – Centro Rio de Janeiro RJ CEP: 20021-370 Brasil Tel.: +55 21 2101 6358 Fax: +55 21 2101 6358 E-mail: thais@cgna.gov.br Web page: www.cgna.gov.br
<i>Mexico / México</i>	
José Inés Gil Jiménez Jefe del Departamento de Tránsito Aéreo	Dirección General de Aeronáutica Civil Providencia 807 – 3er piso 03100 México D. F., México Tel.: +5255 5687 7941 Fax: +5255 5523 6275 E-mail: jjgiljim@sct.gob.mx Web page: www.sct.gob.mx

CAR/SAM GRUPO DE TRABAJO DE ESCRUTINIO (GTE)
TRAINING SEMINAR/MEETING
SEMINARIO/REUNIÓN DEL GRUPO DE TRABAJO DE ESCRUTINIO (GTE) CAR/SAM
 List of Participants / Lista de Participantes

Name / Nombre Position / Cargo	Address / Dirección Telephone / Teléfono Fax, E-mail
<i>Mexico / México (Cont.)</i>	
Marco Antonio Coria Rodríguez Inspector Verificador Aeronáutico	Dirección General de Aeronáutica Civil Providencia 807 – 3er piso 03100 México D. F., México Tel.: +5255 5687 7941 Fax: +5255 5523 6275 E-mail: mcoriario@sct.gob.mx
Manuel Rodríguez Santiesteban Inspector Verificador Aeronáutico	Dirección General de Aeronáutica Civil Providencia 807 – 3er piso 03100 México D. F. México Tel.: +5255 5687 7941 Fax: +5255 5723 6275 E-mail: mrodsant@sct.gob.mx
Luis Manuel Flores Solórzano Jefe del Área de Control de la Calidad ATS	SENEAM Av. 602 No. 161 15620 México D. F., México Tel.: +5255 5786 5515 Fax: +5255 2598 0065 E-mail: lmflores@sct.gob.mx
Ana Luisa Espinosa Noriega Auditora Interna ISO-9000, Técnico Especialista en Electrónica Aeronáutica en Grupo Electro-aeronáutico	SENEAM Apto. Internacional B.J. Oficinas SENEAM Tel.: +5255 5786 5559 Fax: +5255 3200 2978 E-mail: analuisaen@yahoo.com
Nancy Medina Velásquez Especialista en Control de Tránsito Aéreo	SENEAM Av. 602 No. 161 15620 México D. F., México Tel.: +5255 568 5588 Fax: +5255 32 002978 E-mail: ctanancymv@att.net
Oscar Callejas Hipólito Inspector Verificador Aeronáutico	Dirección General de Aeronáutica Civil Providencia 807 – 3er piso 03100 México D. F. México Tel.: +5255 5687 7941 E-mail: ocalleja@sct.gob.mx Web : www.sct.gob.mx
Sergio González Chávez Inspector Verificador Aeronáutico	Dirección General de Aeronáutica Civil Providencia 807 – 3er piso 03100 México D. F. México Tel.: +5255 5687 7941 E-mail: egonz310@sct.gob.mx Web : www.sct.gob.mx
Quetzalcóatl Aguirre Pérez Controlador Aéreo Radar Terminal	SENEAM Av. 602 No. 161 15620 México D. F., México Tel.: +5255 5786 5515 E-mail: ctaquetza@yahoo.com.mx
NETHERLANDS ANTILLES / ANTILLAS NEERLANDESAS	
Ezzard Ignacio ATS/AD - Inspector	Seru Mahuma z/n Curaçao, Netherlands Antilles Tel.: +599 9 839 3313 / 767 2258 E-mail: e.ignacio@onenet.an

CAR/SAM GRUPO DE TRABAJO DE ESCRUTINIO (GTE)
TRAINING SEMINAR/MEETING
SEMINARIO/REUNIÓN DEL GRUPO DE TRABAJO DE ESCRUTINIO (GTE) CAR/SAM
List of Participants / Lista de Participantes

Name / Nombre Position / Cargo	Address / Dirección Telephone / Teléfono Fax, E-mail
Enrique S. Kroon Air Traffic Control Supervisor	Netherlands Antilles Air Traffic Control N.V. (NAATC) Seru Mahuma z/n Curaçao, Netherlands Antilles Tel.: +599 9 839 3506 Fax: +599 9 868 3012 E-mail: info@naatc.an / ekroon@naatc.an / eriekroon@yahoo.com
<i>SAINT LUCIA / SANTA LUCÍA</i>	
Errol Cherubin Senior Air Traffic Control Officer	SLASPA Hewanorra International Airport Vieux Fort, Saint Lucia Tel.: +1758 454 6355 Fax: +1758 454 5146 E-mail: cherubine@slaspa.com
<i>UNITED STATES / ESTADOS UNIDOS</i>	
H. Madison Walton Jr. Aviation Safety Inspector	Federal Aviation Administration 470 L'Enfant Plaza East, Suite 4102, Washington, D.C. United States Tel.: +1202 385 4596 Fax: +1202 385 4653 E-mail: madison.walton@faa.gov Web page: www.faa.gov
Stephanie Beritsky FAA Program Support	CSSI, Inc. William J. Hugues Technical Center Atlantic City, NJ 08405 United States Tel.: +1609 485-7851 Fax: +1609 485 5117 E-mail: sberitsky@cssiinc.com Web page: www.cssiinc.com
Jose Perez Separations Standards Análisis Team	Federal Aviation Administration William J. Hugues Technical Center Atlantic City, NJ 08405 United States Tel.: +1609 485-5365 Fax: +1609 485 5117 E-mail: jose.perez@faa.gov Web page: www.faa.gov
Lauren Martin Separations Standards Análisis Team	Federal Aviation Administration William J. Hugues Technical Center Atlantic City, NJ 08405 United States Tel.: +1609 485-7941 E-mail: lauren.martin@faa.gov Web page: www.faa.gov
Latonia Sewell FAA Program Support	CSSI, Inc. 400 Virginia Avenue, SW Suite # 210 Washington, D.C. 20024 United States Tel.: +1202 863 2175 Fax: +1202 863 3705 E-mail: lsewell@cssiinc.com Web page: www.cssiinc.com

CAR/SAM GRUPO DE TRABAJO DE ESCRUTINIO (GTE)
TRAINING SEMINAR/MEETING
SEMINARIO/REUNIÓN DEL GRUPO DE TRABAJO DE ESCRUTINIO (GTE) CAR/SAM
 List of Participants / Lista de Participantes

Name / Nombre Position / Cargo	Address / Dirección Telephone / Teléfono Fax, E-mail
COCESNA	
Jorge A. Corrales McCarthy Supervisor/Instructor ATS	Corporación Centroamericana de Servicios de Navegación Aérea COCESNA Aeropuerto Toncontín Apdo. 660 - 150 mts al sur Terminal aérea Tegucigalpa, D.C. Honduras, C.A. Tel.: +504 234 3360 Fax: +504 234 2507 E-mail: jcorrales@cocesna.org / jacomccarthy@yahoo.com Web: www.cocesna.org
Jesús Rodríguez Supervisor/Instructor ATS	Corporación Centroamericana de Servicios de Navegación Aérea COCESNA Aeropuerto Toncontín 150 mts al sur Terminal aérea Tegucigalpa, D.C. Honduras, C.A. Tel.: +504 234 2507 E-mail: jrodriguez777@yahoo.com
IFATCA	
Rodrigo Bruce Magallón de la Teja Liaison Officer to ICAO NACC Regional Office	Colegio de Controladores de Tránsito Aéreo de México (COCTAM) Oriente 172 No. 189 Col. Moctezuma 2da Sección 15530 México, D.F., México Tel.: +5255 5571 2533 / 2643-0202 Fax: +5255 5571 2877 E-mail: bruce.magallon@coctam.org.mx Web: coctam.org.mx
IFALPA	
Fernando Álvarez Paczka Vicepresidente Regional Caribe Oeste	IFALPA Palomas No. 110 Col. Reforma Social 11650 México, D.F., México Tel.: +5255 5091 5954 E-mail: sate@aspa.org.mx
ICAO / OACI	
Víctor Hernández Acting Deputy Regional Director	ICAO/OACI North American, Central American and Caribbean (NACC) Office Av. Presidente Masaryk 29 – 3rd Floor Col. Chapultepec Morales México D.F., 11570, México Tel.: + 5255 5250 3211 Fax: + 5255 5203 2757 E-mail: vhernandez@mexico.icao.int ; icao_nacc@mexico.icao.int Web: www.mexico.icao.int

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE



International Civil Aviation Organization

**CARIBBEAN AND SOUTH AMERICAN
RVSM GRUPO DE TABAJÓ DE ESCRUTINIO
(CAR/SAM RVSM GTE)**

REFERENCE GUIDE

1. Introduction

1.1. This reference guide is a consolidation of materials describing the construction, purpose and methodology of the CAR/SAM RVSM Grupo de Trabajo de Escrutinio (GTE). It is intended to be used as a basic reference for anyone interested in Scrutiny Group activity.

1.2. It is essential that regional authorities take into account all possible means of ascertaining and reducing the level of risk of collision resulting from operational errors that cause large height deviations (LHD). The CAR/SAM RVSM GTE is the primary group to evaluate and assess the operational aspects of large height deviations.

2. Background

2.1. System Performance Monitoring

2.1.1. Experience has shown that large height deviations, a deviation in the vertical dimension from the cleared flight level whereby established margins of separation may be eroded, of 90 m (300 ft) or greater in magnitude have a significant impact on operational and technical risk in RVSM airspace. The causes of such deviations have been found to be, but are not limited to:

- a) an error in the altimetry or automatic altitude control system of an aircraft;
- b) turbulence and other weather-related phenomena;
- c) an emergency descent by an aircraft without the crew following established contingency procedures;
- d) response to airborne collision avoidance system (ACAS) resolution advisories;
- e) not following an ATC clearance, resulting in flight at an incorrect flight level;
- f) an error in issuing an ATC clearance, resulting in flight at an incorrect flight level; and
- g) errors in coordination of the transfer of control responsibility for an aircraft between adjacent ATC units, resulting in flight at an incorrect flight level.

The additional risk associated with operational errors and in-flight contingencies influence the outcome of RVSM safety assessments. A diagram illustrating the LHD contribution to the overall risk assessment is included in Appendix A.

2.1.2. System performance monitoring, as outlined in ICAO doc 9574, is necessary to ensure the continued safe use of reduced vertical separation minimum (RVSM) and that

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

established safety goals are met. This activity includes monitoring the minimum risk of collision associated with operational errors and in-flight contingencies. The monitoring process is divided into two main categories:

- a) Risk associated with the aircraft technical height-keeping performance (technical risk), and
- b) The overall risk, i.e. risk due to all causes.

2.1.3. The monitoring process involves the collection and evaluation of operational data. Appropriate methodologies will need to be in place to process this data in order to enable comparison with regionally agreed overall safety objectives.

2.2. Regional Monitoring Agency (RMA) Roles and Responsibilities

2.2.1. ICAO Doc 9574 describes a five-step implementation process for introduction of the RVSM. Among other actions required, the implementation process calls for establishment of a regional monitoring agency (RMA) to act as the safety oversight body. The RMA is required to conduct regular comprehensive safety assessments in order to ensure that the Target Level of Safety (TLS) is met. That is, that the risk associated with the RVSM as estimated by ICAO risk modeling is less than the TLS value. In other words, the RMA determines if the estimated risk of collision, calculated in accordance with ICAO collision risk methodology, is less than the agreed TLS.

2.2.2. A critical component of RVSM safety assessment, as well as a system performance monitoring requirement, is the analysis of large height deviations.

2.2.3. It is the responsibility of the cognizant RMA to establish a program for identifying large height deviations and a mechanism for collecting and analyzing reports of such deviations. It is also the responsibility of the RMA to provide periodic reports of observed height deviations to the appropriate PIRG and/or its subsidiary bodies, in accordance with procedures prescribed by the PIRG.

2.2.4. The Caribbean-South American Monitoring Agency (CARSAMMA) is the regional monitoring agency (RMA) established by GREPECAS to conduct this work for the Caribbean and South American regions.

2.2.5. While the RMA will be the recipient and archivist for reports of large height deviations, it is important to note that the RMA alone cannot be expected to conduct all activities associated with a comprehensive program to detect and assess large height deviations.

2.3. Establishment of a Reduced Vertical Separation Minimum Scrutiny Group

2.3.1. To assist the RMA in analyzing LHDs, a body of experts has been established by GREPECAS. This group of operational, ATC, flight crew and safety experts is called a Scrutiny Group, Grupo de Trabajo de Escrutinio (GTE). The GTE Terms of Reference is included in Appendix B.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

3. Composition

3.1. The Scrutiny Group requires a diverse set of subject-matter experts. The Group is composed of subject matter experts in air traffic control, aircraft operations and maintenance, regulation and certification, data analysis, and risk modeling from the involved regions.

3.2. In the CAR/SAM regions, the following organizations are represented in the Scrutiny Group:

- a) The Caribbean and South American Monitoring Agency (CARSAMMA)
- b) The Federal Aviation Administration (FAA)
- c) Dirección Générale de l'Aviation Civile (DGAC)
- d) International Federation of Air Line Pilots' Associations (IFALPA)
- e) Corporación Centroamericana de Servicios de Navegación Aérea (COCESNA)
- f) Corporación Peruana de Aeropuertos y Aviación Comercial S.A. (CORPAC S.A.)

3.3. Scrutiny Groups in other regions have recommended the formation of a Scrutiny Sub-Group. Participation in the Sub-Group is by subject matter experts and specialists. The Sub-Group is responsible for executing the preparatory work for the Scrutiny Group including the analysis and categorization of selected large height events. The Scrutiny Group shall govern the decisions proposed by the Sub-Group. Sub-Group members are drawn from the Scrutiny Group.

4. Objectives

4.1.1. The Scrutiny Group's work contributes directly to the requirement to provide on-going assessment of factors which affect the estimate of collision risk in RVSM airspaces.

4.1.2. The initial result of the Group's effort is to examine the "event" reports and produce an estimate of time spent at a flight level other than cleared. This estimate is used as a primary input used in the preparation of an estimate of the operational risk for the implementation of Reduced Vertical Separation Minimum (Appendix A). The Group examines both technical risk (affected by reliability and accuracy of the avionics within the aircraft) and operational risk (affected by the human element) in the development of the safety assessment.

4.1.3. Once the Group has made its initial determination, the data are reviewed to look for performance trends. If any adverse trends exist, the Group may make recommendations for reducing or mitigating the effect of those trends as a part of the RVSM

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

implementation. Subsequently, the Group will meet to examine the post-implementation record of performance and to assure that operational errors are kept to a minimum. This information is used to assure that the airspace being examined continues to satisfy the requirements of the target level of safety, which is necessary to support continued RVSM operations. New procedures or other mitigation strategies to reduce occurrences of large height deviations may evolve out of this process.

5. Data Collection

5.1.1. It is the responsibility of the relevant RMA, CARSAMMA, to establish procedures for the collection of information concerning large height deviations of 90m (300ft) or greater in magnitude

5.1.2. The primary source for reports of LHDs is the ATC units. Surveillance data collected by ATC units provides the basis for identifying large height deviations. ATC units should be required to submit monthly reports of large height deviations to the cognizant RMA.

5.1.3. CARSAMMA, with the advisement of the GTE, created a LHD reporting form designed to capture the information necessary to accurately assess large height deviations. The form is available in three different languages, Portuguese, Spanish, and English and is accessible on CARSAMMA's web site at the following location: <http://www.cgna.gov.br/CARSAMMA/siteUSA/inicial.htm> . A sample of this form is included in Appendix C.

5.1.4. Accessibility of LHD reporting materials is essential to encourage the reporting of events by all parties involved in the provision of air traffic services.

5.1.5. The GTE will explore all sources for reports of large height deviations such as State databases of air safety incident reports and voluntary reporting safety databases.

5.1.6. When analyzing reports of large height deviations, the primary concern of the GTE is the impact of such events on the collision risk and on the overall safety of the system. Data collected by the GTE is used for analysis purposes only and all LHD events reviewed by the GTE are de-identified. Confidentiality will be maintained.

6. Data Review and Evaluation

6.1.1. The methodology employed by the GTE is to examine existing databases as well as other sources and analyze events resulting in a large height deviation of 300ft or greater within FL290-FL410. These events are usually the result of Air Traffic Control (ATC) loop errors (the undiscovered misunderstanding of a clearance), instances wherein a controller fails to capture an inaccurate read-back, an altitude over or undershoot, turbulence situations, emergencies, errors in coordination, weather complications or response to an ACAS resolution advisory. The largest source of reports useful for these purposes comes from the established regional safety reporting systems. However, in many instances these reports are designed for other purposes so they may lack the clarity

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

on information that would be desirable to the GTE. Thus, the experience of the members of the Scrutiny Group is essential in order to infer the effect, if any, the events have on risk in the airspace. All data sources undergo an initial review using key RVSM parameters and all reports of interest are extracted for further evaluation.

7. Methodology

7.1.1. The GTE is tasked with the responsibility of analyzing all reports of interest and assigning parameter values, as defined in the GTE LHD White Paper (Appendix D), that consist of cleared flight level, event flight level, levels crossed, final flight level, duration at unplanned flight level and total vertical deviation. Since the reports are not tailored for the needs of the Scrutiny Group, these values are not typically clearly defined. The GTE must rely on the expert judgment and operational experience of its members to assign these values.

7.2. Parameter Values

7.2.1. Cleared Flight Level

7.2.1.1. The flight level at which the pilot was cleared or currently operating. For example, aircrew accepts a clearance intended for another aircraft and ATC fails to capture the read back error or aircrew conforms to a flawed clearance delivered by ATC.

7.2.1.2. This parameter, in some cases, will require expert judgment and operational experience to assign a value. The Scrutiny Group must take into consideration the controller's plan versus the cleared flight level.

7.2.2. Event Flight Level

7.2.2.1. The event flight level is the flight level of error or the incorrect altitude of operation for an identifiable period of time without having received an ATC clearance

7.2.3. Duration at Unplanned Flight Level

7.2.3.1. The greatest exposure to risk is the time spent level at a flight level other than the cleared level. This parameter value contributes significantly to the calculation of operational risk.

7.2.3.2. The duration at unplanned flight level is the length of time that an aircraft was level at an altitude (flight level) that was not cleared, or planned, by air traffic control. Duration is recorded in one second increments.

7.2.3.3. The calculation of duration begins once the aircraft is level at a flight level other than the cleared level or planned level by ATC, and terminates once ATC initiates remedial action.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Figure 1 illustrates a large height deviation that has a duration value larger than zero. The duration calculation begins at point A and terminates at point B.




Figure 1.

7.2.3.4. It is important to note that not all large height deviations result in the aircraft being level at a flight level other than that cleared or planned by ATC; therefore, some events are assigned a duration value of zero.

7.2.3.5. It is also important to note the duration value determined or assigned by the GTE of LHDs that occur in a radar environment will vary significantly from that of a non-radar environment.

7.2.3.6. In most cases, LHD reports reviewed by the GTE lack the information necessary to calculate the time spent at incorrect flight level. Thus, the experience of the members of the Scrutiny Group is essential to provide in-depth analysis of each event

7.2.3.7. If the Scrutiny Group is unable to determine the time spent at incorrect flight level, a default value is assigned.

7.2.3.8. The GTE identified the need to establish a default duration value to assign to those events where there is not enough information included in the report to determine the time spent at incorrect flight level. Two default values were established, one for a radar environment and one for a non-radar environment. The default values are included in the GTE LHD White Paper, Appendix D.

7.2.4. Total Vertical Deviation

7.2.4.1. Total vertical deviation is the distance in feet between the altitude of current operation prior to the deviation and the point at which the aircraft is once again under ATC supervision. A deviation that resulted in an increase of altitude will be recorded as a positive number and a deviation that resulted in a decrease of altitude will be recorded as a negative number.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

7.2.4.2. Figures 2 and 3 illustrate two large height deviations of different magnitudes. The first example, Figure 2, illustrates a large height deviation with a magnitude of 1000ft. The second example, Figure 3, illustrates a large height deviation with a magnitude of 1300 ft.




Figure 2.




Figure 3.

7.2.5. Levels Crossed

7.2.5.1. The total number of flight levels between the point that the aircraft exits the cleared flight level and is once again under ATC supervision is calculated to determine the number of levels crossed. For example, in the examples provided in figures 2 and 3 in section 7.2.4.2, one level was crossed.

7.2.5.2. The Scrutiny Group must consider the hazard zone when calculating the number levels crossed. The hazard zone is also referred to as the buffer zone.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

7.2.5.3. The hazard zone is the minimum physical distance of defined dimensions to accommodate:

- a) Variations in an aircraft's flight path due to air movements, etc.;
- b) The size of the aircraft;
- c) An additional "miss" distance

7.2.5.4. The value of the hazard zone was determined to be ± 90 m (300ft). A brief explanation of the considerations underlying this value is included in paragraph 2.3.6.7 in the *Air Traffic Services Planning Manual (Doc 9426)*. The explanation is also included in Appendix E

7.2.5.5. This buffer zone criterion shall be used to determine that a specific level is occupied by an aircraft. In the LHD illustrated in figure 4, the aircraft penetrates the buffer zone but does not reach the next flight level. Applying the criterion described in paragraph 7.2.5.4, the total number of levels crossed in this example is 1.




Figure 4

7.2.6. Levels Final

7.2.6.1. The final flight level is the cleared flight level after the error/deviation.

7.2.6.2. Some reports of large height deviations do not contain the final flight level. When this information is not available in the LHD report, the Scrutiny Group relies on operational expert judgment to determine the final flight level. The final flight level of the large height deviation illustrated in figure 5 is 370.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE




Figure 5.

7.2.7. Rate of Climb or Descent

7.2.7.1. The rate of climb or descent of an aircraft crossing through an uncleared level also contributes to the estimate of operational risk. In most cases, this parameter value is not included in reports of large height deviations. The GTE must rely on operational expert judgment to determine the rate of climb or descent.

7.2.7.2. The GTE established climb and descent rate default values. The default values are included in the GTE LHD White Paper (Appendix D)

7.2.8. Event Category

7.2.8.1. Classification of each LHD event is necessary for risk assessment purposes and for the identification of adverse trends. Each LHD event is assigned an error type code that identifies the type of event that caused the deviation. The error codes are categorized as operational or technical for consideration in the Collision Risk Model (CRM). A complete list of the error codes is included in table 1.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Table 1. Error Codes

A	Failure to climb/descend as cleared
B	Climb/descend without ATC clearance
C	Entry into airspace at an incorrect flight level
D	Deviation due to turbulence or other weather related cause
E	Deviation due to equipment failure
F	Deviation due to collision avoidance system (TCAS) advisory
G	Deviation due to contingency event
H	Aircraft not approved for operation in RVSM restricted airspace
I	ATC system loop error; (e.g. pilot misunderstands clearance message or ATC issues incorrect clearance)
J	Equipment control error encompassing incorrect operation of fully
K	Incorrect transcription of ATC clearance or re-clearance into the FMS
L	Wrong information faithfully transcribed into the FMS (e.g. flight plan followed rather than ATC clearance or original clearance followed instead of re-clearance)
M	Error in ATC-unit-to-ATC-unit transition message
N	Negative transfer received from transitioning ATC-unit
O	Other
P	Unknown

7.3. Analysis

7.3.1. It is the responsibility of the GTE to summarize their findings and analyze the data with the goal of identifying adverse trends and assess the overall risk.

7.3.2. The benefits of analyzing LHD data over time

7.3.2.1. Maintaining a cumulative summary of analyzed LHD events will allow the GTE to determine the following:

- a) The frequency of occurrence
- b) Whether errors appear to occur systematically or randomly in time
- c) Time between each event

- d) Effect of airspace changes, if any, since RVSM implementation

7.3.3. Identify trends

7.3.3.1. The cumulative LHD summary is also used to identify adverse trends. The Scrutiny Group will evaluate grouped event categories and determine whether one particular event type occurs more often than another. This particular analysis can also be applied to geographic regions.

7.3.3.2. The Scrutiny Group will also identify operational trends that may be revealed in the data. If any exist, the Group may make recommendations for reducing the effect of those trends.

7.4. Remedial Recommendations

7.4.1. If adverse trends are identified, the Scrutiny Group will submit recommendations for remedial actions to ensure that operational errors are kept to a minimum and that the airspace being examined continues to satisfy the requirements of the target level of safety, which is necessary to support continued RVSM operations.

7.4.2. It is important to bear in mind that height deviations, as a consequence of operational errors and in-flight contingencies, occur in all airspace irrespective of the separation minimum. The purpose of this monitoring activity is to ensure that operations in RVSM airspace do not induce an increase in the risk of collision from these events and that the total vertical risk does not exceed the agreed overall safety objectives. The actions and measures proposed to reduce risk should not be exclusive to RVSM airspace.

7.5. Reporting

7.5.1. The Scrutiny Group reports annually to the RMA the results of its operational analysis including the identification of performance trends, summary of categories and estimation of duration at incorrect flight level, and recommended measures to reduce the risk in RVSM airspace. The RMA will incorporate the analysis of the Scrutiny Group in its report to the ICAO Regional Planning Group (GREPECAS) for the CAR/SAM regions.


7.6. Meeting Frequency

The Scrutiny Group should meet regularly so that adverse trends due to operational errors that cause large height deviations can be identified quickly and remedial actions can be taken.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Appendix A

RVSM Dataflow and Decision-Making Process Highlighting Scrutiny Activities



APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Appendix B

**Terms of Reference of the CAR/SAM RVSM Grupo de Trabajo de Scrutinio
(RVSM/GTE)**

- a. To assemble subject matter experts, as needed, in air traffic control, aircraft operations and maintenance, regulation and certification, data analysis and risk modeling;
- b. To analyze and evaluate large height deviations of 300 ft or greater as defined by ICAO Doc 9574;
- c. To coordinate the assembly and review of large height deviation data with the Regional Monitoring Agency;
- d. To produce an estimate of flight time away from the cleared flying level to be used a primary input in the preparation of an estimate of risk by the Regional Monitoring Agency;
- e. To identify large height deviation trends and to recommend remedial actions in order to improve safety;
- f. To report results to GREPECAS through the ATM/CNS subgroup;
- g. To accomplish other tasks as directed by GREPECAS;
- h. Participate in the Regional Aviation Safety Group – Panamerican (RASG-PA) to harmonize regional safety initiatives.

Composition: 1 State/Organization from the CAR Region, 1 State/Organization from the SAM Region, United States, CARSAMMA, COCESNA, IATA, IFALPA, IFATCA.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Appendix C

CARSAMMA Caribbean and South American Monitoring Agency	The information contained in this form is confidential and will be used for safety analysis purposes only.		
ALTITUDE DEVIATION FORM			
Report to the CARSAMMA of an altitude deviation of 300ft or more, including those due to TCAS, Turbulence and Contingency Events			
Today's date:	Reporting Unit:		
INCIDENT DETAILS			
Operator Name:	Call Sign:	Aircraft Type:	Mode C Displayed:
Date of Occurrence:	Time UTC:	Occurrence Position (lat/long or Fix):	
Cleared Route of Flight:			
Cleared Flight Level:	Estimated Duration at Incorrect Flight Level (seconds):	Observed Deviation (+/- ft):	
Other Traffic Involved:			
Cause of Deviation (<i>brief title</i>):			
(Examples: ATC Loop Error, Turbulence, Weather, Equipment Failure)			
AFTER SEPARATION RESTORED:			
Observed/Reported Final Flight Level*:	Mark the appropriate box	Did this FL comply with the ICAO Annex 2 Tables of Cruising Levels?	
*Please indicate the source of information – ModeC/Pilot	Is the FL above the cleared level: <input type="checkbox"/>	<input type="checkbox"/> Yes	
	Is the FL below the cleared level: <input type="checkbox"/>	<input type="checkbox"/> No	
NARRATIVE			
Detailed Description of Incident			
<i>(Please give your assessment of the actual track flown by the aircraft and the cause of the deviation.)</i>			
CREW COMMENTS (IF ANY)			
<p>When complete please forward the report(s) to:</p> <p>Management Center Of Air Navigation Caribbean and South American Monitoring Agency (CARSAMMA) Av. Brig. Faria Lima, 1941 São José dos Campos, SP Cep: 12227-000 Brazil Telephone: (55-12) 3904-5004 or 3904-5010 Fax: (55-12) 3941-7055 E-Mail: carsamma@cqna.gov.br</p>			

Appendix D

Grupo de Trabajo de Scrutinio (GTE) Large Height Deviation (LHD) White Paper

Description of Criteria

Note: The following terms, expressions and definitions are not approved by the ICAO's Council and should be used for analysis of Large Height Deviation purpose only.

Cleared Flight Level – the flight level at which the pilot was cleared or currently operating (eg, Aircrew accepts a clearance intended for another aircraft and ATC fails to capture the read back error or aircrew conforms to a flawed clearance delivered by ATC)

Reference Flight Level – The altitude that would have provided at least the minimum separation (vertical or horizontal) required

That flight level from which the Height Deviation is calculated; this level may be different from the Cleared Flight Level and must often be determined by the Scrutiny Group operational experts from the data in the Large Height Deviation report

Event Flight Level – the flight level of error, the incorrect altitude of operation for an identifiable period of time without having received an ATC clearance

Height Deviation – any altitude variation of 300ft or greater from the assigned altitude, these variations can be the result of turbulence, equipment malfunction, ATC loop errors, etc.

ATC Loop Errors – any incident where there is a misunderstanding between the pilot and the controller, failure to properly coordinate altitude information or unable to maintain situational awareness

Total Deviation – the total amount of feet between the altitudes of current operation prior to the deviation and the point at which the aircraft is once again under ATC supervision, a deviation that resulted in an increase of altitude will be recorded as a positive number, a deviation that resulted in a decrease of altitude will be recorded as a negative number

Hazard Zone – 300ft buffer zone above and below each flight level (Diagram 1-A)

Duration - length of time that an aircraft was level at an altitude that was not cleared by air traffic control, duration will be recorded in one second increments (Diagram 1-A), if the Scrutiny Group is unable to determine the time spent at incorrect flight level, a default value is assigned. The default values are included in Table 1.

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Table 1. Duration Default Values

Radar	Non-Radar
90 s	90 s

Levels Crossed – the total number of flight levels between the point that the aircraft exits the cleared flight level and is once again under ATC supervision (Diagram 1-A)

Levels Final – the cleared flight level after the error/deviation

Code – a category and a subcategory assigned to each event (Diagram 1-B)

Rate of Climb or Descent – the climb and descent values are included in Table 2.


Table 2 Climb and Descent Values

Rate of Descent		Rate of Climb	
Drift	1000 ft per minute	Minimum	500
Normal	1500+ ft per minute	Normal	750
Rapid	2500+ ft per minute	Expedite	1250

APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Diagram 1-A

RVSM Flight Levels



APPENDIX B
CAR/SAM RVSM GTE REFERENCE GUIDE

Diagram 1-B

Error Codes

Code	Cause of Large Height Deviation
A	Failure to climb/descend as cleared
B	Climb/descend without ATC clearance
C	Entry into airspace at an incorrect flight level
D	Deviation due to turbulence or other weather related cause
E	Deviation due to equipment failure
F	Deviation due to collision avoidance system (TCAS) advisory
G	Deviation due to contingency event
H	Aircraft not approved for operation in RVSM restricted airspace
I	ATC system loop error ; (e.g. pilot misunderstands clearance message or ATC issues incorrect clearance)
J	Equipment control error encompassing incorrect operations of fully functional FMS or navigation system (e.g. by mistake the pilot incorrectly operates INS equipment)
K	Incorrect transcription of ATC clearance or re-clearance into the FMS
L	Wrong information faithfully transcribed into the FMS (e.g. flight plan followed rather than ATC clearance or original clearance followed instead of re-clearance)
M	Error in ATC-unit-to-ATC-unit transition message
N	Negative transfer received from transitioning ATC-unit
O	Other
P	Unknown

Appendix E

2.3.6.7 *Accuracy of SSR Mode C data*

2.3.6.7.1 The use of SSR Mode C data must take account of the following errors affecting accuracy:

- a. Correspondence error, reflecting discrepancies between level information used and the level information encoded for automatic transmission. The maximum value of this error has been accepted to be $f \pm 38$ m (125 ft) (95 per cent probability) (cf. ICAO Annex 10, Volume I, Part I, 3.8.7.12.2.5);
- b. Flight technical error, reflecting inevitable deviations by aircraft from intended levels as a reaction to flight control operations, turbulence, etc. This error, when related to manually flown aircraft, tends to be larger than that for aircraft controlled by automatic pilots. The maximum value of this error used so far, based on a 95 per cent probability, is ± 60 m (200 ft) (cf. *Report of COM/OPS Divisional Meeting (1966)*, Item 9, page 9-35, 4.2). However, it should be noted that a number of factors contributing to this value have been improved since.

2.3.6.7.2 The mathematical combination of the non-related errors in a) and b) above results in a value of ± 72 m (235 ft) (based on a 95 per cent probability) and it is therefore believed that a value of $f \pm 90$ m (300 ft) constitutes a valid decision criterion to be applied in practice when:

- a. Verifying the accuracy of SSR Mode C data;
- b. Determining the occupancy of levels.

APPENDIX C
SUMMARY OF LHD ANALYSES FOR THE PERIOD OF JAN 08 TO JUN 08

Tabela LHD 2008	
POSITION	TIMES
?	
05N035W	
0912N03540W	
0919N 03543W	
0951N 04929W	
09N050W	
1140N 03642W	3
120 NM AL W DEL VOR TIK (TIKAL)	
1312N 03723W	2
140615N 0740148W	
15 NM DE REMEK	
1651N03730W	
17N 03730W	
1800N04600W	
18N 058W	
25 NM SE DE BUSMO	
293406S0513214W	
40 NM AL NW DE POSICION VUMAL	
45 NM DEL VOR IQT (NE)	2
50 NM SUR DE BUXOS	2
50 NM NE DE BUSMO	
52 NM SUR DE DAGUD	
60 NM AL N DE NEDUL	
70 NM AL SUR DEL VAS / ASU	
AKPOD	
AKROK	
AL SUR DE PZA VOR / DME	
ALCOT	3
ALGEL - BOBIK	
ALSAL	
AMBIN	4
AMERO	
ANADA	7
ANKON	
ARNAL	
ARNEL	
ARNEL	

Tabela LHD 2008	
POSITION	TIMES
ARORO	3
ARTOM	
ASOKU	
AVELO	3
BAIAN	
BENET	
BEROX	5
BETAR	
BIDEV	
BISUK	3
BOGSI	
BOKAN	9
BRIDE	
BUXOS	5
CLOVE - NEURA	
CRUDE	
DAGUD	2
DAREK	10
DIBOK	4
DORKA	2
DUXUN	
EGEXO	
ELASO	3
ELOPO	2
ENRUT	
ENSOL	7
EPODE / INTOL	
ERBOR	
ESIPO	5
FALLA	
FEMUR	
FIR CW	
FLIRT	
FORTI	
FRONT	
GABAR	
GONZA	
IMBUD	
IRELA	
IREMI	5

APPENDIX C
SUMMARY OF LHD ANALYSES FOR THE PERIOD OF JAN 08 TO JUN 08

Tabela LHD 2008	
POSITION	TIMES
IRGUT	6
ISEBA	2
ISIMO	
ITEGO	15
KAISO	
KAKOL	2
KALAD / VAS / ARPAS	
KONRI	4
KORTO	3
KOVEX	
LAN NDB	
LET	
LIBRA	3
LIMPO	
LIXAS	7
LOGAL	
LOVAX / RMK	
LOVIS	2
MCL (MOROS) / VAS	
MEGIR	
MELLA	
MINDA	3
MIRLO	
MIRNA (S04 FIR CW)	
MORSA	
NANIK	4
NEKOB	
NOREX	
OCTIL	2
ONGAL	7
OROMU	
OROMU - MOROS	
OROSA	3
OSELO	
OTELO	
PADOX	3
PAGAK	
PALAS	9
PELMA	6
PERRY	

Tabela LHD 2008	
POSITION	TIMES
PIGBI	
PLG	
POKAK	4
POS / FOZ	
PULTU	
QDR 252 - 87 NM DE YLH	
QDR 304 - 109 NM DE SGR (Porto Seguro)	
RDL 130 - 50 NM DE REC	
RDL 308 - 64 NM DE SVD	
RDL081 - 110 NM DE LAPA	
RDL236 / 136NM VOR FLZ	
REGIS	
REMEK	
REPAM	
REPAM - VAS	
REPIS	
RETAK	
RUTA LATERAL FOZ / LATERAL KEVUR	
SAGAZ	2
SELAN	2
SELVA	
SIDOS	
SISEL	3
SORTA	
SUR DE DAGUD	
SUR DE UKLOS	
TELAX	
TERAS	3
TRAPP	
TRAVÉS NORTE DE MACEIO	
UB688	
UGADI	
UGUPI	12
UKLOS	3
URIBI	
VAGUR	2
VAKUD	6
VALEM	

APPENDIX C
SUMMARY OF LHD ANALYSES FOR THE PERIOD OF JAN 08 TO JUN 08

Tabela LHD 2008	
POSITION	TIMES
VESKA	33
VODIN	
VOR DE LIM	2
VOR FOZ	
VSJ	

Tabela LHD 2008	
POSITION	TIMES
VUDAL	2
VUMPI	3
VUMPT 180 80 NM	

