



**INTERNATIONAL CIVIL AVIATION ORGANIZATION**

**RLA/03/901**

**FOURTH MEETING ON THE TECHNICAL-  
OPERATIONAL IMPLEMENTATION OF THE  
NEW REDDIG II DIGITAL NETWORK  
(RTO/4)**

**FINAL REPORT**

**(Manaus, Brazil, 20 to 21 April 2015)**

*The designations employed and the presentation of material in this publication do not imply the expression of any opinion whatsoever on the part of ICAO concerning the legal status of any country, territory, city or area of its authorities, or concerning the delimitation of its frontiers or boundaries.*

**INDEX**

i - Index .....ii-1

ii - History of the Meeting .....ii-2  
Place and duration of the Meeting .....ii-2  
Opening .....ii-2  
Agenda .....ii-2  
Working Languages .....ii-2  
Participation and Organization .....ii-2  
List of Conclusions .....ii-2

iii - List of participants .....iii-1

**Report on Agenda Item 1:**  
Performance of the REDDIG II since its commissioning..... 1-1

**Report on Agenda Item 2:**  
Review of the procedures for the maintenance and operation of the REDDIG II ..... 2-1

**Report on Agenda Item 3:**  
Analysis of the requirements for the improvement of the REDDIG II provision..... 3-1

**Report on Agenda Item 4:**  
Other business..... 4-1

## **HISTORY**

### **ii-1 PLACE AND DURATION OF THE MEETING**

The Fourth Meeting on the Technical-Operational Implementation of the New REDDIG II Digital Network (RTO/4), was held in Manaus, Brazil, from 20 to 21 April 2015 at the premises of the Technical Section of the Cuarto Centro Integrado de Defensa Aérea y Control del Tránsito Aéreo – CINDACTA IV.

### **ii-2 OPENING**

Coronel (AV) Carlos Henrique Afonso Silva, Comandante de CINDACTA IV, welcomed the participants highlighting the topics to be debated and wished success in their deliberations. Following, proceeded to inaugurate the meeting.

### **ii-3 AGENDA**

- Agenda Item 1: Performance of the REDDIG II since its commissioning
- Agenda Item 2: Review of the procedures for the maintenance and operation of the REDDIG II
- Agenda Item 3: Analysis of the requirements for the improvement of the REDDIG II provision
- Agenda Item 4: Other business

### **ii-4 WORKING LANGUAGES**

The working languages of the meeting were Spanish and English.

### **ii-5 PARTICIPANTS AND ORGANIZATION**

The Meeting counted with the assistance of 8 member States (Argentina, Brazil, Chile, Ecuador, Paraguay, Peru, Trinidad and Tobago and Uruguay), making a total of 21 participants, including ICAO specialist. List of participants is presented in page iii-1.

Mr. Luis Alejos, REDDIG Administrator, acted as Secretary assisted by Mr. Francisco Almeida, Chief of the Technical Coordination Division of DECEA-Brazil.

### **ii-6 LIST OF CONCLUSIONS**

<b>No.</b>	<b>Title</b>	<b>Page</b>
RTO/4-1	Final Acceptance Test (FNAT) of the REDDIG II	1-2



**INTERNATIONAL CIVIL AVIATION ORGANIZATION**  
**South American Regional Office**

**RLA/03/901 REDDIG**  
**Fourth Meeting on the Technical/Operational Implementation of the New REDDIG II**  
**(RTO/4)**

(Manaus, Brazil, 20 to 21 April 2015)

**LIST OF PARTICIPANTS**

**ARGENTINA**

1. Sergio Vallone
2. Hernán Cana
3. Antonio González

**BRAZIL**

4. Francisco Almeida
5. Vitor Dos Santos Alves
6. Bruno Pacheco S. A. Costa
7. Joan Magno C. Macedo
8. Aguinaldo Brazil Motta
9. Arlindo Ferreira Junior
10. Jefferson M. Cheron
11. Magno Rodrigues
12. Sandro I. M. Mendes

**CHILE**

13. Christian J. Vergara

**ECUADOR**

14. Raúl Avellán Oña

**PARAGUAY**

15. Aldo Omar Pereira Alcaraz
16. Víctor José Morán Maldonado

**PERU**

17. Andrés Arango

**TRINIDAD & TOBAGO**

18. Shiraz Gopaul
19. Varun Dave Sookra

**URUGUAY**

20. Miguel Vera

**ICAO**

21. Luis Alejos

**Agenda Item 1: Performance of the REDDIG II since its commissioning**

1.1 Under this agenda item, the meeting was informed on the follow up on the REDDIG II operation, describing the following activities:

- Provisional Acceptance Testing Process (PSAT)
- Operation the REDDIG II post PSAT
- Spare parts of the REDDIG II

***Provisional Acceptance Testing Process (PSAT)***

1.2 For the provisional acceptance tests, the PSAT – NAT - NT 2022-2141167C rev H was used, the focal points of the REDDIG II proceeded to sign the PSAT certificate from 31 January 31 to 5 February 2015 with comments in each of the nodes.

1.3 The results of the PSAT tests in each of the nodes were registered by the focal points in the PSAT document (H version). In the web page [www1.lima.icao.int/reddig](http://www1.lima.icao.int/reddig) are published the PSAT documents completed by the focal points.

1.4 A summary with the pending list of activities during the PSAT in each of the nodes is presented in **Appendix A** to this Agenda Item.

1.5 From the pending activities, common aspects to all nodes are highlighted as the lack of IP telephone service operation designed to support the control centers in managing the flow of Air Traffic Management (ATFM), false alarms and quality in the presentation of the Management System (NMS) of the REDDIG II, the quality of the AFTN messages, loss of packages above the quantity permitted by the terrestrial network LEVEL 3 and the update of the documents containing the circuit diagrams, result of the changes made during the node's installation of the REDDIG II.

1.6 Likewise in the REDDIG II nodes using E1 as Colombia, Ecuador and Peru, highlights the lack of functioning of the administrative switched voice services, in Colombia the oral ATS switched and dedicated services between Colombia and Panama and the oral ATS switched between Colombia and CENAMER.

1.7 Completion of the AMHS interconnection between Peru-Colombia, Peru-Ecuador and Argentina-Paraguay, as well as the asynchronous and IP connection for radar data exchange between Argentina and Uruguay failed to be achieved.

***Operación de la REDDIG II post PSAT***

1.8 The status of the pending activities as of the date of the RTO/4 meeting is presented in **Appendix B** to this Agenda Item. The information on the implementation progress of the outstanding activities of the Appendix has been filled out by INEO. The Q column of Appendix B contains comments from the States and from ICAO regarding the progress reported by INEO. According to the action plan for the settlement of the pending activities stated in Appendix B, all the pending activities would be completed by 10 April 2015. As of date of the RTO/4 meeting, it has been fixed the IP addresses conflicts between the terrestrial and satellite network, the ATS oral circuit between Guayaquil and CENAMER, the

administrative speech service in Ecuador, the AMHS circuit Peru-Ecuador (by satellite network only) and Peru-Colombia.

1.9 During the operational installation of the REDDIG II equipment, the MODEM 1070 team of the A chain of Lima, MODEM 1070 of COCESNA, and the screen of the GPS clock of the Santiago node did not work and had to be replaced by new equipment. To replace the MODEMS of Peru and COCESNA, equipment of the REDDIG II spares parts warehouse were used and the GPS clock was shipped from the factory to Chile. Once MODEM 1070 equipment are repaired they will be delivered to the ICAO SAM Office where the spare parts warehouse is located.

1.10 INEO, according to the contract signed between ICAO and the INEO consortium & LEVEL 3, has a time of 40 days to solve all the outstanding activities identified in the PSAT and ORD time. As of the date of the RTO/4, the ORD time has finished, remaining most of the outstanding activities uncompleted.

1.11 For the final acceptance of the REDDIG II, the final acceptance of the FNAT tests are missing, which just like the PSAT tests, will be verified and signed by the focal points of the REDDIG II and by the Project Management (ICAO). On this respect, focal points should not sign the FNAT certificate if there are still outstanding aspects in the PSAT or later identified during the ORD period. In this regard, the following conclusion was adopted:

#### **Conclusion RTO/4-1 - Final Acceptance Test (FNAT) of the REDDIG II**

That Member States of the REDDIG II proceed to sign the certificate of final acceptance of the REDDIG II (FNAT) only if all the problems identified during PSAT or later in the ORD period have been resolved.

#### ***Spare parts of the REDDIG II***

1.12 To store the spare parts of the REDDIG II at the Regional Office, a special room was adapted, especially suited for storing spare parts with appropriate equipment to control moisture, with an anti-static floor and racks to place the equipment.

1.13 The list of the REDDIG II equipment can be found in the Detailed Scope of Supply Version F on the website [www1.lima.icao.int/reddig](http://www1.lima.icao.int/reddig). For the accommodation and classification of the spare parts in the special room at the Regional Office, Mr. Harry Peñaranda, Communication's Technician of the Civil Aviation Corporation of Peru was hired. The result of the classification work is presented in Appendix C to this Agenda Item.

1.14 In the same room, are keep the spare parts of the REDDIG I equipment. Regarding the spare parts and equipment of the REDDIG, I the Eighteenth Coordination Committee of the REDDIG II (Lima, Peru 2 to 4 March 2015) formulated the Conclusion RCC/18-5 Provision of equipment and spare parts of the REDDIG I, so that the Secretariat can explore the feasibility of having the equipment and spare parts of the REDDIG I both for sale and other figures that could manifest and report the results to start by the second half of 2015 to all Member States of the RLA/03/901.

1.15 In this regard, the Secretariat proceeds to send to all Member States of the REDDIG letter SA5112 dated 25 March 2015 enquiring the intentions that their administrations have regarding equipment and spare parts of the REDDIG I and asking to reply by 15 May 2015.

**APPENDIX A****SUMMARY OF COMMENTS MADE BY THE FOCAL POINT DURING THE PSAT**

<b>STATE</b>	<b>NODE</b>	<b>PSAT DATE</b>	<b>COMMENTS</b>
Argentina	Ezeiza	2/2/15	<ul style="list-style-type: none"> <li>• Pending to amend circuit diagrams</li> <li>• Poor quality on terrestrial IP telephony and satellite network</li> <li>• Pending BER tests AFTN circuits</li> <li>• False Alarms in serial ports CISCO IA</li> <li>• Low levels of transmission SKYwan A and B</li> <li>• Emergency Number GBB dedicated router (Fig 46 communicates with Manaus with the number 73601 and not the number indicated in the table in Figure 46</li> <li>• Loss of packets in the terrestrial networks of Manaus, Recife, Guyana, Paraguay and Suriname.</li> <li>• Access to the website of LEVEL 3 for service management is not supplied</li> <li>• Two RJ45 connectors damaged Patch Panel</li> </ul>
Bolivia	La Paz	2/2/15	<ul style="list-style-type: none"> <li>• No comments</li> </ul>
Brazil	Curitiba	2/2/15	<ul style="list-style-type: none"> <li>• No comments</li> </ul>
	Manaus	5/2/15	<ul style="list-style-type: none"> <li>• Lima Manaus AFTN circuit does not work</li> <li>• Slope of circuit diagrams update</li> <li>• The loss of packets in the terrestrial network are above what specifies the SLA LEVEL 3</li> <li>• Testing in administrative circuits, switched ATS and AFTN made in one chain in terrestrial network</li> <li>• IP Teleconference does not work according to the technical specifications limited to 10 users</li> </ul>

STATE	NODE	PSAT DATE	COMMENTS
			<ul style="list-style-type: none"> <li>• Image quality unimproved slope aspect from the FAT</li> <li>• Administrative Canal with Ecuador does not operate</li> <li>• Observation slope from the FAT: In case of failure of the central server in Manaus NMS backup server Ezeiza should assume all functions of the central server with all the powers of monitoring and control over all seasons</li> <li>• Pending BER tests on AFTN channels</li> <li>• Pending SAT TEST LOOP VER</li> <li>• Testing pending ATS speech circuits, administrative AFTN in one strand of the satellite network</li> </ul>
	Recife	30/1/15	<ul style="list-style-type: none"> <li>• Loss of packets in the terrestrial network LEVEL 3 with all nodes</li> <li>• Pending BER tests AFTN</li> <li>• False alarm NMS (IBUC) and RX 1 + 1</li> </ul>
Chile	Santiago	1/2/15	<ul style="list-style-type: none"> <li>• Damaged Screen GPS Watch</li> <li>• NMS: refresh state changes very slowly</li> <li>• Image quality is not improved slope aspect from the FAT</li> <li>• IBUC WEB: The indication of voltage does not correspond to the actual value</li> <li>• Pending update diagrams</li> <li>• AFTN circuit with Lima inoperative</li> <li>• Pending BER test AFTN</li> </ul>
Colombia	Bogota	1/2/15	<ul style="list-style-type: none"> <li>• Circuit ATS oral Bogota Panama does not work</li> <li>• AMHS circuit with Peru does not work</li> </ul>
Ecuador	Quito	1/2/15	<ul style="list-style-type: none"> <li>• Administrative Voice Circuits inoperative</li> </ul>

STATE	NODE	PSAT DATE	COMMENTS
			<ul style="list-style-type: none"> <li>• Packet loss Ground Level 3 network Manaus, Recife Guyana Uruguay</li> <li>• BER testing pending AFTN</li> <li>• Test Tx switch (7.1.1) did not</li> <li>• VoIP teleconference poor quality</li> <li>• False alarm operation of the serial interfaces and E1</li> <li>• Pending ATS voice test circuit Between Guayaquil and CENAMER</li> </ul>
French Guyana	Cayenne	2/2/15 Falta firma INEO	<ul style="list-style-type: none"> <li>• The power connector on the IP phone does not work</li> <li>• Diagrams of circuits incorrect (WVG)</li> <li>• Difficulty reading the IP address of WVG</li> <li>• Error in the LAN interface does not work</li> <li>• Modem B is not going green when turned on</li> <li>• Rear Problem with AFTN circuit Manaus</li> </ul>
Guyana	Georgetown	5/2/15 Falta firma INEO	<ul style="list-style-type: none"> <li>• No indication of status on one of the switches in the MAP VIEW</li> <li>• You cannot make setting in voice interfaces</li> </ul>
Paraguay	Asuncion	2/2/15	<ul style="list-style-type: none"> <li>• Audible alarm UPS in battery mode, almost inaudible</li> <li>• Do not have the antivirus that is specified in Document SDD REDDIG II Scope of Supply Rev. F</li> <li>• The breaker Q5 presents a false contact so they must be changed</li> <li>• Administrative line do not configure IP</li> <li>• The graphical representation of the computers on the nodes in the NMS has not been improved, as had been observed in the FAT</li> </ul>

STATE	NODE	PSAT DATE	COMMENTS
			<ul style="list-style-type: none"> <li>• When testing redundancy Chapter 7 Pag. 70/125 of the PSAT, the IBUCs not indicate faults and do not switch automatically</li> <li>• The serial port 0/0/0 GBB router has a fault where lost packets at reception, so Card 2-Port Async / Sync Serial WAN Interface Card must be replaced</li> <li>• Pending updating circuit diagrams</li> <li>• Loss of packets in the terrestrial network LEVEL 3 with Bolivia, Recife (very high), Colombia, French Guiana, Guyana and Uruguay</li> </ul>
Peru	Lima	3/2/15	<ul style="list-style-type: none"> <li>• AFTN circuit with inoperative Manaus and Santiago</li> <li>• Chain MODEM inoperative 1070</li> <li>• The graphical representation of the computers on the nodes in the NMS has not been improved, as had been observed in the FAT</li> <li>• Pending updating circuit diagrams</li> <li>• Loss of network packets Earth Level 3., Manaus Argentina, Colombia, Guyana and Venezuela</li> <li>• ATS number d does not match</li> <li>• Testing chain satellite unrealized chain MODEM failure</li> <li>• BER Test unrealized</li> <li>• Pending testing equipment failures (Section 7.3)</li> <li>• Errors dial plan administrative circuits</li> <li>• Unsatisfactory quality IP voice teleconference</li> </ul>
Suriname	Paramaribo		<ul style="list-style-type: none"> <li>• Presents packet losses in the</li> </ul>

STATE	NODE	PSAT DATE	COMMENTS
			terrestrial network LEVEL 3 with Argentina, Manaus, Recife (very high) .Chile, Colombia, Ecuador, Guyana and Uruguay <ul style="list-style-type: none"> <li>• Pending BER tests</li> <li>• IP Teleconference only ten users</li> </ul>
Trinidad & Tobago	Piarco	4 /2/15 Falta firma de INEO	<ul style="list-style-type: none"> <li>• NMS: refresh state changes very slowly</li> <li>• Image quality unimproved slope aspect from the FAT</li> <li>• IP Teleconference only works with 11 users does not comply with the technical specifications of the REDDIG</li> <li>• No automatic switching on IBUC in case of failure only when power is switched off</li> <li>• Loss of packets in the terrestrial network LEVEL 3 Curitiba and Ecuador.</li> </ul>
Uruguay	Montevideo	2/2/15	<ul style="list-style-type: none"> <li>• Pending renovation plans with circuit diagrams</li> <li>• Unit 1070 B chain does not turn green light even when operating well</li> <li>• Pending change Feed Horn</li> <li>• NMS: refresh state changes very slowly</li> <li>• Image quality is not improved slope aspect from the FAT</li> <li>• Foul install antivirus in the NMS</li> <li>• The NMS has incorrect information</li> <li>• Pending BER tests</li> <li>• The supplied software for VPN remote version is not according to the manual shipped for installation can not be installed as suggested by INEO.</li> <li>• Loss of packets in the terrestrial network LEVEL</li> </ul>

<b>STATE</b>	<b>NODE</b>	<b>PSAT DATE</b>	<b>COMMENTS</b>
			3 with Bolivia, French Guyana, Suriname, Trinidad & Tobago and Venezuela
Venezuela	Maiquetía	31/1/2015	<ul style="list-style-type: none"><li>• The automatic switching is observed in the RSS</li></ul>

STATUS OF PENDING ACTIONS

ITEM NUMBER	STATUS	TYPE O/M	CRI TICITY	COUNTRY	NODE	CITY		OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS - 30 March 2015
P4SAEZ02051	CLOSED	P	4	Argentina	SAEZ	Ezeiza	1	Falta emendar diagramas circuitales	5 February 2015	As-built under realization		Closing date includes finalization of drawings for AFD sites 27/03: documents achieved, to be shipped on Monday 30th March 2015	27th March 2015	30th March 2015	Not closed The action is solved once all the REDDIG II focal points receive the document with the emended circuit diagrams and information presented are OK Pending the CD with the electronic documentation
P3SAEZ02052	ON PROGRESS	P	3	Argentina	SAEZ	Ezeiza	2	Calidad telefonía IP pésima red terrestre y satelital	5 February 2015	1/ Diagnostic of the current configuration 2/ New configuration to be proposed after analysis 3/ Configuration implemented, to be tested (12/03)		05/03 : diagnostic still on progress 13/03: modem configuration changed, test pending. 27/03: tests achieved with Manaus unsuccessful	10th-March-2015 20th-March-2015 10th April 2015		We expect that really the new date would be the 10th April
P4SAEZ02053	ON PROGRESS	P	4	Argentina	SAEZ	Ezeiza	3	Pendiente pruebas BER circuitos AFTN	5 February 2015	During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination		27/11/15 => Procedure for BER test targeted Marsh 02th => expected coordination from ICAO-Lima and FP to proceed 06/03/15 => waiting for a new diagnostic after Lima analysis 12/03/2015: AFTN test conducted between SAEZ and SUMU and then will be spread 27/03: new tested to be conducted at SUMU and SAEZ. In addition to that, hardware was bought by INEO to perform tests at INEO facility	10th-March-2015 20th-March-2015 10th April 2015		We expect that really the 10th April would be the closing date
P4SAEZ02054	solution identified	P	3	Argentina	SAEZ	Ezeiza	4	Falsas alarmas en los puertos seriales del CISCO IA	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 27/03/2015: testes achieved appears to be a communication instability between NMS and routers, as SSH conenction is very sensitive	20th-February-2015 6th-March-2015 12th-March-2015 20 March 2015 10th April 2015		We expect that really the 10th April would be the closing date
P2SAEZ02055	ON PROGRESS	P	2	Argentina	SAEZ	Ezeiza	5	Niveles de transmisión bajos SKYwan A y B	5 February 2015	1/ Remote diagnostic 2/ Remote intervention by INEO Expert		17/03: INEO technician will go to SAEZ to check hardware 27/03: INEO technician checked cables and WG, an antenna pointing will be achieved.	9th-March-2015 10th-March-2015 27th-March-2015 first/second week April		Some action was made but the RF level still low
P3SAEZ02056	CLOSED	P	3	Argentina	SAEZ	Ezeiza	6	Numero de emergencia dedicado GBB router (Fig 46. se comunica con Manaos con el numero 73601 y no con el numero indicado en la tabla de la figura 46	5 February 2015	To be corrected		27/03/15 => targeted 04/03/2015 06/03 : email send to clarify	4th March 2015		OK
P2SAEZ02057	solution identified	P	2	Argentina	SAEZ	Ezeiza	7	Perdida de paquetes en la red terrestre Manaos, Recife, Guyana, Paraguay y Surinam.	5 February 2015	Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)		25/02/2015 => New request retransmitted to Level 3  06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were succesful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Coordination was made to make the test on LEVEL 3 network the 31 March.
P3SAEZ02058	ON PROGRESS	P	3	Argentina	SAEZ	Ezeiza	8	No se suministra el acceso a la página WEB de LEVEL 3 para la gestión de servicio	5 February 2015	Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)				LEVEL 3	The user name and password to acces LEVEL was sent March 27th
P4SAEZ02059	closed	P	4	Argentina	SAEZ	Ezeiza	9	Dos conectores RJ45 del Patch Panel dañados	5 February 2015	To be corrected - New connectors will be sent to FP		05/03/2015 => Connector sent to FP on 27/02 => Waiting for confirmation of receipt			OK

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY		OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS -30 March 2015
P2SAEZ022410	ON PROGRESS	P	2	Argentina	SAEZ	Ezeiza	10	Continue intermittent problem in the AFTN circuit between Argentina and Brazil, Uruguay and Paraguay. Controllers report lost of flight plan	25 February 2015	Under analysis		27/1/15 => Procedure for BER test targeted Marsh 02th => expected coordination from ICAO- Lima and FP to proceed 06/03/15 => waiting for a new diagnostic after Lima analysis 12/03/2015: AFTN test conducted between SAEZ and SUMU and then will be spread 27/03: new tested to be conducted at SUMU and SAEZ. In addition to that	40th-March-2015 20th-March-2015 10th April 2015		We expect that 10th April would be the closing date
O1SLLP17021	CLOSED	O	1	Bolivia	SLLP	La Paz	1	Communication problem with Manaus according to the email from ICAO (17th Feb.)	17 February 2015	OSPF Pb under analysis -> Looking for a technical solution to be implemented	diagnostic on course after identification of the problem on the routing table with Level 3 expected resolution for 25/02	27/02/2015 => New configuration will be used by ICAO to identify on the router, until re-communication with the ICAO experts (SLLP certifiad) 27/02/2015 => New configuration implemented, routing monitoring until 24/02/2015 19/03/2015 => improvement of the routing observed, on still to be confirmed 12/03/2015: communication test achieved with SOCA, pending test with SLLP	06th-March-2015 Test to be performed on 18th-March-2015 test performed successfully		OK Expecting closing day
P2SBMN02051	SOLUTION IDENTIFIED	P	2	Brazil	SBMN	Manaus	1	Circuito AFTN Manaus Lima no funciona	5 February 2015	1/ Check of the Cisco configuration 2/ Local check-up with one of our expert (on-site) in Lima As soon as we have define where exactly is the problem, INEO E&S will correct the bugg.	Problem identified	25/02/2015 => Test must be conducted in cooperation with Manaus AFTN center and REDDIG-II technical persons, waiting for their availability. 05/03/15 => problem solved, disturbsings still appear but were already identified in Reddig I	4/ 19th-February-2015 2/ 25th-February-2015		Solved but not closed pending intermittent loss of AFTN messages
P4SBMN02052	CLOSED	P	4	Brazil	SBMN	Manaus	2	Pendiente actualización diagramas circuitales	5 February 2015	As-built under realization		Closing date includes finalization of drawings to AEL sites 27/03: documents achieved, to be shipped on Monday 30th	27 March 2015	30th March 2015	Not closed The action is solved once all the REDDIG II focal points receive the document with the emended circuit diagrams and information presented are OK Pending the CD with the electronic documentation
P3SBMN02053	SOLUTION IDENTIFIED	P	3	Brazil	SBMN	Manaus	3	La perdida de paquetes en la red terrestre están por encima de lo que especifica el SLA de LEVEL 3	5 February 2015	Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)		25/02/2015 => New request retransmitted to Level 3 06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were succesful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Coordination was made to make the test on LEVEL 3 network the 31 March.
P3SBMN02054	CLOSED	P	3	Brazil	SBMN	Manaus	4	Pruebas en los circuitos administrativos, conmutados ATS y AFTN realizados en una sola cadena en la red terrestre	5 February 2015	During the PSAT, it appears that this test was already performed. It could be easily checked, and upon request by ICAO, it could be done during the ORD period with the local FP and INEO remote coordination		27/02/2015 => INEO re-configuration will continue during the ORD on 30/02/15 05/03/15 => Test done with success	25th-February-2015		OK
P4SBMN02055	SOLUTION IDENTIFIED	P	4	Brazil	SBMN	Manaus	5	Teleconferencia IP no trabaja de acuerdo a las especificaciones técnicas limitada a 10 usuarios	5 February 2015	1/ Diagnostic of the current licence 2/ New 16 users licences to be provided after analysis		05/03 : Hardware limitation found, solution to be provided. Will be codec change or hardware addition	5th-March-2015 20th March 2015		Still pending issue the IP telephone is general problem the date that you have reported in other part of this action plan is 10 April

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P4SBMN02056	CLOSED	P	4	Brazil	SBMN	Manaus	6 Calidad de la imagen no mejorada aspecto pendiente desde la FAT	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	12/03/15 - Problem identified - Implementation of the solution in progress 12/03 => new NMS aspect approved by OACI (L.Alejos email of 12/03), to be deployed in all site	20th-March-2015 06th-March-2015 17th-March-2015		OK in progress provide closing date
P3SBMN02057	ON PROGRESS	P	3	Brazil	SBMN	Manaus	7 Canal administrativo con Ecuador no opera	5 February 2015	1/ Analysis of the Cisco Configuration 2/ Correction to be proposed	To be solved from Ecuador side	12/03/2015 new configuration sent to Ecuador, pending tests 16/03 test achieved, still not operational 27/03 A Cisco expert will assist us for the test on April 3rd	2nd-March-2015 9th-March-2015 20th-March-2015 10th April 2015		We expect that 10th April would be the closing date
P3SBMN02058	CLOSED	P	3	Brazil	SBMN	Manaus	8 Observación pendiente desde la FAT: En caso de falla del servidor central del NMS en Manaus el servidor de reserva de Ezeiza debería asumir todas las funciones del servidor central con todas las atribuciones de monitoreo y control sobre todas las estaciones	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	12/03/15 - Problem identified - Solution will be implemented 19/03/15 05/03/15 : solution implemented, tests passed with success, see email with summary of the test	06th March 2015		Solved but not closed missing the respective test to verify if the transference are working properly
P4SBMN02059	ON PROGRESS	P	4	Brazil	SBMN	Manaus	9 Falta pruebas BER en canales AFTN	5 February 2015		During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination	27/11/15 => Procedure for BER test targetted Marsh 02th => expected coordination from ICAO- Lima and FP to proceed 06/03/15 => waiting for a new diagnostic after Lima analysis 12/03/2015: AFTN test conducted between SAEZ and SUMU and then will be spread 27/03: new tested to be conducted at SUMU and SAEZ. In addition to that, hardware was bought by INEO to perform tests at INEO facility	10th-March-2015 20th-March-2015 10th April 2015		We expect that 10th April would be the closing date
P4SBMN020510	SOLUTION IDENTIFIED	P	4	Brazil	SBMN	Manaus	10 Falta pruebas SAT LOOP BER TEST	5 February 2015		During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination	27/02/2015 => INEO technician will conduct the test on site, on 30/03/15 06/03/15 => As talked during teleconference, the test requires to shutdown the whole satellite network. Need to confirm and coordinate it. 12/03/2015: procedure sent, pending on test to be coordinated by ICAO	27th-February-2015 13 March 2015		Pending issue even though you send a procedure the SAT BER LOOP TEST has to be made in all the node under your coordination
P4SBMN02011	CLOSED	P	4	Brazil	SBMN	Manaus	11 Pruebas pendiente en circuitos orales ATS , administrativos AFTN en una de las cadenas de la red satelital	5 February 2015		During the PSAT, it appears that this test was already performed. It could be easily checked, and upon request by ICAO, it could be done during the ORD period with the local FP and INEO remote coordination	17/02/2015 => INEO technician will conduct the test on site 06/03/2015 => Waiting for Result report	10th-March-2015		OK solved
P1SBRF05021	SOLUTION IDENTIFIED	P	2	Brazil	SBRF	Recife	1 Perdida de paquetes en la red terrestre LEVEL 3 con todos los nodos	5 February 2015		Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)	25/02/2015 => New request retransmitted to Level 3 06/03/2015 => individual tests to be performed 27/03: tests conducted by LEVEL 3 were successful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Coordination was made to make the test on LEVEL 3 network the 31 March.

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRITICALITY	COUNTRY	NODE	CITY		OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P4SBRF05022	ON PROGRESS	P	4	Brazil	SBRF	Recife	2	Pendiente pruebas BER AFTN	5 February 2015	During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination		27/11/15 => Procedure for BER test targetted Marsh 02th => expected coordination from ICAO-Lima and FP to proceed 06/03/15 => waiting for a new diagnostic after Lima analysis 12/03/2015: AFTN test conducted between SAEZ and SUMU and then will be spread 27/03: new tested to be conducted at SUMU and SAEZ. In addition to that, hardware was bought by INEO to perform tests at INEO facility	10th-March-2015 20th-March-2015 10th April 2015		We expect that really the 10th April would be the closing date
P3SBRF05023	ON PROGRESS	P	3	Brazil	SBRF	Recife	3	Falsa alarma NMS (IBUC) y RX 1 + 1	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress, to be achieved on 09/03/15 23/03/15 => new NMS problem identified: graphical issue on representation	20th-February-2015 6th-March-2015 9th-March-2015 20th-March-2015 10th April 2015		We expect that really the 10th April would be the closing date
x				Brazil		Curitiba		Nothing for instance							
					SBCT										
P3SCEL05021	SOLUTION IDENTIFIED	P	3	Chile	SCEL	Santiago	1	Dañada pantalla del reloj GPS	5 February 2015	New equipment received in INEO Premises. Will be sent to the site asap		27/02/2015 => Coordination with FP for shipment in progress 04/03/2015 => New equipment sent 04/03/15: waiting for unit exchange to be done by FP 18/03/15 Delivery pending	4th-March-2015 09th-March-2015 TBD, pending on FP feedback		The GPS clock was sent to Chile. Chile is in the process for custome clearance
P3SCEL05022	CLOSED	P	3	Chile	SCEL	Santiago	2	NMS: refresco cambios de estados muy lento	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => in a local NMS it seems correct the refresh. For the distant NMS it is not possible to improve it due to satellite hop	06th-March-2015 6th March 2015		OK
P3SCEL05023	CLOSED	P	3	Chile	SCEL	Santiago	3	Calidad de la imagen no mejorada aspecto pendiente desde la FAT	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 12/03 => new NMS aspect approved by OACI (L.Alejos email of 12/03), to be deployed in all site	06th-March-2015 06th-March-2015 17th March 2015		OK
P3SCEL05024	CLOSED	P	3	Chile	SCEL	Santiago	4	WEB IBUC : La indicación de voltaje no corresponde al valor real	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress, to be achieved on 09/03/15	06th-March-2015 6th March 2015		Not closed Chile reported that the problem was not solved
P4SCEL05025	CLOSED	P	4	Chile	SCEL	Santiago	5	Pendiente actualización de los diagramas	5 February 2015	As-built under realization		Closing date includes finalization of drawings for ALL sites 27/03: documents achieved, to be shipped on Monday 30th	20th-March-2015 27th March 2015	30th March 2015	Not closed The action is solved once all the REDDIG II focal points receive the document with the enmended circuit diagrams and information presented are OK Pending the CD with the electronic documentation

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P1SCEL05026	ON PROGRESS	P	1	Chile	SCEL	Santiago	6 Circuito AFTN con Lima no operativo	5 February 2015	1/ Check of the Cisco configuration 2/ Local check-up with one of our expert As soon as we have define where exactly is the problem, INEO E&S will correct the bugg.	requested to FP to check cabling and RJ45 adaptor potential problem	27/11/15 => Procedure for BER test targetted Marsh 02th => expected coordination from ICAO-Lima and FP to proceed 06/03/15 => waiting for a new diagnostic after Lima analysis 12/03/2015: AFTN test conducted between SAEZ and SUMU and then will be spread 27/03: new tested to be conducted at SUMU and SAEZ. In addition to that, hardware was bought by INEO to perform tests at INEO facility	40th-March-2015 20th-March-2015 10th April 2015		Pending the internetnt problem of loss of AFTN messages We expect that the 10th April would be the closing day
P4SCEL05027	ON PROGRESS	P	4	Chile	SCEL	Santiago	7 Pendiente prueba BER AFTN	5 February 2015	During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination		27/11/15 => Procedure for BER test targetted Marsh 02th => expected coordination from ICAO-Lima and FP to proceed 06/03/15 => waiting for a new diagnostic after Lima analysis 12/03/2015: AFTN test conducted between SAEZ and SUMU and then will be spread 27/03: new tested to be conducted at SUMU and SAEZ. In addition to that, hardware was bought by INEO to perform tests at INEO facility	40th-March-2015 20th-March-2015 10th April 2015		Still pending We exopt that BER test would be completed the 10th April.
P1SCEK05021	ON PROGRESS	P	1	Colombia	SKED	Bogota	1 Circuito oral ATS Bogota Panamá no funciona	5 February 2015	1/ Analysis of the current configuration 2/ Expert to come on site to finalise the analysis and correct the problem	on site diagnostic to be conducted 21/02	25/02/2015 => INEO expert on investigation on site in coordination with FP and PABX local provider => Close cooperation with those persons is expected to address the problem properly 27/02/2015 => Information on PBX received from provider, New configuration implemented by 02/03/2015 05/03/15 => still on progress with active colaboration of all members concerned 12/03/2015: test today with E1 R2 and no longer E1 E&M 16/03 configuration changed to E1R2 still the same issue 27/03 A Cisco expert will assist us for the test on April 3rd	40th-March-2015 20th-March-2015 10th April 2015		Even though numerous action made the circuit still out of service
P1SCEK05022	ON PROGRESS	P	1	Colombia	SKED	Bogota	2 Circuito AMHS con Peru no funciona	5 February 2015	1/ Local diagnostic with our expert (on-site) in Lima 2/ Solutions to be implemented after diagnostic	Resolution pending of the item P2SBMN02051	25/02/2015 => Conflict of IP address was detected between AMHS system and Reddig-II configuration => Member states must be responsible for the NAT translation between the two systems => Expecting action from ICAO 06/03/2015 => Status & configuration update asked to CORPAC for cooperation 12/03/2015: ping test is working, from SKED (Cisco) to SPIM (router de Corpac). Pending details	18th-February-2015 24th February 2015		Still pending the circuit does not work

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P2SEGU05021	ON PROGRESS	P	2	Ecuador	SEGU	Guayaquil	1 Circuitos de voz administrativos no operativos	5 February 2015	1/ Analysis of the current configuration 2/ Expert to come on site to finalise the analysis and correct the problem	Analysis in progress	12/03/2015: configuration sent, to be installed and tested 16/03: configuration did not solve the issue, it improved communication off hook detection 27/03 A Cisco expert will assist us for the test on April 3rd	10th-March-2015 20th-March-2015 10th April 2015		Still pending no action was made
P2SEGU05022	SOLUTION IDENTIFIED	P	2	Ecuador	SEGU	Guayaquil	2 Perdida de paquetes red terrestre Level 3 con Manaus,Recife Guyana Uruguay	5 February 2015	Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)		25/02/2015 => New request retransmitted to Level 3  06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were successful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Coordination was made to make the test on LEVEL 3 network the 31 March.
P4SEGU05023	ON PROGRESS	P	4	Ecuador	SEGU	Guayaquil	3 Pruebas BER AFTN pendientes	5 February 2015	During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination		27/11/15 => Procedure for BER test targetted Marsh 02th => expected coordination from ICAO- Lima and FP to proceed 06/03/15 => waiting for a new diagnostic after Lima analysis 12/03/2015: AFTN test conducted between SAEZ and SUMU and then will be spread 27/03: new tested to be conducted at SUMU and SAEZ. In addition to that, hardware was bought by INEO to perform tests at INEO facility	40th-March-2015 20th-March-2015 10th April 2015		Still pending . We expect that the AFTN BER test would be completed the 10th April
P3SEGU05024	CLOSED	P	3	Ecuador	SEGU	Guayaquil	4 Prueba Tx switch (7.1.1) no pasó	5 February 2015	After analysis, it appears that the IBUC needs to be updated. To do so, we need to be connected directly to the equipment. INEO requests from ICAO the support from the local FP in order to perform this action.		17/02/2015 => Proceeding to the update of IBUC by FP in guayaquil 17/02/2015: done 19/03/15 => procedure sent, but power connection must be maintained before upload, but this solution already worked in others nodes 09/03/15 => problem solved according to email from Raul Avellan of 09/03	28 February 2015		OK solved
P3SEGU05025	ON PROGRESS	P	3	Ecuador	SEGU	Guayaquil	5 Voz IP teleconferencia calidad pésima	5 February 2015	1/ Diagnostic of the current configuration 2/ New configuration to be proposed after analysis 3/ Configuration implemented, to be tested (12/03)		05/03 : diagnostic still on progress 13/03: modem configuration changed, test pending. 27/03: tests achieved with Manaus unsuccessful	40th-March-2015 20th-March-2015 10th April 2015		Still pending we expect the IP telephone will be ready the 10th of April
P3SEGU05026	SOLUTION IDENTIFIED	P	3	Ecuador	SEGU	Guayaquil	6 Falsas alarmas de operación de las interfaces seriales y E1	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 27/03/2015: testes achieved appears to be a communication instability between NMS and routers, as SSH conenction is very sensitive	20th-February-2015 6th-March-2015 12th-March-2015 20-March-2015 10th April 2015		OK action on progress but not completed
P4SEGU05027	CLOSED	P	4	Ecuador	SEGU	Guayaquil	7 Pending ATS voice circuit test between Guayaquil and CENAMER	5 February 2015	1/ Analysis of the current configuration 2/ Pending to interconnection between Bogota/Maiquetia and Honduras	resolution pending of the item P1SCEK05021	16/03/2015 interconnection achieved, phone number changed in CENAMER, remaining to be confirmed in Bogota 27/03: instability solved	20th-February-2015 6th-March-2015 20th-March-2015 20/ March 2015		Solved but not closed the circuit is under observation

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(S) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P4SOCA05021	CLOSED	P	4	French Guiana	SOCA	Cayenne	1 El conector de energía del teléfono IP no funciona	5 February 2015	A solution will be proposed by INEO to the site		18/02/2015 We proposed to use a simple telephone cable with a different configuration. The solution was implemented on 17/03/2015. 17/03: closed as per email of 17th of march	18th-February-2015 17th-March-2015		OK
P4SOCA05022	CLOSED	P	4	French Guiana	SOCA	Cayenne	2 Diagramas circuitales incorrectos (WVG)	5 February 2015	As-built under realization		Closing date includes finalization of drawings for AEL sites. 27/03: documents achieved, to be shipped on Monday 30th	28th-March-2015 27th-March-2015	30th March 2015	The action is solved once all the REDDIG II focal points receive the document with the emended circuit diagrams and information presented are OK Pending the CD with the electronic documentation
P3SOCA05023	SOLUTION IDENTIFIED	P	3	French Guiana	SOCA	Cayenne	3 Dificultad leer la dirección IP del WVG	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 12/03 => new NMS aspect approved by OACI (L.Alejos email of 12/03), to be deployed in all site	20th-February-2015 6th-March-2015 09th-March-2015 17 March 2015		Not solved yet
P3SOCA05024	CLOSED	P	3	French Guiana	SOCA	Cayenne	4 Error en la interface LAN no trabaja	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress, to be achieved on 09/03/15	20th-February-2015 06th-March-2015 09th-March-2015 20th March 2015		OK
P3SOCA05025	SOLUTION IDENTIFIED	P	3	French Guiana	SOCA	Cayenne	5 Modem B no va en verde cuando se enciende	5 February 2015	1/ Diagnostic with FP to be performed 2/ If faulty equipment, will open an RMA number to replace the equipment	Analysis in progress with NDSatcom	06/03/2015 ND Satcom will send us a new software and an upgrade procedure for the network 27/03: ND Satcom is still working on the new version. Solutions should be exposed next week	20th-February-2015 6th-March-2015 12th-March-2015 30-March-2015 10th April 2015		Still pending
P2SOCA05026	CLOSED	P	2	French Guiana	SOCA	Cayenne	6 Problema posterior con el circuito AFTN con Manaos	5 February 2015	1/ Check of the Cisco configuration -> Conf. OK 2/ Discussions undergoing with local FP	problem already observed during REDDIG 1 operation	25/02/2015 => Closed as per INEO	18th-February-2015		Not closed French Guyana reported that the problem was not solved REDDIG I did not have this problem. This is a REDDIGII problem
O1SOCA05027	CLOSED	O	1	French Guiana	SOCA	Cayenne	7 Communication problem with Manaos according to the email from ICAO (17th Feb.)	17 February 2015	OSPF Pb under analysis -> Looking for a technical solution to be implemented	Resolution pending of the Item M1SLLP17021	27/02/2015 => New configuration will be sent by Cisco as a ready-to-go model, under recommendation made by our Cisco expert (27-02-2015) 27/02/2015 => New configuration implemented, solution monitoring and validation 05/03/2015 => Improvement of the routing agreement will still be continued 12/03/2015: test successful, only SYGC was out due to last mile issue	9th-March-2015		OK
P3SYGC05021	SOLUTION IDENTIFIED	P	3	Guyana	SYGC	Georgetown	1 No hay indicación de status en uno de los switches en el MAP VIEW	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress, to be achieved on 09/03/15	20th-February-2015 6th-March-2015 9th-March-2015 20th March 2015		Still not solved
P3SYGC05022	CLOSED	P	3	Guyana	SYGC	Georgetown	2 No se puede hacer setting en las interfaces de voz	5 February 2015	INEO sent an email on the 18th Feb. explaining that modifications on voice interfaces are possible, mainly to change the attenuation or the gain to make the communication better. We sent to the FP a procedure.			18 February 2015		OK closed

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(S) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
O1MHTG12051	CLOSED	O	1	Honduras		Tegucigalpa	Solicitud de activación de los servicios (email 12/02)	12 February 2015	Procedure to declare the new station in the network to be done	problem identified and expected resolution for 21/02	25/02/2015 Solved by INEO => Closed as per INEO	25th february 2015		Solved but not closed the circuit is under observation
P4SGAS05021	PENDING	P	4	Paraguay	SGAS	Asuncion	Alarma sonora de la UPS en modo batería, prácticamente inaudible	5 February 2015	The equipment is working as presented during the FAT. Please precise the issue.			18th February 2015 20 March 2015		Pending issue
P3SGAS05022	SOLUTION IDENTIFIED	P	3	Paraguay	SGAS	Asuncion	No se cuenta con el antivirus que se halla especificado en el Documento REDDIG II SDD Scope of Supply Rev. F	5 February 2015	To be provided by INEO		27/03/2015: Antivirus almost identified (two remaining systems)	10th March 2015 27th March 2015		Not solved still pending the antivirus
P3SGAS05023	CLOSED	P	3	Paraguay	SGAS	Asuncion	El breaker Q5 presenta un falso contacto por lo que deberá ser cambiado	5 February 2015	INEO have contacted his local subcontractor to perform the modification			26 February 2015		OK Solved
P2SGAS05024	SOLUTION IDENTIFIED	P	2	Paraguay	SGAS	Asuncion	No se configuro la línea Administrativa IP	5 February 2015			27/02/2015 => As per SDD, this request seems to be out of scope of INEO 06/03/2015 A coordination email was sent to Paraguay for configuration changes in the Cisco. We are pending to that information to keep working on this issue and make tests with Paraguay. 12/03/2015: no news from Paraguay 16/03: configuration sent, pending tests 27/03: test resulted not successful, but SIP proxy must be the VCS, not the Cisco	20th February 2015 6th March 2015 12th March 2015 20 March 2015 10th April 2015		Not solved still pending
P3SGAS05025	SOLUTION IDENTIFIED	P	3	Paraguay	SGAS	Asuncion	La grafica de representación de los equipos en los nodos en el NMS no ha sido mejorada, tal como se había observado en la FAT	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 12/03 => new NMS aspect approved by OACI (L.Alejos email of 12/03), to be deployed in all site	20th February 2015 6th March 2015 09th March 2015 17 March 2015		OK on progress almost solved
P3SGAS05026	CLOSED	P	3	Paraguay	SGAS	Asuncion	Al realizar la prueba de redundancia del Capítulo 7 Pag. 70/125 de la PSAT, las IBUCs no indican las fallas y no conmutan automáticamente	5 February 2015	After analysis, it appears that the IBUC needs to be updated. To do so, we need to be connected directly to the equipment. INEO requests to ICAO the support from the local FP in order to perform this action.		25/02/2015 Solved by INEO => Closed as per INEO	28 February 2015		OK
P3SGAS05027	ON PROGRESS	P	3	Paraguay	SGAS	Asuncion	El puerto serial 0/0/0 del router GBB presenta una falla en donde pierde paquetes en Recepción, por lo cual la tarjeta 2-Port Async/Sync Serial WAN Interface Card debe ser reemplazada	5 February 2015	Analysis undergoing => An RMA will be opened if necessary	waiting for a clear diagnostic from SGAS that it is a hardware problem	17/03: update asked to FP	20th February 2015 6th March 2015 12th March 2015 20 March 2015 10th April 2015		Still pending We expect that BER test would be completed the 10th April.
P4SGAS05028	CLOSED	P	4	Paraguay	SGAS	Asuncion	Pendiente actualización de los diagramas circuitales	5 February 2015	As-built under realization		Closing the finalization of drawings in all sites 27/03: documents achieved, to be shipped on Monday 30th	16th March 2015 27th March 2015	30th March 2015	The action is solved once all the REDDIG II focal points receive the document with the emended circuit diagrams and information presented are OK Pending the CD with the electronic documentation
P2SGAS05029	SOLUTION IDENTIFIED	P	2	Paraguay	SGAS	Asuncion	Perdida de paquetes en la red terrestre LEVEL 3 con Bolivia , Recife (Muy alta), Colombia,French Guyana, Guyana y Uruguay	5 February 2015		Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)	25/02/2015 => New request retransmitted to Level 3 06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were succesful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Coordination was made to make the test on LEVEL 3 network the 31 March.
O3SGAS110210	CLOSED	O	1	Paraguay	SGAS	Asuncion	Communication problems which forced Paraguay to pass services through the Level 3 network (email OACI 11/02)	11 February 2015	1/ Remote analysis of the problem 2/ Expert from INEO to be send on site to point again the antena	problem Identified as a bad alignment of the antena. On site technician for 23/02	25/02/2015 => Solved after intervention of INEO expert on site => Closed as per INEO	25th February 2015		OK

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRITICALITY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015	
P1SPIM05021	SOLVED	P	1	Peru	SPIM	Lima	1 Circuito AFTN con Manaus y Santiago inoperativos	5 February 2015	Remote Diagnostic under progress	Resolution pending of the item P2SBMN02051	25/02/2015 => Test must be conducted in cooperation with Manaus AFTN center and REDDIG-II technical persons, waiting for their availability. 06/03/2015 Our expert on site is reporting that the circuit is nominally operating. He identified that the issues were already present with REDDIG I. Additional analysis is thus required.	27th February 2015 27th March 2015		Not solved The REDDIG I did not have problem with these AFTN circuits. These are REDDIG II problem The AFTN circuit Lima Manaus and Lima Santiago are working but with intermittent problem	
P2SPIM05022	CLOSED	P	2	Peru	SPIM	Lima	2 MODEM 1070 cadena A no operativo	5 February 2015	1/ Spare part installed 2/ Faulty equipment to be collected by INEO for reparation & replacement (Waiting for ICAO instructions) 3/ Spare Modem to be declared in the network		25/02/2015 Solved by INEO => Closed as per INEO	24th February 2015		OK	
P4SPIM05023	SOLUTION IDENTIFIED	P	4	Peru	SPIM	Lima	3 La grafica de representación de los equipos en los nodos en el NMS no ha sido mejorada, tal como se había observado en la FAT	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 12/03 => new NMS aspect approved by OACI (L.Alejos email of 12/03), to be deployed in all site	20th February 2015 6th March 2015 09th March 2015 17 March 2015		OK but still pending the installation of the last NMS version	
P3SPIM05024	CLOSED	P	3	Peru	SPIM	Lima	4 Falta actualización de los diagramas circutales	5 February 2015	As-built under realization		Testing and testate identification of drawings for AFD sites 27/03: documents achieved, to be shipped on Monday 30th	27th March 2015	30th march 2015		
P2SPIM05025	SOLUTION IDENTIFIED	P	2	Peru	SPIM	Lima	5 Perdida de paquetes red terrestre Level 3 con Argentina., Manaus, Colombia , Guyana y Venezuela	5 February 2015		Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)	25/02/2015 => New request retransmitted to Level 3  06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were succesful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Still pending Coordination was made to make the test on LEVEL 3 network the 31 March.	
P2SPIM05026	ON PROGRESS	P	2	Peru	SPIM	Lima	6 Numero ATS d no corresponde	5 February 2015	Local intervention of our expert		27/02/2015 => Targetted 02/03/2015	20th February 2015 6th March 2015 12th March 2015 30 March 2015 10th April 2015		Not solved pending	
P4SPIM05027	CLOSED	P	4	Peru	SPIM	Lima	7 Pruebas cadena A satelital no realizadas por falla del MODEM cadena A	5 February 2015			25/02/2015 Solved by INEO => Closed as per INEO	24th February 2015		Not solved Peru reported that tests were not made	
P4SPIM05028	SOLUTION IDENTIFIED	P	4	Peru	SPIM	Lima	8 Prueba BER no realizada	5 February 2015		During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination		27/02/2015 => INEO technician will conduct the test on site, on 30/03/15 06/03/15 => As talked during teleconference, the test requires to shutdown the whole satellite network. Need to confirm and coordinate it. 12/03/2015: Procedure sent	27th February 2015 13 Marsh 2015		No completed pending issues
P4SPIM05029	CLOSED	P	4	Peru	SPIM	Lima	9 Pendiente pruebas fallas de equipos (Sección 7.3)	5 February 2015		During the PSAT, it appears that this test was already performed. It could be easily checked, and upon request by ICAO, it could be done during the ORD period with the local FP and INEO remote coordination		25th February 2015		OK	

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(S) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P3SPIM050210	CLOSED	P	3	Peru	SPIM	Lima	10 Errores plan de discado circuitos administrativos	5 February 2015	Local intervention of our expert		27/02/2015 => Request 20/03/2015 19/03/2015 New configuration implemented 19/03/15 on March 19th, resulting in a successful test case 12/03/2015: configuration sent, first test ok. Pending confirmation 16/03 new test asked to confirm diagnostic 27/03: closed as per email of 19/03	16th-March-2015 20th-March-2015 20th March 2015		Not solved on progress
P3SPIM050211	ON PROGRESS	P	3	Peru	SPIM	Lima	11 Calidad voz IP teleconferencia no satisfactoria	5 February 2015	1/ Diagnostic of the current configuration 2/ New configuration to be proposed after analysis 3/ Configuration implemented, to be tested (12/03)		05/03 : diagnostic still on progress 13/03 : modern configuration changed, test pending. 27/03: tests achieved with Manaus unsuccessful (12/03)	4th-March-2015 20th-March-2015 10th April 2015		IP telephone still pending
O2SPIM120212	SOLVED	O	2	Peru	SPIM	Lima	12 anomalía que está presentándose en la comunicación AFTN de Santiago hacia Lima y Ezeiza (email OACI 12/02)	12 February 2015	OSPF Pb under analysis -> Looking for a technical solution to be implemented	Resolution pending of the item P2SBMN02051	25/02/2015 => New configuration will be tested by Level3 as of today, on all nodes, under recommendation made by our Cisco expert (CCIE certified) 27/02/2015 => New configuration implemented, solution monitoring under validation 05/03/2015 => Improvement of the routing observed, but still to be confirmed	10th April 2015		Not solved yet still pending
P3SMPM05021	SOLUTION IDENTIFIED	P	3	Suriname	SMPM	Paramaribo	1 Presenta perdidas de paquetes en la red terrestre LEVEL 3 con Argentina, Manaus , Recife (muy alta), Chile, Colombia, Ecuador, Guyana y Uruguay	5 February 2015	Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)		25/02/2015 => New request retransmitted to Level 3  06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were successful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Still pending Coordination was made to make the test on LEVEL 3 network the 31 March.
P4SMPM05022	SOLUTION IDENTIFIED	P	4	Suriname	SMPM	Paramaribo	2 Pendiente pruebas BER	5 February 2015	During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination		27/02/2015 => INEO technician will conduct the test on site, on 30/03/15 06/03/15 => As talked during teleconference, the test requires to shutdown the whole satellite network. Need to confirm and coordinate it. 12/03/2015: Procedure sent	10th April 2015		Pending issue not solved
P3SMPM05023	SOLUTION IDENTIFIED	P	3	Suriname	SMPM	Paramaribo	3 Teleconferencia IP solo con diez usuarios	5 February 2015	1/ Diagnostic of the current licence 2/ New 16 users licences to be provided after analysis		05/03 : Hardware limitation found, solution to be provided. Will be codec change or hardware addition	10th April 2015		IP telephone still pending
P3TTZP05021	CLOSED	P	3	Trinidad & Tobago	TTZP	Piarco	1 NMS: refresco cambios de estados muy lento	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => in a local NMS it seems correct the refresh. For the distant NMS it is not possible to improve it due to satellite hop	16th-March-2015 6th March 2015		Not closed Trinidad & Tobago reported the 30 March that the NMS for local monitoring still too slow.
P4TTZP05022	SOLUTION IDENTIFIED	P	4	Trinidad & Tobago	TTZP	Piarco	2 Calidad de la imagen no mejorada aspecto pendiente desde la FAT	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 12/03 => new NMS aspect approved by OACI (L.Alejos email of 12/03), to be deployed in all site	10th April 2015		Waiting to load thnew configuration
P3TTZP05023	SOLUTION IDENTIFIED	P	3	Trinidad & Tobago	TTZP	Piarco	3 Teleconferencia IP solamente trabaja con 11 usuarios no cumple con las especificaciones técnicas de la REDDIG	5 February 2015	1/ Diagnostic of the current licence 2/ New 16 users licences to be provided after analysis		05/03 : Hardware limitation found, solution to be provided. Will be codec change or hardware addition	5th-March-2015 4th-March-2015 20th March 2015		Still pending the IP telephone

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICI TY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(s) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P2TTZP05024	CLOSED	P	2	Trinidad & Tobago	TTZP	Piarco	4 No hay conmutación automática en el IBUC en caso de falla solamente conmuta cuando se apaga la energía	5 February 2015	After analysis, it appears that the IBUC needs to be updated. To do so, we need to be connected directly to the equipment. INEO requests to ICAO the support from the local FP in order to perform this action.		26/02/2015 => New IBUC firmware successfully installed => Switching problem solved => Solved as per INEO	28 February 2015		OK solved
P2TTZP05025	SOLUTION IDENTIFIED	P	2	Trinidad & Tobago	TTZP	Piarco	5 Perdida de paquetes en la red terrestre LEVEL 3 con Curitiba y Ecuador.	5 February 2015	Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)		25/02/2015 => New request retransmitted to Level 3  06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were successful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Still pending Coordination was made to make the test on LEVEL 3 network the 31 March.
O2TTZP18026	CLOSED	O	2	Trinidad & Tobago	TTZP	Piarco	6 Communication problem with Paramaribo and Manaus according to the email from ICAO (18th Feb.)	18 February 2015	OSPF Pb under analysis -> Looking for a technical solution to be implemented	Resolution pending of the item P2SBMN02051	25/02/2015 => New configuration will be tested by Level3 as of today, on all nodes, under recommendation made by our Cisco expert (CCIE certified) 27/02/2015 => New configuration implemented, solution monitoring under validation 05/03/2015 => Improvement of the routing observed, but still to be confirmed			OK
P4SUMU05021	CLOSED	P	4	Uruguay	SUMU	Montevideo	1 Falta actualización los planos con los diagramas circuitales	5 February 2015	As-built under realization		Shipping date includes finalization of drawings for all sites 27/03: documents achieved, to be shipped on Monday 30th	27th March 2015	30th March 2015	Not closed The action is solved once all the REDDIG II focal points receive the document with the emended circuit diagrams and information presented are OK Pending the CD with the electronic documentation
P4SUMU05022	ON PROGRESS	P	4	Uruguay	SUMU	Montevideo	2 Unidad 1070 cadena B no enciende luz verde aun cuando opera bien	5 February 2015	We opened an RMA number. INEO will replace the equipment.		06/03/2015 => shipment of faulty unit towards NDSatCom pending			No action made solution required
P3SUMU05023	CLOSED	P	3	Uruguay	SUMU	Montevideo	3 Falta cambiar Feed Horn	5 February 2015			New Feed Horn and antenna Line Up to be done	24 March 2015		OK
P3SUMU05024	CLOSED	P	3	Uruguay	SUMU	Montevideo	4 NMS: refresco cambios de estados muy lento	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => in a local NMS it seems correct the refresh. For the distant NMS it is not possible to improve it due to satellite hop	6th March 2015		Not solved Uruguay reported that the NMS still slow in the local monitoring presentation
P4SUMU05025	SOLUTION IDENTIFIED	P	4	Uruguay	SUMU	Montevideo	5 Calidad de la imagen no mejorada aspecto pendiente desde la FAT	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress 12/03 => new NMS aspect approved by OACI (L.Alejos email of 12/03), to be deployed in all site	5th April 2015		Pending required to load new NMS configuration
P3SUMU05026	SOLUTION IDENTIFIED	P	3	Uruguay	SUMU	Montevideo	6 Falta instalar antivirus en el NMS	5 February 2015	To be provided by INEO		27/03/2015: Antivirus almost identified (two remaining systems)	10th April 2015		Pending issues stil waiting antivirus in all the nodes not only Montevideo
P3SUMU05027	SOLUTION IDENTIFIED	P	3	Uruguay	SUMU	Montevideo	7 El NMS presenta información incorrecta	5 February 2015	1/ Diagnostic of the current configuration of the NMS 2/ New version of the NMS	NMS works in progress	05/03/15 => Problem identified => Implementation of the solution in progress, to be achieved on 09/03/15	5th April 2015		Still pending solution almost ready

Appendix B to the Report on the Agenda Item 1/  
 Apéndice B al Informe sobre la Cuestión 1 del Orden del Día

ITEM NUMBER	STATUS	TYPE O/M	CRI TICITY	COUNTRY	NODE	CITY	OUTSTANDING ISSUES	OPENING DATE	ACTION(S) TO BE PERFORMED	COMMENTS	CURRENT UPDATE	EXPECTING CLOSING DATE	REAL CLOSING DATE	ICAO AND STATES COMMENTS 30 March 2015
P4SUMU05028	SOLUTION IDENTIFIED	P	4	Uruguay	SUMU	Montevideo	8 Pendiente pruebas BER	5 February 2015	During the PSAT, it appears that this test was not the priority. Now, it's difficult to perform it because it means that States will have to cut the services. If requested by ICAO, it could be done during the ORD period with the local FP and INEO coordination		27/02/2015 => INEO technician will conduct the test on site, on 30/03/15 06/03/15 => As talked during teleconference, the test requires to shutdown the whole satellite network. Need to confirm and coordinate it. 12/03/2015: Procedure sent	10th April 2015		Pending activity not completed yet
P4SUMU05029	SOLUTION IDENTIFIED	P	4	Uruguay	SUMU	Montevideo	9 La versión entregada de software para la VPN remota no es acorde al manual enviado para su instalación, no pudiendo instalarse según lo sugerido por INEO.	5 February 2015	An amendment to the User Manual will be sent to all the Reddig II Members by email.		17/03: new procedure sent, same as for SAEZ and SBMN	5th April 2015		Not solved pending
P3SUMU050210	SOLUTION IDENTIFIED	P	3	Uruguay	SUMU	Montevideo	10 Perdidas de paquetes en la red terrestre LEVEL 3 con Bolivia, French Guyana, Surinam, Trinidad &Tobago y Venezuela.	5 February 2015	Information transmitted to level 3 -> Waiting for the solution proposed and the ECD (Expecting Closing Date)		25/02/2015 => New request retransmitted to Level 3  06/03/2015 => individual tests to be performed 27/03: tests conducted by LE were successful, except French Guiana. Procedure sent on 27th of March for individual tests.	10th April 2015	LEVEL 3	Still pending Coordination was made to make the test on LEVEL 3 network the 31 March.
P2SVIM05021	CLOSED	P	2	Venezuela	SVIM	Maiquetia	1 No se observa el switcheo automatico en el RSS	5 February 2015	We have contacted our site manager, and apparently it was the automatic switching of the RSS from B to A. It's normal that it's doesn't work because it's only possible manually. Please confirm that it's issue can be SOLVED		25/02/2015 Solved by INEO => Closed as per INEO	18 February 2015		OK closed
O1SVIM18022	CLOSED	O	1	Venezuela	SVIM	Maiquetia	2 Communication problem with Georgetown, Paramaribo, and Manaus according to email of the 18th Feb.	18 February 2015	OSPF Pb under analysis -> Looking for a technical solution to be implemented	Resolution pending of the item P2SBMN02051	29/02/2015 => New configuration will be sent by Level 3 as a ready-to-implement, under recommendation made by our client expert (30-03-2015) 27/03/2015 => New configuration implemented, solution implemented/under evaluation 06/04/2015 => Implementation of the routing agreement not yet to be confirmed 17/03: test successful 27/03: no issue reported so far	27 March 2015		Solved expeting closing date
O1SVIM25023	CLOSED	O	1	Venezuela	SVIM	Maiquetia	3 All the AFTN communication out of service	24 February 2015	Problem occurred due to other equipment		25/02/2015 => Waiting for result after OSPF configuration modification done today on LEVEL3 network 27/02/2015 => solved	27 February 2015		OK Closing date
<b>Legend colour</b>	Pending													
<b>Legend colour</b>	On Progress	The colour of this line is automatically updated according the status, except the last column which always remains as initially colored by the customer.												Customer initial color
<b>Legend colour</b>	Solved	The colour of this line is automatically updated according the status, except the last column which always remains as initially colored by the customer.												Customer initial color
<b>Legend colour</b>	Solution identified	The colour of this line is automatically updated according the status, except the last column which always remains as initially colored by the customer.												Customer initial color
<b>Legend colour</b>	Closed	The colour of this line is automatically updated according the status, except the last column which always remains as initially colored by the customer.												Customer initial color

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015


Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
	List A			<b>REDDIG II SPARE PARTES DELIVERED FROM BRAZIL</b>				
	<del> </del>			EQUIPOS Y PIEZAS DE REPUESTO EN GENERAL				
1	A4	1	1.1	Modem Satelital	NDSatcom	skywan 7000	1	730289
2			1.2	Cable de energia			1	-
3			1.3	Tarjeta MOD	NDSatcom		1	-
4			1.4	Tarjeta SIC/DEMOM	NDSatcom		1	-
5			1.5	Tarjeta FPG	NDSatcom		1	-
6			1.6	Tarjeta UIM	NDSatcom		1	-
7			1.7	Cable de consola	NDSatcom		1	-
8			1.8	Cable de RF N-SMA Macho	NDSatcom		1	-
9	C2	2	2.1	ROUTER Cisco 2901	CISCO	2901	1	FCZ1719C1BR
10			2.2	Two port Async-Sync Serial WAN interface card	CISCO	HWIC	1	FOC17173XNG
11			2.3	Two port Async-Sync Serial WAN interface card	CISCO	HWIC	1	FOC17427CCS
12			2.4	two port voice interface card FXS	CISCO	VIC3	1	FOC16450PGJ
13	C2	3	3.1	ROUTER Cisco 2911	CISCO	2911	1	FCZ175060LX
14			3.2	24 PORT RJ45 PATCH PANEL	CISCO		1	-
15			3.3	01 TARJETA EVM-HD TELEFONICO	CISCO		1	-
16			3.4	Cable serial CISCO V.24 DTE DB25	CISCO		1	-
17			3.5	Cable serial CISCO V.24 DCE DB25	CISCO		1	-
18			3.6	Cable telefonico RJ11 cross over	CISCO		1	-
19			3.7	High density 8 port analog and digital extension module	CISCO		1	FOC180475BH
20	C2	4	4.1	ROUTER Cisco 2901	CISCO		1	FCZ175092L8
21			4.2	Two port Async-Sync Serial WAN interface card	CISCO		1	FOC17427CQP
22			4.3	two port voice interface card FXS	CISCO		1	FOC17224X7C
23			4.4	Cable serial CISCO V.24 DCE DB25	CISCO		1	-
24	A2	5	5.1	Rx 1+1	Terrasat		1	TE6010431
25			5.2	Handheld Terminal with 2 m cable	Terrasat		1	439318
26			5.3	Accesorios para RX 1+1	Terrasat		1	-
27			5.4	Cables de energia	Terrasat		2	-
28			5.5	Cable Coaxial de RF con conectores tipo N 6m.	Terrasat		1	-
29			5.6	Cable de Gestion para LNB	Terrasat		1	-
30			5.7	Cable Coaxial de RF con conectores tipo N 30 cm.	Terrasat		2	-

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015

Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
31	A3	6	6.1	Wave Guide Switch for LNB	Logus		1	0244
32			6.2	LNB Banda C			1	2386
33			6.3	LNB Banda C			1	2381
34	B2	7	7.1	Switch Netgear de 26 Puertos	Netgear		1	39223C5U0036F
35			7.2	Cable USB			1	-
36	B2	8	8.1	Switch Netgear de 26 Puertos	Netgear		1	39223C5U00378
37	A1	9	9.1	IBUC 40W	Terrasat		1	TE5022340
38			9.2	IBUC 40W	Terrasat		1	TE5022352
39			9.3	1+1 Interface	Terrasat		1	6410574
40			9.4	Switch de Guia de Onda	Logus		1	0363
41			9.5	Cable Coaxial con conectores tipo N 30cm			2	-
42			9.6	Cables de gestion con conector tipo Militar			2	-
43			9.7	Cable de gestion tipo ethernet			1	-
44			9.8	Cable de Energia			2	-
45	D1	10	10.1	Manuales de Curso de Rio de Janeiro				-
46	D2	11	11.1	Documentos Oficiales REDDIG II				-
47	D1	12	12.1	Manuales REDIG II				-
48	D1	13	13.1	Documentos Oficiales REDDIG II				-
	List B			REDDIG II SPARE PARTS DELIVERED FROM FRANCE				
				EQUIPOS Y PIEZAS DE REPUESTO EN GENERAL				
49	B3	14	14.1	Tarjeta Serial MOXA de 8 Puertos RS-232 PCI	MOXA		1	TADBB1062386
50	B3	15	15.1	Disco Duro Externo IOMEGA NAS 2 Tb	LENOVO		1	V9AP370005
51			15.2	Fuente para Disco Duro	LENOVO		1	-
52			15.3	Manuales	LENOVO		1	-
53	B3	16	16.1	UPS Eaton Eclipse ECO 1200 VA	EATON		1	G030D43420
54	B3	17	17.1	Cable Multipuerto Moxa 8 puertos	MOXA		1	-
55			17.2	Cable Cisco V.24 DTE	CISCO		5	-
56			17.3	Cable Cisco V.24 DCE	CISCO		11	-
57			17.4	Cable DB25 Male-Female			6	-
58			17.5	Cable Patch Cord ethernet RJ45			6	-

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015

Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
59	C3	18	18.01	Cable Multiple Cisco 8 puertos ethernet con adaptadores a DB25	CISCO		2	-
60			18.02	Two port Async-Sync Serial WAN interface card	CISCO		1	FOC17173XSA
61			18.03	Four port Async-Sync Serial HWIC	CISCO		1	FOC17056CG2
62			18.04	Four port Async-Sync Serial HWIC	CISCO		1	FOC17405CTK
63			18.05	Eight port Async interface card	CISCO		1	FOC174673WU
64			18.06	Two Port Voice Interface Card FXS.	CISCO		1	FOC1747821Q
65			18.07	Two Port Voice Interface Card FXS.	CISCO		1	FOC18073ZCY
66			18.08	Two Port Voice Interface Card FXS.	CISCO		1	FOC1747823M
67			18.09	Two Port Voice Interface Card FXS.	CISCO		1	FOC18158WJ8
68			18.10	Two Port Voice Interface Card FXS.	CISCO		1	FOC18158WD0
69			18.11	Two Port Voice Interface Card FXS.	CISCO		1	FOC174781UF
70			18.12	Two Port Voice Interface Card FXS.	CISCO		1	FOC18073ZJL
71			18.13	Two Port Voice Interface Card FXS.	CISCO		1	FOC17461BL9
72			18.14	Two Port Voice Interface Card FXS.	CISCO		1	FOC18158WGP
73			18.15	Two Port Voice Interface Card FXS.	CISCO		1	FOC18158WH7
74			18.16	Four Port Voice Interface Card FXS	CISCO		1	FOC1747523F
75			18.17	Four Port Voice Interface Card FXS	CISCO		1	FOC174752RT
76			18.18	Four Port Voice Interface Card FXS	CISCO		1	FOC174751RP
77			18.19	Four Port Voice Interface Card FXO	CISCO		1	FOC1746833R
78			18.20	One Port 2nd Gen Multiflex trunks Voice Wan Interface Card E1/T1	CISCO		1	FOC17451Q66
79			18.21	High Density voice/fax external Module	CISCO		1	FOC17443E08
80			18.22	Two Port 2nd Gen Multiflex trunks voice wan interface card E1/T1	CISCO		1	FOC17479P39
81			18.23	Eight port Async-Sync interface card	CISCO		1	FOC17446GYD
82	C3	19	19.1	Module Adapter for SM Slot on CI	CISCO		1	FOC17516V0F
83	C3	20	20.1	Module Adapter for SM Slot on CI	CISCO		1	FOC17516UU5
84	B1	21	21.1	Impresora Laser Jet Pro 400 M401dn	Hewlet Packard		1	VNH4222944
85			21.2	Cables de Energia			1	-
86	A3	22	22.1	8 Port Device Server 10/100 eth	MOXA		1	TADAE101113

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015

Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
87	B1	23	23.1	RSS 16 SLOT 4U Chasis	DATAPROBE		1	115010100300024
88			23.2	Power Module	DATAPROBE		1	193008400000128
89			23.3	Network Control Card	DATAPROBE		1	134006500400093
90			23.4	Dual 8 wire Module Jack A/B card	DATAPROBE		1	111020200200892
91			23.5	Dual 8 wire Module Jack A/B card	DATAPROBE		1	111020200200893
92			23.6	D25 A/B Card	DATAPROBE		1	111020000100593
93			23.7	D25 A/B Card	DATAPROBE		1	111020000100594
94			23.8	D25 A/B Card	DATAPROBE		1	111020000100643
95			23.9	D25 A/B Card	DATAPROBE		1	111020000100667
96			B1	24	24.1	RSS 16 SLOT 4U Chasis	DATAPROBE	
97	24.2	Power Module			DATAPROBE		1	193008400000115
98	24.3	Network Control Card			DATAPROBE		1	134006500400080
99	24.4	Dual 8 wire Module Jack A/B card			DATAPROBE		1	11020200889
100	24.5	Dual 8 wire Module Jack A/B card			DATAPROBE		1	11020200890
101	24.6	Dual 8 wire Module Jack A/B card			DATAPROBE		1	11020200891
102	24.7	D25 A/B Card			DATAPROBE		1	111020000100629
103	24.8	D25 A/B Card			DATAPROBE		1	111020000100630
104	C3	25	25.1	High density 8 port analog and digital extension module	CISCO		1	FOC174049WM
105			25.2	High density 8 port analog and digital extension module	CISCO		1	FOC174049YH
106			25.3	Cable de consola de Cisco			2	-
107			25.4	KVM Extender			1	F3D46058D140097
108			25.5	Convertidor USB - Serial			1	-
109			25.6	Telefono IP DEPAEPE	DEPAEPE		1	PE02001120001826
110			25.7	Mouse Optico USB Negro			1	-
111			25.8	Regleta electrica con 05 tomas			2	-
112			25.9	Teclado Estandar K120	Logitech		1	-
113	B2	26	26.1	Filtro RF	NORSAT		1	C001128132
114			26.2	Filtro RF	NORSAT		1	C001128140
115			26.3	Barras de Anclaje de acero			3	-
116			26.4	Bloques de anclaje de plastico negro			6	-
117			26.5	Tornillos de sujecion de acero			20	-
118			26.6	Blank panel para RSS			3	-
119			26.7	Regleta electrica con 05 tomas			2	-

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015

Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
120			26.8	Adaptadores Cambia genero DB25			15	-
121	C1	27	27.1	Pantalla LCD 27"	SAMSUNG		1	0293H4MDB00709
122	C1	28	28.1	HP ProLiant DL160 Gen8 Base - Server	Hewlet Packard		1	CZJ34500JZ
123	A1	29	29.1	NTP Time Server Master Clock	Gorgy Timing		1	138176
124			29.2	GPS Antenna + Cable	Gorgy Timing		1	138389
125	C2	30	30.1	Router Cisco 2901	CISCO	2901	1	FCZ175092KM
126	C2	31	31.1	Router Cisco 2901	CISCO	2901	1	FCZ170391DX
127	C2	32	32.1	Router Cisco 2901	CISCO	2901	1	FCZ170592LK
128	C1	33	33.1	IBUC Terrasat 80 W	Terrasat		1	TE5022355
	<b>List C</b>			<b>REDDIG I SPARE PARTS</b>				
				EQUIPOS Y PIEZAS DE REPUESTO EN GENERAL				
129	E2	34	34.1	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	2634
130			34.2	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	2604
131			34.3	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	1063
132			34.4	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	2434
133			34.5	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	1005
134			34.6	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	1061
135			34.7	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	1067
136			34.8	Fuente de Poder para CX950	Memotec	VLT130-3000S1	1	1088
137	E2	35	35.1	Dual Analog Voice Card	Memotec	AZ004010	1	052171060
138			35.2	Dual Analog Voice Card	Memotec	AZ004010	1	052172487
139			35.3	Dual Analog Voice Card	Memotec	AZ004010	1	052172484
140			35.4	Dual Analog Voice Card	Memotec	AZ004010	1	052172486
141			35.5	Dual Analog Voice Card	Memotec	AZ004010	1	1000339848
142			35.6	Dual Analog Voice Card	Memotec	AZ004010	1	90030009411
143			35.7	Dual Analog Voice Card	Memotec	AZ004010	1	9003000738
144	E2	36	36.1	Fast Ethernet 10/100 Card	Memotec	AZ001011	1	081830913
145			36.2	Fast Ethernet 10/100 Card	Memotec	AZ001011	1	052173027
146			36.3	Fast Ethernet 10/100 Card	Memotec	AZ001011	1	052173028
147			36.4	Fast Ethernet 10/100 Card	Memotec	AZ001011	1	05273174
148			36.5	Fast Ethernet 10/100 Card	Memotec	AZ001011	1	052173175
149			36.6	Fast Ethernet 10/100 Card	Memotec	AZ001011	1	061082686

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015

Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
150			36.7	Fast Ethernet 10/100 Card	Memotec	AZ001011	1	061082680
151	E2	37	37.01	10 Base-T Ethernet Card	Memotec	AC004150	1	9002000306
152			37.02	10 Base-T Ethernet Card	Memotec	AC004150	1	9002000285
153			37.03	ISDN Card	Memotec	AC004060	1	1000328415
154			37.04	Digital Voice Processor	Memotec	AZ004114	1	1000315047
155			37.05	Digital Voice Processor	Memotec	AZ004114	1	1000315043
156			37.06	Digital Voice Processor	Memotec	AZ004114	1	061092235
157			37.07	Digital Voice Processor	Memotec	AZ004114	1	061091982
158			37.08	Digital Voice Processor	Memotec	AZ004114	1	052169078
159			37.09	Digital Voice Processor	Memotec	AZ004114	1	052169066
160			37.10	E1 Expansion	Memotec	AZ004120	1	052169024
161			37.11	V.35 H	Memotec	AZ002312	1	081807596
162	E2	38	38.1	Multi I/O V.24	Memotec	AZ002325	1	062236450
163			38.2	Multi I/O V.24	Memotec	AZ002325	1	9002000160
164			38.3	Multi I/O V.24	Memotec	AZ002325	1	9002001222
165			38.4	Multi I/O V.24	Memotec	AZ002325	1	9002001230
166			38.5	Multi I/O V.24	Memotec	AZ002325	1	062236456
167			38.6	Multi I/O V.24	Memotec	AZ002325	1	9002000250
168	E2	39	39.01	Modulo Ram 32 MB			1	040525
169			39.02	Modulo Ram 32 MB			1	045385
170			39.03	Modulo Ram 64 MB			1	07AD00134
171			39.04	Modulo Ram 64 MB			1	07AD00114
172			39.05	Modulo Ram 64 MB			1	07AD00113
173			39.06	Modulo Ram 64 MB			1	07AD00135
174			39.07	Slim Card E&M	Memotec	AZ004025	1	1000370325
175			39.08	Slim Card E&M	Memotec	AZ004025	1	1000370752
176			39.09	Slim Card E&M	Memotec	AZ004025	1	1000370677
177			39.10	Slim Card E&M	Memotec	AZ004025	1	1000328561
178			39.11	Slim Card E&M	Memotec	AZ004025	1	1000328572
179			39.12	Slim Card E&M	Memotec	AZ004025	1	052167044
180			39.13	Slim Card E&M	Memotec	AZ004025	1	052167058
181			39.14	Slim Card E&M	Memotec	AZ004025	1	052167029
182			39.15	Slim Card E&M	Memotec	AZ004025	1	052167041

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015

Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
183	E2	40	40.1	Universal I/O	Memotec	AZ002320	1	082389450
184			40.2	Universal I/O	Memotec	AZ002320	1	082389447
185			40.3	Universal I/O	Memotec	AZ002320	1	092427151
186			40.4	Universal I/O	Memotec	AZ002320	1	092427153
187			40.5	Universal I/O	Memotec	AZ002320	1	92427152
188			40.6	Universal I/O	Memotec	AZ002320	1	92427154
189	E2	41	41.1	Ring Generator	Memotec	AZ009050	1	072294201
190			41.2	Ring Generator	Memotec	AZ009050	1	082388103
191			41.3	Ring Generator	Memotec	AZ009050	1	92425216
192			41.4	Ring Generator	Memotec	AZ009050	1	92425217
193			41.5	Ring Generator	Memotec	AZ009050	1	92425210
194			41.6	Ring Generator	Memotec	AZ009050	1	052174923
195	C4	42	42.1	Chasis CX950	Memotec	AC001360	1	CA2508
196	B4	43	43.1	Multiplexor CX950e Chasis+Placa Madre	Memotec	AC002010	1	092425306
197			43.2	Cable de consola Memotec	Memotec		1	-
198	E3	44	44.1	Chasis CX950	Memotec	AC001360	1	CA02740
199	E4	45	45.1	Multiplexor CX950e Chasis+Placa Madre	Memotec	AC002010	1	072298778
200	C4	46	46.1	Multiplexor CX950e Chasis+Placa Madre	Memotec	AC002010	1	082389428
201	E3	47	47.1	Modem Linkway 2100	Viasat	2100	1	B6885
202			47.2	Tarjeta MODEM	Viasat		1	31910
203			47.3	Tarjeta Ethernet	Viasat		1	00A09400599A
204			47.4	FR TIA	Viasat		1	CL000225701
205	D4	48	48.1	Fax CANON H12130			1	DRT0671
206			48.2	Telefono analogico CONAIRPHONE			1	-
207	D3	49	49.1	SSPA 40 W	Paradise Datacom	HPAC2040ACBA 001	1	2360
208	D4	50	50.1	SSPA 40 W	Paradise Datacom	HPAC2040ACBA 001	1	2359
209	E3	51	51.1	Fuente para Modem Linkway		CL0003192-01	1	RU140400198
210			51.2	Fuente para Modem Linkway		CL0003192-01	1	RU140400196
211			51.3	Fuente para Modem Linkway		CL0003192-01	1	RU140400197
212			51.4	Fuente para Modem Linkway		CL0003192-01	1	RU140400193
213			51.5	Fuente para Modem Linkway		CL0003192-01	1	RU140400194
214			51.6	Fuente para Modem Linkway		CL0003192-01	1	RU140400195

## APPENDIX C / APENDICE C

## REDDIG I &amp; REDDIG II SPARE PARTS - 2015

Desc: Reddig Spare Parts

	Location	Box#	Item#	Description	Supplier	Type	Quantity	Serial Number
215	E3	52	52.1	Fuente para Modem Linkway		AM-120U-S4-916	1	RU082503487
216			52.2	Fuente para Modem Linkway		AM-120U-S4-916	1	RU082503484
217			52.3	Fuente para Modem Linkway		AM-120U-S4-916	1	RU134100215
218			52.4	Fuente para Modem Linkway		AM-120U-S4-916	1	RU134100212
219			52.5	Fuente para Modem Linkway		AM-120U-S4-916	1	RU134100213
220	D2	53	53.1	Rollo de cable ASSy 3 x 2.5 50 m			1	-
221	D2	54	54.1	Rollo de cable Multipar 50 m			1	-
222	D2	55	55.1	Rollo de cable Multipar 50 m			1	-
223	E2	56	56.1	LNB Banda C	NJS	NJS8477EN	1	00870
224	E2	57	57.1	Cables Patch Cord Ethernet 3m			9	-
225			57.2	Cables DB9-DB25 3m			2	-
226	E4	58	58.1	Rollo de Cable Coaxial 50R 50m			1	-
227	E1	59	59.1	SSPA 40 W	Paradise Datacom	HP AC2040ACBA 001	1	2346
228	D3	60	60.01	GPS Datum	Datum	ET6000-RB1	1	5823
229			60.02	Cable de consola Cisco	Cisco		1	-
230			60.03	Cable de Gestion SSPA Paradise	Paradise Datacom		1	-
231			60.04	Conectores Tipo N 50R sin ensamblar			4	-
232			60.05	Pulsera anti estatica			1	-
233			60.06	Paquete de Placas vacias para equipos Memotec.			1	-
234			60.07	Combinador-Divisor de RF	Global Profesional		1	-
235			60.08	Convertidos RS232-RS485	Lindy		1	78680221KGZ0071
236			60.09	Paquete de instalacion SUN SOLARIS	SUN Microsystems		2	-
237			60.10	Tarjeta Multipuerto Serial	COMTROL		1	5850-075665
238			60.11	Cable multipuerto DB25 para Multi I/O Memotec	Memotec		2	-
239			60.12	Cable Patch Cord Ethernet RJ45 5m			2	-
240			60.13	Cable de consola Memotec			1	-
241			60.14	Adaptador DB9-DB25			2	-
242			60.15	Adaptador DB25-M34			1	-
243			60.16	Cable de energia			1	-
244			60.17	Cable RF Coaxial N-SMA Male			3	-

**Agenda Item2: Review of the procedures for the maintenance and operation of the REDDIG II**

2.1 Under this Agenda Item were explained procedures to follow to report damage, repair of equipment and/or parts, maintenance of the station using the REDDIG II Operation Manual.

***Report of damage***

2.2 The general procedure will remain the same which has been used in REDDIG I. The Management Center -NCC in Manaus is to be informed of the failure or malfunction of a service, providing the precise information, example: the type of service (voice or data) and the corresponding physical or logical port.

2.3 The Management Center-NCC will open an occurrence file with the information received and will make a diagnosis the failure with the technical team of the station to restore the operation of the service, main objective, doing specific procedures depending on the type of fault.

2.4 In case the Management Center–NCC finds a fault that has not been reported, will perform in a similar way, the general procedure by contacting the technician of the station for the diagnostic and restoration of the operation of the service.

2.5 The principal specific proceedings to restore the service operations are:

- Change on baseband equipment (Cisco router)
- Change on Skywan modem equipment (SKW)
- Change on satellite equipment (IBUC)
- Change on satellite reception equipment (LNB)
- Change of the satellite and terrestrial network
- Change to operation in disaster recovery mode
- Reload of the equipment configuration

Those proceedings are referred in the REDDIG II Operation Manual.

2.6 Within the guarantee period of two (2) years from the date of the FNAT, the REDDIG Administration will report to INEO, if merited, the fault or irregularity of operation that the network presents, except in the terrestrial network specified in paragraph 2.5.

2.7 Within the ORD period and for the following six (6) months since the FNAT date, the REDDIG Administration will report the fault or malfunctioning, if applicable to the terrestrial network, to INEO & Level 3 Consortium.

***Repare of equipment and/or parts***

2.8 During the ORD period and the two (2) years guarantee counted since the FNAT, if an equipment or part is diagnosed with a fault that should be repaired or replaced, the procedure below will be followed:

- 1) ICAO SAM Office will send, if available in the REDDIG warehouse, a new equipment or part to the node presenting the problem. The equipment or part will be send on loan as a temporary export.
- 2) In any case, whether or not existence of equipment or spare part in the warehouse, in parallel action, the node will send the equipment or part damaged to INEO for its repair or replacement by applying the clause 16 of Contract 22501200 referred to “Network/Equipment Warranty”.
- 3) Once the equipment or part returns from INEO to the node, the node will return it to ICAO SAM Office for its re-entry to the store.

### ***Maintenance of the REDDIG node station***

2.9 REDDIG II will continue using the current preventive maintenance programme structure for the station and due to the importance of its execution is then reiterated:

a) Energy

Verify on monthly basis than the AC voltage level is in its nominal value and that the difference in voltage between the neutral and terrestrial line is not greater than 1.0 VAC, being the recommended objective 0.5 VAC. This applies for both “indoor” and “outdoor” equipment.

b) Antenna

- Clean the reflector and the antenna pedestal every sixth (6) months.
- Grease the mechanical system of movement in azimuth and elevation of the antenna every six (6) months
- Check the alignment of the antenna every twelve (12) months and make adjustments if needed.
- “Outdoor” Equipment
- IBUC: Cleaning every twelve (12) months in full the air circulation system.
- Antenna GPS and Cables IFL: check every six (6) months the condition of the cable and its connector, including the protective tape.

c) “Indoor” Equipment

- Rack(s): Check the air circulation system on monthly basis.
- Patch panel: Monthly verification of adherence of voice services connectors (RJ45 / RJ11) and data (DB-25 / RJ45).

2.10 Refer to REDDIG II Operation Manual for operative maintenance information.

### ***REDDIG II Operations Manual***

2.11 **The Appendix** of this Agenda Item presents the diagrams of the REDDIG II stations in order to facilitate the understanding of its working, together with the updated plans that INEO will provide at the end of ORD period.

2.12 INEO & Level 3 Consortium developed the “User Manual” and delivered to each Node during the installation period, three hard copies in English and three in Spanish.

2.13 The Manual contains the following chapters:

- 1) GPS
- 2) Converter Serial to Ethernet
- 3) Terrasat
- 4) Switch Ethernet Netgear
- 5) ND SatCom
- 6) NMS – Whatsup Gold
- 7) Cisco Routers
- 8) VPN Netgear
- 9) SkyNMS

2.14 The setup procedures of equipment and sub-systems of the network were explained to the meeting during the analysis of this Agenda Item.


2.15 The REDDIG website [www1.lima.icao.int/reddig/](http://www1.lima.icao.int/reddig/) contains the electronic version of the Manual both English and Spanish.

## **Diagrams of the REDDIG II stations**

# REDDIG II STATION DIAGRAM




NCC - EZEIZA




# REDDIG II STATION DIAGRAM




NCC - MANAUS



# REDDIG II STATION DIAGRAM




# REDDIG II STATION DIAGRAM





# REDDIG II STATION DIAGRAM

SLLP - SKED - SEGU  
SOCA - SYGC - SGAS  
SPIM - SMPM - TTZP  
SUMU



**Agenda Item 3: Analysis of the requirements for the improvement of the REDDIG II provision**

3.1 Under this Agenda Item, the Meeting was asked to carefully review the last planes and the CDs received from INEO and to inform their conformity or observations to the project management (ICAO) and REDDIG Administration, not later than 15 May 2015.

3.2 The REDDIG telephone directory (ATS and Administrative) was received by the Meeting from the REDDIG Administrator and is included as **Appendix A** to this Agenda Item for its review, updating and return to the REDDIG, not later than 15 May 2015.

3.3 Likewise, the REDDIG Administration provided the Meeting a list of connectors, ports and identification of voice services and data of each station. The list is presented as **Appendix B** to this Agenda Item for its review, correction and updating, as applicable and be returned to the Administration of the REDDIG, not later than 31 May 2015.

3.4 The Meeting was informed of the importance of having a VPN gateway in each REDDIG stations for its recovery in the event of a disaster. For this purpose the REDDIG Administration requested members States of the REDDIG, who have not yet done, provide as soon as possible a fixed IP address for the installation of the "router" VPN by the contractor INEO.

3.5 Finally, the Meeting agreed that the Ezeiza NCC continues providing support, assigning the required personnel for the tasks demanded by the REDDIG Administration.

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SAEZ</b>	<b>Ciudad:</b>	<b>Buenos Aires - ARGENTINA</b>	
	Dirección:	Aeropuerto Ministro Pistarini (Ezeiza), 4to piso, DECODI			
	Teléfono:	5411 4480 2362			
	Fax:	5411 4480 2363			
	E-mail:	<a href="mailto:javiervittor@gmail.com">javiervittor@gmail.com</a> (Javier Vittor), <a href="mailto:hernangabriel1@gmail.com">hernangabriel1@gmail.com</a> (Hernán Canna)			
	Teléfonos Red Administrativa:	2057362			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Javier Vittor		2057350	5411 4480 2350	
	Hernán Canna		2057356	5411 4480 2356	
	<b>USUARIO</b>			<b>Teléfono REDDIG</b>	<b>Observ.</b>
<b>A T S</b>	Ezeiza Turno Técnico REDDIG			2000	
	Torre de Control de Vuelo (TWR) Ezeiza			2005	
	Supervisión del Tráfico de la Red AFTN			2006	
	Línea JNB			2015	
	ACC Córdoba (Principal)			2032	
	ACC Comodoro Rivadavia			2033	
	ACC Mendoza			2034	
	ACC Córdoba			2035	
	ACC Resistencia (Principal)			2036	
	ACC Mendoza (Alternativa)			2037	
	Aeroparque Jorge Newbery			2038	
	Torre Control Iguazu (Alternativo)			2039	
	Torre Bariloche (Principal)			2040	
	<b>Torre Control Iguazu</b>			<b>2041</b>	
	<b>Torre Paso de los Libres</b>			<b>2042</b>	
	<b>Torre Concordia</b>			<b>2043</b>	
	Ezeiza I Turno Técnico ACC			2044	
	Ezeiza II Turno Técnico ACC			2045	
	ACC Sur (Control Visual) Manual APP 2 Ezeiza			2050	
	ACC 1Norte I Radar DEO EZEIZA			2051	
	ACC 2 APP 1 DEO TMA ESTE/OESTE/NORTE- Ezeiza			2052	
	Ushuaia (alternativa)			2055	
	Río Gallegos (alternativa)			2056	
ACC Ezeiza Supervisor			2060		
ACC Sur Radar APP2 - Ezeiza			2061		

	ACC Radar Norte II DEO - Ezeiza		2062	
	ACC Radar Norte III DEO - Ezeiza		2063	
	Torre Bariloche (Alternativa)		2064	
	ACC Mendoza Hot-Line punto a punto DOZ-CHI		2065	
	ACC Córdoba (Alternativa)		2066	
	ACC Resistencia (alternativa)		2067	
	Río Gallegos		2068	
	Ushuaia		2069	
	ACC Resistencia (Alternativa)		2090	

		<b>Teléfono REDDIG</b>	<b>Observ.</b>
<b>ADMIN</b>	Jefe División Redes (Sistema REDDIG)	2057350	
	Jefe Esc. Operativo (Telecomunicaciones)	2057356	
	Enc. Esc. Operativo (Sistema REDDIG)	2057386	
		2057352	
		2057361	
	CCAM Centro de Comunicaciones	2057269	
	Sala de Técnica y Supervisión para los Sistemas Oral ATS, REDDIG, AFTN, Red Local Administrativa	2057362	
		2057500	
		2057369	
		<b>2001</b>	
COSPAS-SARSAT (ARMCC) (ARMCC)	2055555		
	Nro FAX		

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SLLP</b>	<b>Ciudad:</b>	<b>La Paz - BOLIVIA</b>	
	Dirección:	Aeropuerto Internacional El Alto			
	Teléfono:	5912 281 0119			
	Fax:				
	E-mail:	<a href="mailto:titohernanh@latinmail.com">titohernanh@latinmail.com</a>			
	Teléfonos Red Administrativa:	2501			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Remigio Blanco	Punto Focal REDDIG	252141	5912 2370340	
	Hernán Tito	Técnico	2501	59122129901	
	Javier Campos	Técnico	2501		

<b>A T S</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Coordinación ACC	2551	
	ACC 1	2552	
	ACC 2	2560	
	APP Puerto Suárez	2533	

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	AASANA - Dirección Ejecutiva	252101	
	AASANA - Dirección Técnica	252104	
	AASANA - Dirección Administrativa	252107	
	AASANA - Directorio	252110	
	AASANA - Jefatura de Obras Civiles	252132	
	AASANA - Jefatura Comercial	252135	
	AASANA - Jefatura de Ingeniería Electrónica	252138	
	AASANA - Jefatura División de Telecomunicaciones	252141	
	AASANA - Oficina de Planificación	252145	
	Mantenimiento Técnico de la REDDIG	2501	
	Departamento Técnico	252233	
	252235		

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada.

<b>DATOS DEL NODO</b>	<b>Nodo: SBCT</b>		<b>Ciudad: Curitiba - BRASIL</b>			
	Dirección:		Av. Erasto Gaertner, 1000. CEP 82515-000, Curitiba - PR, Brasil			
	Teléfono:		55 41 3251 5315 - 55 41 3251 5341- 55 41 3251 5318 / 5416			
	Fax:		5541 3251 5341			
	E-mail:		<a href="mailto:dennielsancho@hotmail.com">dennielsancho@hotmail.com</a>			
	Teléfonos Red Administrativa:		305545, 305441 y/o 3001			
	<b>Personal Técnico</b>		<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Jefferson			305315	5541 3256 1121	-
				305441	5541 3018 1925	-
	Técnico 24 horas			<b>305315</b>	5541 3251 5315	-

<b>ATS</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Supervisor Curitiba	3060	Curitiba
	Asistente Setor 1		Curitiba
	Asistente Setor 2		Curitiba
	Asistente Setor 3		Curitiba
	Asistente Setor 4		Curitiba
	Asistente Setor 5		Curitiba
	Asistente Setor 6		Curitiba
	Asistente Setor 7		Curitiba
	Asistente Setor 8		Curitiba
	Asistente Setor 9		Curitiba
	Asistente Setor 10		Curitiba
	Asistente Setor 11		Curitiba
	Asistente Setor 12		Curitiba
	Control Setor 1		Curitiba
	Control Setor 2		Curitiba
	Control Setor 3		Curitiba
	Control Setor 4		Curitiba
	Control Setor 5		Curitiba
	Control Setor 6		Curitiba
	Control Setor 7		Curitiba
	Control Setor 8		Curitiba
	Control Setor 9		Curitiba
	Control Setor 10		Curitiba
	Control Setor 11		Curitiba
Control Setor 12		Curitiba	
APP Foz de Iguazú	3041	Foz de Iguazú	
APP Corumba	3091	Corumba	
APP Uruguaiana	3083	Uruguaina	

<b>ADMIN</b>	<b>USUARIO</b>	<b>REDDIG Telephone</b>	<b>Comments</b>
	DECEA Director General	306200	RJ
	DECEA Sub-Departamento de Operaciones (SDOP)	306241	RJ
	DECEA Sub-Departamento de Logística (SDLO)	306205	RJ
	CECATI	306250	RJ
	CERNAI	306200	RJ
	División CNS	306267	RJ
	División ATM	306273	RJ
	División de Telecomunicaciones	306220	RJ
	Oficial CNS (Florianopolis)	305545	Florianópolis
	CINDACTA 1 (Brasilia) Supervisor AFTN CCAM-BR	308377	Brasilia
	CINDACTA 2 (Curitiba) Mantenimiento 1	3001	Curitiba
	CINDACTA 2 (Curitiba) Mantenimiento 2	305315	Curitiba

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SBMN</b>	<b>Ciudad: Manaus - BRASIL</b>			
	Dirección:	CINDACTA IV - Av. Do Turismo, No. 1350, Taramã CEP: 69045-630, Manaus, Brasil				
	Teléfono:	55-92-3652 5713 - 55-92-3652 5712				
	Fax:					
	E-mail:	1Ten. Magno: joan.magno@gmail.com				
	Teléfonos Red Administrativa:	3601 / 3602				
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>	
	1T Magno	Jefe Sala Técnica	3622	+55-92-3652 5470	+55-92-98212-6374	
	Sandro Mendes		3601 / 3602	+55-92-3652 5712	+55-92-99112-8089	
	Magno Rodrigues		3601 / 3602	+55-92-3652 5712	+55-92-98241-3087	
	Cleber de Souza		3601 / 3602	+55-92-3652 5712	+55-92-98173-5423	
	Eraldo Menezes		3601 / 3602	+55-92-3652 5712	+55-92-98125-7348	
	Leandro		3601 / 3602	+55-92-3652 5712	+55-92-98247-7414	
Webston		3601 / 3602	+55-92-3652 5712	+55-92-99122-4791		
<b>ATS</b>	<b>USUARIO</b>			<b>Teléfono REDDIG</b>	<b>Observ.</b>	
	Sector 1(BL)			3660		
	Sector 2(BL)			3662		
	Sector 3(BL)			3661		
	Sector 4(BL)			3664		
	Sector 5(BL)			3666		
	Sector 6(MN)			3667		
	Sector 9(MN)			3663		
	Sector 10(MN)			3668		
	Sector 11(PH)			3665		
	Sector 12(PH)			3669		
	Sector 13(PH)			3680		
	Sector 14(PH)			3682		
	Sector 15(PH)			3683		
	RCC MN			3674		
	SBTT (Tabatinga)			3671		
	<b>NCC Manaus - Número Operacional</b>			<b>3612</b>		
<b>ADMIN</b>	<b>USUARIO</b>			<b>Teléfono REDDIG</b>	<b>Observ.</b>	
	DT (Jefe)			3620		
	TEL (Jefe)			3621		
	Sala Técnica (Jefe)			3622		
	<b>NCC Manaus - Técnico</b>	<b>24Horas</b>			<b>3601/3602</b>	
	<b>Administrador REDDIG Tel: 55-92-3652 5714</b>			<b>3611</b>		

Notas:

1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SBRF</b>	<b>Ciudad: Recife - BRASIL</b>		
	Dirección:	Av. Centenario Santos Dumont, s/n, Ibura, Recife-PE. CEP 51250-020			
	Teléfono:	5581 2129 8376			
	Fax:	5581 2129 8116			
	E-mail:	<a href="mailto:carlosefpaes@gmail.com">carlosefpaes@gmail.com</a>			
	Teléfonos Red Administrativa:	3801 / 388376 / 388399 / 388166			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Cap. Carlos Paes	Jefe Enlaces	388180	5581 2129 8180	55-81-997001049
			388376	5581 2129 8376	
			388376	5581 2129 8376	

<b>A T S</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Supervisor Recife	3860	Recife
	Asistente Sector 1	3851	Recife
	Asistente Sector 2	3852	Recife
	Asistente Sector 3	3853	Recife
	Asistente Sector 4	3854	Recife
	Asistente Sector 5	3855	Recife
	Asistente Sector 6	3856	Recife
	Asistente Sector 7	3857	Recife
	Control Sector 1	3871	Recife
	Control Sector 2	3872	Recife
	Control Sector 3	3873	Recife
	Control Sector 4	3874	Recife
	Control Sector 5	3875	Recife
	Control Sector 6	3876	Recife
	Control Sector 7	3877	Recife
	Atlantico ACC - Control 1	3878	Recife
Atlantico ACC - Control 2	3879	Recife	

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	DECEA Director General	306200	RJ
	DECEA Sub-Departamento de Operaciones (SDOP)	306241	RJ
	DECEA Sub-Departamento de Logística (SDLO)	306205	RJ
	CECATI	306250	RJ
	CERNAI	306200	RJ
	División CNS	306267	RJ
	División ATM	306273	RJ
	División de Telecomunicaciones	306220	RJ
	CINDACTA 1 (Brasilia) Supervisor AFTN CCAM-BR	308377	Brasilia
	CINDACTA 3 (Recife) Mantenimiento 1	3801	Recife
CINDACTA 3 (Recife) Mantenimiento 2	388166 / 388376	Recife	

388399

- Notas:
1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada
  2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SKED</b>	<b>Ciudad: Bogotá - COLOMBIA</b>		
	Dirección:	Aeropuerto Internacional El Dorado, Centro Nacional de Aeronavegación			
	Teléfono:	571 2962062 / 571 2962272 / 571 2962237			
	Fax:	571 2962749			
	E-mail:	<a href="mailto:csua@aerocivil.gov.co">csua@aerocivil.gov.co</a> <a href="mailto:luis.lozanos@aerocivil.gov.co">luis.lozanos@aerocivil.gov.co</a>			
	Teléfonos Red Administrativa:	4501 / 4502/ 45258			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Ciro Sua	Técnico Aeronáutico	4501 / 45258		57 3142043758
	Luis Lozano	Técnico Aeronáutico	4501 / 45258		
	Gonzalo Meléndez	Técnico Aeronáutico	4501 / 45258		

<b>A T S</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ACC SWP Bogotá (SKBO)	4545	
	ACC NWP Bogotá (SKBO)	4550	
	ACC NEP Bogotá (SKBO)	4551	
	ACC SWP Bogotá (SKBO)	4552	
	ACC SER Bogotá (SKBO)	4553	
	ACC Supervisor Bogotá (SKBO)	4560	
	ACC Barranquilla (SKEC)	4531	
	ACC Sector Sur Barranquilla (SKEC)	4554	
	ACC Centro de Información de Vuelo Barranquilla (SKEC)	4555	
	ACC Supervisor Barranquilla (SKEC)	4556	
	TWR Pasto ( SKAN )	4518	
	ACC Cali ( SKCL )	4541	
	TWR Leticia ( SKLT )	4546	Ext 5785924562
APP Cucuta ( SKCC )	4557		

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Dirección General Aerocivil	45122	
	Subdirector General	45299	
	Secretario Técnico	45260	
	Director de Telecomunicaciones	45277	
	Director SKED	45277	
	Técnico Mantenimiento REDDIG	4501 / 4502	
	Técnico Mantenimiento REDDIG	45258	
	Técnico Planta HARRIS (Técnico grupo teléfonos)	4590	
	Técnico Planta HARRIS (Técnico grupo teléfonos)	45200	
	Comunicaciones AFTN (Operador)	45268 / 4503	
	Técnico BOGOTA (Técnico grupo comunicaciones)	45281	

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SCEL</b>	<b>Ciudad: Santiago - CHILE</b>		
	Dirección:	San Pablo N° 8411 , Pudahuel, Santiago, Chile			
	Teléfono:	562 6448345	Estación SCEL en Cerro Colorado : 562 8364040		
	Fax:	562 767 2011			
	E-mail:	<a href="mailto:cvergara@dgac.cl">cvergara@dgac.cl</a> <a href="mailto:ppastrian@dgac.cl">ppastrian@dgac.cl</a>			
	Teléfonos Red Administrativa:	404006 / 404007			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Christian Vergara Pedro Pastrian	Mantenimiento Mantenimiento	404006 404007	562 6448345 562 6448345	569 888 6452 569 083 3739

<b>A T S</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	San Pablo ACC 1-2 (Sector Norte)	4057 / 4058	
	San Pablo ACC 4 (Terminal Norte)	4050	
	San Pablo ACC 5 (Terminal)	4051	
	San Pablo ACC 6 (Terminal Sur)	4051	
	San Pablo ACC 7 (Sector VFR)	4053	
	San Pablo ACC 8-9 (Sector Sur)	4052	
	San Pablo Supervisor ACCS	4060	
	Cerro Colorado Jefe ACCS	4079	
	San Pablo Jefe Operaciones ACCS	4078	
	San Pablo Mantenimiento ACCS - REDDIG	4078 4087	
	CCAM	4075	
	Arica APP	4040	
	Puerto Montt SCTE	4032	
	Punta Arenas SCCI	4033	

ADMIN	USUARIO	Teléfono REDDIG	Observ.
	Dirección General Aeronáutica Civil	402500	EAC*(3)
	Secretario General	402504	EAC*(3)
	Director Logístico y Telecomunicaciones	402418	EAC*(3)
	Subdirector de Telecomunicaciones	402415	EAC*(3)
	Director de Meteorología	403340	EAC*(3)
	Jefe de Proyecto REDDIG	402350	EAC*(3)
	Coordinador Proyecto REDDIG	404005	ACCS Sn. Pablo
	San Pablo, Mantenimiento REDDIG	404007	ACCS Sn. Pablo
	San Pablo, Mantenimiento REDDIG	403248	ACCS Sn. Pablo
	San Pablo, Mantenimiento Encargado técnico REDDIG	404005	ACCS Sn. Pablo
	San Pablo, Mantenimiento Planta HARRIS	404006	ACCS Sn. Pablo
	Estación REDDIG en Cerro Colorado	404040	Cerro Colorado
	Comunicaciones AFTN, Supervisores	404029	ACCS Sn. Pablo
		404030	ACCS Sn. Pablo
Banco de Datos NOTAMs (NOF Internacional)	404033	ACCS Sn. Pablo	

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
 2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
 3. Edificio Aeronáutico Central, Miguel Claro 1314, Santiago

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SEGU</b>	<b>Ciudad: Guayaquil - ECUADOR</b>		
	Dirección:	Aeropuerto Internacional Simón Bolívar, Av. de las Américas, Guayaquil			
	Teléfono:	5934 269 2829 / 5934 2287236			
	Fax:	5934 2692829			
	E-mail:	<a href="mailto:ravellan1@yahoo.com">ravellan1@yahoo.com</a>			
	Teléfonos Red Administrativa:	502308 / 502309			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Raúl Avellán, Jefe Area	Jefe Comunic. Satelitales	502309	5934 269 2829	
	Washington Aguilar	Sec. Comunic. Satelitales	502308	5934 269 2829	

<b>ATS</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ACC 1	5051	
	ACC2	5053	
	APP	5052	
	ACC SPV	5060	
	ACC (Con COCESNA)	5071	Interconexión

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Técnico REDDIG	502308	
	Jefatura Comunicaciones Satelitales	502309	
	Técnico Electrónico de Telecomunicaciones	502121	
	Comunicaciones (Centro Mensajes) QUITO	502357	QUITO

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo: SOCA</b>		<b>Ciudad: Cayena - GUYANA FRANCESA</b>			
	Dirección:		Aviation Civile, Aeroport de Rochambeau, 97351 Matoury, Guyane Francaise			
	Teléfono:		594 594 359317 (Sala Técnica) - 594 594 359321 (Estación Antena)			
	Fax:		594 594 356166			
	E-mail:		<a href="mailto:alain.burtin@aviation-civile.gouv.fr">alain.burtin@aviation-civile.gouv.fr</a>			
	Teléfonos Red Administrativa:		9201			
	<b>Personal Técnico</b>		<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Michel Metzlerlard					
	Alain Burtin			9201		
	Serge			9201		594 694273437
Jean-François			9201		594 694465095	
Philippe			9201		594 694155978	

<b>A T S</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ACC	9254	
	ACC	9255	

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Sala Técnica, Mantenimiento 1	9201	
	Estación REDDIG Antena, Mantenimiento 2	9202	

<b>DATOS DEL NODO</b>	<b>Nodo: SYGC</b>		<b>Ciudad: Georgetown - GUYANA</b>			
	Dirección:		Control Tower complex, Cheddi Jagan Int'l Airport, Timehri, East Bank Demerara, Guyana			
	Teléfono:		592 261 2569			
	Fax:		592 261 2279			
	E-mail:		<a href="mailto:mbsalisbury2000@yahoo.com">mbsalisbury2000@yahoo.com</a>			
	Teléfonos Red Administrativa:		9001			
	<b>Personal Técnico</b>		<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Mortimer Salisbury			9001	592 261 2569	
				9001	592 261 2569	
				9001	593 261 2569	
			9001	594 261 2569		

<b>ATS</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ATS - ACC	9051	
	ATS - FIS	9053	
	ATS - Supervisor	9060	

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Mantenimiento Técnico	9001	

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SGAS</b>	<b>Ciudad:</b>	<b>Asunción - PARAGUAY</b>	
	Dirección:	Aeropuerto Internacional Silvio Pettrossi, Luque, Paraguay			
	Teléfono:	595 21 7585208 / 201 / 205			
	Fax:				
	E-mail:	<a href="mailto:moranchu@gmail.com">moranchu@gmail.com</a> <a href="mailto:aldopereira26@gmail.com">aldopereira26@gmail.com</a>			
	Teléfonos Red Administrativa:	5501, 55100			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Víctor Morán	Jefe Dpto. COM	5501 / 55100	595 21 7585208	595961764376
	Aldo Pereira	Jefe Sección Radiocom.	5501 / 55100	595 21 7585208	595985890679

<b>A T S</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ACC	5551	
	ACC	5541	(hotline con Curitiba)

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Oficina Técnica de Mantenimiento	5501 / 55100	
	Jefatura de Control de Area ACC	55101	
	Sala de Control de Area ACC	55102	
	Oficina de la Gerencia de Telecomunicaciones y Electrónica - GTE	55103	
	Oficina de la Gerencia de Tránsito Aéreo - GTA	55104	
	Secretaría Técnica GTE/GTA	55105	
	Centro de Control de Aproximación ASU-APP	55106	
	Torre de Control y Servicio de Rodaje ASU	55107	
	Centro de Control Automático de Mensaje - CCAM	55108	
	Oficina del Servicio Móvil Aeronáutico - SMA	55109	
	Oficina del Servicio Meteorológico - MET	55110	
	Oficina de Notificación de los Servicios de Tránsito Aéreo - ARO	55111	
	Aeropuerto Int'l Guaraní, Minga Guasú, Alto Paraná	55113	
	Aeropuerto Int'l Dr. Luis M. Argaña, Mcal. Estigarribia, Chaco Paraguayo	55114	
	Centro de Investigación de Accidentes	55115	

- Notas:
1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada
  2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SPIM</b>	<b>Ciudad:</b>	<b>Lima - PERU</b>	
	Dirección:	Aeropuerto Internacional Jorge Chávez, Callao, Perú			
	Teléfono:	511 5153015 / 511 4141250			
	Fax:	511 5153015			
	E-mail:	<a href="mailto:reddig@corpac.gob.pe">reddig@corpac.gob.pe</a> ; <a href="mailto:lsilva@corpac.gob.pe">lsilva@corpac.gob.pe</a>			
	Teléfonos Red Administrativa:	6001 - 6016101			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública (1)</b>	<b>Teléfono Red Pública (2)</b>
			ADM		
	Simeón Velásquez	Técnico	6001	511 5153015	511 4141250
	Ricardo Arteaga	Técnico	6001	511 5153015	511 4141250
	Andrés Arango	Técnico	6001		
	Mario Kuan	Técnico AMHS	6040 (ATS)	511 6261214	
	Jeme Arteaga	Técnico AMHS	6040 (ATS)	511 6261214	
	R. Peralta/H. Peñaranda	Sala VSAT	6014 (ATS)		

<b>ATS</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Hot Line con Santiago	6002	
	Hot Line con Bogotá	6003	
	Hot Line con Guayaquil	6004	
	Hot Line con La Paz	6005	
	ACC-SUR Asistente	6051	
	ACC-NE Asistente	6052	
	ACC-NORTE Asistente	6053	
	Nuevo ACC-NORTE Ejecutivo	6034	Nuevo ACC-Lima
	Nuevo ACC-NORTE Planificador	6035	Nuevo ACC-Lima
	Nuevo ACC-SUR Ejecutivo	6036	Nuevo ACC-Lima
	Nuevo ACC-SUR Planificador	6037	Nuevo ACC-Lima
	Nuevo ACC-NOR ESTE Ejecutivo	6038	Nuevo ACC-Lima
	Nuevo ACC-NOR ESTE Planificador	6039	Nuevo ACC-Lima
	Supervisor 1 (ACC)	6060	
	Tacna TWR	6024	
	CCAM AFTN (Supervisor)	6078	
	Técnico AFTN	6040	
	Tecnico ATS	6044	

ADMIN	USUARIO	Teléfono REDDIG	Observ.
	Técnico REDDIG	6001	
	Técnico REDDIG	6016101	
	Técnico REDAP	6016102	

- Notas:
1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada
  2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SMPM</b>	<b>Ciudad: Paramaribo - SURINAME</b>		
	Dirección:	J. A. Pengel International Airport Zanderij, District Para			
	Teléfono:	597 325123			
	Fax:	597 498901			
	E-mail:	Mitchell Themen <a href="mailto:mickiano@live.com">mickiano@live.com</a>			
	Teléfonos Red Administrativa:	9401			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Mitchell Themen		9401	597 325123	
			9401	597 325172	
			9401	597 497143	

<b>ATS</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ACC	9451	
	APP	9452	

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Technical Maintenance	9401	

Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SUMU</b>	<b>Ciudad: Montevideo - URUGUAY</b>		
	Dirección:	Aeropuerto Internacional de Carrasco			
	Teléfono:	5982-6010932 INT. 4520			
	Fax:	5982-6010932 INT. 4501			
	E-mail:	<a href="mailto:miguelvera@adinet.com.uy">miguelvera@adinet.com.uy</a> ; <a href="mailto:wileda@hotmail.com">wileda@hotmail.com</a>			
	Teléfonos Red Administrativa:	5982-6010932			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Wilson Pelayo		<b>6501</b>	5982 6826224	99694790
	Miguel Vera		<b>6501</b>	5982 2093859	99680521

<b>A T S</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ATS ACC	6551	
	ATS APP	6552	
	ATS SUMU ACC - SAEZ (Norte)	6545	
	ATS SUMU APP - SAEZ (Sur)	6544	
	ATS SUMU ACC - BAIREZ	6543	
	ATS SUMU APP - BAIREZ	6546	
	APP Colonia	6550	

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	<b>Marcar 6541 para contactarse con el operador, y solicitar los números que se listan a continuación</b>		
	Recepción - Edificio Centro de Control	<b>6541</b>	
	Director de Circulación Aérea	5102	
	Jefe del Departamento Operativo de Tránsito Aéreo	5105	
	Director de la División de Telecomunicaciones (AFTN)	5107	
	Jefe del Departamento Técnico de Tránsito Aéreo	5109	
	División Comunicaciones	4516	
	Sala de Control Radar ACC y APP Carrasco	5119	
	Torre de Control	5250	
	Sala de CXK AFTN	5123	
	Sala Técnica REDDIG 1	6501 5124	
	Sala Técnica REDDIG 2	5133	
	D.G.A.C. Central General : 5982 6040408 / 5982 6010932		

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>SVMI</b>	<b>Ciudad: Maiquetía - VENEZUELA</b>		
	Dirección:	Edificio ATC, 2do Piso, Depto de Comunic., Maiquetía, Edo. Vargas, Venezuela			
	Teléfono:	58212 3552143 / 58212 3551412			
	Fax:	58212 3551412			
	E-mail:	<a href="mailto:v.fiore@inac.gob.ve">v.fiore@inac.gob.ve</a>			
	Teléfonos Red Administrativa:	8001			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Vicente Fiore	Jefe Reg. MIQ	8001	58212 3551412	4127080132
			8001		
			8001		

<b>ATS</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	RCC - TODOS	8051	
	ACC 5 - ATS-W	8053	
	ACC 3 - ATS-W	8053	
	ACC 4 - ATS-E	8044	
	ACC 6 - ATS-E	8044	

<b>ADMIN</b>	<b>USUARIO</b>	<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Mantenimiento REDDIG	8001	

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

<b>DATOS DEL NODO</b>	<b>Nodo:</b>	<b>TTZP</b>	<b>Ciudad: Piarco -TRINIDAD &amp; TOBAGO</b>		
	Dirección:				
	Teléfono:	1-868 6694028			
	Fax:				
	E-mail:	<a href="mailto:rbaboolal@gmail.com">rbaboolal@gmail.com</a>			
	Teléfonos Red Administrativa:	9101 / 9102			
	<b>Personal Técnico</b>	<b>Cargo</b>	<b>Teléfono REDDIG</b>	<b>Teléfono Red Pública</b>	<b>Celular</b>
	Rupnarine Baboolal			1-868 6694706	1-868 7849434
	Steve Saroop			1-868 6694706	1-868 3812382
	Shiraz Gopaul			1-868 6694706	1-868-4679717

<b>ATS</b>	<b>USUARIO</b>		<b>Teléfono REDDIG</b>	<b>Observ.</b>
	ACC-1	ATSd(Hot Line)		>>> Maiquetia
	ACC-2	ATSd(Hot Line)		>>> Georgetown
	ACC-3	ATSd(Hot Line)		>>> Cayenne
	ACC-4	ATSd(Hot Line)		>>> Paramaribo

<b>ADMIN</b>	<b>USUARIO</b>		<b>Teléfono REDDIG</b>	<b>Observ.</b>
	Maintenance		9101	
	DGCA Office		9140	

- Notas: 1. Para ATS, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada  
2. Para ADMIN, marcar el prefijo de habilitación de salida correspondiente del nodo que inicia llamada

ARGENTINA								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Maintenance		0	2001	SAEZ-CISCO-VSAT-1	0/2/0	FXS	WD-01	J1-A
Hotline - Chile	79901	0	9901	SAEZ-CISCO-VSAT-3	0/0/1	E&M type V	WC-06	J6-B
Hotline - Uruguay	79902	0	9904	SAEZ-CISCO-VSAT-2	0/0/0	E&M type V	WC-01	J1-B
Hotline - Uruguay	79903	0	9905	SAEZ-CISCO-VSAT-2	0/0/1	E&M type V	WC-02	J2-B
Admin		all	20XX	SAEZ-CISCO-VSAT-3	0/0/0	E&M type V	WC-05	J5-B
ATS Switched		5	20XX	SAEZ-CISCO-VSAT-3	0/1/0	E&M type V	WC-07	J7-B
ATS Switched		5	20XX	SAEZ-CISCO-VSAT-3	0/1/1	E&M type V	WC-08	J8-B
ATS Switched		5	20XX	SAEZ-CISCO-VSAT-3	0/2/0	E&M type V	WC-09	J9-B
ATS Switched		5	20XX	SAEZ-CISCO-VSAT-3	0/2/1	E&M type V	WC-10	J10-B
ATS Switched		5	20XX	SAEZ-CISCO-VSAT-3	0/3/0	E&M type V	WC-11	J11-B
Hotline - Uruguay	79904	0	9902	SAEZ-CISCO-VSAT-2	0/1/0	E&M type V	WC-03	J3-B
Hotline - Uruguay	79905	0	9903	SAEZ-CISCO-VSAT-2	0/1/1	E&M type V	WC-04	J4-B
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin - GBB		0	02000	SAEZ_CISCO_GBB_2	0/3/0	FXS	no	no
ATS - GBB		0	02099	SAEZ_CISCO_GBB_2	0/3/1	FXS	no	no
Device	Device	NMS device name	LAN IP address	VRRP IP	mask	gateway		
NMS server	10	SAEZ-REDDIG-II	NMS server - local	10.100.20.10		255.255.255.0	10.100.20.254	
	11	SAEZ-FAIL-REDDIG-II	NMS server failover	10.100.20.11		255.255.255.0	10.100.20.254	
NMS printer	20	SAEZ-IMP-REDDIG-II	impresora	10.100.20.20		255.255.255.0	10.100.20.254	
Skywan	31	SAEZ-SKW-MASTER-A	Skywan-master-A	10.100.20.31		255.255.255.0	10.100.20.254	
	32	SAEZ-SKW-B	Skywan-B	10.100.20.32		255.255.255.0	10.100.20.254	
IBUC	41	SAEZ-IBUC-A	IBUC-A	10.100.20.41		255.255.255.0	10.100.20.254	
	42	SAEZ-IBUC-B	IBUC-B	10.100.20.42		255.255.255.0	10.100.20.254	
RX 1+1	43	SAEZ-RX-1+1	RX 1+1	10.100.20.43		255.255.255.0	10.100.20.254	
Netgear switch	51	SAEZ-SWI-A	Switch-A	10.100.20.51		255.255.255.0	10.100.20.254	
	52	SAEZ-SWI-B	Switch-B	10.100.20.52		255.255.255.0	10.100.20.254	
netgear pro safe	60	SAEZ-VPN	VPN	10.100.20.60		255.255.255.0	10.100.20.254	
RSS	71	SAEZ-RSS-1	RSS-1	10.100.20.71		255.255.255.0	10.100.20.254	
	72	SAEZ-RSS-2	RSS-2	10.100.20.72		255.255.255.0	10.100.20.254	
GPS	80	SAEZ-GPS	GPS	10.100.20.80		255.255.255.0	10.100.20.254	
MPLS access device	90		GBB-ACCESS	10.100.20.90		255.255.255.0	10.100.20.254	
Cisco VSAT	101	SAEZ-CISCO-VSAT-1-A	CISCO-VSAT-1-A	10.100.20.101	10.100.20.254	255.255.255.0	10.100.20.254	
	102	SAEZ-CISCO-VSAT-1-B	CISCO-VSAT-1-B	10.100.20.102	10.100.20.254	255.255.255.0	10.100.20.254	
	103	SAEZ-CISCO-VSAT-2-A	CISCO-VSAT-2-A	10.100.20.103	10.100.20.253	255.255.255.0	10.100.20.254	
	104	SAEZ-CISCO-VSAT-2-B	CISCO-VSAT-2-B	10.100.20.104	10.100.20.253	255.255.255.0	10.100.20.254	
	105	SAEZ-CISCO-VSAT-3-A	CISCO-VSAT-3-A	10.100.20.105	10.100.20.252	255.255.255.0	10.100.20.254	
	106	SAEZ-CISCO-VSAT-3-B	CISCO-VSAT-3-B	10.100.20.106	10.100.20.252	255.255.255.0	10.100.20.254	
cisco GBB	121	SAEZ-CISCO-GBB-1	CISCO-GBB-1	10.100.20.121		255.255.255.0	10.100.20.254	
	122	SAEZ-CISCO-GBB-2	CISCO-GBB-2	10.100.20.122		255.255.255.0	10.100.20.254	
IP to serial	130	SAEZ-Serial	Serial	10.100.20.130		255.255.255.0	10.100.20.254	

SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug
RADAR SUMU RX	SAEZ-CISCO-VSAT-1	0/0/0	12	P	WB 02	J24-A
RADASR SUMU TX	SAEZ-CISCO-VSAT-1	0/0/1	11	P	WB 01	J23-A
METEO SLLP	SAEZ-CISCO-VSAT-1	0/1/0	3	S	WB-30	J23-B
METEO SGAS	SAEZ-CISCO-VSAT-1	0/1/1	4	P	WB-31	J24-B
METEO SPIM	SAEZ-CISCO-VSAT-1	0/1/2	5	P	WB-32	J25-B
SLLP	SAEZ-CISCO-VSAT-1	0/1/3	6	S	WB-33	J26-B
SCEL	SAEZ-CISCO-VSAT-1	0/1/4	7	P	WB-40	J27-B
SUMU	SAEZ-CISCO-VSAT-1	0/1/5	8	P	WB-41	J28-B
SPIM	SAEZ-CISCO-VSAT-1	0/1/6	9	P	WB-42	J29-B
SBCT	SAEZ-CISCO-VSAT-1	0/1/7	10	S	WB-43	J30-B

TDMA SLL	3
----------	---

ARGENTINA

Dialing Plan Dial Plan Table

Dial Plan |

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
79901	40903	-++++>
79902	65945	-++++>
79903	65946	-++++>
79905	65944	-++++>
720XX	20140	-++++>
72553	25153	-++++>
725XX	25100	-++++>
73612	36112	-++++>
736XX	36140	-++++>
738XX	38140	-++++>
730XX	30140	-++++>
745XX	45100	-++++>
750XX	++1++	-++++>
79051	90102	-++++>
79053	90141	-++++>
79060	90142	-++++>
790XX	90100	-++++>
79251	92103	-++++>
79253	92104	-++++>
79254	92141	-++++>
79255	92155	-++++>
75551	55142	-++++>
760XX	60100	-++++>
79451	94102	-++++>
79452	94141	-++++>
794XX	94100	-++++>
76550	65142	-++++>
76551	65102	-++++>
76552	65103	-++++>
78051	80143	-++++>
78053	80144	-++++>
78060	80141	-++++>
79904	65943	-++++>
740XX	40140	-++++>
721XX	++++	-++++>
7XXX	++1++	-++++>

Dialing Plan Dial Plan Table

Dial Plan |2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
72001	20201	-++++>
720XX	20241	-++++>
721XX	++++	-++++>
72501	25201	-++++>
725XX	25240	-++++>
73001	30201	-++++>
730XX	30200	-++++>
736XX	++2++	-++++>
73801	38241	3801
738XX	38200	-++++>
740XX	40200	-++++>
745XX	45200	-++++>
747XX	---++++	- - - - ->
750XX	50200	-++++>
75501	55201	-++++>
755XX	55200	-++++>
760XX	60200	-++++>
765XX	++2++	-++++>
78001	80201	-++++>
780XX	80242	-++++>
790XX	++2++	-++++>
79101	91201	-++++>
791XX	91240	-++++>
792XX	++2++	-++++>
79401	94201	-++++>
794XX	94240	-++++>
7XXX	++2++	-++++>

LA PAZ								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
maintenance		0	2501	SLLP-CISCO-VSAT	EVM/0	FXS	WD-01	J5
ATS switched		3	25XX	SLLP-CISCO-VSAT	0/1/0	E&M type 2	WC-01	J1
ATS switched		3	25XX	SLLP-CISCO-VSAT	0/1/1	E&M type 2	WC-02	J2
ATS switched		0	2553	SLLP-CISCO-VSAT	EVM/1	FXS	WD-02	J6
Admin PBX		2	25XX	SLLP-CISCO-VSAT	0/2/0	E&M type 2	WC-03	J3
Admin PBX		2	25XX	SLLP-CISCO-VSAT	0/2/1	E&M type 2	WC-04	J4
Hotline Manaus	9901	0	9901	SLLP-CISCO-VSAT	EVM/2	FXS	WD-03	J7
Hotline Peru	9902	0	9902	SLLP-CISCO-VSAT	EVM/3	FXS	WD-04	J8
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin - GBB		0	02500	SLLP-CISCO-GBB	0/2/1	FXS	no	no
ATS - GBB		0	2599	SLLP-CISCO-GBB	0/2/0	FXS	no	no
Device	Device	NMS device name	LAN IP address	mask	gateway	VRRP		
NMS server	10	SLLP-REDDIG-II	NMS server - loca	10.100.25.10	255.255.255.0	10.100.25.254		
	210	SLLP-REDDIG-II	iLO	10.100.25.210	255.255.255.0	10.100.25.254		
NMS printer	20	SLLP-IMP-REDDIG-II	impresora	10.100.25.20	255.255.255.0	10.100.25.254		
Skywan	31	SLLP-SKW-A	Skywan-A	10.100.25.31	255.255.255.0	10.100.25.254		
	32	SLLP-SKW-B	Skywan-B	10.100.25.32	255.255.255.0	10.100.25.254		
IBUC	41	SLLP-IBUC-A	IBUC-A	10.100.25.41	255.255.255.0	10.100.25.254		
	42	SLLP-IBUC-B	IBUC-B	10.100.25.42	255.255.255.0	10.100.25.254		
RX 1+1	43	SLLP-RX-1+1	RX 1+1	10.100.25.43	255.255.255.0	10.100.25.254		
Netgear switch	51	SLLP-SWI-A	Switch-A	10.100.25.51	255.255.255.0	10.100.25.254		
	52	SLLP-SWI-B	Switch-B	10.100.25.52	255.255.255.0	10.100.25.254		
netgear pro safe	60	SLLP-VPN	VPN	10.100.25.60	255.255.255.0	10.100.25.254		
RSS	71	SLLP-RSS	RSS	10.100.25.71	255.255.255.0	10.100.25.254		
GPS	80	SLLP-GPS	GPS	10.100.25.80	255.255.255.0	10.100.25.254		
MPLS access device	90		GBB-ACCESS	10.100.25.90	255.255.255.0	10.100.25.254		
Cisco VSAT	101	SLLP-CISCO-VSAT-A	CISCO-VSAT-A	10.100.25.101	255.255.255.0	10.100.25.254	10.100.25.254	
	102	SLLP-CISCO-VSAT-B	CISCO-VSAT-B	10.100.25.102	255.255.255.0	10.100.25.254		
cisco GBB	121	SLLP-CISCO-GBB	CISCO-GBB	10.100.25.121	255.255.255.0	10.100.25.254		
SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug		
SPIM	SLLP-CISCO-VSAT	0/0/0	2	P	WB-01	J23		
SAEZ	SLLP-CISCO-VSAT	0/0/1	6	P	WB-02	J24		
SBCT	SLLP-CISCO-VSAT	0/0/2	1	P	WB-03	J25		
METEO SAEZ	SLLP-CISCO-VSAT	0/0/3	3	P	WB-04	J26		
			60					
		SLL	11					
			12					

Dialing Plan Dial Plan Table      Dial Plan 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
2553	25153	>
25XX	25100	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
9251	92103	>

Dialing Plan Dial Plan Table      Dial Plan 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
72001	20201	>
720XX	20241	-++++>
72501	25201	-++++>
725XX	25240	-++++>
736XX	--+2++	-++++>
73801	38241	3801
738XX	38200	-++++>
73001	30201	-++++>
730XX	30200	-++++>
740XX	40200	-++++>
745XX	45200	-++++>
750XX	50200	-++++>
790XX	--+2++	-++++>
792XX	--+2++	-++++>
75501	55201	-++++>
755XX	55200	-++++>
760XX	60200	-++++>
79401	94201	-++++>
794XX	94240	-++++>
765XX	--+2++	-++++>
78001	80201	-++++>
780XX	80242	-++++>
7XXXX	--+2++	-++++>

CURITIBA								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS switched		3	30XX	SBCT-CISCO-VSAT-2	0/0/0	E&M type V	WC-01	J12 (à confirmer !)
ATS switched		3	30XX	SBCT-CISCO-VSAT-2	0/0/1	E&M type V	WC-02	J11 (à confirmer !)
ATS switched		3	30XX	SBCT-CISCO-VSAT-2	0/1/0	E&M type V	WC-03	J10 (à confirmer !)
ATS switched		3	30XX	SBCT-CISCO-VSAT-2	0/1/1	E&M type V	WC-04	J9 (à confirmer !)
Hotline Paraguay	9902	0	9901	SBCT-CISCO-VSAT-1	0/1/1	FXO	WD-01	J2
Hotline Uruguay	9903	0	9901	SBCT-CISCO-VSAT-1	0/1/2	FXO	WD-02	J3
Maintenance		3	3001	SBCT-CISCO-VSAT-1	0/2/0	FXS	WD-06	J5
Admin		2	30XX	SBCT-CISCO-VSAT-2	0/2/0	E&M type V	WC-05	J8 (à confirmer !)
Admin		2	30XX	SBCT-CISCO-VSAT-2	0/2/1	E&M type V	WC-06	J7 (à confirmer !)
Hotline	9901	0	?	SBCT-CISCO-VSAT-1	0/1/0	FXO	WD-03	J1
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin - GBB		0	03000	SBCT-CISCO-GBB-2	0/0/1	FXS	no	no
ATS - GBB		0	03099	SBCT-CISCO-GBB-2	0/0/0	FXS	no	no
Device	Device	NMS device name	LAN IP address	mask	gateway	VRRP		
NMS server	10	SBCT-REDDIG-II	NMS server - local	10.100.30.10	255.255.255.0	10.100.30.254		
NMS printer	20	SBCT-IMP-REDDIG-II	impresora	10.100.30.20	255.255.255.0	10.100.30.254		
Skywan	31	SBCT-SKW-A	Skywan-A	10.100.30.31	255.255.255.0	10.100.30.254		
	32	SBCT-SKW-B	Skywan-B	10.100.30.32	255.255.255.0	10.100.30.254		
IBUC	41	SBCT-IBUC-A	IBUC-A	10.100.30.41	255.255.255.0	10.100.30.254		
	42	SBCT-IBUC-B	IBUC-B	10.100.30.42	255.255.255.0	10.100.30.254		
RX 1+1	43	SBCT-RX-1+1	RX 1+1	10.100.30.43	255.255.255.0	10.100.30.254		
Netgear switch	51	SBCT-SWI-A	Switch-A	10.100.30.51	255.255.255.0	10.100.30.254		
	52	SBCT-SWI-B	Switch-B	10.100.30.52	255.255.255.0	10.100.30.254		
netgear pro safe	60	SBCT-VPN	VPN	10.100.30.60	255.255.255.0	10.100.30.254		
RSS	71	SBCT-RSS-1	RSS-1	10.100.30.71	255.255.255.0	10.100.30.254		
	72	SBCT-RSS-2	RSS-2	10.100.30.72	255.255.255.0	10.100.30.254		
GPS	80	SBCT-GPS	GPS	10.100.30.80	255.255.255.0	10.100.30.254		
MPLS access device	90		GBB-ACCESS	10.100.30.90	255.255.255.0	10.100.30.254		
Cisco VSAT	101	SBCT-CISCO-VSAT-1-A	CISCO-VSAT-1-A	10.100.30.101	255.255.255.0	10.100.30.254	10.100.30.254	
	102	SBCT-CISCO-VSAT-1-B	CISCO-VSAT-1-B	10.100.30.102	255.255.255.0	10.100.30.254	10.100.30.254	
	103	SBCT-CISCO-VSAT-2-A	CISCO-VSAT-2-A	10.100.30.103	255.255.255.0	10.100.30.254	10.100.30.253	
	104	SBCT-CISCO-VSAT-2-B	CISCO-VSAT-2-B	10.100.30.104	255.255.255.0	10.100.30.254	10.100.30.253	
cisco GBB	121	SBCT-CISCO-GBB-1	CISCO-GBB-1	10.100.30.121	255.255.255.0	10.100.30.254		
	122	SBCT-CISCO-GBB-2	CISCO-GBB-2	10.100.30.122	255.255.255.0	10.100.30.254		
IP to serial	130	SBCT-Serial	Serial	10.100.30.130	255.255.255.0	10.100.30.254		
SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug		
SLLP	SBCT-CISCO-VSAT-1	0/0/0	1	S	WB-01	J23		
SGAS	SBCT-CISCO-VSAT-1	0/0/1	2	P	WB-02	J24		
SAEZ	SBCT-CISCO-VSAT-1	0/0/2	10	P	WB-03	J25		
SUMU	SBCT-CISCO-VSAT-1	0/0/3	3	P	WB-04	J26		
	SLL	5						
		6						

Dialing Plan Dial Plan Table			Dial Plan	Dialing Plan Dial Plan Table			Dial Plan
			2				1
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern		Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern	
2001	20201	>		50XX	++1++	>	
20XX	20241	>		XXXX	++1++	>	
2501	25201	>		20XX	20140	>	
25XX	25240	>		25XX	25100	>	
36XX	++2++	>		2553	25153	>	
3801	38241	3801		30XX	30140	>	
38XX	38200	>		3612	36112	>	
40XX	40200	>		36XX	36140	>	
45XX	45200	>		38XX	38140	>	
50XX	50200	>		40XX	40140	>	
90XX	++2++	>		45XX	45100	>	
92XX	++2++	>		5551	55142	>	
5501	55201	>		9901	55904	>	
55XX	55200	>		9902	55941	>	
60XX	60200	>		60XX	60100	>	
9401	94201	>		6551	65102	>	
94XX	94240	>		6552	65103	>	
65XX	++2++	>		6550	65142	>	
8001	80201	>		9903	65904	>	
80XX	80242	>		8060	80141	>	
3001	30201	>		8051	80143	>	
30XX	30200	>		8053	80144	>	
XXXX	++2++	>		90XX	90100	>	

<b>MANAUS</b>								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin		0	3611	SBMN-CISCO-VSAT-2	0/2/0	FXS	WD-01	J8
ATS switched		0	3612	SBMN-CISCO-VSAT-2	0/3/0	FXS	WD-05	J12
Maintenance		0	3601	SBMN-CISCO-VSAT-2	0/2/1	FXS	WD-02	J9
Maintenance		0	3602	SBMN-CISCO-VSAT-2	0/2/2	FXS	WD-03	J10
Hotline French Guiana	9906	0	9901	SBMN-CISCO-VSAT-2	0/2/3	FXS	WD-04	J11
Hotline Bolivia	9901	0	9901	SBMN-CISCO-VSAT-2	0/3/1	FXS	WD-06	J13
Hotline Venezuela	9902	0	9902	SBMN-CISCO-VSAT-1	0/0/0	E&M type I	WC-01	J1
ATS switched		2	36XX	SBMN-CISCO-VSAT-1	0/0/1	E&M type I	WC-02	J2
ATS switched		2	36XX	SBMN-CISCO-VSAT-1	0/1/0	E&M type I	WC-03	J3
ATS switched		2	36XX	SBMN-CISCO-VSAT-1	0/1/1	E&M type I	WC-04	J4
Hotline Colombia	9903	0	9905	SBMN-CISCO-VSAT-1	0/2/0	E&M type I	WC-05	J5
Hotline Colombia - Porto V	9904	0	9904	SBMN-CISCO-VSAT-1	0/2/1	E&M type I	WC-06	J6
Hotline Colombia Porto Laeti	9905	0	9906	SBMN-CISCO-VSAT-1	0/3/0	E&M type I	WC-07	J7
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin - GBB		0	03600	SBMN-CISCO-GBB	1/0/0	FXS	no	no
ATS - GBB		0	03699	SBMN-CISCO-GBB	1/0/1	FXS	no	no
skynms	Administrator	gdfsuez						
Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	SBMN-REDDIG-II	NMS server - local	10.100.36.10	255.255.255.0	10.100.36.254		
	11	SBMN-CENT-REDDIG-II	NMS server failover	10.100.36.11	255.255.255.0	10.100.36.254		
	12	SBMN-BDD1-REDDIG-II	NMS server failover	10.100.36.12	255.255.255.0	10.100.36.254		
	13	SBMN-BDD2-REDDIG-II	NMS server failover	10.100.36.13	255.255.255.0	10.100.36.254		
NMS printer	20	SBMN-IMP-REDDIG-II	impresora	10.100.36.20	255.255.255.0	10.100.36.254		
Skywan	31	SBMN-SKW-MASTER-A	Skywan-master-A	10.100.36.31	255.255.255.0	10.100.36.254		
	32	SBMN-SKW-B	Skywan-B	10.100.36.32	255.255.255.0	10.100.36.254		
IBUC	41	SBMN-IBUC-A	IBUC-A	10.100.36.41	255.255.255.0	10.100.36.254		
	42	SBMN-IBUC-B	IBUC-B	10.100.36.42	255.255.255.0	10.100.36.254		
RX 1+1	43	SBMN-RX-1+1	RX 1+1	10.100.36.43	255.255.255.0	10.100.36.254		
Netgear switch	51	SBMN-SWI-A	Switch-A	10.100.36.51	255.255.255.0	10.100.36.254		
	52	SBMN-SWI-B	Switch-B	10.100.36.52	255.255.255.0	10.100.36.254		
netgear pro safe	60	SBMN-VPN	VPN	10.100.36.60	255.255.255.0	10.100.36.254		
RSS	71	SBMN-RSS-1	RSS-1	10.100.36.71	255.255.255.0	10.100.36.254		
	72	SBMN-RSS-2	RSS-2	10.100.36.72	255.255.255.0	10.100.36.254		
GPS	80	SBMN-GPS	GPS	10.100.36.80	255.255.255.0	10.100.36.254		
MPLS access de	90		GBB-ACCESS	10.100.36.90	255.255.255.0	10.100.36.254		
Cisco VSAT	101	SBMN-CISCO-VSAT-1-A	CISCO-VSAT-1-A	10.100.36.101	255.255.255.0	10.100.36.254	10.100.36.254	
	102	SBMN-CISCO-VSAT-1-B	CISCO-VSAT-1-B	10.100.36.102	255.255.255.0	10.100.36.254	10.100.36.254	
	103	SBMN-CISCO-VSAT-2-A	CISCO-VSAT-2-A	10.100.36.103	255.255.255.0	10.100.36.254	10.100.36.253	
	104	SBMN-CISCO-VSAT-2-B	CISCO-VSAT-2-B	10.100.36.104	255.255.255.0	10.100.36.254	10.100.36.253	
cisco GBB	121	SBMN-CISCO-GBB	CISCO-GBB	10.100.36.121	255.255.255.0	10.100.36.254		
IP to serial	130	SBMN-Serial	Serial	10.100.36.130	255.255.255.0	10.100.36.254		

SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug
SKED	SBMN-CISCO-VSAT-2	0/0/0	1	P	WB-01	J23
SMPM	SBMN-CISCO-VSAT-2	0/0/1	2	P	WB-02	J24
SOCA	SBMN-CISCO-VSAT-2	0/1/0	3	P	WB-03	J25
KATL	SBMN-CISCO-VSAT-2	0/1/1	4	P	WB-04	J26
SPIM	SBMN-CISCO-VSAT-2	0/1/2	7	P	WB-05	J27
SYGC	SBMN-CISCO-VSAT-2	0/1/3	6	P	WB-06	J28

MANAUS		
	SLL	1
		2

Dialing Plan Dial Plan Table Dial Plan 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
3001	30201	>
30XX	30200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
90XX	++2++	>
92XX	++2++	>
5501	55201	>
55XX	55200	>
60XX	60200	>
9401	94201	>
94XX	94240	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
47XX	-- +++++	-- - - - - ->
9101	91201	>
91XX	91240	>
21XX	++++	>
XXXX	++2++	>

Dialing Plan Dial Plan Table Dial Plan 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
94XX	94100	>
9901	25943	>
9902	80903	>
9903	45905	4505
9904	45904	4504
9905	45906	4506
XXXX	++1++	>

BRAZIL RECIFE								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Maintenance		0	3801	SBRE-CISCO-VSAT-1	0/1/0	FXS	WD-01	J1
ATS switched		4	38XX	SBRE-CISCO-VSAT-2	0/0/0	E&M - type V	WC-01	J3
ATS switched		4	38XX	SBRE-CISCO-VSAT-2	0/0/1	E&M - type V	WC-02	J4
ATS switched		4	38XX	SBRE-CISCO-VSAT-2	0/1/0	E&M - type V	WC-03	J5
ATS switched		4	38XX	SBRE-CISCO-VSAT-2	0/1/1	E&M - type V	WC-04	J6
ATS switched		4	38XX	SBRE-CISCO-VSAT-2	0/2/0	E&M - type V	WC-05	J7
Admin		2	38XX	SBRE-CISCO-VSAT-2	0/2/1	E&M - type V	WC-06	J8
Admin		2	38XX	SBRE-CISCO-VSAT-2	0/3/0	E&M - type V	WC-07	J9
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin - GBB		0	03800	SBRE-CISCO-GBB	1/0/0	FXS	no	no
ATS - GBB		0	03899	SBRE-CISCO-GBB	1/0/1	FXS	no	no
Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	SBRE-REDDIG-II	NMS server - local	10.100.38.10	255.255.255.0	10.100.38.254		
NMS printer	20	SBRE-IMP-REDDIG-II	impresora	10.100.38.20	255.255.255.0	10.100.38.254		
Skywan	31	SBRE-SKW-A	Skywan-A	10.100.38.31	255.255.255.0	10.100.38.254		
	32	SBRE-SKW-B	Skywan-B	10.100.38.32	255.255.255.0	10.100.38.254		
IBUC	41	SBRE-IBUC-A	IBUC-A	10.100.38.41	255.255.255.0	10.100.38.254		
	42	SBRE-IBUC-B	IBUC-B	10.100.38.42	255.255.255.0	10.100.38.254		
RX 1+1	43	SBRE-RX-1+1	RX 1+1	10.100.38.43	255.255.255.0	10.100.38.254		
Netgear switch	51	SBRE-SWI-A	Switch-A	10.100.38.51	255.255.255.0	10.100.38.254		
	52	SBRE-SWI-B	Switch-B	10.100.38.52	255.255.255.0	10.100.38.254		
netgear pro safe	60	SBRE-VPN	VPN	10.100.38.60	255.255.255.0	10.100.38.254		
RSS	71	SBRE-RSS	RSS	10.100.38.71	255.255.255.0	10.100.38.254		
GPS	80	SBRE-GPS	GPS	10.100.38.80	255.255.255.0	10.100.38.254		
MPLS access device	90		GBB-ACCESS	10.100.38.90	255.255.255.0	10.100.38.254		
Cisco VSAT	101	SBRE-CISCO-VSAT-1-A	CISCO-VSAT-1-A	10.100.38.101	255.255.255.0	10.100.38.254	10.100.38.254	
	102	SBRE-CISCO-VSAT-1-B	CISCO-VSAT-1-B	10.100.38.102	255.255.255.0	10.100.38.254	10.100.38.254	
	103	SBRE-CISCO-VSAT-2-A	CISCO-VSAT-2-A	10.100.38.103	255.255.255.0	10.100.38.254	10.100.38.253	
	104	SBRE-CISCO-VSAT-2-B	CISCO-VSAT-2-B	10.100.38.104	255.255.255.0	10.100.38.254	10.100.38.253	
cisco GBB	121	SBRE-CISCO-GBB	CISCO-GBB	10.100.38.121	255.255.255.0	10.100.38.254		
IP to serial	130	SBRE-Serial	Serial	10.100.38.130	255.255.255.0	10.100.38.254		
SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug		
AFTN SVMI	SBRE-VSAT-1	0/0/0	1	P	WB-01	J23		
BRAZIL RECIFE								
SLL	21							
	22							

Dialing Plan Dial Plan Table Dial Plan 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
3001	30201	>
30XX	30200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
90XX	++2++	>
92XX	++2++	>
5501	55201	>
55XX	55200	>
60XX	60200	>
9401	94201	>
94XX	94240	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
XXXX	++2++	>

Dialing Plan Dial Plan Table Dial Plan 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
2553	25153	>
25XX	25100	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
94XX	94100	>
XXXX	++1++	>

CHILE - SANTIAGO								
Service	PLAR number (autodia l)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin		2	40XX	SCEL-CISCO-VSAT-2	0/0/0	E&M type V	WC 01	J1
Admin		2	40XX	SCEL-CISCO-VSAT-2	0/0/1	E&M type V	WC 02	J2
Hotline Argentina	9901	0	79901 ---> 9901	SCEL-CISCO-VSAT-2	0/1/0	E&M type V	WC 03	J3
Hotline Peru	9902	0	9902	SCEL-CISCO-VSAT-2	0/1/1	E&M type V	WC 04	J4
ATS switched		2	40XX	SCEL-CISCO-VSAT-2	0/2/0	E&M type V	WC 05	J5
ATS switched		2	40XX	SCEL-CISCO-VSAT-2	0/2/1	E&M type V	WC 06	J6
ATS switched		2	40XX	SCEL-CISCO-VSAT-2	0/3/0	E&M type V	WC 07	J7
ATS switched		2	40XX	SCEL-CISCO-VSAT-2	0/3/1	E&M type V	WC 08	J8
Service	PLAR number (autodia l)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin - GBB		0	04000	SCEL-CISCO-GBB	0/1/1	E&M type V	no	no
ATS - GBB		0	04099	SCEL-CISCO-GBB	0/1/0	E&M type V	no	no
Device	Device	NMS device name	LAN IP address	mask	gateway	VRRP		
NMS server	10	SCEL-REDDIG-II	NMS server - local	10.100.40.10	255.255.255.0	10.100.40.254		
NMS printer	20	SCEL-IMP-REDDIG-II	impresora	10.100.40.20	255.255.255.0	10.100.40.254		
Skywan	31	SCEL-SKW-A	Skywan-A	10.100.40.31	255.255.255.0	10.100.40.254		
	32	SCEL-SKW-B	Skywan-B	10.100.40.32	255.255.255.0	10.100.40.254		
IBUC	41	SCEL-IBUC-A	IBUC-A	10.100.40.41	255.255.255.0	10.100.40.254		
	42	SCEL-IBUC-B	IBUC-B	10.100.40.42	255.255.255.0	10.100.40.254		
RX 1+1	43	SCEL-RX-1+1	RX 1+1	10.100.40.43	255.255.255.0	10.100.40.254		
Netgear switch	51	SCEL-SWI-A	Switch-A	10.100.40.51	255.255.255.0	10.100.40.254		
	52	SCEL-SWI-B	Switch-B	10.100.40.52	255.255.255.0	10.100.40.254		
netgear pro safe	60	SCEL-VPN	VPN	10.100.40.60	255.255.255.0	10.100.40.254		
RSS	71	SCEL-RSS	RSS	10.100.40.71	255.255.255.0	10.100.40.254		
GPS	80	SCEL-GPS	GPS	10.100.40.80	255.255.255.0	10.100.40.254		
MPLS access device	90		GBB-ACCESS	10.100.40.90	255.255.255.0	10.100.40.254		
Cisco VSAT	101	SCEL-CISCO-VSAT-1-A	CISCO-VSAT-1-A	10.100.40.101	255.255.255.0	10.100.40.254	10.100.40.254	
	102	SCEL-CISCO-VSAT-1-B	CISCO-VSAT-1-B	10.100.40.102	255.255.255.0	10.100.40.254	10.100.40.254	
	103	SCEL-CISCO-VSAT-2-A	CISCO-VSAT-2-A	10.100.40.103	255.255.255.0	10.100.40.254	10.100.40.253	
	104	SCEL-CISCO-VSAT-2-B	CISCO-VSAT-2-B	10.100.40.104	255.255.255.0	10.100.40.254	10.100.40.253	
cisco GBB	121	SCEL-CISCO-GBB	CISCO-GBB	10.100.40.121	255.255.255.0	10.100.40.254		
IP to serial	130	SCEL-Serial	Serial	10.100.40.130	255.255.255.0	10.100.40.254		

<b>CHILE - SANTIAGO</b>						
SLL	7					
	8					
<b>SERIAL</b>	<b>Router</b>	<b>Port</b>	<b>BSTUN num</b>	<b>Primary /secondary</b>	<b>Cable number</b>	<b>Plug</b>
AFTN SAEZ	R1	0/0/0	7	S	WB-01	J23
AFTN SPIM	R1	0/0/1	1	P	WB-02	J24

Dialing Plan Dial Plan Table		Dial Plan 2
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
3001	30201	>
30XX	30200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
90XX	++2++	>
92XX	++2++	>
5501	55201	>
55XX	55200	>
60XX	60200	>
9401	94201	>
94XX	94240	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
47XX	--+++++	-- ---->
XXXX	++2++	>

Dialing Plan Dial Plan Table		Dial Plan 1
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
50XX	++1++	>
XXXX	++1++	>
20XX	20140	>
4601	20201	---->
25XX	25100	>
2553	25153	>
9905	25943	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
9902	40904	>
45XX	45100	>
9903	45902	>
9904	50905	>
5551	55142	>
60XX	60100	>
6551	65102	>
6552	65103	>
6550	65142	>
8060	80141	>
8051	80143	>
8053	80144	>
90XX	90100	>
9051	90102	>
9053	90141	>
9060	90142	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
94XX	94100	>
9451	94102	>
9452	94141	>

COLOMBIA- BOGOTA									
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	TS	Type	Cable number	Plug
Hotline Ecuador	9901	4	9901	SKED-CISCO-VSAT	0/2/0.1	1	E1 - E&M	WE-01	J1
Hotline Peru	9902	4		SKED-CISCO-VSAT	0/2/0.2	2	E1 - E&M	WE-01	J1
Hotline Venezuela	9903	4	9901	SKED-CISCO-VSAT	0/2/0.3	3	E1 - E&M	WE-01	J1
Hotline Manaus	9904	4	9904	SKED-CISCO-VSAT	0/2/0.4	4	E1 - E&M	WE-01	J1
Hotline Manaus	9905	4	9903	SKED-CISCO-VSAT	0/2/0.5	5	E1 - E&M	WE-01	J1
Hotline Manaus	9906	4	9905	SKED-CISCO-VSAT	0/2/0.6	6	E1 - E&M	WE-01	J1
Hotline Venezuela	9907	4	9903	SKED-CISCO-VSAT	0/2/0.7	7	E1 - E&M	WE-01	J1
ATS switched		4	145..	SKED-CISCO-VSAT	0/2/0.8	8	E1 - E&M	WE-01	J1
ATS switched		4	145..	SKED-CISCO-VSAT		9	E1 - E&M	WE-01	J1
ATS switched		4	145..	SKED-CISCO-VSAT		10	E1 - E&M	WE-01	J1
Admin		4	245..	SKED-CISCO-VSAT	0/2/0.9	11	E1 - E&M	WE-01	J1
Admin		4	245..	SKED-CISCO-VSAT		12	E1 - E&M	WE-01	J1
MEVA	3950	0	45199	SKED-CISCO-VSAT	0/2/0.10	13	E1 - E&M	WE-01	J1
MEVA		all	22..	SKED-CISCO-VSAT	0/2/0.11	14	E1 - E&M	WE-01	J1
MEVA		all	39..	SKED-CISCO-VSAT	0/2/0.12	15	E1 - E&M	WE-01	J1
MEVA		all	22..	SKED-CISCO-VSAT	0/2/0.13	17	E1 - E&M	WE-01	J1
MEVA		all	39..	SKED-CISCO-VSAT	0/2/0.14	18	E1 - E&M	WE-01	J1
MEVA	3950	0	45199	SKED-CISCO-VSAT	0/2/1.1	1	E1 - E&M	WE-02	J2
MEVA		all	22..	SKED-CISCO-VSAT	0/2/1.2	2	E1 - E&M	WE-02	J2
MEVA		all	39..	SKED-CISCO-VSAT	0/2/1.3	3	E1 - E&M	WE-02	J2
MEVA		all	22..	SKED-CISCO-VSAT	0/2/1.4	4	E1 - E&M	WE-02	J2
MEVA		all	39..	SKED-CISCO-VSAT	0/2/1.5	5	E1 - E&M	WE-02	J2

Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP		
NMS server	10	SKED-REDDIG-II	NMS server - local	10.100.45.10	255.255.255.0	10.100.45.254			
NMS printer	20	SKED-IMP-REDDIG-II	impresora	10.100.45.20	255.255.255.0	10.100.45.254			
Skywan	31	SKED-SKW-A	Skywan-A	10.100.45.31	255.255.255.0	10.100.45.254			
	32	SKED-SKW-B	Skywan-B	10.100.45.32	255.255.255.0	10.100.45.254			
IBUC	41	SKED-IBUC-A	IBUC-A	10.100.45.41	255.255.255.0	10.100.45.254			
	42	SKED-IBUC-B	IBUC-B	10.100.45.42	255.255.255.0	10.100.45.254			
RX 1+1	43	SKED-RX-1+1	RX 1+1	10.100.45.43	255.255.255.0	10.100.45.254			
Netgear switch	51	SKED-SWI-A	Switch-A	10.100.45.51	255.255.255.0	10.100.45.254			
	52	SKED-SWI-B	Switch-B	10.100.45.52	255.255.255.0	10.100.45.254			
netgear pro safe	60	SKED-VPN	VPN	10.100.45.60	255.255.255.0	10.100.45.254			
RSS	71	SKED-RSS	RSS	10.100.45.71	255.255.255.0	10.100.45.254			
GPS	80	SKED-GPS	GPS	10.100.45.80	255.255.255.0	10.100.45.254			
MPLS access device	90		GBB-ACCESS	10.100.45.90	255.255.255.0	10.100.45.254			
Cisco VSAT	101	SKED-CISCO-VSAT-A	CISCO-VSAT-A	10.100.45.101	255.255.255.0	10.100.45.254	10.100.45.254		
	102	SKED-CISCO-VSAT-B	CISCO-VSAT-B	10.100.45.102	255.255.255.0	10.100.45.254	10.100.45.254		
cisco GBB	121	SKED-CISCO-GBB	CISCO-GBB	10.100.45.121	255.255.255.0	10.100.45.254			
SLL	13		<b>SERIAL</b>	<b>Router</b>	<b>Port</b>	<b>BSTUN num</b>	<b>Primary /secondary</b>	<b>Cable number</b>	<b>Plug</b>
	14		AFTN SVM1	R1	0/0/0	5	P	WB-01	J23
			AFTN SEGU	R1	0/0/1	2	P	WB-02	J24
			AFTN SP1M ((KBMN 9600))	R1	0/0/2	3	P	WB-03	J25
			AFTN SBMN 1	R1	0/0/3	1	S	WB-04	J26
			AFTN SBMN 2 (KATL)	R1	0/1/0	4	S	WB-05	J27

Dialing Plan Dial Plan Table		Dial Plan   2
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
3001	30201	>
30XX	30200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
90XX	++2++	>
92XX	++2++	>
5501	55201	>
55XX	55200	>
60XX	60200	>
9401	94201	>
94XX	94240	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
21XX	++++	>
XXXX	++2++	>

Dialing Plan Dial Plan Table		Dial Plan   1
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
9901	50904	>
9902	60100	AA03
9903	80902	>
9904	36945	>
9905	36944	>
9906	36946	>
9907	80904	>
20XX	20140	>
2553	25153	>
25XX	25100	>
3612	36112	>
36XX	36140	>
38XX	38140	>
30XX	30140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
5551	55142	>
60XX	60100	>
9451	94102	>
9452	94141	>
94XX	94100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
22XX	++++	>
13XX	30--++	>
39XX	++++	>
21XX	++++	>
XXXX	++1++	>



SERIAL	Router	Port	BSTUN num	Primary /secondar	Cable number	Plug
AFTN-SKED	VSAT-1	0/0/0	2	S	WB-01	J23
AFTN-SVMI	VSAT-1	0/0/1	3	P	WB-02	J24

Dialing Plan Dial Plan Table Dial Plan 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
3001	30201	>
30XX	30200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
90XX	++2++	>
92XX	++2++	>
5501	55201	>
55XX	55200	>
60XX	60200	>
9401	94201	>
94XX	94240	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
21XX	++++	>
XXXX	++2++	>

Dialing Plan Dial Plan Table Dial Plan 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
21XX	++++	>
2553	25153	>
25XX	25100	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
94XX	94100	>
9901	45901	>
9902	60100	AA04
XXXX	++1++	>

FRENCH GUIANA - CAYENNE								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	9254	SOCA-VSAT	0/0/0	FXS	WD-01	J1
ATS Switched		0	9255	SOCA-VSAT	0/0/1	FXS	WD-02	J2
Admin		0	9201	SOCA-VSAT	0/1/0	FXS	WD-05	J5
Admin		0	9202	SOCA-VSAT	0/1/1	FXS	WD-06	J6
Hotline Trinidad	9903	0	9251	SOCA-VSAT	0/0/3	FXS	WD-04	J4
Hotline Manaus	9901	0	9253	SOCA-VSAT	0/0/2	FXS	WD-03	J3
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	09299	SOCA-CISCO-GBB	0/1/1	FXS		
Admin		0	09200	SOCA-CISCO-GBB	0/1/0	FXS		
Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	SOCA-REDDIG-II	NMS server - local	10.100.92.10	255.255.255.0	10.100.92.254		
NMS printer	20	SOCA-IMP-REDDIG-II	impresora	10.100.92.20	255.255.255.0	10.100.92.254		
Skywan	31	SOCA-SKW-A	Skywan-A	10.100.92.31	255.255.255.0	10.100.92.254		
	32	SOCA-SKW-B	Skywan-B	10.100.92.32	255.255.255.0	10.100.92.254		
IBUC	41	SOCA-IBUC-A	IBUC-A	10.100.92.41	255.255.255.0	10.100.92.254		
	42	SOCA-IBUC-B	IBUC-B	10.100.92.42	255.255.255.0	10.100.92.254		
RX 1+1	43	SOCA-RX-1+1	RX 1+1	10.100.92.43	255.255.255.0	10.100.92.254		
Netgear switch	51	SOCA-SWI-A	Switch-A	10.100.92.51	255.255.255.0	10.100.92.254		
	52	SOCA-SWI-B	Switch-B	10.100.92.52	255.255.255.0	10.100.92.254		
netgear pro safe	60	SOCA-VPN	VPN	10.100.92.60	255.255.255.0	10.100.92.254		
RSS	71	SOCA-RSS	RSS	10.100.92.71	255.255.255.0	10.100.92.254		
GPS	80	SOCA-GPS	GPS	10.100.92.80	255.255.255.0	10.100.92.254		
MPLS access device	90		GBB-ACCESS	10.100.92.90	255.255.255.0	10.100.92.254		
Cisco VSAT	101	SOCA-CISCO-VSAT-A	CISCO-VSAT-A	10.100.92.101	255.255.255.0	10.100.92.254	10.100.92.254	
	102	SOCA-CISCO-VSAT-B	CISCO-VSAT-B	10.100.92.102	255.255.255.0	10.100.92.254	10.100.92.254	
cisco GBB	121	SOCA-CISCO-GBB	CISCO-GBB	10.100.92.121	255.255.255.0	10.100.92.254	10.100.92.254	

FRENCH GUIANA - CAYENNE						
SLL	23					
	24					
SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug
AFTN-SVMI	VSAT-1	0/2/0	2	P	WB-01	J23
AFTN-SBMN	VSAT-1	0/2/1	3	S	WB-02	J24

Dialing Plan Dial Plan Table Dial Plan 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
3001	30201	>
30XX	30200	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
5501	55201	>
55XX	55200	>
60XX	60200	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
90XX	++2++	>
9101	91201	>
91XX	91240	>
92XX	++2++	>
9401	94201	>
94XX	94240	>
XXXX	++2++	>

Dialing Plan Dial Plan Table Dial Plan 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
2553	25153	>
25XX	25100	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
915X	91943	>
9251	92903	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
94XX	94100	>
9903	91943	++++
XXXX	++1++	>

GUYANA - GEORGETOWN								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	9053	SYGC-VSAT-1	0/2/0	FXS	WD-03	J3
ATS Switched		0	9060	SYGC-VSAT-1	0/2/1	FXS	WD-04	J4
Admin		0	9001	SYGC-VSAT-1	0/1/0	FXS	WD-01	J1
ATS Switched		0	9051	SYGC-VSAT-1	0/2/2	FXS	WD-05	J5
Hotline Trinidad	9902	4	909902	SYGC-VSAT-1	0/2/3	FXS	WD-06	J6
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	09099	SYGC-CISCO-GBB	0/1/0	FXS		
Admin		0	09000	SYGC-CISCO-GBB	0/1/1	FXS		
Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	SYGC-REDDIG-II	NMS server - local	10.100.90.10	255.255.255.0	10.100.90.254		
NMS printer	20	SYGC-IMP-REDDIG-II	impresora	10.100.90.20	255.255.255.0	10.100.90.254		
Skywan	31	SYGC-SKW-A	Skywan-A	10.100.90.31	255.255.255.0	10.100.90.254		
	32	SYGC-SKW-B	Skywan-B	10.100.90.32	255.255.255.0	10.100.90.254		
IBUC	41	SYGC-IBUC-A	IBUC-A	10.100.90.41	255.255.255.0	10.100.90.254		
	42	SYGC-IBUC-B	IBUC-B	10.100.90.42	255.255.255.0	10.100.90.254		
RX 1+1	43	SYGC-RX-1+1	RX 1+1	10.100.90.43	255.255.255.0	10.100.90.254		
Netgear switch	51	SYGC-SWI-A	Switch-A	10.100.90.51	255.255.255.0	10.100.90.254		
	52	SYGC-SWI-B	Switch-B	10.100.90.52	255.255.255.0	10.100.90.254		
netgear pro safe	60	SYGC-VPN	VPN	10.100.90.60	255.255.255.0	10.100.90.254		
RSS	71	SYGC-RSS	RSS	10.100.90.71	255.255.255.0	10.100.90.254		
GPS	80	SYGC-GPS	GPS	10.100.90.80	255.255.255.0	10.100.90.254		
MPLS access devi	90		GBB-ACCESS	10.100.90.90	255.255.255.0	10.100.90.254		
Cisco VSAT	101	SYGC-CISCO-VSAT-A	CISCO-VSAT-A	10.100.90.101	255.255.255.0	10.100.90.254	10.100.90.254	
	102	SYGC-CISCO-VSAT-B	CISCO-VSAT-B	10.100.90.102	255.255.255.0	10.100.90.254	10.100.90.254	
cisco GBB	121	SYGC-CISCO-GBB	CISCO-GBB	10.100.90.121	255.255.255.0	10.100.90.254	10.100.90.254	

GUYANA - GEORGETOWN						
SLL	25					
	26					
SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug
AFTN-SBMN	VSAT-1	0/0/0	6	S	WB-01	J23
AFTN-SVMI	VSAT-1	0/0/1	4	P	WB-02	J24
AFTN-TTZP	VSAT-1	0/0/2	1	S	WB-03	J25

Dialing Plan Dial Plan Table			Dial Plan
			2
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern	
2001	20201	>	
20XX	20241	>	
2501	25201	>	
25XX	2524036	>	
3001	30201	>	
30XX	30200	>	
36XX	++2++	>	
3801	38241	3801	
38XX	38200	>	
40XX	40200	>	
45XX	45200	>	
50XX	50200	>	
5501	55201	>	
55XX	55200	>	
60XX	60200	>	
65XX	++2++	>	
8001	80201	>	
80XX	80242	>	
90XX	++2++	>	
9101	91201	>	
91XX	91240	>	
92XX	++2++	>	
9401	94201	>	
94XX	94240	>	
XXXX	++2++	>	

Dialing Plan Dial Plan Table			Dial Plan
			1
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern	
20XX	20140	>	
2553	25153	>	
25XX	25100	>	
30XX	30140	>	
3612	36112	>	
36XX	36140	>	
38XX	38140	>	
40XX	40140	>	
45XX	45100	>	
50XX	++1++	>	
5551	55142	>	
60XX	60100	>	
6550	65142	>	
6551	65102	>	
6552	65103	>	
8051	80143	>	
8053	80144	>	
8060	80141	>	
9051	90102	>	
9053	90141	>	
9059	90903	>	
9060	90142	>	
90XX	90100	>	
915X	91942	>	
9251	92103	>	
9253	92104	>	
9254	92141	>	
9255	92155	>	
9451	94102	>	
9452	94141	>	
94XX	94100	>	
9902	91942	++++	
XXXX	++1++	>	

PARAGUAY - ASUNCION								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Hotline Curitiba	9902	3	5592	SGAS-VSAT-1	0/1/0	FXS	WD-01	J1
ATS-Switched		3	5551	SGAS-VSAT-1	0/1/1	FXS	WD-02	J2
Admin		3	5501	SGAS-VSAT-1	0/1/2	FXS	WD-03	J3
Hotline Curitiba	9901	3	5591	SGAS-VSAT-1	0/1/3	FXS	WD-04	J4
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS-Switched		3	05599	SGAS-CISCO-GBB	0/1/1	FXS		
Admin		3	05500	SGAS-CISCO-GBB	0/1/0	FXS		
Device	Device	NMS device name	LAN IP address	mask	gateway	VRRP		
NMS server	10	SGAS-REDDIG-II	NMS server - local	10.100.55.10	255.255.255.0	10.100.55.254		
NMS printer	20	SGAS-IMP-REDDIG-II	impresora	10.100.55.20	255.255.255.0	10.100.55.254		
Skywan	31	SGAS-SKW-A	Skywan-A	10.100.55.31	255.255.255.0	10.100.55.254		
	32	SGAS-SKW-B	Skywan-B	10.100.55.32	255.255.255.0	10.100.55.254		
IBUC	41	SGAS-IBUC-A	IBUC-A	10.100.55.41	255.255.255.0	10.100.55.254		
	42	SGAS-IBUC-B	IBUC-B	10.100.55.42	255.255.255.0	10.100.55.254		
RX 1+1	43	SGAS-RX-1+1	RX 1+1	10.100.55.43	255.255.255.0	10.100.55.254		
Netgear switch	51	SGAS-SWI-A	Switch-A	10.100.55.51	255.255.255.0	10.100.55.254		
	52	SGAS-SWI-B	Switch-B	10.100.55.52	255.255.255.0	10.100.55.254		
netgear pro safe	60	SGAS-VPN	VPN	10.100.55.60	255.255.255.0	10.100.55.254		
RSS	71	SGAS-RSS	RSS	10.100.55.71	255.255.255.0	10.100.55.254		
GPS	80	SGAS-GPS	GPS	10.100.55.80	255.255.255.0	10.100.55.254		
MPLS access device	90		GBB-ACCESS	10.100.55.90	255.255.255.0	10.100.55.254		
Cisco VSAT	101	SGAS-CISCO-VSAT-A	CISCO-VSAT-A	10.100.55.101	255.255.255.0	10.100.55.254	10.100.55.254	
	102	SGAS-CISCO-VSAT-B	CISCO-VSAT-B	10.100.55.102	255.255.255.0	10.100.55.254	10.100.55.254	
cisco GBB	121	SGAS-CISCO-GBB	CISCO-GBB	10.100.55.121	255.255.255.0	10.100.55.254	10.100.55.254	
Cental telefonica	150							
SLL	,							
	18							
SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug		
AFTN SBCT	VSAT-1	0/0/0	2	S	WB-01	J23		
METEO SAEZ	VSAT-1	0/0/1	4	S	WB-02	J24		

PERU - LIMA								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:1	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:2	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:3	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:4	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:5	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:6	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:7	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:8	E1 - E&M	WE-01	J1
ATS-Switched		4	60..	LIMA-CISCO-VSAT	0/1/0:9	E1 - E&M	WE-01	J1
Admin		4	60..	LIMA-CISCO-VSAT	0/1/0:10	E1 - E&M	WE-01	J1
Admin		4	60..	LIMA-CISCO-VSAT	0/1/0:11	E1 - E&M	WE-01	J1
Admin		4	60..	LIMA-CISCO-VSAT	0/1/0:12	E1 - E&M	WE-01	J1
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS-Switched		3	06099	LIMA-CISCO-GBB	0/3/1	FX0		
Admin		3	06000	LIMA-CISCO-GBB	0/3/0	FX0		
Device	Device	NMS device name	LAN IP address	mask	gateway	VRRP		
NMS server	10	SPIM-REDDIG-II	NMS server - local	10.100.60.10	255.255.255.0	10.100.60.254		
NMS printer	20	SPIM-IMP-REDDIG-II	impresora	10.100.60.20	255.255.255.0	10.100.60.254		
Skywan	31	SPIM-SKW-A	Skywan-A	10.100.60.31	255.255.255.0	10.100.60.254		
	32	SPIM-SKW-B	Skywan-B	10.100.60.32	255.255.255.0	10.100.60.254		
IBUC	41	SPIM-IBUC-A	IBUC-A	10.100.60.41	255.255.255.0	10.100.60.254		
	42	SPIM-IBUC-B	IBUC-B	10.100.60.42	255.255.255.0	10.100.60.254		
RX 1+1	43	SPIM-RX-1+1	RX 1+1	10.100.60.43	255.255.255.0	10.100.60.254		
Netgear switch	51	SPIM-SWI-A	Switch-A	10.100.60.51	255.255.255.0	10.100.60.254		
	52	SPIM-SWI-B	Switch-B	10.100.60.52	255.255.255.0	10.100.60.254		
netgear pro safe	60	SPIM-VPN	VPN	10.100.60.60	255.255.255.0	10.100.60.254		
RSS	71	SPIM-RSS-1	RSS-1	10.100.60.71	255.255.255.0	10.100.60.254		
	72	SPIM-RSS-2	RSS-2	10.100.60.71	255.255.255.0	10.100.60.254		
GPS	80	SPIM-GPS	GPS	10.100.60.80	255.255.255.0	10.100.60.254		
MPLS access device	90		GBB-ACCESS	10.100.60.90	255.255.255.0	10.100.60.254		
Cisco VSAT	101	SPIM-CISCO-VSAT-A	CISCO-VSAT-A	10.100.60.101	255.255.255.0	10.100.60.254	10.100.60.254	
	102	SPIM-CISCO-VSAT-B	CISCO-VSAT-B	10.100.60.102	255.255.255.0	10.100.60.254	10.100.60.254	
cisco GBB	121	SPIM-CISCO-GBB	CISCO-GBB	10.100.60.121	255.255.255.0	10.100.60.254	10.100.60.254	
IP to serial	130	SPIM-Serial	Serial	10.100.60.130	255.255.255.0	10.100.60.254		
PERU - LIMA								
SLL	19							
	20							

SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug
AFTN-SBMN	VSAT-1	0/0/0	7	S	WB-10	J23
AFTN-SAEZ	VSAT-1	0/0/1	9	S	WB-11	J24
AFTN-SCel	VSAT-1	0/0/2	1	S	WB-12	J25
AFTN-KBMN (SKED 9600bps)	VSAT-1	0/0/3	3	S	WB-13	J26
AFTN-SLLP	VSAT-1	0/0/4	2	S	WB-14	J27
METEO SAEZ	VSAT-1	0/0/5	5	S	WB-15	J28
AFTN SVMl	VSAT-1	0/0/6	6	P	WB-16	J29

Dialing Plan Dial Plan Table Dial Plan | 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
3001	30201	>
30XX	30200	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
40XX	40200	>
45XX	45200	>
47XX	-- +++++	-- - - - ->
50XX	50200	>
5501	55201	>
55XX	55200	>
60XX	60200	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
90XX	++2++	>
92XX	++2++	>
9401	94201	>
94XX	94240	>
XXXX	++2++	>

Dialing Plan Dial Plan Table Dial Plan | 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
2553	25153	>
25XX	25100	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
4601	20201	- - - ->
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
94XX	94100	>
9902	40904	>
9903	45902	>
9904	50905	>
9905	25943	>
XXXX	++1++	>

SURINAME -PARAMARIBO								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS-Switched		0	9452	MPPM-CISCO-VSA	0/1/3	FXS	WD-04	J4
Admin		0	9401	MPPM-CISCO-VSA	0/1/0	FXS	WD-01	J1
ATS-Switched		0	9451	MPPM-CISCO-VSA	0/1/1	FXS	WD-02	J2
Hotline Trinidad	9901	4	9901 (94903)	MPPM-CISCO-VSA	0/1/2	FXS	WD-03	J3
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	09499	SMPM-CISCO-GBB	0/1/1	FXS		
Admin		0	09400	SMPM-CISCO-GBB	0/1/0	FXS		
Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	SMPM-REDDIG-II	NMS server - local	10.100.94.10	255.255.255.0	10.100.94.254		
NMS printer	20	SMPM-IMP-REDDIG-II	impresora	10.100.94.20	255.255.255.0	10.100.94.254		
Skywan	31	SMPM-SKW-A	Skywan-A	10.100.94.31	255.255.255.0	10.100.94.254		
	32	SMPM-SKW-B	Skywan-B	10.100.94.32	255.255.255.0	10.100.94.254		
IBUC	41	SMPM-IBUC-A	IBUC-A	10.100.94.41	255.255.255.0	10.100.94.254		
	42	SMPM-IBUC-B	IBUC-B	10.100.94.42	255.255.255.0	10.100.94.254		
RX 1+1	43	SMPM-RX-1+1	RX 1+1	10.100.94.43	255.255.255.0	10.100.94.254		
Netgear switch	51	SMPM-SWI-A	Switch-A	10.100.94.51	255.255.255.0	10.100.94.254		
	52	SMPM-SWI-B	Switch-B	10.100.94.52	255.255.255.0	10.100.94.254		
netgear pro safe	60	SMPM-VPN	VPN	10.100.94.60	255.255.255.0	10.100.94.254		
RSS	71	SMPM-RSS	RSS	10.100.94.71	255.255.255.0	10.100.94.254		
GPS	80	SMPM-GPS	GPS	10.100.94.80	255.255.255.0	10.100.94.254		
MPLS access device	90		GBB-ACCESS	10.100.94.90	255.255.255.0	10.100.94.254		
Cisco VSAT	101	SMPM-CISCO-VSAT-A	CISCO-VSAT-A	10.100.94.101	255.255.255.0	10.100.94.254	10.100.94.254	
	102	SMPM-CISCO-VSAT-B	CISCO-VSAT-B	10.100.94.102	255.255.255.0	10.100.94.254	10.100.94.254	
cisco GBB	121	SMPM-CISCO-GBB	CISCO-GBB	10.100.94.121	255.255.255.0	10.100.94.254	10.100.94.254	
SLL	27	SURINAME -PARAMARIBO						
	28							
SERIAL	Router	Port	BSTUN num	primary /secondar	Cable number	Plug		
AFTN-SVMI	VSAT-1	0/0/0	T	P	WB-01	J23		
AFTN-SBMN	VSAT-1	0/0/1	2	S	WB-02	J24		

Dialing Plan Dial Plan Table		Dial Plan   2
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
3001	30201	>
30XX	30200	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
5501	55201	>
55XX	55200	>
60XX	60200	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
90XX	++2++	>
9101	91201	>
91XX	91240	>
92XX	++2++	>
9401	94201	>
94XX	94201	>
XXXX	++2++	>

Dialing Plan Dial Plan Table		Dial Plan   1
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
2553	25153	>
25XX	25100	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
915X	91941	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
9459	94903	>
94XX	94100	>
9901	91941	++++
XXXX	++1++	>

TRINIDAD - PIARCO PORT OF SPAIN								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Hotline Cayenne	9903	0	9153	TTZP-CISCO-VSAT	0/0/2	FXS	WD-03	J3
Hotline Guyana	9902	0	9152	TTZP-CISCO-VSAT	0/0/1	FXS	WD-02	J2
Hotline Suriname	9901	0	9151	TTZP-CISCO-VSAT	0/0/0	FXS	WD-01	J1
Admin		0	9101	TTZP-CISCO-VSAT	0/1/0	FXS	WD-05	J5
Admin		0	9140	TTZP-CISCO-VSAT	0/1/1	FXS	WD-06	J6
Hotline Venezuela	9904	0	9154	TTZP-CISCO-VSAT	0/0/3	FXS	WD-04	J4
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	09199	SMPM-CISCO-GBB	0/1/1	FXS		
Admin		0	09100	SMPM-CISCO-GBB	0/1/0	FXS		
Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	TTZP-REDDIG-II	NMS server - local	10.100.91.10	255.255.255.0	10.100.91.254		
NMS printer	20	TTZP-IMP-REDDIG-II	impresora	10.100.91.20	255.255.255.0	10.100.91.254		
Skywan	31	TTZP-SKW-A	Skywan-A	10.100.91.31	255.255.255.0	10.100.91.254		
	32	TTZP-SKW-B	Skywan-B	10.100.91.32	255.255.255.0	10.100.91.254		
IBUC	41	TTZP-IBUC-A	IBUC-A	10.100.91.41	255.255.255.0	10.100.91.254		
	42	TTZP-IBUC-B	IBUC-B	10.100.91.42	255.255.255.0	10.100.91.254		
RX 1+1	43	TTZP-RX-1+1	RX 1+1	10.100.91.43	255.255.255.0	10.100.91.254		
Netgear switch	51	TTZP-SWI-A	Switch-A	10.100.91.51	255.255.255.0	10.100.91.254		
	52	TTZP-SWI-B	Switch-B	10.100.91.52	255.255.255.0	10.100.91.254		
netgear pro safe	60	TTZP-VPN	VPN	10.100.91.60	255.255.255.0	10.100.91.254		
RSS	71	TTZP-RSS	RSS	10.100.91.71	255.255.255.0	10.100.91.254		
GPS	80	TTZP-GPS	GPS	10.100.91.80	255.255.255.0	10.100.91.254		
MPLS access device	90		GBB-ACCESS	10.100.91.90	255.255.255.0	10.100.91.254		
Cisco VSAT	101	TTZP-CISCO-VSAT-A	CISCO-VSAT-A	10.100.91.101	255.255.255.0	10.100.91.254	10.100.91.254	
	102	TTZP-CISCO-VSAT-B	CISCO-VSAT-B	10.100.91.102	255.255.255.0	10.100.91.254	10.100.91.254	
cisco GBB	121	TTZP-CISCO-GBB	CISCO-GBB	10.100.91.121	255.255.255.0	10.100.91.254	10.100.91.254	

TRINIDAD - PIARCO PORT OF SPAIN						
SLL	29					
	30					
SERIAL	Router	Port	BSTUN num	Primary /secondary	Cable number	Plug
AFTN SVM1	R1	0/2/0	8	P	WB-01	J23
AFTN SYGC	R1	0/2/1	1	P	WB-02	J24

Dialing Plan Dial Plan Table Dial Plan 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
3001	30201	>
30XX	30200	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
40XX	40200	>
45XX	45200	>
60XX	60200	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
90XX	++2++	>
9101	91201	>
91XX	91240	>
92XX	++2++	>
9401	94201	>
94XX	94240	>
XXXX	++2++	>

Dialing Plan Dial Plan Table Dial Plan 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
3612	36112	>
36XX	36140	>
60XX	60100	>
8051	80143	>
8053	80144	>
8059	80942	>
8060	80141	>
9051	90102	>
9053	90141	>
9059	90903	>
9060	90142	>
90XX	90100	>
9151	91941	>
9152	91942	>
9153	91943	>
9154	91904	>
9251	92903	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
9459	94903	>
94XX	94100	>
9901	94903	++++>
9902	90903	++++>
9903	92903	++++>
9904	80942	++++>
XXXX	++1++	>

URUGUAY - MONTEVIDEO								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
Admin		0	6541	SUMU-CISCO-VSAT	1/0/4	FXS	WD-01 sur port 5	J1
ATS switched		0	6550	SUMU-CISCO-VSAT	1/0/0	FXS	WD-30 sur port 1	J3
Hotline Argentina	9902	310004	6592	SUMU-CISCO-VSAT	1/0/11	FXO	WD-34 sur port 12	J7
Hotline Argentina	9903	310002	6593	SUMU-CISCO-VSAT	1/0/12	FXO	WD-35 sur port 13	J8
Hotline Argentina	9904	310004	6594	SUMU-CISCO-VSAT	1/0/13	FXO	WD-36 sur port 14	J9
Hotline Argentina	9905	310002	6595	SUMU-CISCO-VSAT	1/0/14	FXO	WD-37 sur port 15	J10
Admin		0	6501	SUMU-CISCO-VSAT	1/0/5	FXS	WD-02 sur port 6	J2
ATS switched		0	6551	SUMU-CISCO-VSAT	1/0/1	FXS	WD-31 sur port 2	J4
ATS switched		0	6552	SUMU-CISCO-VSAT	1/0/2	FXS	WD-32 sur port 3	J5
Hotline Curitiba	9901	0	6591	SUMU-CISCO-VSAT	1/0/3	FXS	WD-33 sur port 4	J6
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	06599	SUMU-CISCO-GBB	0/1/1	FXS		
Admin		0	06500	SUMU-CISCO-GBB	0/1/0	FXS		
Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	SUMU-REDDIG-II	NMS server - local	10.100.65.10	255.255.255.0	10.100.65.254		
NMS printer	20	SUMU-IMP-REDDIG-II	impresora	10.100.65.20	255.255.255.0	10.100.65.254		
Skywan	31	SUMU-SKW-A	Skywan-A	10.100.65.31	255.255.255.0	10.100.65.254		
	32	SUMU-SKW-B	Skywan-B	10.100.65.32	255.255.255.0	10.100.65.254		
IBUC	41	SUMU-IBUC-A	IBUC-A	10.100.65.41	255.255.255.0	10.100.65.254		
	42	SUMU-IBUC-B	IBUC-B	10.100.65.42	255.255.255.0	10.100.65.254		
RX 1+1	43	SUMU-RX-1+1	RX 1+1	10.100.65.43	255.255.255.0	10.100.65.254		
Netgear switch	51	SUMU-SWI-A	Switch-A	10.100.65.51	255.255.255.0	10.100.65.254		
	52	SUMU-SWI-B	Switch-B	10.100.65.52	255.255.255.0	10.100.65.254		
netgear pro safe	60	SUMU-VPN	VPN	10.100.65.60	255.255.255.0	10.100.65.254		
RSS	71	SUMU-RSS	RSS	10.100.65.71	255.255.255.0	10.100.65.254		
GPS	80	SUMU-GPS	GPS	10.100.65.80	255.255.255.0	10.100.65.254		
MPLS access device	90		GBB-ACCESS	10.100.65.90	255.255.255.0	10.100.65.254		
Cisco VSAT	101	SUMU-CISCO-VSAT-A	CISCO-VSAT-A	10.100.65.101	255.255.255.0	10.100.65.254	10.100.65.254	
	102	SUMU-CISCO-VSAT-B	CISCO-VSAT-B	10.100.65.102	255.255.255.0	10.100.65.254	10.100.65.254	
cisco GBB	121	SUMU-CISCO-GBB	CISCO-GBB	10.100.65.121	255.255.255.0	10.100.65.254	10.100.65.254	
URUGUAY - MONTEVIDEO								
SLL	9							
	10							

SERIAL	Router	Port	BSTUN num	Primary /secondary
AFTN SBCT	R1	0/0/0	3	S
AFTN SAEZ	R1	0/0/1	8	S
RADAR SAEZ TX	R1	0/0/2		
RADAR SAEZ RX	R1	0/0/3		

Dialing Plan Dial Plan Table Dial Plan 2

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
3001	30201	>
30XX	30200	>
36XX	++2++	>
3801	38241	3801
38XX	38200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
5501	55201	>
55XX	55200	>
60XX	60200	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
90XX	++2++	>
92XX	++2++	>
9401	94201	>
94XX	94240	>
XXXX	++2++	>

Dialing Plan Dial Plan Table Dial Plan 1

Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
20XX	20140	>
2553	25153	>
25XX	25100	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
94XX	94100	>
9901	30946	++++>
9902	20947	++++>
9903	20948	++++>
9904	20903	++++>
9905	20904	++++>
XXXX	++1++	>

VENEZUELA - MAIQUETIA								
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	8001	SVMI-CISCO-VSAT-1	0/3/0	FXS	WD-04	J4
ATS Switched		0	8002	SVMI-CISCO-VSAT-1	0/3/1	FXS	WD-05	J5
ATS Switched		0	8003	SVMI-CISCO-VSAT-1	0/3/2	FXS	WD-06	J6
		0	8060	SVMI-CISCO-VSAT-2	0/2/0	E&M V	WC-05	J12
Hotline Trinidad	9904	0	8091	SVMI-CISCO-VSAT-2	0/1/1	E&M V	WC-04	J11
ATS Switched		0	8051	SVMI-CISCO-VSAT-2	0/2/1	E&M V	WC-06	J13
ATS Switched		0	8053	SVMI-CISCO-VSAT-2	0/3/0	E&M V	WC-07	J14
Admin		0	8001	SVMI-CISCO-VSAT-1	0/3/3	FXS	WD-07	J7
Hotline Colombia	9901	0	9903	SVMI-CISCO-VSAT-2	0/0/1	E&M V	WC-02	J9
Hotline Manaus	9902	0	9902	SVMI-CISCO-VSAT-2	0/1/0	E&M V	WC-03	J10
Hotlien Colombia	9903	0	9907	SVMI-CISCO-VSAT-2	0/0/0	E&M V	WC-01	J8
ATS Switched-MEVA		2	18,,	SVMI-CISCO-VSAT-1	0/2/0	FXO	WD-01	J1
ATS Switched-MEVA		2	22,,	SVMI-CISCO-VSAT-1	0/2/1	FXO	WD-02	J2
ATS Switched-MEVA		2	29,,	SVMI-CISCO-VSAT-1	0/2/2	FXO	WD-03	J3
Service	PLAR number (autodial)	#of difgits forwarded	Usual dial number	Router name	Slot/port	Type	Cable number	Plug
ATS Switched		0	08099	SVMI-CISCO-GBB-2	0/2/0	FXS		
Admin		0	08000	SVMI-CISCO-GBB-2	0/2/1	FXS		

Device		Device	NMS device name	LAN IP address	mask	gateway	VRRP	
NMS server	10	SVMI-REDDIG-II	NMS server - local	10.100.80.10	255.255.255.0	10.100.80.254		
NMS printer	20	SVMI-IMP-REDDIG-II	impresora	10.100.80.20	255.255.255.0	10.100.80.254		
Skywan	31	SVMI-SKW-A	Skywan-A	10.100.80.31	255.255.255.0	10.100.80.254		
	32	SVMI-SKW-B	Skywan-B	10.100.80.32	255.255.255.0	10.100.80.254		
IBUC	41	SVMI-IBUC-A	IBUC-A	10.100.80.41	255.255.255.0	10.100.80.254		
	42	SVMI-IBUC-B	IBUC-B	10.100.80.42	255.255.255.0	10.100.80.254		
RX 1+1	43	SVMI-RX-1+1	RX 1+1	10.100.80.43	255.255.255.0	10.100.80.254		
Netgear switch	51	SVMI-SWI-A	Switch-A	10.100.80.51	255.255.255.0	10.100.80.254		
	52	SVMI-SWI-B	Switch-B	10.100.80.52	255.255.255.0	10.100.80.254		
netgear pro safe	60	SVMI-VPN	VPN	10.100.80.60	255.255.255.0	10.100.80.254		
RSS	71	SVMI-RSS-1	RSS-1	10.100.80.71	255.255.255.0	10.100.80.254		
	72	SVMI-RSS-2	RSS-2	10.100.80.72	255.255.255.0	10.100.80.254		
GPS	80	SVMI-GPS	GPS	10.100.80.80	255.255.255.0	10.100.80.254		
MPLS access device	90		GBB-ACCESS	10.100.80.90	255.255.255.0	10.100.80.254		
Cisco VSAT	101	SVMI-CISCO-VSAT-1-A	CISCO-VSAT-1-A	10.100.80.101	255.255.255.0	10.100.80.254	10.100.80.254	
	102	SVMI-CISCO-VSAT-1-B	CISCO-VSAT-1-B	10.100.80.102	255.255.255.0	10.100.80.254	10.100.80.254	
	103	SVMI-CISCO-VSAT-2-A	CISCO-VSAT-2-A	10.100.80.103	255.255.255.0	10.100.80.254	10.100.80.253	
	104	SVMI-CISCO-VSAT-2-B	CISCO-VSAT-2-B	10.100.80.104	255.255.255.0	10.100.80.254	10.100.80.253	
cisco GBB	121	SVMI-CISCO-GBB-1	CISCO-GBB-1	10.100.80.121	255.255.255.0	10.100.80.254	10.100.80.254	
	122	SVMI-CISCO-GBB-2	CISCO-GBB-2	10.100.80.122	255.255.255.0	10.100.80.254		
IP to serial	130	SVMI-Serial	Serial	10.100.80.130	255.255.255.0	10.100.80.254		
<b>VENEZUELA -MAIQUETIA</b>								
SLL	31							
	32							

SERIAL	Router	Port	BSTUN num	Primary /secondary
AFTN SBRF	R1	0/1/0	1	S
AFTN SKED	R1	0/1/1	5	S
AFTN SMPM	R1	0/1/2	7	S
AFTN SOCA	R1	0/1/3	2	S
AFTN TTZP	R1	0/1/4	8	S
AFTN SYGC	R1	0/1/5	4	S
AFTN Curacao	R1	0/1/6		
AFTN SAN JUAN	R1	0/1/7		
AFTN SPIM	R1	0/0/0	6	S
AFTN SEGU	R1	0/0/1	3	S

Dialing Plan Dial Plan Table		Dial Plan   2
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
2001	20201	>
20XX	20241	>
2501	25201	>
25XX	25240	>
3001	30201	>
30XX	30200	>
36XX	++2++	>
<b>3801</b>	<b>38241</b>	<b>3801</b>
38XX	38200	>
40XX	40200	>
45XX	45200	>
50XX	50200	>
5501	55201	>
55XX	55200	>
60XX	60200	>
65XX	++2++	>
8001	80201	>
80XX	80242	>
90XX	++2++	>
9101	91201	>
91XX	91240	>
92XX	++2++	>
9401	94201	>
94XX	94240	>
XXXX	++2++	>

Dialing Plan Dial Plan Table		Dial Plan   1
Dialing Pattern	RemoteExtension Pattern	CalledNumber Pattern
18XX	++++	>
20XX	20140	>
22XX	++++	>
2553	25153	>
25XX	25100	>
29XX	++++	>
30XX	30140	>
3612	36112	>
36XX	36140	>
38XX	38140	>
40XX	40140	>
45XX	45100	>
50XX	++1++	>
5551	55142	>
60XX	60100	>
6550	65142	>
6551	65102	>
6552	65103	>
8051	80143	>
8053	80144	>
8059	80942	>
8060	80141	>
9051	90102	>
9053	90141	>
9060	90142	>
90XX	90100	>
915X	91904	>
9251	92103	>
9253	92104	>
9254	92141	>
9255	92155	>
9451	94102	>
9452	94141	>
94XX	94100	>
9901	45903	++++>
9902	36904	++++>
9903	45907	++++>
9904	91904	++++>
XXXX	++1++	>

COCESNA - Honduras								
Cisco VSAT	101	MHTG-CISCO-VSAT-A	CISCO-VSAT-A	10.100.21.101	255.255.255.0	10.100.21.254	cofelyineo	gdfsuez
	102	MHTG-CISCO-VSAT-B	CISCO-VSAT-B	10.100.21.102	255.255.255.0	10.100.21.254	cofelyineo	gdfsuez
Netgear switch	51	MHTG-SWI-A	Switch-A	10.100.21.51	255.255.255.0	10.100.21.254	cofelyineo	gdfsuez
SLL	33							
Type	Regen number	REDDIG II local number	Forwarded digits (to PBX/user)	Remote usual dial number	Router	Slot/port		
FXS	Rien	12101	Rien		R1	0/0/0		
FXS	Rien	12102	Rien		R1	0/0/1		
FXS	Rien	22101	rIEN	Rien	R1	0/0/2		

**Agenda Item 4: Other business**

4.1 Nil.