

# AIRCRAFT ACCIDENT INVESTIGATION



2015. 6.

AVIATION AND RAILWAY ACCIDENT<sub>1</sub>

INVESTIGATION BOARD

# CONTENTS



1	Synopsis
2	Factual Information
3	Analysis
4	Conclusions
5	Safety Recommendations

# 1. Synopsis



- Operator: Asiana Airlines
- Type: A321-200
- Registration Mark: HL7730
- Manufacturer: Airbus
- Date & Time: 16 April 2013, 17:37 (Local)
- Location: Incheon International Airport

## 2. Factual Information ( History of Flight )



- Asiana Airlines flight 340 took off from Harbin International Airport, China for Incheon International Airport (ICN), ROK
  - ❖ Before descent for ICN
  - ❖ Duty change: CAP PM, FO PF
- After 15,000 ft, CAP said to FO, “manually fly the airplane”
  - ❖ After intercept localizer ILS RWY 16, CAP was informed
    - by the tower that base ceiling was 200 ft
  - ❖ Duty change: CAP PF, FO PM
  - ❖ CAP disconnected A/T at 1,209 ft AGL

## 2. Factual Information ( History of Flight )




- ❖ CAP and FO saw RWY at 200 ft
- ❖ A/C speed was 137.6kt at 100 ft, 131.4kt at 59 ft AGL, and 129kt at 29 ft AGL (flare point)
- ❖ After touchdown, A/C bounced, then touched down again about 491.3 m from RWY 16 threshold
- ❖ At this time, A/C was at 136.9kt at a pitch angle of 10.9° with vertical gravity of 1.7 g
- ❖ A/C completed landing roll and taxied to ramp for itself

## 2. Factual Information ( Damage to Aircraft )



- Exterior Fuselage

- ❖ Rear fuselage damage 100 cm wide and 600 cm long




## 2. Factual Information ( Damage to Aircraft )



- Interior Fuselage

- ❖ Frames damage (major structure of the fuselage)

### Fuselage



## 2. Factual Information ( Damage to Aircraft )



- Repair of the Aircraft Damage
  - ❖ Length: 3 months
  - ❖ Cost of repairs: 3.7 billion won (\$ 3.37 million)

Fuselage





## 2. Factual Information ( Personnel Information )



- CAP

- 7,530 total flight hr, and 722 hr as PIC
- Promoted to CAP on A321 in Mar. 2012

- FO

- 383 total flight hr, and 33 hr and 31 min as A321 FO
- Completed A321 FO training 2 weeks ago

## 2. Factual Information ( Tail Skid Mark )



## 2. Factual Information ( Training )



### ● Bounce Recovery Procedures in FCTM

#### **BOUNCING AT TOUCHDOWN**

In case of a light bounce, maintain the pitch attitude and complete the landing, while keeping thrust at idle.

Do not allow the pitch attitude to increase, particularly following a firm touchdown with a high pitch rate.

In case of a high bounce, maintain the pitch attitude and initiate a go-around.

Do not try to avoid a second touchdown during the go-around. Should it happen, it would be soft enough to prevent damage to the aircraft, if pitch attitude is maintained.

## 2. Factual Information ( Stabilized App. Criteria



- Asiana Airlines Flight Operations Manual (FOM)
  - ❖ Stabilized approach criteria is pilots should maintain max target speed of + 10kt and min target speed of - 5kt until A/C passes above the RWY landing threshold
  - ❖ All approaches should be stabilized by 1,000 ft above field elevation (AFE) regardless of meteorological conditions (IMC/VMC)
  - ❖ If a stabilized approach is not established above or below 1,000 ft AFE, immediate go-around should be done

## 2. Factual Information ( Tail Strike )



- According to A321 FCOM, if pitch attitude during landing is more than  $9.7^\circ$ , with main gear position fully compressed (by the weight of the fuselage), a tail strike will occur

# 3. Analysis



## ● Un stabilized Approach

- ❖ During approach and landing after RWY in sight, CAP failed to control A/C speed (target speed 138kt)
- ❖ Crossing at about 60ft, A/C speed slowed down
- ❖ At 29ft, A/C speed was 129kt (138kt – 9kt)
- ❖ CAP increased thrust and started landing flare
- ❖ After A/C bounced at initial touchdown, CAP increased pitch and decreased thrust, then A/C made a second touchdown

# 3. Analysis



## ● Inadequate Actions of CAP

- ❖ Failed to control A/C speed due to A/T disconnection during approach
- ❖ Failed to make an immediate go-around at 29 ft
- ❖ Failed to maintain pitch and keep thrust at idle after bouncing
- ❖ Increased pitch to  $10.9^\circ$  (more than  $9.7^\circ \rightarrow$  tail strike)

## ● Inadequate Actions of FO

- ❖ Failed to call out speed during landing
- ❖ Failed to call out pitch after bouncing

## 4. Conclusions



### ● Findings

- ❖ During landing, right cross wind at 10kt with no wind shear, and base ceiling 200ft
- ❖ When A/C made an initial touchdown and bounced, thrust was not kept at idle, then when it made a second touchdown with pitch attitude exceeding A321 airplanes' limitation, it sustained a tail strike.



## 4. Conclusions



### ● Causes

- ❖ A/C bounced due to PF's failure to maintain proper approach speed until flare just before touchdown, and due to increased thrust and speed just before touchdown
- ❖ A/C made a second touchdown at the pitch attitude exceeding an A321 airplane's limitation and sustained a tail strike due to PF's failure to keep thrust at idle and proper pitch attitude during the bounce

## 4. Conclusions



### ● Contributing Factors

- ❖ Inadequate training program on recovery from bounce
- ❖ PM's inadequate advice on PF's A/C speed control
- ❖ PF's disconnection of A/T and failure to manually control  
thrust and speed
- ❖ PF's failure to execute a go-around when stabilized approach criteria are not met

# 5. Safety Recommendations



## ● To Asiana Airlines

- ❖ Reemphasize, through your pilot training program, that if a stabilized approach is not established, executing go-around is the safest choice for safe operation so that flight crew can be fully aware of it
- ❖ Train your pilots in a simulator to ensure that they can operate A/C in a stable manner after bouncing on touchdown, and add this training to your ground training program
- ❖ Reinforce, through your training program, flight crew adherence to POM's approach briefing and standard callout procedures on every flight`

# 5. Safety Recommendations



- To the Ministry of Land, Infrastructure and Transport
  - ❖ Review measures to ensure that all pilots of Korean airlines can be given simulator training as part of ground training programs to attain proficiency that enables them to operate A/C in a stable manner after bouncing during landing

Thank you!