



Conducting investigations on similar incidents that occurred in different countries

A complex organization

Arnaud TOUPET
Senior Safety Investigator
Capt. Nurcahyo 'Ray' UTOMO

NTSC Senior Safety Investigator



Investigating on similar incidents


- A practical case : the investigation on several incidents involving propeller severe vibrations during flight
- Organization of investigations according to ICAO Annex 13
- Highlighted Solutions
- Possible ways of improvement




- On 18th September 2013, in Indonesia, ATR 72-212A equipped with Hamilton Sundstrand Propellers 568F-1
 - → Severe vibrations on engine #2 propeller during descent
 - → Engine #2 was shut down after landing
 - → Differentblade anglesobserved onground












Damages :


- One blade was turning freely (blade trunnion pin broken)
- Blade angle actuator forward plate found bent





- Damages :
 - → Two engine fittings found broken









Serious Incident – full investigation


- According to the Attachment C of the ICAO Annex 13, this occurrence was classified as serious incident.
- NTSC conducted full investigation and sent notification to direct involve parties including France BEA as State of Manufacture.
- Significant supports received from the BEA.
- 30 days after the occurrence NTSC issued safety recommendation to the aircraft operator.




- On 4th May 2014, in Trinidad and Tobago, ATR 72-212A equipped with Hamilton Sundstrand Propellers 568F-1
 - → Severe vibrations on engine #2 propeller during descent
 - No findings from maintenance
 - → On 5th May 2015, vibrations after landing
 - → Test runs leading to damages



Propeller governing system description









Damages :

- One blade was turning freely (blade trunnion pin broken)
- Blade angle actuatorforward plate found bent





NOT A SERIOUS INCIDENT but SIMILAR INCIDENT



INVESTIGATION proposed by BEA




INVESTIGATION delegated to BEA



- On 30th November 2014, in Sweden, ATR 72-212A equipped with Hamilton Sundstrand Propellers 568F-1
 - → Severe vibrations on engine #2 propeller during descent
 - → Impossible to read instruments and to walk in cabin
 - → Engine #1 fatheared then engine #2







- One blade was turning freely (blade trunnion pin broken)
- Blade angle actuator forward plate found bent






Damages :

→ A 180° crack





INCIDENT but SIMILAR INCIDENT | INVESTIGATION by SHK









Organization of investigations according to ICAO Annex 13

Serious incident






Organization of investigations according to ICAO Annex 13






Incident Notification






Information sharing between SIA






Examination requests and "to do list"






Highlighted Solutions Update meetings






Safety recommendations





What about the reports and final recos?





Possible ways of improvement

Improve SIA awareness of an on going investigation



Focal point(SIA or safety organization)





Possible ways of improvement

Improve confidentiality principles for information sharing

Harmonization of reports and recommendations



Similar investigations to be considered as a unique big one?



Thank you for your attention

www.bea.aero

