



ICAO Accident/Incident Investigation Workshop, Mexico 2015

Ricardo Asensio,
Air Safety Investigator
Textron Aviation
316-676-7824
rasensio@txtav.com

Beechcraft



Hawker

TEXTRON AVIATION

Who is Textron Aviation?

Beechcraft



Hawker

TEXTRON AVIATION

Textron
Corporation

Textron
Aviation, Inc.

Cessna
Aircraft

Hawker/
Beechcraft

Air Safety Investigations (ASI)



Manager
Welch

Senior ASI
A. Hall



Senior ASI
Basile



Senior ASI
Soderlund



ASI
Asensio



Senior ASI
Smith



ASI
Weber



Senior ASI
Yoos



ASI
E. Hall



Qualifications



- 9 College Degrees
- 5 Advanced Degrees
- Pilot Certificates
 - 4 CFI-I
- 9 A & P Mechanic Certificates
 - 4 Inspection Authorizations
- 140+ years of investigation experience
- 1,400+ field investigations

Primary Duties



- Provide assistance to NTSB, FAA, and foreign governments
- Conduct an accurate detailed investigation
- Reports
 - Field Notes
 - Preliminary
 - Final
 - Company Management
 - Engineering Department
- Offer technical assistance during separate component analytical examinations

- Fatal Injury
- Serious Injury
- When our help is requested
- Special interest
 - New production singles
 - Trends
 - Survivability
 - New seats and rails on new production singles
 - 206 rear door system
 - Air bags

Simple single engine



Challenging

Beechcraft

Cessna

Hawker

TEXTRON AVIATION



Drive-Up

Beechcraft

Cessna

Hawker

TEXTRON AVIATION



Climb Up

Beechcraft

Cessna

Hawker

TEXTRON AVIATION



Mountain Top



Swamp



Wind 30 knots; Temperature -20° F
Snow, 4' Deep

Beechcraft



Hawker

TEXTRON AVIATION



**Winds, Calm; Temperature 80° F;
Sand, Warm**

Beechcraft



Hawker

TEXTRON AVIATION



All Here

Beechcraft

Cessna

Hawker

TEXTRON AVIATION



Consumed by fire



Notification of Accidents



- NTSB or Foreign Authority notification
- FAA Preliminary Accident and Incident Reports
- Local and International news services
- Law Enforcement
- Other manufacturers


Historical Data

Beechcraft



Hawker

TEXTRON AVIATION



Beechcraft



Hawker

TEXTRON AVIATION



Beechcraft



Hawker

TEXTRON AVIATION



On Call



24/7

Beechcraft



Hawker

TEXTRON AVIATION

Questions?



Case Studies

Ricardo Asensio,
Air Safety Investigator
Textron Aviation
316-676-7824
rasensio@txtav.com

Case Study 1



- Cessna 172M
- San Juan, PR
- During final approach
 - Fernando Luis Ribas Dominicci Airport (TJIC)
- Pilot reported problems with aileron control
- Aircraft impacted the water surface with the right wing tip
 - The aircraft cart wheeled and disappeared below the water surface
- Pilot received fatal injuries

Beechcraft



Hawker

TEXTRON AVIATION



Beechcraft



Hawker

TEXTRON AVIATION



Investigation



- All flight control surfaces were observed and attached
- Left and right wings remained attached to fuselage
- Control cable continuity was established
 - Through multiple cable separations
- Flap actuator was found at 10°
- Elevator trim was found with 10° tab up
- Co-pilot control yoke was fractured
 - Recovered within the pilot's hands
- Pilot control yoke remained attached
 - Operation and continuity of the control yoke was confirmed

Investigation

- Ailerons interconnect control cable exhibited broomstrawing
- Right aileron direct control cable was found separated
- Top left doorpost pulley exhibited signs of scoring on the rim



Beechcraft

Cessna

Hawker

TEXTRON AVIATION




Aileron Pulley

Beechcraft

Cessna

Hawker

TEXTRON AVIATION



NTSB Probable Cause



“Maintenance personnel’s improper lubrication of the right direct aileron control cable and failure to detect the severe corrosion of the cable during a maintenance inspection, which resulted in the in-flight failure of the cable, the pilot’s subsequent inability to maintain aircraft control, and the airplane’s impact with terrain.”

Questions?

Case Study 2



- 525B (CJ3)
- Sao Paulo, Brazil
- Owner is PIC
- Low time co-pilot
- Landed at Congonhas Airport (SBSP)
 - Runway 35R (4,708' x 148' Asphalt)
- Aircraft exited the end of Runway 35R
 - Impacted the perimeter fence
- Crew reported brake issues to SERIPA





Investigation



- Aircraft flying too fast and too high.
- Aircraft touched-down halfway down the runway and bounced.
- Touched-down a second time almost at end of runway.
- Radar shows aircraft airspeed of 170 knots
 - 100' from Runway 35R threshold
- Landing calculations
 - Approach Speed (V_{app}) of 117 knots
 - Touchdown Speed (V_{ref}) of 107 knots
- Flaps 15° (Takeoff and Approach)
- The tires had no flat spots, the wheels spun normally, and the brake pads were not worn.

Questions?