



**National  
Transportation  
Safety Board**

# Accident Case Studies

Tim LeBaron, IIC / US Acc Rep  
Washington, DC

# Incident Summary

- September 2011
- Bombardier CRJ-200
- Baton Rouge, LA
- Landed with left main landing gear retracted



# Incident


- No injuries
- No substantial damage



# So why investigate?


- December 2008
- Bombardier CRJ-200
- Philadelphia, PA
- Landed with left main landing gear retracted

Bolt not fitted through uplock upper lugs



**NOTE**

Right proximity sensor identification shown in brackets.




0.035 - 0.045 in.  
(0.9 - 1.14 mm)

**B**

# Safety payback

- Airline - “Alert Bulletin”
- Manufacture - “Service Letter”

Installation of Upper/Lower Bolts on MLG Uplock Assembly		
 ATLANTIC SOUTHEAST AIRLINES	Issue Date: 09/15/11 Exp. Date: 03/15/12	ALERT BULLETIN

**Applicability** All Atlantic Southeast Maintenance Personnel

**Purpose** To inform Maintenance Personnel of the possibility of installing the bolts incorrectly in the main landing gear (MLG) uplock.

**Synopsis** It has been discovered that the upper bolt of the MLG uplock can be installed improperly.

**Additional Information**

Bombardier released AOM 1307 to notify operators of this event. See the below figure.



- #1 - Bolt installed through the Airframe Structure and MLG Uplock.
- #2 - Bolt not installed through the MLG Uplock, but Airframe Structure only.

**Effective Date** Immediately

**Action Required** When installing a MLG uplock assembly, ensure that you follow the AMM TASK 32-32-05-400-801 and/or Bombardier Task Card precisely.

**Contact** Contact Technical Support with any questions regarding this bulletin.

## BOMBARDIER

40350402  
Bombardier Inc.  
1300, Henri-Guyon Blvd.  
Montreal, Quebec H3R 2S5  
800-228-2689  
514-855-6500  
514-855-6501

## SERVICE LETTER

In-Service  
Engineering

CRJ100/200/440-SL-32-048

ATA: 3230

DATE: 11 Oct '11

**SUBJECT:** Main Landing Gear Up-lock installation - "Maintenance Best Practice"

**MODEL:** CL-600-2B19 (CRJ200)

**APPLICABILITY:** All CRJ100/200/440/850 aircraft

**PURPOSE:**

To inform Operators of a recent event that resulted in an aircraft landing with the left Main Landing Gear (MLG) in the retracted position following replacement of the associated up-lock assembly and to recommend steps that can be taken to reduce the potential of reoccurrence. Reference the All Operator Memo (AOM) 1307 for details of the event.

**DISCUSSION:**

The event flight was the first after maintenance had been carried out on the landing gear up-lock system. Preliminary investigation results revealed that the upper attachment bolt for the left up-lock assembly, which is designed to be attached to both the up-lock assembly and structure, was attached to the structure only, ref fig. 1. The left up-lock assembly had been replaced prior to the flight however AMM task 32-32-05-400-801 was not followed, and as part of this procedure the visual inspection as per Step 8 to make sure the attaching holes of the MLG up-lock assembly align with holes in the adjacent structure and the additional safeguard as per step 16, which instructs to manually move the up-lock up and down had also not been performed by either the Technician or the Inspector.

This was the second occurrence of this type of event with two different Operators and Fig 2 illustrates the proper and improper installation as found on the latest incident aircraft.

# Probable Cause


- The improperly installed upper attachment bolt in the left main landing gear uplock assembly, which led to the failure of the left main landing gear to extend before landing. Contributing to the accident was maintenance personnel's lack of training on the installation and inspection of the uplock assembly

# Accident Summary

- Nov 2009
- Burnet, TX
- Sonex
- 1 fatal
- Loss of engine power
- Crashed during forced landing







EXPERIMENTAL

NEW











# Probable Cause

- The pilot's failure to maintain aircraft control, resulting in an aerodynamic stall. Contributing to the accident was the loss of engine power due to a clogged fuel screen that resulted in fuel starvation caused by the builder's inappropriate use of a fuel tank sealant in a plastic tank

# Accident Summary

- March, 2006
- Patterson, LA
- Bell 206
- 2 fatal, 2 minor





# Accident Summary

- Takeoff appeared normal and they departed south from the airport at an approximate altitude of 500-700 feet above ground level.
- The helicopter "dropped" several times. Each time the helicopter regained the lost altitude; however, it appeared to do so slowly as if "he, [the pilot], didn't have the power to keep it up."



# Accident Summary

- The pilot then made a descending right turn, of approximately 90 degrees, to an open field. As they approached the ground, the pilot brought the nose of the helicopter up as if he was attempting to "slow down." The helicopter impacted the ground on the front left side and came to an abrupt stop in an upright position.





Digital Photo 5, View of wreckage looking south.



Digital Photo 1, Aerial View



Digital Photo 6, View of engine



Digital Photo 7, View of Fuel nozzle "B" nut.

# Accident Summary

- Log entry revealed that a 50-hour fuel nozzle inspection had been performed the night before
- The mechanic reinstalled the fuel nozzle into the engine combustion chamber, “torqued it and lockwired it”
- Engine run-up was not performed
- The inspector stated that he performed a visual inspection of the fuel nozzle installation



# Probable Cause

- The improper installation of an engine fuel line by maintenance personnel, which resulted in a loss of engine power during cruise flight. Factors associated with the accident are a tailwind, and the lack of a suitable site for a forced landing



# Accident Summary

- July, 2006
- Petal, MS
- Cessna 172
- fatal
- Impacted trees on takeoff







# Probable Cause

- The pilot's improper use of flaps, which resulted in an impact with trees during takeoff-initial climb

# Accident Summary

- Aug, 2004
- Port Angeles, WA
- Cessna 182
- VFR flight
- Dark night conditions
- Rain, clouds and fog
- 1 fatal 2 minor











# Probable Cause

- The pilot's VFR flight into IMC and his failure to maintain clearance from trees. Trees, mountainous terrain, dark night conditions, clouds and VFR flight into IMC were factors

# Accident Summary


- June 2010
- Broomfield, CO
- P2V-5 air tanker
- Drop retardant drop on Fire.
- Following retardant drop, crew noticed flaps did not retract



# Accident Summary

- Hydraulic systems had lost fluid and pressure
- Pilot declared an emergency and returned to land






# AIRPORT DIAGRAM

DENVER/ROCKY MOUNTAIN METROPOLITAN (BJC)  
AL-5612 (FAA)  
DENVER, COLORADO

SW-1, 03 JUN 2010 to 01 JUL 2010



# AIRPORT DIAGRAM

DENVER/ROCKY MOUNTAIN METROPOLITAN (BJC)  
DENVER, COLORADO

SW-1, 03 JUN 2010 to 01 JUL 2010

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.  
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

- RWY 2-20 S40, D45, DT65
- RWY 11L-29R S55, D75, ST95
- RWY 11R-29L S12.5

JANUARY 2005  
ANNUAL RATE OF CHANGE  
0.1°W

VAR 9.8° E

FIELD ELEV 5673

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

ELEV 5660

105°08'W

105°07'W

105°06'W

39°55'N

126.25

118.6 233.7

121.7

**Pilot used accumulator brake pressure to slow and turn off the Runway.**



Upon arriving at the end of A-13 the pilot pulled the emergency brake with no result







• Checklist was for different model of airplane




NTSB

# Findings

- Flight Manual – “Placing the nose gear emergency extension switch in “bypass” will result in loss of hydraulics to the emergency brakes”
- Emergency landing gear selector was placed in “bypass”, resulting in loss of pressure to the emergency brakes
- Company policy – Stay on runway until stopped



# Loss of Hydraulic Pressure



# Probable Cause

- The pilot's failure to follow published emergency procedures by taxiing to the parking ramp with a known hydraulic system failure. Contributing to the accident was the co-pilot's improper selection of the bypass position on the emergency nose gear extension system, which shut off emergency hydraulic system pressure to the brakes, and a ruptured hydraulic line, which resulted in a total loss of the main hydraulic system pressure.

# Accident Summary

- Dec 3, 2011
- Silverton, CO
- Socata TB21
- 4 fatal



Air-Britain Photographic Images Collection

© Steve Homewood




NTSB

# Accident Summary

- Pilot contacted ATC while at 20,000 feet requested visual flight rules (VFR) flight following
- Reported that he could not descend below his altitude and maintain VFR.
- Moments later, the airplane disappeared from radar and contact with the pilot was lost





**Clouds with tops to 22,000 feet**

**KASE**

**KTEX**

**KDRO**

**Accident Site**



10001 G-11 IMG 4 3 DEC 11337 203000 03957 18613 00 50

McIDAS



**NTSB**











NTSB





# Media Briefing

- War Story



# Probable Cause

The non-instrument-rated pilot's decision to embark on a flight through forecasted instrument meteorological conditions (IMC), and his subsequent flight into IMC, which resulted in the pilot's spatial disorientation and subsequent maneuvering of the airplane in a manner that exceeded the airplane's structural limits



# Accident Summary

- March 4, 2008
- Oklahoma City, OK
- Cessna 500
- 5 fatal



N113SH | Copyright by Richard T Davis | 2008-02-28 | DAN | Airport-Data.com



# Flight Sequence

- Cleared for takeoff about 1512
- Crew reported 2,000 for 3,000 feet
- Controller acknowledged, provided further clearance
- No response from flight crew
- Crash reported about 1515





Airport

Lake



Witness

Sep 21, 20  
8:00:00pm

Airport



NTSB





NO PUSH

Splatter  
residue



# American White Pelicans



# American White Pelican

- Common in Oklahoma
- Weight: about 8 to 20 lbs
- Length: about 4 to 5 feet
- Wingspan: about 8 to 10 feet





# Findings

- Right engine not producing power
- Cockpit voice recorder inoperative
- Airplane wing damage sustained during collision with American white pelicans



# Probable Cause

- Airplane wing-structure damage sustained during impact with one or more large birds (American white pelicans), which resulted in a loss of control of the airplane

E-500 JT15D-1A  
INLET DIAMETER



# Accident Summary

- March, 2004
- Vail, Washington
- Van's RV-4
- 1 fatal
- Complete loss of engine power
- Nose over during forced landing





N6596X







# Probable Cause

- A loss of engine power due to the pilot's inadequate in-flight decision by failing to refuel while en route, resulting in fuel exhaustion. Contributing factors were the non-operating (vandalized) runway lights, the pilot's delayed departure to his destination, dusk light conditions, rough/uneven terrain and high vegetation.

# Accident Summary

- August 2011,
- Alpine, Texas
- Piper Aerostar
- Emergency landing due to a vibration in the tail



08/22/2011



# Probable Cause

- The pilot's improper flare which resulted in a hard landing.  
Contributing to the accident was the pilot's improper decision to fly the airplane with a known mechanical deficiency

# Accident Summary

- July 2006
- Owasso, OK
- Cessna 180
- 1 fatal
- 1 serious











# Probable Cause

- The pilot's selection of unsuitable terrain, a residential street, for both takeoff and landing, which resulted in a collision with a static wire and terrain during takeoff-initial climb

# Short Investigation – No travel

- Landing rollout
- Hard braking
- Airplane nosed over
- Substantial damage
- No injuries
- Known circumstances with little no safety payback



# Probable Cause

- The pilot's excessive use of brakes during the landing



# National Transportation Safety Board

# Questions?