

ADT equipage in aircraft

ICAO EUR/APAC SAR WORKSHOP 2024
Export Control - Not technical
ADNS X3134PR2406502

COMMERCIAL AIRCRAFT

Peter Walther, Certification Manager RALS
03 September 2024

Agenda

- Basic overview
- Current Status Inadvertent ELT-DT activations
- Way forward / Lines To Take

Basic overview

Basic overview / Major system components



ELT-DT Antenna

- 406MHz & 121,5 MHz transmission
- GNSS reception



Remote Control Panel

- ON-ARMED-TEST/RESET
- Status Indication (LED)



ELT-DT Unit

- Crash survivable
- Acceleration Sensors
- Internal GNSS receiver

Aircraft Identification Module

- LADR compatible coding available



ADT Software

- Hosted on avionics computer
- Logic for detection of “in flight” status, distress detection & ADT triggering
- Interface between ELT-DT and aircraft display & maintenance systems

Basic overview / Activation types

- Autonomous

Initiated by the ADT software after detection of:

- Unusual Aircraft Attitude: excessive pitch angle, excessive roll angle
- Unusual Speed: excessive vertical speed, stall warning, Speed or Mach excessive
- Collision with Terrain: radio altitude and inertial vertical speed in mode 1 warning envelope
- Total loss of thrust/propulsion on all engines
- Excessive Cabin Altitude

Autonomous activation is also done by ELT-DT unit directly in case of total loss of communication with onboard avionic or loss of ELT power supply

- Automatic

Initiated by the Acceleration Measurement Device within the ELT-DT

- Manual

Initiated via switch on the RCP in the cockpit or on the ELT-DT unit itself (Remark: ELT-DT unit not accessible in flight)


Basic overview / Flight Crew alerting of ELT-DT activation

Primary:

Alert via the Electronic Centralized Aircraft Monitoring (ECAM)

The ECAM alert is categorized as a CAUTION:

- visual attention getters lighted (Master Caution lights - amber steady lights located in front of each pilot) and
- it has an AMBER text **COM ELT EMITTING** on the Engine/Warning Display (upper part of the central display) and
- is associated with aural attention getters (Single Chime)



Supplemented by:
LED on the RCP will flash periodically

Additionally:
If A/C is on ground a horn is activated

Basic overview / Key figures

- **Standards**

406 MHz ELT-DT (First Generation Beacon) in accordance with European Technical Standard Order (ETSO)-C126c, Eurocae ED-62B and COSPAS-SARSAT C/S T.001 & C/S T.007

- **Capabilities**

C (crash survivability)

H1 (121.5-MHz homing signal)

G (internal/integral GNSS receiver) - Aircraft navigation system as backup

- **Transmission Duration**

406 MHz signal at least 24 hours

121.5 MHz signal at least 48 hours

- **Position accuracy of 406 MHz signal for location of point of end of flight**

If the system survives the accident: within 200 meters radius

In case of a non-survivable accident: within 6 nautical miles

Basic overview / Testing and Maintenance

- Testing

Automatic: Power on self test

Manual: Test via switch on RCP or on ELT-DT unit

ELT-DT is connected to the onboard maintenance system. Detected failures will be displayed to flight crew and as part of the Post Flight Report.

- Scheduled Maintenance Tasks

Replace ELT-DT unit (battery discard) 60 month

Operational check of discrete interfaces 180 month or 24000FH


Inadvertent activations

Inadvertent ELT-DT activations


Status End of July 2024 / Observations

- **Based on COSPAS / SARSAT data as per 02.Aug.2024:**
 - **1161 transmission events from Airbus ELT-DTs were detected since 1st a/c delivery in April 23**
Remark: Until end of July 2024 Airbus delivered a total number of 437 aircraft equipped with ELT-DT
-> 588 new events since last status provide in April 2024
- All inadvertent transmissions (Manual / Automatic / Autonomous) started on ground
- One activation in flight linked to temporary loss of 28V emergency power during flight / considered as 1st autonomous activation started in flight as loss of ELT-DT emergency power supply is a defined trigger reason, hence it is considered as justified alert
- Some operators have several issues, while others less or even none

Inadvertent ELT-DT activations per month (autonomous activations only) (until 02.08.)




Inadvertent ELT-DT activations per month (manual activations only) (until 02.08.)



Inadvertent ELT-DT activations per month (automatic activations only) (until 02.08.)

(Note: In total 14 activations (May (1), June (2) and July (11)) could be traced down to a single unit installed on A320 MSN 11859. This ELT has been replaced and sent to Safran to be analyzed)



Inadvertent ELT-DT activations

Status Root Cause Analysis

- Root cause analysis based on Airbus, SAFRAN and C/S data is still ongoing but some contributors already identified:
 - Operators and maintenance personnel were not aware of the difference between ELT(DT) and ELT(AF), including the consequences of triggering
 - Autonomous activations on ground due to incorrect detection of “in flight” status
 - Autonomous activations on ground as ELT-DT was not deactivated prior maintenance activities as defined in the maintenance documentation
 - Erroneous manual activation by installers and maintenance crews
 - Automatic activation due ELT-DT beacon internal issues (voltage tolerance/power cycle)

Inadvertent ELT-DT activations

Mitigation actions launched

- Dedicated electronic informations (ISI), Airline visits and webinars were performed to bring awareness and introduce improvements in airline operations / to be continued
- Maintenance manuals and trainings are updated / in update to promote the awareness of cautious ELT(DT) handling
- Technical improvements on aircraft level to robustify the “In Flight” detection logic are launched
- Technical improvements of the ELT(DT) beacon are defined and shall be part of the next equipment standard

Way forward / Lines To Take

Way forward / Lines To Take

- All unintended transmissions started on ground
→ Core distress detection logic is robust and working as per intention
- Some airline operators have several issues, while others less or even none
→ Issue is not solely related to the new ELT-DT system
- Reduction of inadvertent autonomous & automatic activations
→ For all three programs Airbus is working on ADT software update to improve the ground / airborne detection and to robustify the ELT(DT) beacon
- Mitigations of inadvertent activations via training & awareness
→ Several Awareness sessions performed (with customers but also Airbus internal)
- Update of maintenance procedures
→ Improvements ongoing on AMM & TSM

© Copyright Airbus - (Airbus Operations GmbH 2024) / ADT equipage in aircraft

This document and all information contained herein is the sole property of Airbus. No intellectual property rights are granted by the delivery of this document or the disclosure of its content. This document shall not be reproduced or disclosed to a third party without the expressed written consent of Airbus. This document and its content shall not be used for any purpose other than that for which it is supplied.

Airbus, its logo and product names are registered trademarks.