

Safety Recommendation 003/2015 LAM

DAAI¹ recommends that ICAO should establish standards that implement recommendations of the working group, formed under safety recommendation number 002/2015 LAM to suitably avert the locking out of the cockpit of authorized crew members.

¹ Directorate of Aircraft Accident Investigation