

Safety Recommendation 004/2015 LAM

DAAI¹ recommends that ICAO should establish a working group to review the installation of visual recording inside and outside the cockpit that should provide information on who was in the cabin, who exactly was controlling the plane at the time of the accident and even where their hands were in relation to the plane's controls.

¹ Directorate of Aircraft Accident Investigation