

Synopsis

After an initial missed approach due to wind shear, the aircraft landed on runway 30 at the Bilbao Airport. During the landing run, the airplane was unable to remain on its heading and exited the runway via the left shoulder, momentarily taxiing over an unpaved area with the left main gear before returning to the runway and subsequently stopping on the taxiway.