



Participants of Group B

- ENRIQUE STORM
- VICTOR VASQUEZ
- ROBERTO TIRADO
- JOSE MARIA GARCIA
- BEYLE ROJAS
- ALEJANDRO NUÑES
- EDUARDO MONTENEGRO
- FABIO VASQUEZ
- MARCEL SANCHEZ
- CARLOS TOMBA
- GUSTAVO FAVARON
- CARLOS DIAZ
- JORGE SUAREZ
- JUAN ROLDAN
- VICTOR ALBA



VISITED AREAS

- ✓ **CONTROL TOWER**
- ✓ **R.F.F. (RESCUE AND FIRE FIGHTING)**
- ✓ **ENERGY SUB-STATION**
- ✓ **FUEL INSTALLATIONS**



CONTROL TOWER

REMARKS:

X This team observed the presence of columns that do not permit the controllers' visibility of the north and south sides

✓Excellent system of air traffic approach visibility

✓Excellent automatic system for the elaboration of flight plans at local level with video record of 24 hours

✓Excellent location of control with a good view of the airport perimeter

✓Excellent marking control system



R.F.F. (Rescue and Fire Fighting)

- The equipment observed the personnel quantity and the existing equipment (fire car)
- The personnel quantity is not appropriate for the quantity of vehicles in service
- In presence of the team, phase I no simulated was activated. It was observed that it took 1min and 15 s since the alarm signal was on until they finish dressing, and completing their activities
- The recommendations provided by a member of the team were:
 - Non written list of the two service units on the blackboard
 - It was observed more beds than the number of personnel in charge
 - **No daily training register was observed.** However, it is recommended that: These registers must be done daily during 365 days of the year without considering Saturdays, Sundays and holidays. The register form should have the following items: Instructor Names, theme, name and signature of all the trained staff and from the persons that are sick or on vacation, which have to be replaced



ENERGY SOURCE

- It was observed that no detection and fire fighting system was available at the control room
- It was observed that the equipment is excellent and sufficient for the needs and requirements of the airport



FUEL INSTALLATION

- It was observed that no detection and fire fighting system was available
- It was observed that the equipment is excellent and sufficient for the needs and requirements of the airport







26/09/2002