

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA									
AGA 139C	Airfield maintenance (Annex 14, Vol. I, Ch. 9.4)	This problem exists in both CAR and SAM Regions.	Deficiencies in pavements, lights, markings, signs, secondary power supply and fencing.	2001	ASB/2 Meeting	Establishment and implementation of airfield maintenance programmes "PENDING ACTION PLAN"	States	Permanent	U
AGA 218C	Airport development (Doc 9184-AN/902, Part 1)	Argentina/International aerodromes	Master plans have not been updated/developed for all international aerodromes	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Update/Develop master plans for the international aerodromes and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 222C	Apron management service (Annex 14, Vol. I, Ch. 9.6, Doc 9137-AN/898, Ch. 10, Doc 9476-AN/927)	Argentina/BUENOS AYRES/Ezeiza/Min. Pistarini Int'l Airport	The cargo apron and most part of the passenger's apron cannot be seen from the control tower	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	"Construct a new control tower which could permit complete visibility of the aprons" or "Change the apron control of the tower to an independent apron control system, keeping close coordination with the tower" and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 141C	Bird Hazard Committee (Annex 14, Vol. I Ch. 9.5 and its Amendment No. 5)	Argentina/All international airports	Bird Hazard Committee is not totally implemented	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Intensify the implementation of the Bird Hazard Committee in order to comply with Ch. 9 of Annex 14, Vol. I, Amendment No. 5, scheduled to become applicable on 27 November 2003 "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 220C	Emergency plans (Annex 14, Vol. I, Ch. 9, Doc 9137-AN/898, Part 7)	Argentina/BUENOS AYRES/Ezeiza/Min. Pistarini Int'l Airport	Last aerodrome emergency exercise was conducted on 9 NOV 2000	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Carry out aerodrome emergency exercises at intervals not exceeding two years and comply with ICAO SARPS and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	U
AGA 219C	FOD (Annex 14, Vol. I, Ch. 9.4.3, Attach. A, Sect. 8, Doc 9137-AN/898, Parts 8 and 9)	Argentina/BUENOS AYRES/Ezeiza/Min. Pistarini Int'l Airport	FOD at the apron surface, such as paper, plastic, metal, coarse aggregates, rope, etc. Joint slab deterioration	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Intensify daily inspections according to the ICAO SARPS. Use hot asphalt mixture to block the coarse aggregates(in process of deterioration) and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina/Argentina 2000	TBD	U
AGA 212C	Physical characteristics (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 3.8)	Argentina/TUCUMAN/Tte. Benjamin Matienzo Aerodrome	No parallel TWY to RWY 01, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Construct parallel TWY to RWY 01 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 181C	Physical characteristics (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 3.8)	Argentina/RESISTENCIA/Resistencia Aerodrome	No Parallel TWY to RWY 21, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Construct parallel TWY to RWY 21 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 153C	Physical characteristics (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 3.8)	Argentina/CORDOBA/Ing. Aer. Taravella Aerodrome	There is no TWY parallel to RWY 18, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Construct a parallel TWY to RWY 18 and/or inform to the ICAO SAM Office when it will be built "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 175 C	Physical characteristics (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 3.8)	Argentina/POSADAS/Libertad or Gral. D. José de San Martín Aerodrome	There is no parallel TWY to RWY 19, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Construct parallel TWY to RWY 19 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 192 C	Physical characteristics (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 3.8)	Argentina/RÍO GRANDE/Río Grande Aerodrome	No parallel TWY to RWY 25, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Construct parallel TWY to RWY 25 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 198 C	Physical characteristics (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 3.8)	Argentina/ROSARIO/Rosario Aerodrome	No parallel TWY to RWY 19, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Construct parallel TWY to RWY 19 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 202 C	Physical characteristics (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 3.8)	Argentina/SALTA/Salta Aerodrome	No parallel TWY to RWY 01, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Construct parallel TWY to RWY 01 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 142 C	Physical characteristics (Doc 8733, Vol. II, FASID)	Argentina/BUENOS AYRES/Ezeiza Aerodrome	RWY 11/29 length is 3300 m. The Regional ANP recommends 3700 m	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Inform the SAM Office when the remaining 400 m will be constructed "PENDING ACTION PLAN"	Argentina/Argentina 2000	TBD	B
AGA 193 C	Radio aids (Doc 8733, Vol. II, FASID)	Argentina/RÍO GRANDE/Río Grande Aerodrome	No DME installed at the ILS of RWY 25, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install DME at the ILS of RWY 25 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 203 C	Radio aids (Doc 8733, Vol. II, FASID)	Argentina/SALTA/Salta Aerodrome	No VOR with DME, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install DME and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 207 C	Radio aids (Doc 8733, Vol. II, FASID)	Argentina/SAN CARLOS DE BARILOCHE/San Carlos de Bariloche Aerodrome	The APP does not have radar , as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide radar for the APP and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 145 C	Rescue and Fire Fighting Service (Annex 14, Vol. I, Ch. 9.2 and Doc 8733, Vol. II, FASID)	Argentina/CATARATAS DEL IGUAZU/My. Carlos Eduardo Krause Aerodrome	RFF is currently Category 6. The Regional ANP requires Category 9	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Upgrade the RFF to Category 9, as recommended by the Regional ANP and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	A
AGA 221 C	RFF (Annex 14, Vol. I, Ch. 9.2)	Argentina/BUENOS AYRES/Ezeiza/Min. Pistarini Int'l Airport	The fire station is not well located in relation to both RWYs. The response time obtained during the last exercise was 2'45''	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Relocate fire station in order to reduce the response time to less than 2 min, in order to comply with the ICAO Recommendation 9.2.22 of Annex 14, Vol. I "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 148 C	RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/COMODORO RIVADAVIA/General Moscón Aerodrome	RFF is currently Category 6. The Regional ANP requires Category 7	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide category 7, as it is recommended by the Regional ANP and/or inform the ICAO SAM Regional Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 152 C	RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/CORDOBA/Ing. Aer. Taravella Aerodrome	The RFF is currently Category 7. The Regional ANP recommends Category 9	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provid RFF Category 9 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
AGA 156 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/FORMOSA	The RFF is currently Category 5. The Regiona ANP requires Category 6	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 6 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 160 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/JUJUY/Gobernador Guzmán Aerodrome	The RFF is currently Category 4. The Regional ANP requires Category 7	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF category 7 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 164 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/MAR DEL PLATA/Gral. B. Colina Aerodrome	The RFF is currently Category 6. The Regional ANP recommends Category 7	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provid RFF category 7 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 170 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/NEUQUEN/Presidente Perón Aerodrome	The RFF currently is Category 4. The Regional ANP requires Category 7	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 7 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 173 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/POSADAS/Libertad or Gral. D. José de San Martín Aerodrome	The RFF currently is Category 5. The Regional ANP requires Category 6	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Categoría 6 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 179 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/RESISTENCIA/Resistencia Aerodrome	The RFF is currently Category 5. The Regional ANP recommends Category 9	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 9 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
AGA 184 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/RÍO GALLEGOS/Piloto Civil N. Fernández Aerodrome	The RFFis currently Category 7. The Regional ANP recommends Category 9	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 9 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 189 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/RÍO GRANDE/Río Grande Aerodrome	The RFF is currently Category 4. The Regional ANP recommends Category 7	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 7 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 196 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/ROSARIO/Rosario Aerodrome	The RFF is currently Category 6. The Regional ANP recommends Category 9	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 9 and/or inform the ICAO SAM office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 201 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/SALTA/Salta Aerodrome	The RFF is currently Category 4. The Regional ANP recommends Category 7	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 7 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 206 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/SAN CARLOS DE BARILOCHE/San Carlos de Bariloche Aerodrome	The RFF is currently Category 6. The Regional ANP recommends Category 7	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 7 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 211 C RFF (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 9.2)	Argentina/TUCUMAN/Tte. Benjamin Matienzo Aerodrome	The RFF currently is Category 4. The Regional ANP recommends Category 6	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RFF Category 6 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
AGA 147 C RVR (Doc 8733, Vol. II, FASID)	Argentina/CATARATAS DEL IGUAZU/My. Carlos Eduardo Krause Aerodrome	No RVR in operation at RWY 31 touchdown zone, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at runway 31 touchdown zone and/or inform the SAM Regional Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 151 C RVR (Doc 8733, Vol. II, FASID)	Argentina/COMODORO RIVADAVIA/General Moscón Aerodrome	No RVR in operation at RWY 25 touchdown zone, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 25 touchdown zone and/or inform the ICAO SAM Regional Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 155 C RVR (Doc 8733, Vol. II, FASID)	Argentina/CORDOBA/Ing. Aer. Taravella Aerodrome	No RVR in operation at RWY 18 touchdown zone as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install the RVR at RWY 18 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 159 C RVR (Doc 8733, Vol. II, FASID)	Argentina/FORMOSA	No RVR in operation at RWY 21, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 21 and/or inform to ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 163 C RVR (Doc 8733, Vol. II, FASID)	Argentina/JUJUY/Gobernador Guzmán aerodrome	No RVR at RWY 33 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 33 touchdown zone and/or inform to ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 166 C RVR (Doc 8733, Vol. II, FASID)	Argentina/MAR DEL PLATA/Gral. B. Colina Aerodrome	No RVR in operation at RWY 13 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 13 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
AGA 169 C RVR (Doc 8733, Vol. II, FASID)	Argentina/MENDONZA/El Plumerillo Aerodrome	No RVR in operation at RWY 36 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 36 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 172 C RVR (Doc 8733, Vol. II, FASID)	Argentina/NEUQUEN/Presidente Perón	No RVR in operation at the RWY 08 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 08 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 178 C RVR (Doc 8733, Vol. II, FASID)	Argentina/POSADAS/Libertador or Gral. D. José de San Martín Aerodrome	No RVR in operation at RWY 19 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 19 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 183 C RVR (Doc 8733, Vol. II, FASID)	Argentina/RESISTENCIA/Resistencia Aerodrome	No RVR in operation at RWY 21 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 21 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 188 C RVR (Doc 8733, Vol. II, FASID)	Argentina/RÍO GALLEGOS/Piloto Civil N. Fernández Aerodrome	No RVR at RWY 25 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 25 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 195 C RVR (Doc 8733, Vol. II, FASID)	Argentina/RÍO GRANDE/Río Grande Aerodrome	No RVR in operation at RWY 25 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 25 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
AGA 200C RVR (Doc 8733, Vol. II, FASID)	Argentina/ROSARIO/Rosario Aerodrome	No RVR in operation at RWY 19 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 19 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 205C RVR (Doc 8733, Vol. II, FASID)	Argentina/SALTA/Salta Aerodrome	No RVR in operation at RWY 01 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 01 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 210C RVR (Doc 8733, Vol. II, FASID)	Argentina/SAN CARLOS DE BARILOCHE/San Carlos de Bariloche Aerodrome	No RVR in operation at RWY 29 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 29 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 213C RVR (Doc 8733, Vol. II, FASID)	Argentina/TUCUMAN/Tte. Benjamin Matienzo Aerodrome	No RVR in operation at RWY 01 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR at RWY 01 touchdown zone and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 217C RVR (Doc 8733, Vol. II, FASID)	Argentina/USHUAIA/Malvinas Argentinas Aerodrome	No RVR in operation at RWY 25 touchdown zone, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install RVR and inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 140C Strength of pavements (Annex 14, Vol. I, Ch. 2)	Argentina/All international airports	Pavement strength is not reported, as specified in Anex 14, Volume I, Ch. 2, using PCN values	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Report PCN values according to Ch. 2 of Anex 14, Vol. I "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 19C	Visual aids (Annex 14, Vol. I, Ch. 5)	Argentina, BUENOS AIRES/Ezeiza Aerodrome	Bad illumination of the apron area	11/2000	IATA/Letter sent to the President of ORSNA in November 2000 Fax letter 286/02 dated 30 OCT 2002 from Argentina	To improve the apron area illumination. ACTION TAKEN: The Administration is preparing a Corrective Action Plan. A requirement was formulated through the Regulatory Agency (ORSNA) to the Concessionaire in order to present a Corrective Action Plan	Argentina	TBD	A
AGA 20C	Visual aids (Annex 14, Vol. I, Ch. 5)	Argentina, BUENOS AIRES/Ezeiza Aerodrome	Lack of edge illumination in taxiway H and insufficient letter signs for information	11/2000	IATA/Letter sent to the President of ORSNA in November 2000 Fax 286/02 dated 30 OCT 2002 from Argentina	To provide edge illumination in taxiway H and to improve the letter signs for information. ACTION TAKEN: The Administration is preparing a Corrective Action Plan. A requirement was formulated through the Regulatory Agency (ORSNA) to the Concessionaire in order to present a Corrective Action Plan.	Argentina	TBD	A
AGA 149C	Visual aids (Doc 8733, Vol II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/COMODORO RIVADAVIA/General Moscón Aerodrome	No PAPI at runway 07, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide PAPI for runway 07, as it is recommended by the Regional ANP and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 143C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/BUENOS AYRES/San Fernando Aerodrome	No simple approach lighting system in RWYs 05 y 23 as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Comply with the requirements of the Regional ANP and/or inform the SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 144C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/BUENOS AYRES/San Fernando Aerodrome	No PAPIs in RWYs 05 y 23, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide PAPIs for RWYs 05 y 23 and/or inform the SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 146C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/CATARATAS DEL IGUAZU/My. Carlos Eduardo Krause Aerodrome	No PAPIs in RWYs 13 and 31, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPIs for RWYs 13 and 31 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 150C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/COMODORO RIVADAVIA/General Moscón Aerodrome	No precision approach Category I lighting system at RWY 25, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 25 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 154C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/CORDOBA/Ing. Aer. Taravella Aerodrome	There is no PAPI at RWY 18, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPI at RWY 18 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 157C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/FORMOSA	No PAPIs at runways 03 and 21, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPIs at RWYs 03 and 21 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 161C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/JUJUY/Gobernador Guzmán Aerodrome	No simple approach lighting system at RWY 15, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide simple approach lighting system at RWY 15 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 162C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/JUJUY/Gobernador Guzmán Aerodrome	No PAPI at RWY 15, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPI at RWY 15 and/or inform to ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 165 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/MAR DEL PLATA/Gral. B. Colina Aerodrome	No precision approach Category I lighting system at RWY 13, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 13 and/or inform the ICAO SAM office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 167 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/MENDOZA/EI Plumerillo Aerodrome	No simple approach lighting system at RWY 18, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide simple approach lighting system at RWY 18 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 168 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/MENDOZA/EI Plumerillo Aerodrome	No precision approach Category I lighting system at RWY 36, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category lighting system at RWY 36 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 171 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/NEUQUEN/Presidente Perón	No precision approach Category I lighting system at RWY 08, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 08 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 174 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/POSADAS/Libertad or Gral. D. José de San Martín Aerodrome	No PAPI at RWY 01, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPI at RWY 01 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 176 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/POSADAS/Libertad or Gral. D. José de San Martín Aerodrome	No precision approach Category I lighting system at RWY 19, as recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 19 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 177 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/POSADAS/Libertad or Gral. D. José de San Martín Aerodrome	No RWY touchdown zone marking on RWY 19, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide RWY touchdown zone marking on RWY 19 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 180 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/RESISTENCIA/Resistencia Aerodrome	No PAPIs at RWYs 03 and 21, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPIs at RWYs 03 and 21 and inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 182 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/RESISTENCIA/Resistencia Aerodrome	No precision approach Category I lighting system at RWY 21, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 21 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 185 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/RÍO GALLEGOS/Piloto Civil N. Fernández Aerodrome	No PAPI at RWY 07, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPI at RWY 07 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 187 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/RÍO GALLEGOS/Piloto Civil N. Fernández Aerodrome	No precision approach Category I lighting system at RWY 25, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 25 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 190 C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/RÍO GRANDE/Río Grande Aerodrome	No PAPIs at RWYs 07 and 25, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPIs en las pistas 07 and 25 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 194C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/RÍO GRANDE/Río Grande Aerodrome	No touchdown zone marking at RWY 25, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide touchdown zone marking at RWY 25 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 197C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/ROSARIO/Rosario Aerodrome	No PAPI at RWY 01, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPI at RWY 01 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 199C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/ROSARIO/Rosario Aerodrome	No precision approach Category I lighting system at RWY 19, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 19 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 204C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/SALTA/Salta Aerodrome	No PAPI at RWY 01, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPI at RWY 01 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 208C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/SAN CARLOS DE BARILOCHE/San Carlos de Bariloche Aerodrome	No PAPI at RWY 11, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install PAPI at RWY 11 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 209C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/SAN CARLOS DE BARILOCHE/San Carlos de Bariloche Aerodrome	No precision approach Category I lighting system at RWY 11, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system for RWY 11 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 214C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/TUCUMAN/Tte. Benjamin Matienzo Aerodrome	No PAPI at RWY 19, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install a PAPI at RWY 19 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 215C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/USHUAIA/Malvina Argentinas Aerodrome	No PAPI at RWY 07, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install a PAPI at RWY 07 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 216C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5)	Argentina/USHUAIA/Malvina Argentinas Aerodrome	No precision approach Category I lighting system at RWY 25, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 25 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 186C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5.3.3)	Argentina/RÍO GALLEGOS/Piloto Civil N. Fernández Aerodrome	No aerodrome beacon, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Instal an aerodrome beacon and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 191C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch. 5.3.3)	Argentina/RÍO GRANDE/Río Grande Aerodrome	No aerodrome beacon, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Install aerodrome beacon and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B
AGA 158C	Visual aids (Doc 8733, Vol. II, FASID and Annex 14, Vol. I, Ch.5)	Argentina/FORMOSA	No precision approach Category I lighting system at RWY 21, as it is recommended by the Regional ANP	4-6 DEC 2002	Detected during mission conducted by ICAO Secretariat	Provide precision approach Category I lighting system at RWY 21 and/or inform the ICAO SAM Office when it will be done "PENDING ACTION PLAN"	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS 35 C	Doc 8733 ANP, Part VI, Chapter 10, Para. 10.4.	Argentina	Lack of use of English for plain language texts.	18/09/96	Records and files in SAM Regional Office. GREPECAS reports.	Need of use of English for plain language texts.	Indicated State.	sooner	A
AIS 81 C	Doc 8733 ANP, Part VI, Para. 11.1, 11.5.	Argentina	Non production of Aerodrome Obstacle Chart - ICAO Type C.	06/01/94	Records and files in SAM Regional Office. GREPECAS and AIS/SG reports.	Need for production of aeronautical charts of this series.	Indicated State	soonest	A
AIS 60 C	ICAO Annex 4, Chapters 16 and 17.	Argentina	Production of the world aeronautical charts and/or VFR chart, scale 1:500,000 - with non ICAO specification (PAIGH).	06/01/94	Records and files in SAM Regional Office. GREPECAS and AIS/SG reports.	Need for production of aeronautical charts according to the ICAO specifications.	Indicated State.	soonest	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action

ATM

ATM	1 C	English proficiency in Air Traffic Services, CAR/SAM/3 Rec. 5/35	Argentina	The proficiency in the English language of some ATC units is below the desired level and could be a contributory factor for the occurrence of incidents and/or aeronautical accidents.	Oct/1995	a) After the effective date of Amendment to Annex 1, which establishes that the English level required for ATC personnel, the States/Territories/International Organizations, should evaluate the personnel of their ATC units and further provide information regarding the deviation level required in the box "Remarks". b) In order to reach and maintain the English language level required, the States/Territories/International Organizations shall establish a permanent and continuous training plan of ATC units, which contemplates the follow-up of the improvements of personnel of ATC units and shall implement in the same, the ATS quality assurance programme. c) The States/Territories/International Organizations shall demand the personnel who works in ATC units, the English language knowledge to be required by ICAO Annex 1.	A continuous English language training plan is being implemented for air traffic controllers. The following measures have been taken: 1) Incorporate personnel with a good level of colloquial English. 2) Incorporation of a CTA course, 1 month intensive colloquial English in a language center. 3) Implementation of a Training, Improvement of the English language for ATCOs (PCPIIC).	CRA Argentina	2003	U
-----	-----	--	-----------	--	----------	---	---	---------------	------	---

ATM	12C	Use of the aeronautical phraseology	Argentina	In general, the use of aeronautical phraseology in Spanish and English does not meet the required levels and it is a relevant factor with regard to ATS incidents	Sep/2000	Continuous training and supervision in the use of aeronautical phraseology is required.	The Argentinean Administration emphasized training to air traffic controllers on the correct use of ICAO aeronautical phraseology. The verification of a correct use was initiated through tapes listening, and also a high level of non-compliance by crews was also detected. A Training, Improvement and Continuous Updating Plan (PCPAC) has been implemented	CRA Argentina	2003	U
-----	-----	-------------------------------------	-----------	---	----------	---	---	---------------	------	---

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
CNS 11 C	Aeronautical Mobile Service Plan. Table CNS 1A. Lack of HF communicaitons coverage in the Ezeiza FIR, Oceanic Sector	Argentina	Deficiencies in the HF communications have been identified in the oceanic part of the Ezeiza FIR.	09/1994	GREPECAS/4. IATA Report.	A COMPLETE UPDATING OF EZEIZA HF EQUIPMENT WAS MADE IN OCTOBER 1999. A NEW POSITION WAS INCORPORATED IN THE ACC OF EZEIZA TO CONTROL THE ATLANTIC SECTOR.	Argentina CAA	12/02	U
CNS 3 C	AFTN circuits Buenos Aires (M) - Johannesburg (M)	Argentina	This circuit is not yet implemented	05/1989	CAR/SAM/2 RAN Meeting	FUTURE BILATERAL AGREEMENT FOR THE IMPLEMENTANTION OF THIS AFTN CIRCUIT.	Argentina and South Africa	TBD	A
CNS 9 C	ATS speech circuits plan. Table CNS 1C. Ezeiza ACC/Johannesburg ACC	Argentina	This circuit was not yet implemented. Its implementation was planned as part of the ATS speech switched network using the Ezeiza ATS voice switch so as to meet requirements with the ACCs of Ezeiza, Johannesburg, Montevideo and Brasilia	05/1989	CAR/SAM/2 RAN Meeting	A DDI CIRCUIT WAS ESTABLISHED SINCE 17/05/01 SUCH AS SPECIFIED IN TABLE CNS 1C OF THE FASID. IN THE NEXT FUTURE A DEDICATED LINE WILL BE INSTALLED	Corresponding CAAs	TBD	A
CNS 27 C	Radio Navigation Service Plan. Table CNS 3. DME	Argentina, Rio Grande	This DME is not implemented	05/1989	This facility was recommended to be associated with a VOR for en route and terminal navigation to support several air routes. The VOR station is oeprating at the significant point	Argentina shall inform on plans to implement this DME WAITING BUDGER ASSIGNATION	Argentina	TBD	B

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE REGION SAM - Argentina

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
MET									
MET 29C	Adequate number of MET trained staff	Argentina	There are requirements of specialized meteorology personnel in the aeronautica meteorology field and of an increase of the number of aeronautical meteorologists	22/06/96	To use CAR/SAM technical cooperation regional projects for the training in aeronautical meteorology	To make every effort to have the adequate number of aeronautical meteorologists. Starting 2000 a fellowship plan was implemented for the training of MET personnel and was concluded at the end of 2002, including courses on aeronautical operational meteorology and use of satellite images, with which, by the end of 2002, the provision of AMO and MWO at national level will be completed. There are no problems at MET stations.	Indicated State	TBD	A
MET 53C	CAR/SAM ANP MET Requirements, Table AOP 1	Argentina	All RVR have not been implemented	22/06/96	Installation of all RVR is foreseen for the following five years.	To ensure the implementation of all required RVR	State	TBD	U
MET 24C	CAR/SAM ANP requirements, Part VI, para. 6 and Annex 3 provision, Chapter 7, para. 7.2.1	Argentina	There is no follow-up on local procedures for issuance of SIGMETs	22/05/96	MWOs should review the local procedures for the issuance of SIGMETs and for the control of its issuance on a periodical basis	Ensure the correct preparation of SIGMETs and their dissemination, in accordance with Table MET 2A requirements	State	04/03	U