# Chet Collett – Director Flight Ops Engineering Alaska Airlines



FLIGHT OPS ENGINEERING

Alaşka Airlineş.


### **Agenda**

- Runway Condition Assessment Matrix (RCAM) TALPA ARC Back Ground
- Fido ICE
- Wet Runway Reporting
- RCAM / Vertical and Horizontal
- SRM On the risks of landing on short runways in Moderate or Heavy Rain
- TAKEOFF RCAM
- Questions



Alaska Airlines operates into some of the most challenging airports in the world.

Alaska Airlines has been using the TALPA ARC Matrix for the Pilot in flight analysis since 2006 – 2007 winter season.





## The Original RCAM – Published by Alaska Airlines in Jan 2007

BF	RAKING ACTION	APPROXIMATE COR	RELATI	ONS
TERM	DEFINITION	RUNWAY SURFACE CONDITION	IC	AO
			CODE	MU
GOOD	Braking deceleration is normal for the wheel braking effort applied. Directional control is normal.	Water depth of 1/8" or less     Dry snow less than 3/4" depth     Compacted snow with OAT at or below -15°C	5	40 & ABOVE
GOOD TO MEDIUM			4	39 - 36
MEDIUM (FAIR)	Braking deceleration is noticeably reduced for the wheel braking effort applied. Directional control may be slightly reduced.	Dry snow 3/4" or greater in depth     Sanded snow     Sanded ice     Compacted snow with OAT above -15°C	3	35 - 30
MEDIUM TO POOR			2	29 - 26
POOR	Braking deceleration is significantly reduced for the wheel braking effort applied. Potential for hydroplaning exists. Directional control may be significantly reduced.	Wet snow Slush Water depth more than 1/8" Ice (not melting)	1	25 - 21
NIL	Braking deceleration is minimal to non-existent for the wheel braking effort applied. Directional control may be uncertain.	• Ice (melting) • Wet Ice		20 & BELOW
Note: Taxi, t	akeoff, and landing operation	s are prohibited in Nil condition	is.	

CUD (Can U lanD?)

The decision process to land Alaska Airlines jets can be very confusing. This landing flowchart is presented for the benefit of Anchorage line pilots and is to be provided for each pilot. If ever there is a doubt about landing, sit back, ruminate, and chew your CUD.





### **Runway Surface Condition Reporting**


#### TALPA ARC Recommendation:

- Use Runway Surface Condition Matrix Report and Pilot BA to best describe the conditions.
- Improvements to address known deficiencies
- Beta test proposed method
  - First Winter 2009 10
  - Completed Winter 2010-11
- Changes to the Final TALPA ARC Matrix completed Summer 2011

### **RWYCC** for ICE

- Alaska Airlines was one of the lone voices on the TALPA ARC for ICE
  - How do you upgrade a Poor or NIL (RWYCC 1 or 0) without Mu?
  - If upgraded, what can it be upgraded to?
- ICE upgrade (after validation testing) was a compromise
  - Mu Values 40 or greater
  - Continuous monitoring
  - Highest Upgrade possible was RWYCC 3

### **An Example of our Experience**



### An Example of our Experience

UTC


CDV 01/265 Aerodrome 01/14/2019 2346 01/15/2019 2346 RWY 09 FICON 3/3/3 30 PCT ICE SANDED 80FT WID AND DEICED SOLID 80FT WID OBS AT 1901142346. (1546 PST)

CDV 01/266 Aerodrome 01/14/2019 2348 01/15/2019 2348 APRON ALL FICON PATCHY ICE OBS AT 1901142348. 1901142348-1901152348

CDV 01/260 Aerodrome 01/14/2019 2037 01/15/2019 2037 RWY 09 FICON 3/3/3 100 PCT ICE SANDED 80FT WID AND DEICED SOLID 80FT WID OBS AT 1901142037. (1237 PST)

CDV 01/255 Aerodrome 01/14/2019 1842 01/15/2019 1842 RWY 09 FICON 3/3/3 100 PCT ICE SANDED 80FT WID AND DEICED SOLID 80FT WID OBS AT 1901141842. (1042 PST)

CDV 01/256 Aerodrome 01/14/2019 1842 01/15/2019 1842 TWY B, D FICON ICE OBS AT 1901141842. 1901141842-1901151842




### **An Example of our Experience**

Pilot Report: PST

AS	61	622AS	01/14/2019	01/14/2019 13:16:55	FLT SUMMARY	QU SEADLAS .DDLXCXA 142116 A80 FI AS61/AN N622AS DT DDL CDV 142116 M17A - 3501 SUMMRY 0061/14 PAJN/PACV .N622AS /OUT 1949/FOB 0178 /OFF 2008/FOB 0174 /ON 2108/FOB 0126 /IN 2113/FOB 0124 /TKO F.O. /CRW 25475 /LND F.O. /CRW 25475 /CPT 23961 /FO 25475 /CHK /HGST 3/RNPD Y N /AIII 3/RNPA Y N /ELEC N/BA 5/RWY 27
AS	7098	625AS	01/14/2019	01/14/2019 15:59:05	FLT SUMMARY	QU SEADLAS .DDLXCXA 142359 A80 FI AS7098/AN N625AS DT DDL CDV 142359 M65A - 3501 SUMMRY 7098/14 PANC/PACV .N625AS /OUT 2311/FOB 0220 /OFF 2322/FOB 0220 /ON 2353/FOB 0188 /IN 2357/FOB 0184 /TKO F.O. /CRW 20917 /LND F.O. /CRW 20917 /CPT 91822 /FO 20917 /CHK /HGST 3/RNPD N 3 /AIII 3/RNPA Y N /ELEC N/BA 5/RWY 27
AS	66	622AS	01/14/2019	01/14/2019 17:03:15	FLT SUMMARY	QU SEADLAS .DDLXCXA 150103 A80 FI AS66/AN N622AS DT DDL CDV 150103 M55A - 3501 SUMMRY 0066/15 PANC/PACV .N622AS /OUT 0003/FOB 0261 /OFF 0021/FOB 0263 /ON 0057/FOB 0231 /IN 0102/FOB 0226 /TKO CAPT /CRW 31762 /LND CAPT /CRW 31762 /CPT 31762 /FO 82935 /CHK /HGST N/RNPD N 3 /AIII N/RNPA Y N /ELEC Y/BA /RWY 27

### **Aviation Safety Technology (AST)**




### **Aviation Safety Technology (AST)**


PST

PACV 01/14/2019 15:57:29 27

View

Airport Landing Detail Data





### **TALPA RCAM after Validation**

	Airport Runway Condition Assess		(PIREPs	Reports ) Provided		
	Assessment Criteria	A		Downgrade essment Criteria	To ATC Dis	And Flight patch
Code	Runway Condition Description		lu ) <sup>1</sup>	Deceleration Directional Co Observation	ontrol	PIREP
6	• Dry			-		Dry
5	Wet (Includes water 1/8" or less and Damp) Frost  1/8" or less depth of: Slush Dry Snow Wet Snow  Wet Snow		40 or Higher	Braking deceler normal for the whe effort applied. Din control is nor	el braking rectional	Good
4	-15°C and Colder outside air temperature: • Compacted Snow	39		Brake decelerat controllability is t Good and Me	etween	Good to Medium
3	Wet ("Slippery when wet" runway) Dry Snow or Wet Snow (Any Depth) over Compacted Snow Orester than 1/8" depth of: Ory Snow Wet Snow Warmer than -15°C outside air temperature: Compacted Snow	to 30		Braking deceler noticeably reduce wheel braking effo Directional contro noticeably red	d for the rt applied. I may be	Medium
2	Greater than 1/8" depth of:  • Water  • Slush		29 to	Brake decelerat controllability is to Medium and Poor, for hydroplaning	etween Potential	Medium to Poor
1	• Ice <sup>2</sup>	21	21	Braking deceler significantly reduc wheel braking effo Directional contro significantly red	ed for the rt applied. I may be	Poor
0	Wet Ice <sup>2</sup> Water on top of Compacted Snow <sup>2</sup> Dry Snow or Wet Snow over Ice <sup>2</sup>	20 or Lower		Braking deceler minimal to non-ex the wheel brakin applied. Direction may be uncer	istent for ig effort al control	Nil

**Contaminants not on the RCAM** 



### **RCAM – Vertical**

Table 5-2. Runway Condition Assessment Matrix (RCAM) (for Airport Operators' Use Only)

Assessment Criteria			D	owngrade Assessment Crite	ria
Runway Condition Description	Code	Mu (	[μ) <sup>1</sup>	Vehicle Deceleration or Directional Control Observation	Pilot Reported Braking Action
• Dry	6				
Frost Wet (Includes Damp and 1/8 inch depth or less of water)  1/8 inch (3mm) depth or less of: Slush Dry Snow Wet Snow	5		40 or Higher	Braking deceleration is normal for the wheel braking effort applied AND directional control is normal.	Good
5° F (-15°C) and Colder outside air temperature • Compacted Snow	4	39	Ш	Braking deceleration OR directional control is between Good and Medium.	Good to Medium
Slippery When Wet (wet runway) Dry Snow or Wet Snow (Any depth) over Compacted Snow Greater than 1/8 in.ch (3mm) depth of: Dry Snow Wet Snow Warmer than 5° F (-15°C) outside air temperature Compacted Snow	3	to 30	П	Braking deceleration is noticeably reduced for the wheel braking effort applied OR directional control is noticeably reduced.	Medium
Greater than 1/8 (3mm) inch depth of:  • Water  • Slush	2	Ш	29	Braking deceleration OR directional control is between Medium and Poor.	Medium to Poor
• Ice <sup>1</sup>	1		to 21	Braking deceleration is significantly reduced for the wheel braking effort applied OR directional control is significantly reduced.	Poor
Wet Ice <sup>2</sup> Sush over Ice Water over Compacted Snow <sup>2</sup> Dry Snow or Wet Snow over Ice <sup>2</sup>	0	20 or Lower		Braking deceleration is minimal to non-existent for the wheel braking effort applied OR directional control is uncertain.	Nil

### **RCAM** – Horizontal

	Dry	(Inclu	Wet ides water 1/8" or ss and Damp)						Cont	aminant			
Type	N/A	Any Slippery When Wet		Frost	Standing Water or Slush			t Snow or Compacted Snow ry Snow (May include imbedded Ice)				Ice 1	Wet Ice <sup>1</sup> Water Over Compacted Snow <sup>1</sup> Dry or Wet Snow Over Ice <sup>1</sup>
Depth	N/A	N/A		N/A	N/A 1/8" or less Greater than 1/8" or less 1/8" or less 1/8" Any 1/8"		Any	Any	Any	Any			
NOTES		Silppery When Wet used to Indicate excess rubber deposits in touchdown zones.			For Standing Water 1/8" or less report as WET				OAT -15°C or Colder				Taxi, takeoff, and landing operations in Nil conditions are prohibited.
RWYCC	6	5	3	5	5	2	5	3	4	3	3	1	0

In some circumstances, these runway surface conditions may not be at slippery at the runway condition code essigned by the Matrix. The airport operator may issue a higher runway condition code (but no higher than code 3) if Mu values 40 or greater are obtained on all three third of the runway by a properly operated and calibrated friction measuring device and all other observations, judgment, and vehicle braking action support the higher runway condition code. The decision to issue a higher runway condition code than would be called for by the Matrix cannot be based on Mu values alone; all available means of assessing runway slipperiness must be used and must support the higher runway condition code. This ability to raise the reported runway condition code to a code 3 can only be appoiled to those runway condition codition is the durative.

The airport operator must also continually monitor the runway surface as long as the higher code is in effect to ensure that the runway surface condition does not deteriorate below the assigned code. The extent of monitoring must consider all variables that may affect the runway surface condition, including any precipitation conditions, changing temperatures, affects of wind, frequency of runway use, and type of aircraft using the runway. If sand or other approved runway treatments are used to satisfy the requirements for issuing this higher runway condition code, the continued monitoring program must confirm continued effectiveness of the treatment.

Caution: Temperatures near and above freezing (e.g., at -3°C and warmer) may cause contaminants to behave more slippery than indicated by the runway condition code given in the Matrix. At these temperatures, airport operators should exercise a heightened level of runway assessment, and should downgrade the runway condition code if appropriate.

	Downgrade Assessment Criteria (Mu), Pilot Braking Action Descriptors														
RWYCC from ABOVE	6	5	4	3	2		1	0							
Mu (μ) <sup>2</sup>	4	0 or higher			29		- 21								
Mu (μ)			39	-	30			20 or lower							
Deceleration & Directional Control Observation	Braking deceleration is normal for the wheel braking effor applied. Directional control is normal.		Brake deceleration and controllability is between Good and Medium.	Braking deceleration is noticeably reduced for the wheel braking effort applied. Directional control may be slightly reduced.	Brake decelera between Mediu Poor. Potenti hydroplaning e	ım and al for	Braking deceleration is significantly reduced for the wheel braking effort applied. Directional control may be significantly reduced.	Braking deceleration is minimal to non-existent for the wheel braking effort applied. Directional control may be uncertain.							
PIREP	Dry	Good	Good to Medium	Medium	Medium to Poor		Poor	Nil							

<sup>2</sup>The correlation of the Mu (µ) values with runway conditions and condition codes in the Matrix are only approximate ranges for a generic friction measuring device and are interheded to be used only to downgrade a runnway condition code. Airport operators should use their best judgment when using friction measuring devices for downgrade assessments, including their experience with the specific measuring devices used educes to a constant of the control of the control

### AC 150-5200-30D Errata

- Required WET Runway Reporting
- October 1, 2016 was the implementation date

## **Wet Runway Reporting**

1.12.23 Wet Runway.

A runway is wet when it is neither dry nor contaminated. For purposes of condition reporting and airplane performance, a runway can be considered wet when more than 25 percent of the runway surface area within the reported length and the width being used is covered by any visible dampness or water that is 1/8-inch or less in depth.

Note: A significant change to condition reporting includes the requirement and ability to report '*Wet' when visible dampness*, or water that is 1/8-inch (3.3 mm) or less in depth exists on any surface (runways, taxiways, aprons, holding bays). This change is largely due to the airplane performance differences that exist between wet, dry, or runways with water greater than 1/8-inch (3.3 mm) in depth.

#### AC 150-5200-30D Errata

# Then on September 30, 2016 . . . FAA Published CertAlert 16-06

3. Guidance Change. The FAA will change Advisory Circular 150/5200-30D, Airport Field Condition Assessments and Winter Operations Safety, to remove the current requirement to report runway "wet" conditions (1/8<sup>th</sup> inch or less of water) when it is the only contaminant present. Instead, because of the impact on performance of some aircraft, the FAA will hiehly encourage airports to report "wet" conditions (1/8<sup>th</sup> inch or less of water) when it is the only condition present on the runway.

### Wet Runway Reporting

- 28 days after the FAA made WET runway Reporting optional
- Moderate to Heavy rain at LGA with NO FICON
- Could a 5/5/5 100% WET FICON have alerted the flight crew?

BREAKING NEWS



PENCE'S PLANE SKIDS OFF RUNWAY

## **Standing Water - Depth**

- 1/8" or less Code 5 Good BA (Wet Runway)
- Greater than 1/8" Code 2 Medium to Poor BA
  - Risk of hydroplaning

But How Does Rainfall Intensity

Effect the Potential for Standing

Water?

## **Operations in Heavy Rain**

- Alaska Airlines prohibits operation in Heavy Rain (+RN) if it is in conjunction with Convective Activity
- But there are times of Heavy Rain without Convective Activity that had us concerned.

# SRM – Landing on Short Runways in Heavy Rain

Determined that the risk was a Level 3

• If the runway actually has water greater than 1/8 Inch, the use of "Wet" runway will overestimate the braking effectiveness the aircraft will encounter. On a short runway, this could lead to a runway overrun.

### **Grooved vs Un-Grooved**

- Heavy Rain (+RN) It doesn't matter if the runway is grooved or not. Assume 1/8" or greater unless better information is available.
- Moderate Rain (RN)
  - If the runway is Grooved, use Code 5 Good data.
  - If the runway is Un-Grooved, assume Code 2
     Medium to Poor

# SRM – Landing on Short Runways in Heavy Rain Mitigation

 Direct Pilots to use Degraded Braking Action Landing Data (15% additional safety margin) when Rainfall intensity is Moderate (RN) or Heavy (+RN)

### **Definition of Standing Water**

Water depths sufficient to rise above the micro texture depth of the runway grooving or PFC overlay. In conditions of steady rain, the depth of standing water on a runway may be a function of the rainfall intensity. In the absence of a current FICON Report/PIREP or the ability to visually assess the runway condition (takeoff), assume standing water depths of more than 1/8 inch when rainfall intensity is moderate on an ungrooved runway, or if the rainfall intensity is heavy.

#### Landing RCAM

#### LANDING RUNWAY CONDITION ASSESSMENT MATRIX (RCAM)

		Dry		Wet :ludes water less and Damp)						Contam	inant			
т	ype	N/A	when wet		Frost	Standing 1	Water or Slush		Snow or y Snow	(May include		Dry or Wet Snow Over Compacted Snow	Ice <sup>1</sup>	Wet Ice <sup>1</sup> Water Over Compacted Snow <sup>1</sup> Dry or Wet Snow Over Ice <sup>1</sup>
De	epth	N/A	A 1/8" or less		N/A	1/8" or less	Greater than 1/8"	1/8" or less	Greater than 1/8"	Any	Any Any		Any	Any
N	otes		Slippery When Wet used to indicate excess rubber deposits in touchdown zones.			May include moderate rainfall intensity.	Includes moderate rainfall intensity on smooth runways or heavy rainfall intensity. <sup>2</sup>			OAT-15°C or Colder	OAT Warmer than -15°C			Takeoff and landing operations in NIL conditions are prohibited.
RV	VYCC	6	5 (GOOD)	3 (MEDIUM)	5 (GOOD)	5 (GOOD)	2 (MED to POOR)	5 (GOOD)	(MEDIUM)	4 (GOOD to MED)	(MEDIUM)	(MEDIUM)	1 (POOR)	0 (NIL)

The Runway Codes of 1 or 0 may be upgraded to Code 3 by airport operator if conditions warrant. A current FICON Report/PIREP can upgrade the Rwy Condition Code in Moderate or Heavy Rain.

#### CAUTION!

Temperatures near and above freezing (e.g., at -3°C and warmer) may cause contaminants to behave more slippery than indicated by the runway condition code given in the Runway Surface Condition Report Assessment Table. At these temperatures, airport operators should exercise a heightened level of runway assessment, and should downgrade the runway condition code if appropriate.

		Pilot Brakii	ng Action Descrip	tors and Crosswind (	Component Limits		
Runway Condition Codes (RWYCC)	6	5	4	3	2	1	0
Deceleration & Directional Control Observation		Braking deceleration is normal for the wheel braking effort applied. Directional control is normal.	Brake deceleration and controllability is between GOOD and MEDIUM.	Braking deceleration is noticeably reduced for the wheel braking effort applied, or directional control is slightly reduced.	Brake deceleration is between MEDIUM and POOR. Potential for hydroplaning exists.	Braking deceleration is significantly reduced for the wheel braking effort applied, or directional control is significantly reduced.	Braking deceleration is minimal to non-existent for the wheel braking effort applied, or directional control is minimal to non-existent.
PIREP	Dry	GOOD	GOOD to MEDIUM	MEDIUM	MEDIUM to POOR	POOR	NIL
Landing Max Allowable Crosswind Component (Boeing)	Landing Max lowable Crosswind 40 kts (700) 4 Component 37 Kts (800 & 900) 37 kts		35 kts	25 kts	17 kts	15 kts	N/A

### **WET vs Standing Water – Effects of Rainfall Intensity**

Aircraft Performance differences are huge.

- DRY
- WET
- Standing Water Greater than 1/8 INCH

Standing Water or Slush									
1/8" or less	Greater than 1/8"								
May include moderate rainfall intensity.	Includes moderate rainfall intensity on smooth runways or heavy rainfall intensity. <sup>2</sup>								
5 (GOOD)	2 (MED to POOR)								

 $<sup>\</sup>frac{1}{2}$  The Runway Codes of 1 or 0 may be upgraded to Code 3 by airport operator if conditions warrant.

A current FICON Report/PIREP can upgrade the Rwy Condition Code in Moderate or Heavy Rain.


#### **Less Than 7000 Rules**

### If the runway is less than 7000 ft.

- If it is WET (Damp or more) Request Data based on RWYCC 5 – GOOD vs WET
- (Or) Less than Good Calculate Latest Touchdown Point (LTP)
- (And) Less than Good Use Max Auto-Brakes with Max Manual Braking until stopping is assured

### **ACARS Page for WET**







### Takeoff RCAM

#### TAKEOFF RUNWAY CONDITION ASSESSMENT MATRIX (RCAM) - (BOEING ONLY - AIRBUS SEE ORH OR AORG)

I	Туре	Dry	1	Wet (5/5/5)			Loos	e Co	n tamin ar	nts			Hard Packed Contaminants				
I	Contaminant		Water, Dry S	Wet Snow, now, Slush	Frost	Wet Snow , Standing Water , or Slush				Dry Sno	ow		Compacted Snow	npacted Snow I			
I	Depth		1/8	1/8" or less		orless N/A		> 1/8" > 1/4" to ≤ 1/4" to ≤ 1/2" 1		> 1/2"	> 1/8" > 1" " to ≤ 1" to ≤ 2"		> 2" to ≤ 4"	> 4"	Any	А	ny
	Notes			Slippery When Wet										See Not	e Below <sup>2</sup>		
	Takeoff Performance Level	DRY	WET	Medium (or PIREP value)	WET	> 1/8" to ≤ 1/4"	1/8" > 1/4" No ≤ 1/4" to ≤ 1/2" Ops				> 2" to ≤ 4"	No Ops	Medium² (or PIREP value)	Medium² (or PIREP value)	Poor		
	Crosswind Limit <sup>1</sup> (Boeing)	40 kts (400 & 700) 33 Kts (800 & 900)	25 kts	15 kts (400) 20 kts (NG)	25 kts	Wet Snow 15 kts (400) 20 kts (NG)	Water/Slush 7 kts (400) 15 kts (NG)			15 kts (400) 20 kts (NG)			15 kts (400) 20 kts (NG)	15 kts (400) 20 kts (NG)	7 kts (400) 13 kts (NG)		

Туре								La	yered (	ontamina	nts							
Contaminant	(	Dry Over Com	Snow pacted S	now						Wet Ice or Water Over Ice <sup>3</sup> Wet Snow Over Ice <sup>3</sup> Slush Over Ice <sup>3</sup> Water or Slush Over Compacted Snow <sup>3</sup>				Dry Snow Over Ice <sup>3</sup>				
Depth	≤ 1/8"	> 1/8" to ≤ 1"	> 1" to ≤ 2"	> 2" to ≤ 4"	> 4"	≤ 1/8"	> 1/8" to ≤ 1/4"	> 1/4" to ≤ 1/2"	> 1/2"	≤ 1/8"	> 1/8" to ≤ 1/4"	> 1/4" to ≤ 1/2"	> 1/2"	≤ 1/8"	> 1/8" to ≤ 1"	> 1" to ≤ 2"	> 2" to ≤ 4"	> 4"
Notes										See N				otes Below				
										No Ops³	No Ops <sup>3</sup>	No Ops <sup>3</sup>		No Ops <sup>3</sup>	No Ops³	No Ops <sup>3</sup>	No Ops <sup>3</sup>	
Takeoff Performance Level	Medium <sup>2</sup> (or PIREP value)	Dry Snow > 1/8" to ≤ 1"	Dry Snow > 1" to ≤ 2"	Dry Snow > 2" to ≤ 4"	No Ops	Medium <sup>2</sup> (or PIREP value)	Wet Snow > 1/8" to ≤ 1/4"	Wet Snow > 1/4" to ≤ 1/2"	OPI	(or PIREP	> 1/8"	or Wet Snow > 1/4" to ≤ 1/2"	No Ops	or Medium <sup>2</sup> (or PIREP value)	or Dry Snow > 1/8" to ≤ 1"	or Dry Snow > 1" to ≤ 2"	or Dry Snow > 2" to ≤ 4"	No Ops
Crosswind Limit <sup>1</sup> (Boeing)	15 kts (400) 20 kts (NG)					15 kts (400) 20 kts (NG)				See Note 1 Below			See Note 1 Below					

<sup>1</sup> Grosswind Limits are not enforced by Takeoff Performance Tools. If available, use PIREP values to determine actual crosswind limits. See applicable flight manual, Limitations, for crosswind limits.
2 If RWYCC allow operations, use the code provided (Code 3 = Medium, Code 2 or 1 = Poor).

PIREPS can be used to override No Ops conditions (allowing operations). Any PIREP that allows operation and contaminant depths greater than 1/8 inch, use the depth value to determine takeoff performance.

### IN CONCLUSION

- The TALPA RCAM is a fantastic tool that can be used by all concerned parties (Airports, Pilots, Dispatchers, ATC, Airplane Manufacturers etc.)
- The key to the success of the program is TRAINING. Unfortunately, the FAA failed to mandate Airport Training – choosing to rely on the Digital NOTAM System to control erroneous inputs.
- ICE upgrades should be allowed up to RWYCC 4 or 5. Our experience and data supports this.
- 1000 ft Air Run should be authorized provided the Airline has Training and a mitigation plan in place (like LTP)
- Factored Data is (and should be) required for Degraded Braking Action only! Non-Normal and Dry/Wet data should be allowed to be displayed UNFACTORED.

