



RASG-EUR Accident Investigation and ECCAIRS user Workshop

Review of 2018 accident data

ICAO EUR/NAT, Paris 8-10 April 2019







2018-01-01	Spain		AIRBUS A319	G-EZII	
During descent at FL210 to Barcelona airport, the aircraft suffered the effects of turbulence, falling one of the cabin crew member to the aisle breaking her right wrist.					
Phase of Flight:		Approach			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:		150			
Occurrence category		TURB			
Report		Interim			
Date of publication of Report		2018-01-29			





2018-01-03	Italy		AIRBUS A319	G-DBCA	
During the descent toward Verona The flight crew was informed about	• •		vere turbulence area.		
Phase of Flight:		En Route			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:					
Occurrence category		TURB			
Report					
Date of publication of Report					





2018-01-04	Finland	IAI 1125	OE-GKA

During pre-flight preparations the captain stated the APU so as to heat the cabin and to provide power for aircraft systems. When he went back out he closed the cabin door, pressurizing the cabin. When he opened the door, he was hit with excessive force was was fatally injured.

Phase of Flight:	Standing
Scheduled Commercial Ops:	FALSE
Fatalities:	1
Persons on board:	3
Occurrence category	RAMP
Report	Final
Date of publication of Report	2018-10-11





2018-01-10	Poland		DE HAVILLAND CANADA DHC-8	SP-EQG
Aircraft came to rest with the nose	e resting on the runv	vay after landing at V	Varszawa-Frédéric Chopin	n airport
Phase of Flight:		Landing		
Scheduled Commercial Ops:		TRUE		
Fatalities:		0		
Persons on board:		63		
Occurrence category		SCF-NP		
Report				
Date of publication of Report				





2018-01-13	Turkey		BOEING 737	TC-CPF	
Runway excursion after landing on runway 11 at Trabzon Airport,		on Airport, Turkey.			
Phase of Flight:		Landing			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:		168			
Occurrence category		RE			
Report					
Date of publication of Report					





2018-01-25	Germany		AIRBUS A320	VP-BKY	
Damage of the fuselage by a loadi	Schönefeld airport.				
Phase of Flight:		Standing			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:		108			
Occurrence category		RAMP			
Report					
Date of publication of Report					





2018-02-10	Spain	BOEING 737	EI-EKI
	Spani	DOLING 757	

The aircraft, which was in route in the Canaries airspace, requested to descend to flight level 130. The air control service authorized it to descend to the requested flight level, but when the aircraft was at flight level 364, it instructed it to stop at flight level 360. The aircraft descended below flight level 360 with the autopilot on and the pilot manually attempted to recover flight level 360. It was in this maneuver when the passenger fell and broke a leg.

Phase of Flight:	En Route
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	
Occurrence category	AMAN
Report	
Date of publication of Report	





2018-02-11 Russian Federation ANTONOV AN-148 RA-61704

Shortly after takeoff, at an altitude of about 1300 meters (4265 feet) and an instrument speed of 465-470 km/h, there were discrepancies between the air speed readings on the captain's side compared to the standby airspeed indicator. The flight crew disconnected the autopilot. The airspeed on the captain's side continued to decrease, while the standby ASI showed 540-560 km/h. The flight passed an altitude of 1700-1900 m (5580-6230 ft) with vertical loads ranging from 1.5 to 0.5 g. Subsequently the aircraft entered a steep descent with the ASI on the captain's side showing 0 km/h, and the standby ASI showing 200 km/h. The pitch angle decreased to -30/-35 degrees with a vertical load factor of 0 g. The aircraft impacted a snowy field and disintegrated.

Phase of Flight:	Climb
Scheduled Commercial Ops:	TRUE
Fatalities:	71
Persons on board:	71
Occurrence category	LOC-I
Report	Interim
Date of publication of Report	





2018-02-21	United Kingdom		CESSNA 208 CARAVAN	G-BZAH	
Nose landing gear drag link spring failed during a normal landing, Netheravon Airfield, Wiltshire					
Phase of Flight:		Landing			
Scheduled Commercial Ops:		FALSE			
Fatalities:		0			
Persons on board:		1			
Occurrence category		SCF-NP			
Report		Final			
Date of publication of Report		2018-07-12			





2018-02-28	Estonia	AIRBUS A320	ES-SAN
------------	---------	-------------	--------

(Training flight)

The engines touched the runway and the main landing gear doors broke.

The aircraft then managed to gain altitude and the pilots were able to stabilize the aircraft and turn back. Both engines, however, lost power after the turn back to the airport. An emergency landing was carried out at 17:11, about 150 meters from the runway. The aircraft came to a halt in the snow 15 meters south of the runway.

Phase of Flight:	Landing
Scheduled Commercial Ops:	FALSE
Fatalities:	0
Persons on board:	7
Occurrence category	ARC
Report	
Date of publication of Report	





2018-03-15	Russian Federation	ANTONOV AN-12B	11130

Improper loading of cargo led to cargo shift and partial failure of the rear cargo door during takeoff from Yakutsk Airport, Russia. Part of the cargo, consisting of gold concentrate ingots, fell onto the runway and the departure path, up to 26 km from the airport.

Phase of Flight:	Take-off
Scheduled Commercial Ops:	FALSE
Fatalities:	0
Persons on board:	
Occurrence category	RAMP
Report	
Date of publication of Report	





2018-03-16	France	PILATUS PC-6	F-BTCG
2010 00 10	Transc	1121103100	. 5.00

During a technical flight, the pilot observed that the rudder control was less effective. He advised the ATC that there was a yaw control failure and asked to land on unpaved runway 09 at Grenoble airport. While landing, a little before the flare out, the pilot lost control of the aeroplane. The aeroplane touched down heavily, performed a ground loop and came to rest on the paved runway.

Phase of Flight:	Landing
Scheduled Commercial Ops:	FALSE
Fatalities:	0
Persons on board:	2
Occurrence category	SCF-NP
Report	Final
Date of publication of Report	2019-02-25





2018-03-23	Hungary		BOEING 737	OK-TVP
During the push back procedure the aircraft was evacu		uated because of smo	ell of smoke. One passeng	er was seriously injured.
Phase of Flight:		Standing		
Scheduled Commercial Ops:		TRUE		
Fatalities:		0		
Persons on board:		166		
Occurrence category		EVAC		
Report				
Date of publication of Report				



2018-03-27

Occurrence category

Date of publication of Report

Report

NO COUNTRY LEFT BEHIND

G-EZMK

AIRBUS A319



During takeoff run several birds impacted the aircraft the takeoff and the aircraft stopped on the runway a	t engines. As a result of this, both engines stopped. The crew rejected t Murcia/San Javier airport.
Phase of Flight:	Take-off
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	130

BIRD

Spain





2018-03-28	Israel		BOEING 737	D-ABLB
Ground collision between a Germa for departure from Tel Aviv-Ben G		•	Al Boeing 767-300ER (4X-E	EAK) while on push back
Phase of Flight:		Taxi		
Scheduled Commercial Ops:		TRUE		
Fatalities:		0		
Persons on board:		127		
Occurrence category		GCOL		
Report				
Date of publication of Report				





2018-04-09	Norway		BEECHCRAFT SUPER KING AIR	LN-NOA
The aircraft came to rest on the belly 278 m after touc		hdown at Stavanger	airport Sola	
Phase of Flight:		Landing		
Scheduled Commercial Ops:		TRUE		
Fatalities:		0		
Persons on board:		2		
Occurrence category		ARC		
Report				
Date of publication of Report				





2018-04-16	France		CESSNA 525 CITATIONJET	D-ISWA		
The pilot said that during the land landing gear. The aeroplane veere	•		ort, there was a braking p	roblem on the left main		
Phase of Flight:		Landing	Landing			
Scheduled Commercial Ops:		FALSE				
Fatalities:		0				
Persons on board:						
Occurrence category		RE				
Report						
Date of publication of Report						





2018-04-17	United Kingdom	DE HAVILLAND CANADA DHC-8	G-JECX
------------	----------------	------------------------------	--------

On the second approach to Runway 12 of Newquay airport, the aircraft developed a high sink rate below 50 ft. The pilot flying reacted to the sink by increasing the pitch attitude, which resulted in the aircraft tail striking the runway before the main landing gear

Phase of Flight:	Landing
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	59
Occurrence category	ARC
Report	Final
Date of publication of Report	2018-11-08





2018-05-02	Morocco		BOEING 737	OO-JAY		
The aircraft struck its tail onto the	couchdown at Marral	kesh airport.				
Phase of Flight:		Landing	Landing			
Scheduled Commercial Ops:		TRUE				
Fatalities:		0				
Persons on board:		188				
Occurrence category		ARC				
Report						
Date of publication of Report						





2018-05-13	Turkey	AIRBUS A321	TC-JMM
Z010-03-13	luikey	AINDUS ASZI	I C-DIVIIVI

An Asiana Airlines Airbus A330-323 (HL7792) and a THY Turkish Airlines Airbus A321-231 (TC-JMM) suffered substantial damage in a ground contact accident at Istanbul-Atatürk International Airport, Turkey.

The Airbus A321 had arrived from Ercan as flight TK969 and turned towards the gate at Terminal A at 14:47 UTC. The aircraft stopped about 30 meters before the intended parking position at the gate.

At the same time the Airbus A330 had commenced taxiing along taxiway G to the runway. Flight OZ552 was returning to Seoul, South Korea. While taxiing past the A321, the right hand wing tip impacted the vertical stabilizer of TK969. The A321's vertical stabilizer was knocked over entirely and the A330's wing tip sustained serious damage.

Phase of Flight:

Scheduled Commercial Ops:

TRUE

Fatalities:

Occurrence category

GCOL

Report

Date of publication of Report





2018-05-13	Ireland	CESSNA 208 CARAVAN	G-KNYS
	ii ciaiia	CLOSITI LOG CITITITI	U 14111

The aircraft impacted bog and woodland terrain subsequent to a successful skydiving jump by 16 of the occupants onboard. The airplane sustained unreported damage and the two remaining occupants onboard received serious injuries.

The Cessna 208B Grand Caravan had departed Clonbullogue Aerodrome in Ireland about 14:13 hours local time. The skydivers were dropped at 14:32 an altitude of about 13,000 feet overhead the airfield.

Phase of Flight:	En Route
Scheduled Commercial Ops:	FALSE
Fatalities:	2
Persons on board:	2
Occurrence category	UNK
Report	Interim
Date of publication of Report	2019-06-11





2018-05-25	United Kingdom	NORTH AMERICAN MUSTANG P-51	N51BS
------------	----------------	--------------------------------	-------

As the aircraft moved for takeoff from Woodchurch Airfield, its wheels sank into the ground and it did not reach the desired speed for takeoff. At the end of the runway the pilot turned the aircraft to avoid a ditch. It struck a fence and came to rest approximately 180 m beyond the end of the runway.

Phase of Flight:	Take-off
Scheduled Commercial Ops:	FALSE
Fatalities:	0
Persons on board:	1
Occurrence category	RE
Report	Final
Date of publication of Report	2018-11-08





2018-06-10	Greece		BOEING 737	N276EA	
The aircraft bounced upon landing	t and experienced a t	ail strike causing damage	to the aircraft belly.		
Phase of Flight:		Landing			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:		173			
Occurrence category		ARC			
Report					
Date of publication of Report					





2018-06-11	United Kingdom	BRITTEN NORMAN BN- 2 ISLANDER	VP-FBM
		I Z ISLANDEN	

The aircraft touched down short of the undershoot area at Beaver Island airfield (Falkland Islands) causing significant damage to the right landing gear, wing and engine mounts. The accident was probably caused by a stall or unexpected descent due to turbulence or windshear under the prevailing conditions.

Phase of Flight:	Approach
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	3
Occurrence category	LOC-I
Report	
Date of publication of Report	





2019 06 14	Likusina	MCDONNELL DOUGLAS	LID CDD
2018-06-14	Ukraine	MD-83	UK-CPK

Bravo Airways flight 4406 from Antalya, Turkey, suffered a runway excursion after landing on runway 08 at Kiev's Igor Sikorsky International Airport, Ukraine. At the time of landing a thunderstorm was passing the airport with light rain and wind changing in direction at 19 knots, gusting to 33 knots.

Phase of Flight:	Landing
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	169
Occurrence category	RE
Report	
Date of publication of Report	





2018-06-26	United Kingdom		CESSNA 414	N414FZ
Collision with farm buildings durin	ig forced landing, Ens	stone Airfield, Oxford	dshire	
Phase of Flight:		Approach		
Scheduled Commercial Ops:		FALSE		
Fatalities:		0		
Persons on board:		2		
Occurrence category		LOC-I		
Report				
Date of publication of Report				





2018-06-27	Russian Federation		ANTONOV AN-2	RA-62524
An aircraft engaged in a forest fire had just departed Nizhneudinsk A	, ,	over during a forced	landing on an island in th	e Uda River. The aircraft
Phase of Flight:		Climb		
Scheduled Commercial Ops:		FALSE		
Fatalities:		0		
Persons on board:		4		
Occurrence category		SCF-PP		
Report				
Date of publication of Report				





2018-07-06	Morocco		ATR ATR72	CS-DJG		
Firm landing, during which the tail bumper contacted the ground and the belly scraped the runway when landing at Fez airport.						
The investigation was delegated to	o GPIAA (Portugal).					
Phase of Flight:		Landing				
Scheduled Commercial Ops:		TRUE				
Fatalities:		0				
Persons on board:		62				
Occurrence category		ARC				
Report		Interim				
Date of publication of Report		2018-07-23				





2018-07-16	United Kingdom	SUPERMARINE	G-ILDA
2010-07-10	United Kingdom	SPITFIRE	G-ILDA

The aircraft had landed on Runway 14 at Goodwood after completing a passenger flight. As the aircraft was slowing, the pilot became aware that it had started to deviate from the centre line towards the left side of the runway, which he attempted to gently correct by braking. As he did so the aircraft veered to the right, into wind. Despite the application of full left rudder and brake, the aircraft rotated through 90° and the left main landing gear collapsed.

Phase of Flight:	Landing
Scheduled Commercial Ops:	FALSE
Fatalities:	0
Persons on board:	2
Occurrence category	LOC-G
Report	Final
Date of publication of Report	2019-01-10





2018-07-26	Kazakhstan		BOEING 757	UP-B5705	
The aircraft suffered a tailstrike du	uring go-around at A	lmaty airport.			
Phase of Flight:		Landing			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:		245			
Occurrence category		ARC			
Report		Final			
Date of publication of Report		2018-11-27			





2018-07-27	France		PILATUS PC-6	F-GOCC	
In the fourth rotation, after the te with the jumper aeroplane which		ling two wearing win	gsuits had been dropped,	one of the latter collided	
Phase of Flight:		Maneuvering			
Scheduled Commercial Ops:		FALSE			
Fatalities:		1			
Persons on board:		11			
Occurrence category		OTHR			
Report					
Date of publication of Report					





2018-07-30	Russian Federation		ANTONOV AN-2	RA-40649
The aircraft crashed in the region	of the Krasnoyarsk Kr	rai.		
Phase of Flight:		Take-off		
Scheduled Commercial Ops:		FALSE		
Fatalities:		0		
Persons on board:		7		
Occurrence category		SCF-PP		
Report				
Date of publication of Report				





2018-08-04	Switzerland		JUNKERS JU-52	нв-нот
The aircraft impacted a mountain	nd.			
Phase of Flight:		En Route		
Scheduled Commercial Ops:		FALSE		
Fatalities:		20		
Persons on board:		20		
Occurrence category		UNK		
Report		Interim		
Date of publication of Report		2018-11-20		





2018-08-09	Turkey		BOEING 787	CN-RGT	
The aircraft struck the tail section right hand wing tip of the aircraft		•			
Phase of Flight:		Taxi			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:					
Occurrence category		GCOL			
Report					
Date of publication of Report					





2018-08-19	Germany	ANTONOV AN-2	D-FOJB

The right hand wings of the aircraft carrying skydivers caught fire during start-up of the engine at Gera-Leumnitz Airport, Germany. The occupants and pilot were able to evacuate and the fire was put out by fire services.

Phase of Flight:	Standing
Scheduled Commercial Ops:	FALSE
Fatalities:	0
Persons on board:	9
Occurrence category	F-NI
Report	Interim
Date of publication of Report	2019-02-14





2018-08-31	Bulgaria	CESSNA 680 CITATION SOVEREIGN	TC-OYD
------------	----------	----------------------------------	--------

Runway excursion upon landing at Bourgas airport

During the rollout a few seconds after the touchdown, the aircraft veered to the right from the centerline, hit a concrete block with aeronautical equipment and stopped at about 108 meters from the runway.

Phase of Flight:	Landing
Scheduled Commercial Ops:	FALSE
Fatalities:	0
Persons on board:	3
Occurrence category	RE
Report	
Date of publication of Report	





2018-09-01 Russian Federation BOI	BOEING 737	VQ-BJI
-----------------------------------	------------	--------

The aircraft suffered a runway excursion accident after landing at Adler/Sochi Airport, Russia. It went through a fence and came to rest on a dry and rocky surface in a river bed. Subsequent fire broke out, causing substantial damage to the aircarft.

Phase of Flight:	Landing
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	172
Occurrence category	RE
Report	
Date of publication of Report	





2018-09-16	Germany		BOEING 747	TC-ACM	
During landing, the A/C lost an inb	lamaged the fuselag	e.			
Phase of Flight:		Landing			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:		2			
Occurrence category		SCF-NP			
Report					
Date of publication of Report					





2018-10-10	Russian Federation	SUKHOI SUPERJET 100	RA-89011
------------	--------------------	---------------------	----------

The aircraft overran the runway upon landing at Yakutsk airport and went onto an area that was under reconstruction, stopping after 250 meters. This caused damage to the forward fuselage, separation of both main landing gear bogies and a fuel tank leak.

Phase of Flight:	Landing
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	92
Occurrence category	RE
Report	
Date of publication of Report	





2018-10-31	France		AIRBUS A330	N817NW	
The left winglet of N817NW dama at the holding point for runway 08		GZCI at a standstill on tax	iway RT1 behind an A320		
Phase of Flight:		Taxi			
Scheduled Commercial Ops:		TRUE			
Fatalities:		0			
Persons on board:					
Occurrence category		GCOL			
Report					
Date of publication of Report					





2018-11-08	Russian Federation	ANTONOV AN-2	RA-84674
------------	--------------------	--------------	----------

While en route at an altitude of 150 m, on distance of 50 km from the airport of Arkhangelsk, the plane got into icing conditions. The pilots decided to return to the departure aerodrome. The aircraft then lost engine power and a forced landing was made in a forest.

Phase of Flight:	En Route
Scheduled Commercial Ops:	TRUE
Fatalities:	0
Persons on board:	13
Occurrence category	LOC-I
Report	
Date of publication of Report	





2018-11-20	Russian Federation		BOEING 737	VP-BCG	
The aircraft hit a person during ta	The aircraft hit a person during takeoff from runway 24L at Moscow's Sheremetyevo Airport, Russia				
Phase of Flight:		Take-off			
Scheduled Commercial Ops:		TRUE			
Fatalities:		1			
Persons on board:					
Occurrence category		SEC			
Report					
Date of publication of Report					





2018-12-04	Greece		AIRBUS A320	SX-EMY
During disembarkation at Athens a	sustained damage in	the fuselage after collidir	ng with passenger stairs.	
Phase of Flight:		Standing		
Scheduled Commercial Ops:		TRUE		
Fatalities:		0		
Persons on board:		131		
Occurrence category		RAMP		
Report				
Date of publication of Report				





Thank you you for your attention Спасибо за внимание.