

# RADIO ALTIMETER INTERFERENCE IN APPROACH

ICAO Frequency Spectrum Management Panel (FSMP)  
Eleventh Working Group meeting (WG11)  
Web meeting: 1 – 12 March 2021

Agenda item 3: RadAlt and WAIC issues  
Information Paper 06 (IP06)

Josep Giné – ATR / Radio  $f(x)$



# Introduction




- **Context**
  - Erroneous Radio Altimeter indication when in approach on a regional aircraft fleet
  - Airworthiness certified Radio Altimeter
  - Finland (Helsinki), Estonia (Tallinn), Sweden (Visby)
- **Initial investigation**
  - **Radio Altimeter**
    - Checked equipment operational reliability with Radio Altimeter supplier
      - Stable removal rate on worldwide fleet along the last 5 years
      - No deviations to certified design found on repairs leading to an erroneous indication condition
  - **Factual analysis on 20 flight recorded occurrences**
    - Indication > true radioaltitude (positive bias)
    - Disturbance ^ shaped lasting ~ 4..6 s (typical at usual final approach speed)
    - Final approach (typically h < 1000 ft Above Ground Level (AGL))
    - Concentrated at very specific locations along the approach (deterministic pattern)
- **How are these disturbed radioaltimeter locations related to licenced radio sources ?**

# Identified radio sources along EETN 26 approach



## Location # 1 - P1

- Operator : Elisa
  - Bus parking (6, Lennuradari tee)
  - (59.413°N, 24.897°E)
- Mobile technology : 3G & 4G
- Bands : ( 800, 900, 2100 ) MHz



## Location # 2 - P2

- Operators : Telia & Tele2
  - Coop Logistikakeskus building
  - (59.416°N, 24.886°E)
- Mobile technology : 3G & 4G
- Bands : ( 800, 900, 1800, 2100 ) MHz



Mobile station & aeronautical radio sources : see details on Annex#2


Image credits: Location#1 : Google, Yandex  
Location#2 : Coop Logistikakeskus, Tasstuvenergia

# Location of radio sources along EETN 26 approach




# Typical occurrence @ EETN 26

median values (n=10 occurrences) → See full dataset on Annex#1




# Worst occurrence : dual pulse @ EETN 26

max values (n=10 occurrences) → See full dataset on Annex#1




# Systematic correlation occurrences ↔ mobile networks



# Concluding remarks



- **Facts**
  - All these occurrences are linked to licenced 3G/4G mobile networks stations close to final approach area
- **Causes**
  - Drastical spectrum usage changes since first airworthy radio altimeter specification (FAA TSO C87 dated 1966)
  - RF susceptibility when RadAlt is exposed to a crowded spectrum environment (> 2300 cases since 2017)
  - No interference mitigation strategies implemented around aerodromes (e.g.  $\Delta$ distance → interference isolation)
- **Mobile networks/5G/RadAlt coexistence considerations**
  - Need to improve awareness of these issues by Spectrum Management / National Aviation Authorities (NAAs)
    - 3G/4G/(5G) mobile network stations proliferation around aerodromes
    - Airworthiness certification of new RadAlt robust to 3G/4G/5G is long and costly (> 3 years dev + > 5 retrofit)
      - Approximately 1200 units of this same radio altimeter type are estimated in operation today
  - What could we do in the short & mid term horizon (next 2-3 years) for a better coexistence?
    - Aerodrome mitigation actions are necessary to protect RadAlt safety of life function
    - Interim France 5G policy implemented by DGAC FR & Spectrum Management (ANFR) authorities:
      - Safe area free of 5G stations (red) to protect RadAlt critical function from interference







## Annex#1

Detailed recorded data on  
Tallinn (EETN 26) occurrences



# Occurrence 20181129\_0848 (REC=455303.dat, A/C Registered XXXTK)





# Occurrence 20190319\_0792 (REC=471061.dat, A/C Registered XXXTJ)





# Occurrence 20190913\_0848 (REC=496517.dat, A/C Registered XXXTK)





# Occurrence 20191010\_0757 (REC=500398.dat, A/C Registered XXXTG)





# Occurrence 20191011\_0757 (REC=500411.dat, A/C Registered XXXTG)





# Occurrence 20191007\_0769 (REC=502163.dat, A/C Registered XXXTH)





# Occurrence 20191226\_0851 (REC=510769.dat, A/C Registered XXXTL)





# Occurrence 20191231\_0744 (REC=511398.dat, A/C Registered XXXTF)



# Occurrence 20200518\_0792 (REC=524444.dat, A/C Registered XXXTJ)



# Occurrence 20190402\_0741 (REC=472942.dat, A/C Registered XXXTE)





## Annex#2



Location of radio sources  
close to Tallinn (EETN 26) approach

# Tallinn aerodrome radio environment above 1GHz




- Exhaustive list (supported by the courtesy of Estonia Spectrum Management Authority <https://www.ttja.ee/>)
  - Surface Movement Radar @ 9 GHz
  - C band VSAT 4 km apart from aerodrome (uplink ~ 6 GHz, downlink ~ 4 GHz)
  - Enroute DME 59X (80 NM range @ FL500)
  - Approach DME CH20X or CH30X (25 NM range)
- High isolation to these sources (frequency & distance to occurrences) allows to discard them as the likely cause

# Telia mobile network




- Location : Coop Logistikakeskus building
- Frequency bands : 800 MHz (#20), 900 MHz (#8), 1800 MHz (#3), 2100 MHz (#1)

# Tele2 mobile network




- Location : Coop Logistikakeskus building
- Frequency bands : 800 MHz (#20), 2100 MHz (#1)

# Elisa mobile network



- Location : Bus parking
- Frequency bands : 800 MHz (#20), 900 MHz (#8), 2100 MHz (#1)

# Telia 5G mobile network (trial)



- Location : Tallinna Technikaülikool → ~ 10 km from Tallinn Airport → no impact on A/C
- Frequency bands : 1800 MHz (#3)



© ATR. All rights reserved. Confidential and proprietary document.

This document shall not be reproduced or disclosed to a third party without the written consent of ATR. This document and its content shall not be used for any purpose other than that for which it is supplied.

ATR, its logo, the distinctive ATR aircraft profiles and patented information relating to the ATR aircraft are the exclusive property of ATR and are subject to copyright. This document and all information contained herein are the sole property of ATR. No intellectual property right is granted through, or induced by, the delivery of this document or the disclosure of its content.

The statements made herein do not constitute an offer or a representation. They are based on the mentioned assumptions and are expressed in good faith.