

ICAO Action

The two safety recommendations (2004-84 and 85) address flight recorder issues which are related to the work programme of the ICAO Flight Recorder Panel (FLIRECP). Accordingly, both recommendations will be forwarded to the panel for their consideration. The next meeting for the FLIRECP is scheduled for the third quarter of 2006.