

## **Safety Recommendation (18/2009)**

The International Civil Aviation Organization (ICAO) should include in Annex 6, Parts II and III, or in Annex 10, Part III, that 406 MHz emergency locator transmitters (ELT) for aircraft must have an additional internal antenna, or that the external antenna is designed in a way that the emission of the emergency signal is ensured after an accident.