## **Safety Recommendation 2**

## To ICAO

Recommend your Flight Data Recovery Working Group<sup>1</sup> to deal with the following issues:

. .

2. Resolve problems facing when the ULB is buried under the sea floor consisting of thick mud and sand.

. . .

An international working group created to resolve technical problems about the recovery of recorders in the three following areas: flight data transmission; new flight recorder technology; and wreckage localization technology.