

Safety Recommendation

Consider the practicability of introducing additions to Standard 5.2.10.7 of ICAO Annex 14, Volume 1 Aerodrome Design and Operations (Edition 6, July 2013) in terms of marking the runway holding point at the runway/runway intersection even if there are no standard taxiing routes passing through the location.