Synopsis

Aircraft Type and Registration: Boeing B737-800, EI-CSZ

No. and Type of Engines: 2 x CFM 56 –7B

Aircraft Serial Number: 32780

Year of Manufacture: 16 July 2002

Date and Time (UTC): 13 September 2002 @ 14.30 hrs

Location: Charleroi Airport, Brussels South (CRL)

Belgium

Type of Flight:Scheduled Public TransportPersons on Board:Crew - 6 Passengers - 137Injuries:Crew - 1 Passengers - Nil

Nature of Damage: Nil

Commander's Licence: Irish ATPL

Commander's Age: Male, aged 57 years

Commander's Flying Experience: 19,500 hours of which 15,500 were on type

The aircraft departed Charleroi Airport on a scheduled flight to Stanstead, UK. Shortly after take off the First Officer noted that the Captain had leaned to one side and did not respond to prompting. Realising that the Captain was incapacitated the First Officer advised Brussels ATC that he had a pilot incapacitation problem and requested a return to the departure airfield, Charleroi. An Emergency was declared.

The No. 1 Cabin Crew Member (CCM) (1) was summoned to the cockpit and put a therapeutic oxygen mask on the unconscious Captain. It appeared that the Captain was lifeless. The aircraft returned immediately and landed safely at Charleroi. A husband and wife medical doctor team on board the aircraft attempted to revive the Captain. Eventually with the aid of the airport and Local Authority Emergency Services, the Captain responded to intensive revival efforts and was removed to hospital in a critical condition.

This Report makes three safety recommendations.