

Synopsis

Place :	Groningen Airport Eelde
Date and Time :	17 June 2003, 07:22 hours ²
Aircraft :	Boeing McDonnell Douglas MD 88
Operator :	Onur Air
Flight Crew :	2, no injuries
Cabin Crew :	5, one minor injury
Passengers :	142, a few minor injuries
Type of Flight :	Holiday charter
Phase of Flight :	Take-off
Type of accident :	Runway overrun after rejected take off above V1
Runway condition :	Dry

During take-off at a speed of approximately 130 knots the captain, who was the pilot flying, rejected the take-off above the decision speed because he experienced a heavy elevator control force at rotation. The stabilizer warning sounded during the entire take-off roll. The aircraft overran the runway end and came to a stop in the soft soil. During subsequent evacuation one cabin crew member and a few passengers sustained minor injuries. The aircraft sustained substantial damage. There was no fire.