

**DEFICIENCIES UPON WHICH ASB FOUND REQUIREMENT FOR REGION WIDE ACTION
REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AGA FIELD IN THE CAR/SAM REGIONS**

ASB/7
WP/03
APPENDIX B

Identification		Deficiencies			Corrective Action				ASB Action		
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Comp. date	P	ASB remedial action	Executing body	Results

AGA CAR/SAM

AGA 139 S	Airfield maintenance (Annex 14, Vol. I, Ch. 9.4)	This problem exists in both CAR and SAM Regions.	Deficiencies in pavements, lights, markings, signs, secondary power supply and fencing.	2001	ASB/2 Meeting	Establishment and implementation of airfield maintenance programmes "ACTION PLAN" 1. AGA/AOP/SG established a Task Force on Pavements. 2. ICAO held a seminar on Pavement Maintenance and a Short Course on the ACFT/PAV. Interaction in July 2002. 3. Latin America and Caribbean Association of Airfield Pavement was created in July 2002 during the seminar/short course held in Santa Cruz de la Sierra, Bolivia. 4. ICAO held a seminar on Pavement Management Systems & a Short Course on the PCI Method in November 2003. 5. Seminar on Pavement Design & a Short Course on Managing the Annex 14 is planned for 2004. 6. SIP (Seminar/Workshop/Short Course - NOV 07) - GREPECAS CONCLUSION 13/90	States	2007	U	1. AGA/AOP/SG established a Task Force on Pavements. 2. ICAO held a seminar on Pavement Maintenance and a Short Course on the ACFT/PAV. Interaction in July 2002 3. Latin America and Caribbean Association of Airfield Pavement was created in July 2002 during the seminar/short course held in Santa Cruz de la Sierra, Bolivia. 4. ICAO held a seminar on Pavement Management Systems & a Short Course on the PCI Method in November 2003. 5. Seminar on Pavement Design & a Short Course on Managing the Annex 14 is planned for 2004.	ICAO	No results
-----------	--	--	---	------	---------------	--	--------	------	---	---	------	------------

DEFICIENCIES UPON WHICH ASB FOUND REQUIREMENT FOR REGION WIDE ACTION
REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR/SAM REGIONS

Identification		Deficiencies			Corrective Action			ASB Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Comp. date	P	ASB remedial action	Executing body	Results

AIS CAR/SAM

AIS	309 C	Complete WGS-84 implementation	This problem exists in the CAR/SAM Regions	Lack of completion o the WGS-84 system implementation	1998	GREPECAS AIS/MAP/SG	Need to implement the WGS-84 Geodetic System	States	TBD	U	The AIS/MAP/SG Meeting should analyze the situation in order to implement the WGS-84 Geodetic System. ICAO to undertake a survey of States to update implementation status.	ICAO	Circular Letter requesting urgent correction
-----	-------	--------------------------------	--	---	------	---------------------	--	--------	-----	---	---	------	--