

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AGA FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA Antigua and Barbuda/Antigua y Barbuda									
AGA 97 C	Rescue and Fire Fighting (Annex 14, Vol. I, Chap. 9.2, 9.2.22 & 26)	Antigua and Barbuda, ST. JOHNS, V. C. Bird Intl	Access from rescue and fire-fighting services facilities to the runway is not the most direct	07/2001	ICAO Visit July 2001	Corrected	Antigua and Barbuda	2002	A
AGA Bahamas									
AGA 10 C	Runway Strip (Annex 14, Vol. I, Chap. 3.4, Rec. 3.4.6)	Bahamas, FREEPORT, Grand Bahama Intl	Runway strip contains objects and does not comply with Annex 14, Vol. I Section 3.3.6	10/2000	ICAO Visit October 2000	Corrected	Bahamas	May 2003	A
AGA Barbados									
AGA 159 C	Runway Strip (Annex 14, Vol. I, Chap. 3, 3.4 & 3.4.3)	Barbados, BRIDGETOWN, Grantley Adams Intl	Runway strip width is insufficient along southwest portion between hangar and glide slope antenna	12/2001	ICAO Visit December 2001	Corrected	Barbados	2004	A
AGA Cayman Islands/Islas Caimanes									
AGA 75 C	Pavement Surface Conditions (Annex 14, Vol. I, Chap. 10, 10.2 & 10.2.1)	Cayman Islands, CAYMAN BRAC, Gerrard Smith Intl	Taxiway and apron pavement surfaces deficient - Ref. Annex 14 Vol. I Section 9.4	10/2000	ICAO Visit October 2000	Corrected	Cayman Islands	2002	A
AGA Costa Rica									
AGA 44 C	Visual Aids (Annex 14, Vol. I, Chap. 5, 5.2.1, 5.4.1.1 and ANP, Table AOP 1)	Costa Rica, ALAJUELA, Juan Santamaria Intl.	Non standard TWY markings and non standard signs	1996	IFALPA Meeting November 2000	Replaced by deficiency AGA 232 C	Costa Rica	2002	A
AGA Cuba									
AGA 134 C	Runway Strips (Annex 14, Vol. I, Chap. 3.4 -3.4.6)	Cuba, VARADERO, Juan Gualberto Gómez International	The runway strip on the southeast area has vegetation which are considered objects.	06/2001	ICAO Visit June 2001	Corrected	Cuba	2002	A
AGA 137 C	Visual Aids (Annex 14, Vol. I, Chap 7, 7.2 Rec. 7.2.2, 7.2.3 and ANP, Table AOP1)	Cuba, VARADERO, Juan Gualberto Gómez International	There are no taxiway edge markings.	06/2001	ICAO Visit June 2001	Corrected	Cuba	2002	A
AGA 141 C	Visual Aids (Annex 14, Vol. I, Chap. 5 - 5.3.5, 5.3.5.1 and ANP Table AOP1)	Cuba, HOLGUIN, Frank Pais	There is no visual approach slope indicator system on Runway 23.	06/2001	ICAO Visit June 2001	Corrected	Cuba	2002	A
AGA 136 C	Visual Aids (Annex 14, Vol. I, Chap. 5 - 5.4.1.1 and ANP, Table AOP1)	Cuba, VARADERO, Juan Gualberto Gómez International	The signs are not illuminated	06/2001	ICAO Visit June 2001	Corrected	Cuba	2002	A
AGA 144 C	Visual Aids (Annex 14, Vol. I, Chap. 5 - 5.3.5.1 and ANP Table AOP1)	Cuba, CAMAGUEY, Ignacio Agramonte	There is no visual approach slope indicator system on Runway 25.	06/2001	ICAO Visit June 2001	Corrected	Cuba	2002	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AGA FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 142 C	Visual Aids (Annex 14, Vol. I, Chap. 5 - 5.3.5.1 and ANP, Table AOP1)	Cuba, CIEGO DE AVILA, Maximo Gomez	There is no visual approach slope indicator system on Runway 25.	06/2001	ICAO Visit June 2001	Cancelled - Aerodrome downgraded to domestic	Cuba	2003	A
AGA Dominican Republic/República Dominicana									
AGA 13 C	Runway Strip (Annex 14, Vol. I, Chap. 3.4, 3.4.1)	Dominican Republic, SANTO DOMINGO, Las Americas Intl	Runway strip contains objects	05/2000	ICAO Visit May 2000	Corrected	Dominican Republic	2003	A
AGA El Salvador									
AGA 79 C	Pavement Surface Conditions (Annex 14, Vol. I, Chap. 10, 10.2 & 10.2.1)	El Salvador, SAN SALVADOR, El Salvador Intl	Apron pavement has failed in some areas	2000	ICAO Visit November 2000 IATA Report January 2001	Upgraded apron pavement	El Salvador	2002	A
AGA 48 C	Visual Aids (Annex 14, Vol. I, Chap. 5, 5.3.5, 5.3.5.1 and ANP Table AOP 1)	El Salvador, SAN SALVADOR, El Salvador Intl	VASIS non standard - Ref. Annex 14, Vol. I, Section 5.3.5 & CAR/SAM ANP FASID Table AOP1	2000	ICAO Visit November 2000 IATA Report January 2001	Replaced with PAPIs	El Salvador	2002	A
AGA Mexico									
AGA 348 C	Taxiways (Annex 14, Chap 10, 10.2 & 10.2.1)	México, MÉXICO, Lic.Benito Juárez International Airport	The surfaces of the shoulders in some taxiways are deficient, contain FOD, depressed manholes and light holes that are no longer used	April 2003	ICAO Visit - April 2003	Corrected	AICM (Mexico)	2003	A
AGA Netherlands Antilles/Antillas Neerlandesas									
AGA 245 C	Runway Strip (Annex 14, Vol. I, Chap. 3.4 - 3.4.1)	Netherlands Antilles, CURACAO/ WILLEMSTAD, Hato Int'l	The runway strip contains objects such as the arresting gear facility and vegetation along the north-central portion	02/2002	ICAO Visit February 2002	Corrected	Netherlands Antilles	2002	A
AGA 267 C	Visual Aids (Annex 14, Vol. I, Chap. 5 - 5.2.14.3, Rec. 5.2.14.4)	Netherlands Antilles, SINT MAARTEN/ PHILIPSBURG, Princess Juliana Int'l	Apron safety line markings are not provided	02/2002	ICAO Visit February 2002	Corrected	PJIAE (Netherlands Antilles)	2002	A
AGA 271 C	Visual Aids (Annex 14, Vol. I, Chap. 5 - 5.3.17, 5.3.17.1)	Netherlands Antilles, SINT MAARTEN/ PHILIPSBURG, Princess Juliana Int'l	Taxiway edge lights are not provided on the old apron	02/2002	ICAO Visit February 2002	Corrected	PJIAE (Netherlands Antilles)	2002	A
AGA 269 C	Visual Aids (Annex 14, Vol. I, Chap. 5 - 5.3.5, 5.3.5.1 and ANP FASID Table AOP1)	Netherlands Antilles, SINT MAARTEN/ PHILIPSBURG, Princess Juliana Int'l	A visual approach slope indicator system is not provided for Runway 27	02/2002	ICAO Visit February 2002	Corrected	PJIAE (Netherlands Antilles)	2002	A
AGA Nicaragua									
AGA 1 C	Runway Geometry (Annex 14, Vol. I, Chap. 3.1 & 3.2)	Bahamas, FREEPORT, Grand Bahama Intl	Runway shoulders are not provided as specified in Annex 14, Vol. I, Section 3.2.1	10/2000	ICAO Visit October 2000	Corrected	Bahamas.	2002	B

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AGA FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AGA 11 C	Runway Strip (Annex 14, Vol. I, Chap. 3, 3.4., 3.4.1)	Bahamas, FREEPORT, Grand Bahama Intl	North side of runway strip requires strengthening in accordance with specifications in Annex 14, Vol. I Section 3.3.8	10/2000	ICAO Visit October 2000	Corrected	Bahamas	May 2003	A
AGA Saint Lucia/Santa Lucía									
AGA 105 C	Obstacles (Annex 14, Vol. I, Chap. 4, 4.2 & 4.2.5)	Saint Lucia, CASTRIES, George F. L. Charles Intl	Obstacles infringing on the transitional obstacle limitation surface include aircraft parked on the apron, fencing, roads, street lighting, terrain, buildings and vegetation	07/2001	ICAO Visit July 2001	Corrected	SLASPA	08/2003	A
AGA 115 C	Runway Strip (Annex 14, Vol. I, Chap. 3.4, 3.4.4 & 6)	Saint Lucia, VIEUX FORT, Hewanorra Intl	Runway strip width insufficient: East end – fence and road South side – fence	07/2001	ICAO Visit July 2001	Corrected	Saint Lucia	2002	A
AGA 103 C	Runway Strip (Annex 14, Vol. I, Chap. 3.4, 3.4.5 & 6)	Saint Lucia, CASTRIES, George F. L. Charles Intl	Runway strip width is insufficient on both sides	07/2001	ICAO Visit July 2001	Corrected	SLASPA	08/2003	A
AGA 108 C	Visual Aids (Annex 14, Vol. I, Chap. 5, 5.2.13.1 & 5.2.13.2 & 5.2.14.1)	Saint Lucia, CASTRIES, George F. L. Charles Intl	No apron taxiway centreline, aircraft stand and safety line markings are provided	07/2001	ICAO Visit July 2001	Corrected	SLASPA	2002	A
AGA United States/Estados Unidos									
AGA 339 C	Bird Strike Hazards (Annex 14, Chap. 9.4, 9.4.2, 9.4.3 & 9.4.4)	United States, Puerto Rico, Luis Muñoz Marín International Airport	Bird strikes were reported	10/2003	ICAO Visit - October 2003	Corrected	United States	2005	A
AGA 331 C	Fencing (Annex 14, Vol.I, Chap. 9, 9.10, Rec. 9.10.3)	United States, Puerto Rico, Luis Muñoz Marín International Airport	The perimeter road is incomplete	10/2003	ICAO Visit - October 2003	Corrected	United States	2005	B
AGA 330 C	Fencing (Annex 14, Vol.I, Chap. 9.10, Rec.9.10.5)	United States, Puerto Rico, Luis Muñoz Marín International Airport	Runway closures were reported due to the presence of iguanas and dogs	10/2003	ICAO Visit - October 2003	Corrected	United States	2005	A
AGA 157 C	Obstacles (Annex 14, Vol. I, Chap. 4, 4.2, 4.2.3)	United States, San Juan, Luis Muñoz Marín International	Trees, vehicles on public road, are obstacles infringing in the transitional surface	30/04/2002	ICAO Review of Aerodrome Layout & ICAO Visit - October 2003	Corrected	United States	2003	A
AGA 325 C	Obstacles (Annex 14, Vol.I, Chap. 4.2, Rec. 4.2.3)	United States, Puerto Rico, Luis Muñoz Marín International Airport	Trees are obstacles infringing on the transitional obstacle limitation surfaces	10/2003	ICAO Visit - October 2003	Corrected	United States	2005	A
AGA 337 C	Pavement Surface Conditions (Annex 14, Vol. I, Chap. 10, 10.2, 10.2.1, 10.2.2, 10.2.3 & 10.2.4)	United States, Puerto Rico, Luis Muñoz Marín International Airport	Some taxiway and apron areas are in very poor condition-concrete slabs broken and FOD	10/2003	ICAO Visit - October 2003	Corrected	United States	2005	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AGA FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
AGA 333 C Rescue and Fire Fighting (Annex 14, Vol. I, Chap. 9.2 - 9.2.2)	United States, Puerto Rico, Luis Muñoz Marin International Airport	No sea rescue boat is provided for RFFS at airport	10/2003	ICAO Visit - October 2003	Corrected	United States	2005	A
AGA 278 C Runway Geometry (Annex 14, Vol. I, Chapter 3.1.6.2)	United States, San Juan, Luis Muñoz Marin International	Runway shoulders of the required width are not provided	08/2003	ICAO Observation - July 2003	Corrected	United States	2003	B

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE ATM FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
ATM Mexico								
ATM 45 C	Provision of air traffic control service CAR/SAM/3 Rec. 5/33 Mexico	Some segments of ATS routes of the Mazatlan Control Area (lower airspace) within the Mexico FIR do not count yet with ATS at the required levels.	Feb/2002	ATM Evaluation to Mexico	Corrected	DGAC / SENEAM Mexico	2003	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE CNS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
CNS Belize/Belice									
CNS 8 C	ATS Speech Circuits Plan (Table CNS 1C) - Belize APP-La Aurora APP	Belize-Guatemala-COCESNA	The required circuit is not implemented.	11/99	COCESNA informed that the circuit was implemented through the the Central American (CAMSAT) VSAT network, but its integration in the final equipment of La Aurora APP is pending.	COCESNA informed the implementation of this circuit.	Belize, Guatemala and COCESNA.	04/2004	A
CNS 7 C	ATS Speech Circuits Plan (Table CNS 1C) - Belize APP-Tikal APP	Belize-Guatemala	The required circuit is not implemented. International direct dialling by public switch telephone network (IDD) is being used.	11/99	COCESNA informed that the circuit was implemented through the Central American (CAMSAT) VSAT network, but its integration to the final equipment of Tikal APP is pending	COCESNA informed that this circuit has been implemented.	Belize, Guatemala and COCESNA	04/2004	A
CNS COCESNA									
CNS 32 C	ATS Speech Circuits Plan (Table CNS 1C) and AFTN Plan (Table CNS1A)	COCESNA-Mexico	Merida-CENAMER communications link is in bad conditions (2 ATS voice circuits, 1 AFTN circuit and other future circuits.	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Mexico	09/2004	A
CNS 33 C	ATS Speech Circuits Plan (Table CNS 1C) ATS Speech Circuit Bogota ACC/CENAMER ACC.	COCESNA-Colombia	The circuit presents low availability, but there are plans for improvement.	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Colombia	2004	A
CNS 34 C	ATS Speech Circuits Plan (Table CNS 1C) ATS Speech Circuit Guayaquil ACC/CENAMER ACC	COCESNA-Ecuador		04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Ecuador-Colombia	2004	A
CNS 35 C	Communications Plan VHF/HF AMS (Table CNS 2A)	COCESNA	Deficient VHF/AMS coverage in the Northeast sector of the Central America FIR.	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA	2006	A
CNS 36 C	Radio Navigation Aids (Table CNS 3) VOR/DME Limon International	COCESNA-Costa Rica	VOR/DME Station Puerto Limon Airport, Costa Rica. Has exceeded his useful life, no logistic support is available.	004/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Costa Rica	2006	B
CNS 41 C	Radio Navigation Aids (Table CNS 3) DME Gen. Anacleto Maza Castellanos Airport, Tical, Guatemala.	COCESNA-Guatemala	The replacement of the equipment is required	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Guatemala	2005	B
CNS 45 C	Radio Navigation Aids (Table CNS 3) DOVR Monseñor Scharlet, Bluefields, Nicaragua	COCESNA-Nicaragua	The replacement of the equipment is required	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Nicaragua	2006	B

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE CNS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
CNS 44 C	Radio Navigation Aids (Table CNS 3) DVOR/DME Intl. Airport of Managua, Nicaragua	COCESNA-Nicaragua	The replacement of the equipment is required	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Nicaragua	2005	B
CNS 37 C	Radio Navigation Aids (Table CNS 3) ILS Daniel Oduber Quiroz Airport, Liberia, Costa Rica.	COCESNA-Costa Rica	The equipment is obsolete	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Costa Rica	2005	B
CNS 43 C	Radio Navigation Aids (Table CNS 3) ILS/DME Airport Ramon Villeda Morales, San Pedro Sula, Honduras	COCESNA-Honduras	The replacement of the equipment is required	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	COCESNA-Honduras	2006	B
CNS Dominican Republic/República Dominicana									
CNS 25 C	Radio Navigation Aids (Table CNS 3) -DME	Dominican Republic/Punta Cana	This DME is not implemented.		The facility was recommended for final approach and landing.	Corrected	Dominican Republic	2001	A
CNS El Salvador									
CNS 10 C	ATS Speech Circuits Plan (Table CNS 1C) - El Salvador APP-La Aurora APP	El Salvador-Guatemala/COCESNA	The required circuit is not implemented. A multi-point circuit is being used, but it has some deficiencies.	11/99	COCESNA informed that the circuit was implemented, but its integration in the final equipment of La Aurora APP is pending.	Corrected	El Salvador, Guatemala and COCESNA	2004	A
CNS 11 C	ATS Speech Circuits Plan (Table CNS 1C) - El Salvador APP-La Mesa APP	El Salvador-Honduras-COCESNA	The required circuit is not implemented. A multipoint circuit is being used, but it has some deficiencies.	11/99	.	Corrected	El Salvador, Honduras and COCESNA.	2002	A
CNS 12 C	ATS Speech Circuits Plan (Table CNS 1C) - El Salvador APP-Managua APP	El Salvador-Nicaragua and COCESNA	The required circuit is not implemented. A multipoint circuit is being used, but it has some deficiencies.	11/99		Corrected	El Salvador, Nicaragua and COCESNA.	2002	A
CNS 13 C	ATS Speech Circuits Plan (Table CNS 1C) - El Salvador APP-Toncontin APP	El Salvador-Honduras and COCESNA	The required circuit is not implemented. A multipoint circuit is being used, but it has some deficiencies.	11/99		Corrected	El Salvador, Honduras and COCESNA.	2002	A
CNS Guatemala									
CNS 15 C	ATS Speech Circuits Plan (Table CNS 1C) - La Aurora APP - La Mesa APP	Guatemala-Honduras-COCESNA	The required circuit is not implemented. A multipoint circuit is being used, but it has some deficiencies.	11/99	COCESNA informed that the circuit is implemented, but its integration in the final equipment of La Aurora APP is pending.	Corrected	Guatemala, Honduras and COCESNA	2004	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE CNS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
CNS 14 C	ATS Speech Circuits Plan (Table CNS 1C) - La Aurora APP - Tikal APP	Guatemala-COCESNA	The required circuit is not implemented. International direct dialling by public switch telephone network (IDD) is being used.	11/99	COCESNA informed that the circuit was implemented through the CAMSAT, but its integration in the final equipment of La Aurora APP and Tikal APP is pending.	Corrected	Guatemala and COCESNA.	2004	A
CNS 19 C	ATS Speech Circuits Plan (Table CNS 1C) - Tikal APP - CENAMER ACC	Guatemala-COCESNA	The required circuit is not implemented.	11/99	COCESNA informed that the circuit was implemented, but its integration in the final equipment at Tikal APP is pending.	Corrected	Guatemala y COCESNA	2004	A
CNS Honduras									
CNS 17 C	ATS Speech Circuits Plan (Table CNS 1C) - La Aurora APP - Toncontin APP	Guatemala- Honduras-COCESNA	The required circuit is not implemented. An IDD is being used.	11/99	COCESNA informed that the circuit was implemented through the CAMTSAT, but its integration in the final equipment of La Aurora APP is pending.	Corrected	Guatemala, Honduras and COCESNA	2005	A
CNS Jamaica									
CNS 26 C	Radio Navigation Aids (Table CNS 3) - ILS Cat I	Jamaica/Kingston/Norman Manley Int'l.	This ILS is not implemented.		Jamaica informed that in November 2005 the ILS at the Norman Manley International Airport in Kingston, Jamaica was in service.	Corrected	Jamaica	2006	A
CNS 21 C	VHF/HF-AMS Communications Plan (Table CNS 2A) VHF/AMS Voice coverage implementation	Jamaica/Kingston FIR VHF frequencies	Deficient VHF coverage in the Eastern portion of the Kingston FIR (TARBA and AMBIN point) and in the western end (PESTO point, FL 190).	03/99	Jamaica informed that new VHF radio equipment were put in service in November 2002. They consider that all their coverage is appropriate.	Corrected	Jamaica	03/2003	A
CNS Mexico									
CNS 50 C	ATS Speech Circuits Plan (Table CNS 1C) and AFTN Plan (Table CNS1A)	Mexico-COCESNA	Merida-CENAMER communications link is in bad conditions (2 ATS voice circuits, 1 AFTN circuit and other future circuits)	04/2003	89 Meeting of Civil Aviation General Directors of Central America and Panama (DGAC CAP/89)	Corrected	Mexico-COCESNA	2006	A
CNS Netherlands Antilles/Antillas Neerlandesas									
CNS 1 C	AFTN Plan (Table CNS 1A) AFTN Circuits Aruba (S)- Curacao (S)	Aruba-Netherlands Antilles / AFTN COM Centres	The circuit is implemented by a LTT/a circuit with velocity of 75 baud and ITA-2 code, and it has some deficiencies.			Corrected	Netherlands Antilles.	2003	B
CNS 20 C	VHF/HF-AMS Communications Plan (Table CNS 2A) VHF/AMS Voice coverage implementation	Netherlands Antilles/Curacao FIR frequencies	Deficient VHF coverage in the Northwest portion of the Curacao FIR.	03/99		Corrected	Netherlands Antilles.	2003	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE CNS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
CNS Trinidad and Tobago/Trinidad y Tabago									
CNS 3 C	AFTN Plan (Table CNS 1A) AFTN Circuits - Caracas (M)/Port of Spain (M)	Venezuela-Trinidad & Tobago/AFTN COM Centres	The circuit is implemented by a LTT/a circuit with velocity of 300 bps and ITA-2 code and it has some deficiencies of capacity and availability. The circuit is out of service during temporary periods since September 2001.	03/01	Reported by CAR/SAM AIS/ATM/CNS 02/00 Informal Meeting	Corrected This circuit was implemented through REDDIG.	Venezuela and Trinidad & Tobago	October 2006	A
CNS 5 C	ATS Speech Circuits Plan (Table CNS 1C) - Piarco ACC/Maiquetia ACC	Trinidad and Tobago-Venezuela	The circuit is reliable only at 80%.	03/98	Reported by the NACC and SAM Regional Offices.	Corrected This circuit was implemented through REDDIG.	CAAs Trinidad & Tobago and Venezuela	October 2006	A
CNS 6 C	ATS Speech Circuits Plan (Table CNS 1C) - Piarco ACC/Point Salines APP (A4 Circuit)	Trinidad & Tobago-Grenada	The circuit is now secondary to E/CAR AFS voice network and will be decommissioned. The circuit is occasionally out of service.	02/98	Reported by the NACC Regional Office. Problems have been attributed to the commercial provider (Cable & Wireless)	Corrected	CAAs Trinidad & Tobago and Grenada	11/2003	A
CNS United States/Estados Unidos									
CNS 30 C	AFTN Plan (Table CNS 1A) AFTN Circuits United States (M) - Panama (T)	United States / AFTN COM Centres	This circuit is implemented by a SAT/a circuit with velocity of 75 baud and ITA-2 protocol. This indicates a deficiency.		During the MEVA/6 Meeting, April 1999, actions were coordinated with the involved States to implement the circuit through the MEVA network, pending the finalization of the contract between Panama and MEVA Provider. The target date of implementation was 30 August 1999.	Corrected	Panamá, United States and MEVA provider.	2002	B

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE MET FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
MET Bahamas									
MET 28 C	CAR/SAM ANP MET Requirements, Table AOP 1.	Bahamas	RVR have not been implemented.	22/06/96		Corrected	State	2004	B
MET Barbados									
MET 62 C	CAR/SAM ANP Requirements, Part VI, para. 8.	Barbados	There are deficiencies in the OPMET exchange.	20/06/96	Review the OPMET exchange procedures, both in the meteorology and communications areas.	Corrected	States	27/10/04	A
MET 29 C	Notify the RVR for CAT I operations (Annex 3, Part I, Chapter 4, Recommendation 4.6.3.2)	Barbados	RVR have not been implemented.	22/06/96	Recommended practice, therefore, RVR will not be implemented.	Recommended practice, therefore, RVR will not be implemented.	State	06/2006	B
MET Cuba									
MET 13 C	Adequate number of MET trained staff.	Cuba	There are requirements of specialized meteorology personnel in the aeronautical meteorology field and of an increase of the number of aeronautical meteorologists.	22/06/96	To use CAR/SAM technical cooperation regional projects for the training of aeronautical meteorology.	To implement from September 2003 the professional degree on "Licenciate on Meteorology" at the "Universidad de la Habana"	States	2008	A
MET 65 C	CAR/SAM ANP Requirements, Part VI, para. 8.	Cuba	There are deficiencies in the OPMET exchange.	20/06/96	Review the OPMET exchange procedures, both in the meteorology and communications areas.	Corrected	ICAO	10/02	A
MET French Antilles/Antillas Francesas									
MET 68 C	Exchange of OPMET information (ANP Basic CAR/SAM para. 35 to 39)	French Antilles	OPMET information is not being disseminated in accordance with the requirements of CAR/SAM FASID Tables MET 2A and MET 3B	20/06/96	a) Implement the SIP COM/MET Recommendations for the CAR Region, b) Make use of the Guide for the preparation, dissemination and use of SIGMET messages in the CAR/SAM Regions	Corrected	State	2005	A
MET Mexico									
MET 21 C	Adequate number of MET trained staff.	Mexico	There are requirements of specialized meteorology personnel in the aeronautical meteorology field and of an increase of the number of aeronautical meteorologists.	22/06/96	To use CAR/SAM technical cooperation regional projects for the training of aeronautical meteorology.	Corrected	States	2005	A
MET Trinidad and Tobago/Trinidad y Tabago									
MET 25 C	Adequate number of MET trained staff.	Trinidad and Tobago	There are requirements of specialized meteorology personnel in the aeronautical meteorology field and of an increase of the number of aeronautical meteorologists.	22/06/96	To use CAR/SAM technical cooperation regional projects for the training of aeronautical meteorology.	Corrected	State	2004	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE MET FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
MET United States/Estados Unidos									
MET 26 C	Compliance with the requirements of WMO with regard to qualifications and training of aeronautical meteorology personnel (Annex 3, Part I, Chapter 2, standard 2.1.5)	United States	Not all personnel complies with the requirements related to qualifications and training of WMO Publications N°. 49	22/06/96	Review the functions and training of the aeronautical meteorologist.	Corrected	State	2005	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS Anguilla									
AIS 280 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Anguilla	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 158 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Anguilla	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Antigua and Barbuda/Antigua y Barbuda									
AIS 294 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Antigua and Barbuda	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO.	Corrected	State	2003	A
AIS 279 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Antigua and Barbuda	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 121 C	Annex 15. Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Antigua and Barbuda	Pre- flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO;	Corrected	State	2005	A
AIS 244 C	Annex 4 Chap. 13; Doc 8733 Basic ANP, Part VIII, Paras. 59 h) and 64 6); FASID Table AIS 6	Antigua and Barbuda	Partial application of ICAO requirements for the production of Aerodrome/Heliport chart-ICAO	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS 143 C	Annex 4 Chap. 16 Append. 5. FASID Table AIS 7.	Antigua and Barbuda	Production of the world aeronautical charts-ICAO not according to the sheet layout index established for this series of chart.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	B
AIS 218 C	Annex 4 Chap. 5; Doc 8733 Basic ANP, Part VIII, Paras. 59 b) and 64 2); FASID Table AIS 6	Antigua and Barbuda	Non production of Aerodrome obstacle chart-ICAO Type C or the concerned data in the AIP.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS 44 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Antigua and Barbuda	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Implemented.	Corrected.	State	30-11-05	A
AIS 159 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Antigua and Barbuda	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Aruba									
AIS 307 C	Annex 4Chap. 11; Doc. 8733 Basic ANP, Part VIII, Paras. 59 i) and 64 5); FASID Table AIS 6	Aruba	Partial application of ICAO requirements for the production of Instrument approach charts.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	01/03/2000	B
AIS 81 C	Doc. 8733 Basic ANP, Part VIII, Paras. 61 to 64, FASID Table AIS 7	Aruba	Lack of production of the World Aeronautical Chart ICAO 1:1000 000	01/11/94	Requirement does not apply to this States.	Corrected.	State		B

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS Bahamas									
AIS 108 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Bahamas	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	No action plan reported.	Corrected.	State	30-11-04	A
AIS 1 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33.	Bahamas	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	2005	A
AIS 46 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Bahamas	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Records/files in NACC RO.	Corrected	State	14/11/2001	A
AIS 184 C	Annex 4Chap. 11; Doc. 8733 Basic ANP, Part VIII, Paras. 59 i) and 64 5); FASID Table AIS 6	Bahamas	Partial application of ICAO requirements for the production of Instrument approach charts.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2005	B
AIS 82 C	Doc. 8733 Basic ANP, Part VIII, Paras. 61 to 64, FASID Table AIS 7	Bahamas	Lack of production of the World Aeronautical Chart ICAO 1:1000 000	01/11/94	No requerida	Corrected.	State		B
AIS Barbados									
AIS 292 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Barbados	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO.	Corrected	State	20/11-2001	A
AIS 276 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Barbados	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/01/2002	A
AIS 295 C	Annex 15. Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Barbados	Pre- flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO.	Corrected	State	29/11/2001	A
AIS 303 C	Annex 4 Chap. 13; Doc 8733 Basic ANP, Part VIII, Paras. 59 h) and 64 6); FASID Table AIS 6	Barbados	Partial application of ICAO requirements for the production of Aerodrome/Heliport chart-ICAO	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	18/04/2002	A
AIS 144 C	Annex 4 Chap. 16 Append. 5. FASID Table AIS 7.	Barbados	Production of the world aeronautical charts-ICAO not according to the sheet layout index established for this series of chart.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	TBD	B
AIS 170 C	Annex 4 Chap. 17.	Barbados	Production of the VFR chart, scale 1:500,000-with non ICAO specifications.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected,	State	06/04	B
AIS 47 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Barbados	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Records/files in NACC RO.	Corrected	State	2003	A
AIS 160 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Barbados	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS Belize/Belice									
AIS 2 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Belize	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	2005	A
AIS 71 C	Annex 15, Chapter 4, Paras. 4.2.8 and 4.3.4., Chapter 6; Doc 8733 Basic ANP Part VIII, Paras. 45 to 49	Belize	Lack of effective compliance with the AIRAC system requirement	01/11/94	Records/files NACC RO; GREPECAS reports	Corrected	State	TBD	A
AIS 125 C	Annex 15. Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Belize	Pre-flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO;	Corrected	State	TBD	A
AIS 83 C	Doc. 8733 Basic ANP, Part VIII, Paras. 61 to 64, FASID Table AIS 7	Belize	Lack of production of the World Aeronautical Chart ICAO 1:1000 000	01/11/94	Not requested.	Corrected.	State		B
AIS British Virgin Islands/Islas Vírgenes Británicas									
AIS 287 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	British Virgin Islands	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 168 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	British Virgin Islands	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Cayman Islands/Islas Caimanes									
AIS 109 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Cayman Islands	Pre-flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO;	Corrected	State	2001	A
AIS 288 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Cayman Islands	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/01/2001	A
AIS 72 C	Annex 15, Chapter 4, Paras. 4.2.8 and 4.3.4., Chapter 6; Doc 8733 Basic ANP Part VIII, Paras. 45 to 49	Cayman Islands	Lack of effective compliance with the AIRAC system requirement	01/11/94	Records/files NACC RO; GREPECAS reports	Corrected	State	2001	A
AIS 124 C	Annex 15. Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Cayman Islands	Pre-flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO;	Corrected	State	TBD	A
AIS 247 C	Annex 4 Chap. 13; Doc 8733 Basic ANP, Part VIII, Paras. 59 h) and 64 6); FASID Table AIS 6	Cayman Islands	Partial application of ICAO requirements for the production of Aerodrome/Heliport chart-ICAO	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	31/01/00	A
AIS 48 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Cayman Islands	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Records/files in NACC RO.	Corrected	State	2001	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS Costa Rica									
AIS 296 C	Annex 15, Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Costa Rica	Pre-flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO.	Corrected	State	29/11/2001	A
AIS 224 C	Annex 4 Chap. 5; Doc 8733 Basic ANP, Part VIII, Paras. 59 b) and 64 2); FASID Table AIS 6	Costa Rica	Non production of Aerodrome obstacle chart-ICAO Type C or the concerned data in the AIP.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports. No action plan reported.	Need for production of aeronautical charts of this series.	State	TBD	A
AIS 91 C	Doc. 8733 Basic ANP, Part VIII, Para.24	Costa Rica	Lack of use of English for plain language texts.	18/09/96	Records/files NACC RO; GREPECAS reports. No action plan reported.	Need of use of English for plain language texts.	State	TBD	A
AIS Cuba									
AIS 3 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Cuba	Lack of Publication of the restructured AIP	25/4/96	Published the new AIP editon in the new format (2002)	Corrected	State	11/07/2002	A
AIS 51 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Cuba	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Records/files in NACC RO.	Corrected	Cuba	2002	A
AIS Dominica									
AIS 277 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Dominica	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 161 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Dominica	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Dominican Republic/República Dominicana									
AIS 110 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Dominican Republic	Pre-flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO. Already established.	Corrected.	State		A
AIS 305 C	Annex 4 Chap. 16 Append. 5. FASID Table AIS 7.	Dominican Republic	Production of the world aeronautical charts-ICAO not according to the sheet layout index established for this series of chart.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	12/07/2001	B
AIS 300 C	Annex 4Chap. 17.	Dominican Republic	Production of the VFR chart, scale 1:500,000-with non ICAO specifications.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	12/07/2001	B
AIS El Salvador									
AIS 299 C	Annex 15, Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	El Salvador	Pre-flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO;	Corrected	State	30/112000	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS French Antilles/Antillas Francesas									
AIS 147 C	Annex 4 Chap. 16 Append. 5. FASID Table AIS 7.	French Antilles	Production of the world aeronautical charts-ICAO not according to the sheet layout index established for this series of chart.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	B
AIS 162 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	French Antilles	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Grenada/Granada									
AIS 111 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Grenada	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO. Already established.	Corrected.	State	30-11-04	A
AIS 278 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Grenada	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 163 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Grenada	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Guatemala									
AIS 86 C	Doc. 8733 Basic ANP, Part VIII, Paras. 61 to 64, FASID Table AIS 7	Guatemala	Lack of production of the World Aeronautical Chart ICAO 1:1000 000	01/11/94	Records/files NACC RO; GREPECAS reports. No action plan reported. Not required.	Corrected.	State		B
AIS Haiti									
AIS 4 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Haiti	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/01/2000	A
AIS 75 C	Annex 15, Chapter 4, Paras. 4.2.8 and 4.3.4., Chapter 6; Doc 8733 Basic ANP Part VIII, Paras. 45 to 49	Haiti	Lack of effective compliance with the AIRAC system requirement	01/11/94	Records/files NACC RO; GREPECAS reports	Corrected	State	TBD	A
AIS 253 C	Annex 4 Chap. 13; Doc 8733 Basic ANP, Part VIII, Paras. 59 h) and 64 6); FASID Table AIS 6	Haiti	Partial application of ICAO requirements for the production of Aerodrome/Heliport chart-ICAO.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	31/01/00	A
AIS 230 C	Annex 4 Chap. 5; Doc 8733 Basic ANP, Part VIII, Paras. 59 b) and 64 2); FASID Table AIS 6	Haiti	Non production of Aerodrome obstacle chart-ICAO Type C or the concerned data in the AIP.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	TBD	A
AIS 57 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Haiti	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Records/files in NACC RO.	Corrected	State	TBD	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action
AIS 191 C Annex 4 Chap. 11; Doc. 8733 Basic ANP, Part VIII, Paras. 59 i) and 64 5); FASID Table AIS 6	Haiti	Partial application of ICAO requirements for the production of Instrument approach charts.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	TBD	B
AIS Honduras								
AIS 150 C Annex 4 Chap. 16 Append. 5. FASID Table AIS 7.	Honduras	Production of the world aeronautical charts-ICAO not according to the sheet layout index established for this series of chart.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports. No action plan reported.	Corrected.	State		B
AIS Jamaica								
AIS 114 C Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Jamaica	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO;	Corrected	State	2005	A
AIS 286 C Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Jamaica	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/01/2000	A
AIS 77 C Annex 15, Chapter 4, Paras. 4.2.8 and 4.3.4., Chapter 6; Doc 8733 Basic ANP Part VIII, Paras. 45 to 49	Jamaica	Lack of effective compliance with the AIRAC system requirement	01/11/94	Records/files NACC RO; GREPECAS reports	Corrected	State	2005	A
AIS 132 C Annex 15. Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Jamaica	Pre- flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO;	Corrected	State	2005	A
AIS 141 C Annex 15. Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Jamaica	Pre- flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO. No action plan reported. Already implemented.	Corrected.	State	30-01-05	A
AIS Mexico								
AIS 293 C Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Mexico	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO.	Corrected	State	2002	A
AIS 78 C Annex 15, Chapter 4, Paras. 4.2.8 and 4.3.4., Chapter 6; Doc 8733 Basic ANP Part VIII, Paras. 45 to 49	Mexico	Lack of effective compliance with the AIRAC system requirement	01/11/94	Not required.	Corrected.	SENEAM		A
AIS 298 C Annex 15. Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Mexico	Pre- flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO;	Corrected	2002	TBD	A
AIS 151 C Annex 4 Chap. 16 Append. 5. FASID Table AIS 7.	Mexico	Production of the world aeronautical charts-ICAO not according to the sheet layout index established for this series of chart.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports. It was observed that this deficiency was included in 177C.	Need for production of aeronautical charts according to the established requirements.	State		B

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS Montserrat									
AIS 285 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Montserrat	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 289 C	Annex 4 Chap. 5; Doc 8733 Basic ANP, Part VIII, Paras. 59 b) and 64 2); FASID Table AIS 6	Montserrat	Non production of Aerodrome obstacle chart-ICAO Type C or the concerned data in the AIP.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	TBD	A
AIS Netherlands Antilles/Antillas Neerlandesas									
AIS 115 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Netherlands Antilles	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO. Already established.	Corrected.	State		A
AIS 89 C	Doc. 8733 Basic ANP, Part VIII, Paras. 61 to 64, FASID Table AIS 7	Netherlands Antilles	Lack of production of the World Aeronautical Chart ICAO 1:1000 000	01/11/94	Records/files NACC RO; GREPECAS reports. No requerida.	Corrected.	State		B
AIS Nicaragua									
AIS 6 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Nicaragua	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	2005	A
AIS 62 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Nicaragua	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Records/files in NACC RO.	Corrected	State	2004	A
AIS 95 C	Doc. 8733 Basic ANP, Part VIII, Para.24	Nicaragua	Lack of use of English for plain language texts.	18/09/96	Records/files NACC RO; GREPECAS reports	Corrected	State	2004	A
AIS Saint Kitts and Nevis/San Kitts y Nevis									
AIS 284 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Saint Kitts and Nevis	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 164 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Saint Kitts and Nevis	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Saint Lucia/Santa Lucía									
AIS 117 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Saint Lucia	Pre- flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO. Already established.	Corrected.	State	TBD	A
AIS 282 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Saint Lucia	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 165 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Saint Lucia	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A

CORRECTED DEFICIENCIES (A,B)

GREPECAS/14
WP/17
Appendix E

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN THE AIS FIELD IN THE CAR REGION

Identification		Deficiencies			Corrective Action				
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Date of completion	Priority for action	
AIS Saint Vincent and the G./San Vicente y las Granadinas									
AIS 118 C	Annex 15 Chap. 8; Doc. 8733 Basic ANP, Part VIII, Para. 25; FASID Tables AIS 1 and 2	Saint Vincent and the Grenadines	Pre-flight information/(implementation of required AIS aerodrome units).	18/09/96	Records/files NACC RO;	Corrected	State	TBD	A
AIS 283 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Saint Vincent and the Grenadines	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 138 C	Annex 15, Chap. 8, Para. 8.1.3; Doc 8733 Basic ANP, Part VIII, Para. 26	Saint Vincent and the Grenadines	Pre-flight information (provision of pre-flight bulletins in all the designated aerodromes).	18/09/96	Records/files NACC RO;	Corrected	State	TBD	A
AIS 259 C	Annex 4 Chap. 13; Doc 8733 Basic ANP, Part VIII, Paras. 59 h) and 64 6); FASID Table AIS 6	Saint Vincent and the Grenadines	Partial application of ICAO requirements for the production of Aerodrome/Heliport chart-ICAO.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	31/01/00	A
AIS 156 C	Annex 4 Chap. 16 Append. 5. FASID Table AIS 7.	Saint Vincent and the Grenadines	Production of the world aeronautical charts-ICAO not according to the sheet layout index established for this series of chart.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	TBD	B
AIS 238 C	Annex 4 Chap. 5; Doc 8733 Basic ANP, Part VIII, Paras. 59 b) and 64 2); FASID Table AIS 6	Saint Vincent and the Grenadines	Non production of Aerodrome obstacle chart-ICAO Type C or the concerned data in the AIP.	06/01/94	Records/files in NACC RO; GREPECAS and AIS/MAP/SG reports.	Corrected	State	TBD	A
AIS 65 C	Annex 4, Para. 2.18; Doc. 8733 Basic ANP, Part VIII, Paras. 51 b) and 56	Saint Vincent and the Grenadines	Production of aeronautical charts according to requirements of the WGS-84 System	01/01/98	Records/files in NACC RO.	Corrected	State	2004	A
AIS 199 C	Annex 4Chap. 11; Doc. 8733 Basic ANP, Part VIII, Paras. 59 i) and 64 5); FASID Table AIS 6	Saint Vincent and the Grenadines	Partial application of ICAO requirements for the production of Instrument approach charts.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	31/01/01	B
AIS 181 C	Annex 4Chap. 17.	Saint Vincent and the Grenadines	Production of the VFR chart, scale 1:500,000-with non ICAO specifications.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	TBD	B
AIS 166 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Saint Vincent and the Grenadines	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A
AIS Trinidad and Tobago/Trinidad y Tabago									
AIS 281 C	Annex 15, Chap. 4; Doc 8733 Basic ANP, Part VIII, Para. 33	Trinidad and Tobago	Lack of Publication of the restructured AIP	25/4/96	GREPECAS AIS/MAP Subgroup Survey to States.	Corrected	State	01/10/2001	A
AIS 167 C	Doc 8733 Basic ANP, Part VIII, Paras. 59 k), 61, 62, 64 7) and FASID Table AIS 7.	Trinidad and Tobago	Lack of production of the world aeronautical charts-ICAO.	06/01/94	Records/files in NACC R0; GREPECAS and AIS/MAP/SG reports.	Corrected	State	2003	A