

Safety Recommendation

The IAC recommends that ICAO consider the reasonability of amending Annex 6 to the Convention on International Civil Aviation related to mandatory installation of an AOA¹ indicator in the cockpit.

¹ Angle of attack