


# Sixth Meeting of the MIDANPIRG Air Traffic Management Sub-Group (ATM SG/6)

(9 - 12 November 2020)







# ATM SG/6 Meeting

Agenda Item 4: ATM Planning and Implementation Issues:

- Follow-up on ATM SG/5 Draft Conclusions and Decisions
- Revised MID Air Navigation Strategy
- **RVSM Implementation**
- Review of the Outcomes of ATFM TF/4 Meeting
- Review of the Outcomes of FWC2022 TF/4 Meeting
- Other ATM Issues
- Air Navigation Deficiencies related to ATM and SAR





## **Review of Air Navigation Deficiencies related to ATM and SAR**

- In the ATM field:

the total number of deficiencies is twenty-four (24); fifteen (15) priority "A" and nine (9) priority "B". Thirteen (13) related to the uncompleted signature of contingency agreements; Nine (9) related to the non-implementation of planned regional ATS Routes; and four (4) related to unsatisfactory reporting of large Height deviation (LHD) to the MIDRMA.

- In the SAR field:

the total number of deficiencies is ten (10) priority "A". Five (5) related to the lack of SAR provisions; and five (5) related to non-compliance with the carriage of Emergency Locator Transmitter (ELT) requirements.

## https://mandd.icao.int/







	Deficiencies in the ATM field										
			IRAN								
Item No	Identification	Deficiencies									
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action		
1	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Still to sign with Kuwait	Corrective Action Plan Has not been formally provided by the State	Iran	Dec 2018 Dec 2020 <u>To be</u> <u>closed</u>	A		
2	MID ANP TABLE ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-	ATS routes A418/UP574 not implemented	Dec 2006	KUMUN-PAPAR segment not implemented.	S O Corrective Action Plan has not been formally provided by the State	Iran- UAE	<del>Dec 2018</del> <del>Dec 2020</del> Dec 2021	В		
3	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-	ATS Route G202 is restricted to certain defined airspace users	Jun 2014	Not all Operators are authorized to fly G202	O Corrective Action Plan has not been formally provided by the State	Iran	<del>Dec 2018</del> <del>Dec 2020</del> Feb 2021	В		

ID		$\mathbf{n}$	
IK.	Δ		

	Deficiencies in the ATM field									
			IRAQ							
Item No	Identification		Deficiencies				Corrective Action			
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	r	Facilities/ Services	Executing body	Date of completetion	Priority for action
1	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route G667 not implemented	Sep 2006	Segment ALSAN-ABD not implemented		Corrective Action Plan has not been formally provided by the State	Iraq- Iran- Kuwait	<del>Dec 2018</del> <del>Dec 2020</del> Dec 2021	В
2	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.		Contingency Agreement to be signed with Syria		Corrective Action Plan has not been formally provided by the State	Iraq	<del>Dec 2018</del> Dec 2020 Aug 2021	A
3	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route A424 not implemented	May 2008	LOTAN-LOVEK segment not implemented	0	Corrective Action Plan has not been formally provided by the State	Iraq	<del>Dec 2018</del> <del>Dec 2020</del> Dec 2021	В
4	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route G795 not implemented	May 2008	RAF-BSR segment not implemented	S	Corrective Action Plan has not been formally provided by the State	Iraq- Saudi Arabia	<del>Dec 2018</del> <del>Dec 2020</del> Dec 2021	В
5	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	ATS route	ATS Route G669 not implemented		segment RAF - SOLAT not implemented		Corrective Action Plan has not been formally provided by the State	Iraq	<del>Dec 2018</del> <mark>Dec 2020</mark> To be closed	В

	Deficiencies in the ATM field JORDAN									
Iten No	Item No     Identification     Deficiencies		Corrective Action							
	Requirement	Facilities/ Services	Description	11	Remarks/ Rationale for non-elimination		Facilities/ Services	Executing body		Priority for action
1	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	11	Contingency agreements not signed with Syria.	н	Corrective Action Plan has not been formally provided by the State. State comment: due to political impact in the region Jordan is not able to complete the signature of contingency agreements with all adjacent States	Jordan	<del>Dec 2018</del> <del>Dec 2020</del> Dec 2021	A

	Deficiencies in the ATM field								
	KUWAIT								
Item No	Identification Deficiencies		Corrective Action						
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services		Date of completetion	Priority for action
1	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency Plan to S	Corrective Action Plan has not been formally provided by the State	Kuwait	<del>Dec 2018</del> Dec 2020 To be closed	A

	Deficiencies in the ATM field								
	LEBANON								
Item No	m     Identification     Deficiencies		Corrective Action						
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completetion	Priority for action
1	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency agreements not signed with Syria	Corrective Action Plan has not been formally provided by the State	Lebanon	<del>Dec 2018</del> Dec 2020	A

	Deficiencies in the ATM field									
	LIBYA									
Item No	I I dentification II Deficiencies			Corrective Action						
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination		Facilities/ Services	0	Date of completetion	Priority for action
	Annex 11 Para 3.3.5.1	-	Not reporting the required data to the MIDRMA in a timely manner.	Dec 2013	-	н	Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> <del>Dec 2020</del>	A
	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs	11	Agreement signed only with Egypt		Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> <del>Dec 2020</del>	A

	Deficiencies in the ATM field									
	OMAN									
	Item NoIdentificationDeficiencies			Corrective Action						
	Req	amrement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	0	Date of completetion	Priority for action
1		<del>nex 11</del> ra. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.		Contingency Agreements to be signed with Saudi Arabia.	Corrective Action Plan has not been formally provided by the State	Oman	<del>Dec 2018</del>	A

### Deficiencies in the ATM field QATAR Item Identification Deficiencies **Corrective Action** No Facilities/ Date first Remarks/ Rationale for Requirement Description Facilities/ Services reported Services non-elimination Development of **contingency plan for implementation** in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address Contingency Corrective Action Annex 11 Nov 2006 agreements not S has not been form natural disasters and public health emergencies. Contingency agreements should be signed Para. 2.31 signed with UAE. provided by the S with all adjacent ACCs.

n			
es	Executing	Date of	Priority
	body	completetion	for action

	Deficiencies in the ATM field SAUDI ARABIA									
Item No					Corrective Action					
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non- elimination	Facilities/ Services	Executing body	Date of completetion	Priority for action	
1	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency Agreements not signed with Iraq, Qatar, Sudan and Yemen. Contingency Agreements not signed with Iraq, Qatar and Sudan.	Corrective Action Plan has not been formally provided by the State	Saudi Arabia	<del>Dec 2018</del> <del>Dec 2020</del> Dec 2021	A	

	Deficiencies in the ATM field								
	SUDAN								
Item No	m Identification Deficiencies		Corrective Action						
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completetion	Priority for action
1	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Dec 2014	Agreement signed	Corrective Action Plan has not been formally provided by the State	Sudan	<del>Dec 2018</del> <del>Dec 2020</del>	A

177	DI	
٦Y	кі	A

	Deficiencies in the ATM field													
	SYRIA													
Item No	Identification	Corrective Action												
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	0	Date of completetion	Priority for action					
1	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route G202 not implemented	Dec 1997 Damascus not S		Corrective Action Plan has not been formally provided by the State	Syria	<del>Dec 2018</del> <mark>Dec 2020</mark>	В					
2	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-			Corrective Action Plan has not been formally provided by the State	Syria	<del>Dec 2018</del> <mark>Dec 2020</mark>	В						
3	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.		No signed agreement yet	Corrective Action Plan has not been formally provided by the State	Syria	Dec 2018	A					
4	Annex 11 Para 3.3.5.1	-	Reporting unsatisfactory LHDs to MIDRMA	Oct 2013	Syria to coordinate with MIDRMA.	Corrective Action Plan has not been formally provided by the State	Syria	<del>Dec 2018</del> <mark>Dec 2020</mark>	A					

	Deficiencies in the ATM field UAE												
Item No	Identification		Deficiencies	Corrective Action									
	Requirement	quirement     Facilities/ Services     Description     Date first reported     Remarks/ Rationale for non-elimination			Facilities/ Services		Date of completetion	Priority for action					
1	Annex 11 Para. 2.31	-	Development of <b>contingency plan for implementation</b> in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Plan completed and Agreements signed with Bahrain, Iran, Oman and Saudi Arabia. The plan next is to sign with Qatar after the finalisation of the LoA.		Corrective Action Plan has not been formally provided by the State	UAE	<del>Dec 2018</del> Dec 2020 Dec 2021	A			
	MID ANP Table ATM II- MID-1 MID REGION ATS ROUTE NETWORK	-	ATS routes A418/UP574 not implemented	Dec 2006	KUMUN-PAPAR segment not implemented.	S	Corrective Action Plan has not been formally provided by the State	Iran- UAE	<del>Dec 2018</del> Dec 2020 Dec 2021	В			

	Deficiencies in the ATM field												
	YEMEN												
Iter No	l Identification		Deficiencies				Corrective Action						
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination		Facilities/ Services	0	Date of completetion	Priority for action			
1	Annex 11 Para. 2.31		Nov 2006	Contingency Agreement signed only with Oman.	н Ө	Corrective Action Plan has not been formally provided by the State	Yemen	<del>Dec 2018</del>	A				
2	Annex 11 Para 3.3.5.1	Para - Granting RVSM approvals for aircraft without known hight-keeping monitoring results		Dec 2012	-	H O	Corrective Action Plan has not been formally provided by the State	Yemen	<del>Dec 2018</del> <mark>Dec 2020</mark>	A			
3	3     Annex 11 Para 3.3.5.1     -     Reporting Unsatisfactory LHDs to MIDRMA		Oct 2013	Yemen to coordinate with MIDRMA.	н	Corrective Action Plan has not been formally provided by the State	Yemen	<del>Dec 2018</del> <mark>Dec 2020</mark>	A				

MANDD - All Rights Reserved ICAO MID Office Cairo

## Deficiencies in the SAR field

IRAO

				IRAQ					
Item No	Identification		Deficiencies	Corrective Action					
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non- elimination	Facilities/ Services	Executing body	Date of completetion	Priority for action
1	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Apr 2012		Corrective Action Plan has not been formally provided by the State	Iraq	<del>Dec 2018</del> <del>Jun 2020</del>	A
	Annex 6 Part I, Chap.6 and Part II Chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	ELT	Non-compliance with carriage of Emergency Locator Transmitter (ELT) requirements	Apr 2012	- 0	Corrective Action Plan has not been formally provided by the State	Iraq	<del>Dec 2018</del> <del>Jun 2020</del>	A

### Deficiencies in the SAR field KUWAIT Item Identification Deficiencies **Corrective Action** No Facilities/ Date first Remarks/ Rationale for non-Requirement Description Facilities/ Services Services reported elimination Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. Corrective Action Plan been formally provide Non-compliance with carriage of Emergency Locator Transmitter (ELT) requirements ELT Apr 2012 0 2.6.4 State

	Executing body	Date of completetion	Priority for action
n has not ed by the	Kuwait	<del>Dec 2018</del> J <del>un 2020</del>	А

	Deficiencies in the SAR field												
	LEBANON												
Item No	Idontification		Deficiencies			Corrective Action							
	Roguiromont	Facilities/ Services	Description	11 1	Remarks/ Rationale for non- elimination	Facilities/ Services	Executing body		Priority for action				
1	Annex 12 Para. 2.1	-	Lack of provision of required <b>SAR</b> services	Apr 2012	- 0	Corrective Action Plan has not been formally provided by the State	Lebanon	<del>Dec 2018</del> Dec 2020	A				

	Deficiencies in the SAR field											
	LIBYA											
Item No	Identification		Deficiencies	Corrective Action								
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non- elimination	Facilities/ Services		Date of completetion	Priority for action			
1	Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	-	Non-compliance with carriage of <b>Emergency</b> Locator Transmitter (ELT) requirements	Dec 2014		Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> <mark>Dec 2020</mark>	A			
2	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Dec 2014	- H S O	Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> <mark>Dec 2020</mark>	A			

	Deficiencies in the SAR field											
	SYRIA											
Item No	Identification		Deficiencies	Corrective Action								
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non- elimination	Facilities/ Services	0	Date of completetion	Priority for action			
1	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Apr 2012		Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> <mark>Dec 2020</mark>	A			
2	Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	-	Non-compliance with carriage of <b>Emergency</b> Locator Transmitter (ELT) requirements	Apr 2012		Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> Dec 2020	A			

	Deficiencies in the SAR field												
	YEMEN												
Item No	Identification		Deficiencies	Corrective Action									
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non- elimination	Facilities/ Services	Executing body	Date of completetion	Priority for action				
1	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Apr 2012		Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> <mark>Dec 2020</mark>	A				
2	Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	-	Non-compliance with carriage of <b>Emergency</b> Locator Transmitter (ELT) requirements	Apr 2012	- 0	Corrective Action Plan has not been formally provided by the State		<del>Dec 2018</del> <mark>Dec 2020</mark>	A				

MANDD - All Rights Reserved ICAO MID Office Cairo