GROUPE D'EXPERTS SUR LES MARCHANDISES DANGEREUSES (DGP)

VINGT-SIXIÈME RÉUNION

Montréal, 16 – 27 octobre 2017

Point 2 : Élaboration de recommandations relatives à des amendements des *Instructions* techniques pour la sécurité du transport aérien des marchandises dangereuses (Doc 9284) à introduire dans l'édition de 2019-2020

MISE EN MARCHE ACCIDENTELLE DE CIGARETTES ÉLECTRONIQUES TRANSPORTÉES PAR LES PASSAGERS ET LES MEMBRES D'ÉQUIPAGE

(Note présentée par A. Stubblefield)

RÉSUMÉ

La présente note de travail propose de modifier la liste des marchandises dangereuses que les passagers et les membres d'équipage (Tableau 8-1) sont autorisés à transporter compte tenu des préoccupations de sécurité associées à la mise en marche accidentelle d'appareils électroniques portables pour fumer (cigarettes électroniques) transportés dans des bagages de cabine.

Suite à donner par le Groupe DGP: Le Groupe DGP est invité à examiner les propositions de modifications du Tableau 8-1 comme cela est indiqué dans l'Appendice A de la présente note de travail.

1. **INTRODUCTION**

- 1.1 Specific provisions were added into the ICAO Technical Instructions, Part 8, Table 8-1, for portable electronic smoking devices (e-cigarettes) through the issuance of Addendum No. 1 to the 2015-2016 ICAO Technical Instructions (26-May-2015). The provisions added were the prohibition of e-cigarettes in checked baggage, spare batteries must be protected from short circuits, and the recharging of the device and batteries is not permitted on board the aircraft.
- 1.2 In the United States, there have been ten documented heat/smoke/fire incidents involving e-cigarettes since the introduction of these provisions in Table 8-1 (i.e. during the period May 2015 through May 2017). Seven of those incidents occurred inside a passenger plane and three occurred inside

^{*} Seuls le résumé et l'Appendice A sont traduits.

the airport.¹ These incidents typically involved the e-cigarette device while it was being transported in carry-on baggage (See Appendix B for incidents). While the specific cause of each of these incidents is unknown, a concern in all these incidents is the accidental activation of the e-cigarette device. When these e-cigarette devices are activated, the power from the battery is allowed to energize a heating coil. This heating coil is only designed to be turned on for a few seconds while it is submerged or surrounded by e-cigarette liquid (E-liquid, E-juice, etc.). If the heating coil is energized for longer than a few seconds, all the e-cigarette liquid is vaporized, and the entire e-cigarette device starts to overheat, smoke, and potentially catch on fire. This heat is also transferred to the battery, which are mostly lithium ion batteries, with the potential to drive the lithium ion battery into thermal runaway.

1.3 The proposal introduces a provision in the e-cigarette entry in Table 8-1 that requires passengers or crew to take effective measures for preventing accidental activation of the heating element of the e-cigarette device when transporting such devices in carry-on baggage on-board passenger aircraft. Examples of effective measures include, but are not limited to, removing the battery from the e-cigarette; separating the battery from the heating coil; placing the e-cigarette into a protective case; using a protective cover, safety latch, or locking device on the e-cigarette's heating coil activation button; and electronics or technology in the device designed to prevent accidental activation such as requiring the e-cigarette to be powered on before the heating coil button can be activated. In most e-cigarettes, the battery can either be easily removed or easily separated from the heating element.

2. **ACTION BY THE DGP**

2.1 The DGP is invited to consider the amendment of the provisions for dangerous goods carried by passengers or crew as shown in Appendix A to this working paper.

one. These incidents are considered near-misses because they could have occurred on-board the aircraft.

1

¹ The three incidents that occurred inside the airport may be relevant to the safety risk of lack of effective measures to prevent accidental activation of an e-cigarette's heating element inside a passenger aircraft because the passengers in possession of such devices were either imminently going to be boarding a passenger aircraft or had just departed

APPENDICE A

PROPOSITION D'AMENDEMENT DE LA PARTIE 8 DES INSTRUCTIONS TECHNIQUES

Partie 8

DISPOSITIONS RELATIVES AUX PASSAGERS ET AUX MEMBRES D'ÉQUIPAGE

(...)

Tableau 8-1. Dispositions relatives au transport de marchandises dangereuses par les passagers ou les membres d'équipage

| | Emplacement | | | ss Se | s e ord | |
|---|------------------------|----------------------|---------|--|--|--|
| Produits ou articles | Bagages enregistrés | Bagages de cabine | Sur soi | Approbation de l'exploitant ou des exploitants requise | Renseignements à foumir au pilote commandant de bord | Restrictions |
| () | | | | | | |
| Produits de consommation | | | | | | |
| () | | | | | | |
| Appareils électroniques portables pour fumer, alimentés par batteries (ex. cigarettes électroniques, cigares électroniques, pipes électroniques, vaporisateurs personnels, inhalateurs électroniques de nicotine) | Non | Oui | Oui | Non | Non | a) transportés par des passagers ou des membres d'équipage pour un usage personnel; b) les batteries de rechange doivent être protégées individuellement contre les courts-circuits (par l'utilisation de l'emballage original de vente au détail ou par un autre moyen pour isoler les bornes, par exemple pose de ruban sur les bornes non protégées ou utilisation de pochettes de protection ou de sacs de plastique distincts pour chacune); c) pour chaque batterie, les valeurs ci-après ne doivent pas être dépassées: — pour les batteries au lithium métal, une quantité de lithium de 2 grammes; ou — pour les batteries au lithium ionique, une énergie nominale en wattheures de 100 Wh; d) chaque batterie doit être d'un type qui satisfait aux prescriptions de chaque épreuve de la sous-section 38.3 de la Partie III du Manuel d'épreuves et de critères de l'ONU; e) il est interdit de recharger les appareils et/ou batteries à bord de l'aéronef; |
| () | | | | I. | ı | , |

APPENDIX B

E-CIGARETTE DEVICE SMOKE/HEAT/FIRE EVENTS

(Specific to Carry-On Baggage Since May 25, 2015)

| Date | Source | Type of Battery | Device (if applicable) | Carrier | Aircraft Type (Passenger or Cargo) | Incident Summary |
|------------|-------------------------|--------------------|------------------------------|----------------------|---|---|
| 5/14/2017 | Airport Authority | Li-ion | E-cig | N/A | N/A | Information, including video footage, from the Seattle Airport Authority and witness statements show an individual's e-cig exploding, resulting in burning of his shirt and backpack. |
| 4/19/2017 | Carrier | Li-ion | E-cig | Southwest | Passenger | Passenger on Southwest flight number 4639 from Columbus, OH to Chicago, IL (MDW) reported to a flight attendant that there was smoke coming from her purse. Passenger was carrying an e-cigarette/vaping device. The flight attendant put the e-cigarette/vaping device and two spare lithium ion batteries into a fire safe bag to extinguish the smoke. |
| 4/9/2017 | Media | Li-ion | E-cig | N/A | N/A | A passenger was at Hudson News convenience store, near gate "D" in LAS airport prior to boarding a flight. Left front pocket exploded and fire erupted. Passenger was burned and hospitalized with burns to his left thigh and left hand. |
| 12/15/2016 | Carrier | Lithium -ion | E-cig | American Airlines | Passenger | American Airlines flight 1129, which was en route from Dallas-Fort Worth, TX to Indianapolis IN, diverted to Little Rock, AR, after a passenger observed that his e-cigarette had overheated and was emitting smoke. The cabin crew used fire extinguishers to extinguish the e-cigarette. |
| 10/30/2016 | Carrier/SPO T Report | Lithium -ion | E-cig | Alaska | Passenger | At Ketchikan, AK (KTN) airport, during boarding of Alaska Airlines flight 67, a passenger's backpack containing an ecigarette caught fire. The passenger dumped contents on the floor and crew used fire extinguishers to put out the fire. No injuries reported. Scorch marks to carpet of the aircraft were the result of the fire. |
| 9/7/2016 | Airport Operations | Lithium -ion | E-cig | N/A | N/A | As a passenger was entering the baggage claim area of DAL airport an e-cig in her purse exploded and burned the purse, some of its contents and charred her shirt. Witnesses stated there were small projectiles, which were on fire exiting her purse. They were extinguished by people standing at the baggage claim area waiting for their bags. |

| Date | Source | Type of Battery | Device (if applicable) | Carrier | Aircraft Type (Passenger or Cargo) | Incident Summary |
|-----------|---------|--------------------|------------------------------|-----------------------|---|--|
| 6/14/2016 | Carrier | Lithium -ion | E-cig | Spirit | Passenger | During boarding a passenger was carrying a backpack when another passenger noticed the fire. The plane was offloaded immediately. The DEN Fire Department responded, extinguished the fire and determined the e-cigarette in the carryon bag (backpack) was the cause. The aircraft was cleared, cleaned and put back in service. The passenger chose to take the remains of the backpack with him. |
| 6/10/2016 | Carrier | Lithium -ion | E-cig | Spirit | Passenger | Flt 765 from San Jose Costa Rica to Fort Lauderdale, e-cig began to smoke in a passenger's backpack on seat. Fire extinguished with a fire extinguisher and then the e-cig was submerged in water. Flight continued and landed in FLL without further issues. |
| 3/16/2016 | Carrier | Lithium -ion | E-cig | Delta | Passenger | DL flt 689- E-cig in passenger's carry-on caught fire during boarding process. Fire extinguished by flt attendant |
| 6/17/2015 | Carrier | Lithium -ion | E-cig | Southwest Airlines | Passenger | During a Southwest flight from LAS-ALB a passenger stated he felt the e-cigarette in his pants pocket pop and he leg began to burn. When he removed the e-cig from his pocket he saw the battery shoot out of the device. The e-cig was cracked and smoking. The crew submerged the battery and device in water. The passenger had minor burns on his leg but refused medical attention upon arrival in ALB. |