

Identification		Shortcomings/Deficiencies				Corrective action			
Requirements	States/Facilities	Description	Date first reported	Implement- ation status	Comments	Description	Executing body	Date of completion	Priority
1	2	3	4	5	6	7	8	9	10
AFI/7, Rec. 10/4	Angola /Cuito Cuanavale	VOR/DME	15/01/98	S		Implement facility	Angola		U
	Angola/Huambo	VOR/DME	15/01/98	D		To repair	“	2001	A
	Angola/Kuito	VOR/DME	15/01/98	S		Implement facility	“	2001	A
	Angola/Luena	VOR/DME	15/01/98	S		Implement	”	2001	U
	Angola/Saurimo	VOR/DME	15/01/98	S		“	”	2001	U
	Cameroon /Foumban	VOR	15/01/98	S		Implement facility	Cameroon		U
	Cameroon/Maroua	VOR	15/01/98	S		“	Cameroon		A
	Côte d’Ivoire /Bouake	ILS 21	1/1/97	D		To repair	Côte d’Ivoire		A
	Dem. Rep. of Congo /Kalemie	VOR/DME	15/1/98	D		To repair	D.R. Congo		U
	Dem. Rep. of Congo/Kindu	VOR	15/01/98	S		Implement facility	“		U
	Dem. Rep. of Congo/Kinshasa	DME	15/1/98	D		To repair	“		A
	Dem. Rep. of Congo/Kisangani	VOR/DME	15/01/98	D		“	”		A

Identification		Shortcomings/Deficiencies				Corrective action			
Requirements	States/Facilities	Description	Date first reported	Implementation status	Comments	Description	Executing body	Date of completion	Priority
1	2	3	4	5	6	7	8	9	10
	Dem. Rep. of Congo/Lubumbashi	DME	15/1/98	D	Flight calibration not done	“	D.R. Congo		A
	Gambia /Banjul	DME	15/01/98	D	Unserviceable	To repair	Gambia		U
	Guinea /Kankan	VOR	15/01/98	S		Implement facility	Guinea		A
	Guinea/Labe	VOR	15/01/98	S		Implement facility	“		A
	Guinea/Nzerekore	VOR	15/01/98	S		“	”		A
	Guinea Bissau	ILS	1/10/99	D	Intermittent		Guinea Bissau		A
	Kenya /Mandera	VOR/DME	15/01/98	S		Implement facility	Kenya		U
	Kenya/Nairobi	All nav aids frequently not available VOR/DME*	1/4/98	⊘ ⊘	VOR MV, GV, TV Not calibrated	Improve maintenance and power supply	Kenya		⊘
	Kenya/Mombasa	VOR/DME unreliable	1/4/98	⊘		——“	Kenya		⊘

Identification		Shortcomings/Deficiencies				Corrective action			
Requirements	States/Facilities	Description	Date first reported	Implementation status	Comments	Description	Executing body	Date of completion	Priority
1	2	3	4	5	6	7	8	9	10
	Lesotho/Maseru	VOR/DME	15/01/98	D	OP on one unit	To repair	Lesotho		A
		ILS unreliable	15/01/98	D		“	“		A
	Liberia/Robertsfield	ILS 04	15/01/98	S		Implement facility	Liberia		A
	Libya/Benghazi	ILS 33L	15/01/98	S		Implement facility	Libya		A
	Libya/Sarir	VOR/DME	15/01/98	S		“	”		U
	Libya/Tripoli	ILS 09	15/01/98	S		“	”		A
	Madagascar/Antsiranana	VOR	15/1/98	D		To repair	Madagascar		U
	Madagascar/Morondava	VOR	15/01/98	S		Implement facility	Madagascar		A
	Madagascar/Nosy-Be/Fascene	ILS 23	15/01/98	S		“	”		A
	Madagascar/Nosy-Be/Fascene	VOR/DME	15/01/98	D		To repair	Madagascar		A
	Madagascar/Sainte Marie	VOR	15/01/98	S		Implement facility	“		A
	Madagascar/Tolagnaro	VOR/DME	15/01/98	S		“	”		U

Identification		Shortcomings/Deficiencies				Corrective action			
Requirements	States/Facilities	Description	Date first reported	Implementation status	Comments	Description	Executing body	Date of completion	Priority
1	2	3	4	5	6	7	8	9	10
	Madagascar/Toliara	VOR	15/01/98	S		“	”		U
	Mali/Kayes	VOR	15/01/98	S		Implement facility	Mali		U
	Mali/Kidal	VOR	15/01/98	S		“	”		A
	Mali/Nioro	VOR	15/01/98	S		“	”		A
	Mali/Tessalit	VOR	15/01/98	S		“	”		U
	Mali/Tombouctou	ILS 07	15/01/98	S		“	”		A
	Nigeria/Ilorin	ILS 05	15/01/98	S		Implement facility	Nigeria	2001	A
	Nigeria/Kano	ILS/DME VORDME	01/02/00	D	facilities not calibrated			2001	A
	Nigeria/Port Harcourt	ILS	01/10/99	D	Unservice-able		Nigeria	2000	A
	Sao Tome/Sao Tome	ILS 01	15/01/98	S		Implement facility	Sao Tome		A
	Sierra Leone Freetown/Lungi	ILS VOR/DME	01/01/99 01/01/99	D D	Unservice-able		Sierra Leone		A A
	Somalia/Hargeisa	VOR/DME	15/01/98	S		Implement facility	Somalia		U

Identification		Shortcomings/Deficiencies				Corrective action			
Requirements	States/Facilities	Description	Date first reported	Implementation status	Comments	Description	Executing body	Date of completion	Priority
1	2	3	4	5	6	7	8	9	10
	Somalia/Mogadishu	VOR/DME	15/01/98	S		“	”		U
	Sudan /Juba	ILS 13	15/01/98	S		Implement facility	Sudan		A
	Sudan/Juba	VOR/DME	15/01/98	S		“	”		U
	Sudan/Malakal	VOR/DME	15/01/98	S		“	”		U
	Sudan/Port Sudan	ILS 36	15/01/98	S		“	”		A
	Tanzania /Dar es Salaam	VOR/DME ILS RW 905	09/99	D	6° error	Repair in progress. DME being replaced. DVOR/DME contract signed	Tanzania	1999	U
	Tanzania/Dodoma	VOR/DME	15/01/98	S		Implement facility	Tanzania		U
	Tanzania/Kilimanjaro	ILS 09	15/01/98	S		“	”		A
	Tanzania/Kilimanjaro	VOR/DME	01/10/99	D	No flight check	“	“		
	Dar-Es-Salaam	DME	01/09/99	D	Unserviceable		Tanzania		A

Identification		Shortcomings/Deficiencies				Corrective action			
Requirements	States/Facilities	Description	Date first reported	Implementation status	Comments	Description	Executing body	Date of completion	Priority
1	2	3	4	5	6	7	8	9	10
	Tanzania/Mbeya	VOR/DME	15/01/98	S		“	”		U
	Tanzania/Mwanza	DME	15/01/98	S		DME being installed	”	1998	U
	Tanzania/Zanzibar	VOR/DME	15/01/98	S		Implement facility	Tanzania		A
	Zambia /Kaoma	VOR	15/01/98	S		Implement facility	Zambia		U
	Zambia/Livingstone	ILS 10	15/01/98	S		“	”		A
	Zambia/Ndola	ILS 10L	15/01/98	S		Implement facility	Zambia		A
	Zambia/West Two	VOR	15/01/98	S		“	”		U
