

Experience summary of FPP's previous training MA GANG



International Civil Aviation Organization
Asia and Pacific Regional Sub-Office

1st Floor, Section C, China Service Mansion
No. 9, Erwei Road, Shunyi District
Beijing, China 100621

Ma Gang + Flight Procedure Designer +

Mobile: +86-13661172308 (China)

Tel: +86-10-64557168

Fax: +86-10-64557164

Email: GMa@icao.int.



CONTENT

- Data Story of FPP
- Experience summary

Data Story of FPP



- Data mining
- Inspiration







Overview of FPP (Asia-Pacific)

"BIG DATA" OF FPP


"BIG DATA" OF FPP'S Training




"BIG DATA" OF FPP'S Training



"BIG DATA" OF FPP'S Training



"BIG DATA" OF FPP'S Previous



Instructors







Most active member?

DATA MINING

Active member (PANOPS Course)



Active member (PANOPS course)






Big data tell us


INSPIRATION



"TAKE OFF" from FPP



"TAKE OFF" from FPP



NEXT STEP

- Full DOC 8168 training
 - PANOPS + PBN
 - Suitable Duration of Training
- Specialized Workshops
 - VNAV, ILS CAT II/III, CRM, Path terminator

Experience summary



Data MGT VS Situation MGT

- Mutual cooperation
- New challenges




How to design a IFP

DATA MGT(MANAGEMENT) VS SITUATION MGT

IFPD Experience summary

Data management VS Situation



IFPD Experience summary

Situation:

MA segment

Obs at ENTR

Data management



Better ~ Best

MUTUAL COOPERATION



Mutual cooperation

Cir 336 "RNAV to RNP Instrument Approach Chart Depiction"




Figure 1-1. New PBN chart designation (with PBN requirements box)



mutual cooperation

the Display of MCDU



mutual cooperation

RNP RWY 23

RNP RWY 24 (AR)

RNV XX

RNAV (GPS) RWY 23


RNAV (RNP) RWY 24

RNV XX



Mutual cooperation


EOSID





Mutual cooperation

Protection area for EOSID VS IFP



If VPA < 2.5

NEW CHALLENGES

