

Aerodromes in APAC Region used for International Operations and yet to be certified

S. No in APAC Database	Sub-region	State / Admin	ICAO Code	Name of City	Name of Aerodrome
1	SA	Afghanistan	OAHR	Herat	Herat Intl
2	SA	Afghanistan	OAKB	Kabul	Kabul Intl
3	SA	Afghanistan	OAKN	Kandahar	Kandahar Intl
4	SA	Afghanistan	OAMS	Mazar-e-Sharif	Mazar-e-Sharif
42	SEA	Brunei	WBSB	Brunei	Brunei Intl
73	NA	China	RCYU	Hualien	Hualien
107	NA	China	RCMQ	Taichung	Cingcyuangang
108	NA	China	RCNN	Tainan	Tainan
149	SA	India	VICG	Chandigarh	Shaheed Bhagat Singh Intl
154	SA	India	VOGO	Goa	Dabolim
155	SA	India	VEGK	GORAKHPUR	Mahayogi Gorakhnath
157	SA	India	VIDX	HINDAN	Hindon
161	SA	India	VIJO	JODHPUR	Jodhpur
172	SA	India	VOPB	Port Blair	Veer Savarkar Intl
173	SA	India	VAPO	Pune	Jagadguru Sant Tukaram Maharaj
175	SA	India	VISR	Srinagar	Srinagar
180	SA	India	VOVZ	VISAKHAPATAN	Visakhapatnam Intl
250	PAC	Kiribati	PLCH	Kiritimati	Christmas I.
251	PAC	Kiribati	NGTA	Tarawa	Bonriki Intl
253	SEA	Lao PDR	VLLB	Luangprabang	Luangprabang Intl
254	SEA	Lao PDR	VLSK	Kaisonphimvihan	Savannakhet Intl
255	SEA	Lao PDR	VLPS	Pakse	Pakse Intl
264	SEA	Malaysia	WMKD	Kuantan	Haji Ahmad Shah
282	PAC	Micronesia	PTPN	Pohnpei I.	Pohnpei Intl
283	PAC	Micronesia	PTKK	Weno I.	FM Chuuk Intl
284	PAC	Micronesia	PTYA	Yap I.	Yap Intl
285	PAC	Micronesia	PTSA	Kosrae I.	Kosrae
292	PAC	Nauru	ANYN	Nauru I.	Nauru intl
321	SEA	Philippines	RPVK	Kalibo, Aklan	Kalibo Intl [*]
325	SEA	Philippines	RPLC	Pampanga	Diosdado Macapagal Intl [*]

S. No in APAC Database	Sub-region	State / Admin	ICAO Code	Name of City	Name of Aerodrome
326	SEA	Philippines	RPVP	Puerto Princesa City	Puerto Princesa Intl [*]
327	SEA	Philippines	RPSP	Panglao	Bohol-Panglao Intl [*]
350	SEA	Thailand	VTSG	Krabi	
357	SEA	Timor Leste	WPDB	Suai	Commander-in-Chief of the FALINTIL – Kay Rala Xanana Gusmão Intl
360	PAC	Tuvalu	NGFU	Funafuti	Funafuti Intl

* Airports granted with temporary aerodrome certificates

States / Administrations that have yet to publish the status of
certification of aerodromes in AIP AD 1.5

States	North Asia (5 States & 2 SARs)	South East Asia (11 States)	South Asia (8 States)	Pacific (15 States & 8 OTs)
Status of Certification of aerodromes not listed in AD 1.5/ or AD 1.5 missing in AIP	--	1) Brunei Darussalam	1) Afghanistan	1) Kiribati 2) Nauru 3) Tuvalu 4) Marshall Is. 5) Micronesia (Federated States of) 6) Palau
Total (8 States)	0 State	1 State	1 State	6 States / OTs

Notes:-

The following States that have published the status of Certification of Aerodromes in other Section of AD in AIP as below are encouraged to publish the same in AIP AD 1.5:

- 1) Solomon Islands - AD 1.1, 1.1.5
- 2) US Territories (American Samoa, Guam and Northern Mariana Islands) – AD 2.6.

Appendix C to the Report of AP-AA/WG/7

**Status of RST Establishment based on ICAO RST Survey and State's Response to ICAO APAC SL
Ref.: T 11/5.13.2 – AP111/24 (AGA) on 3 September 2024**

States	Number of Aerodromes that Established RST	% Established	No information or Not Established	Total Aerodromes
Afghanistan	0	0%	4	4
American Samoa	0	0%	1	1
Australia	4	14%	24	28
Bangladesh	0	0%	3	3
Bhutan	1	50%	1	2
Brunei	0	0%	1	1
Cambodia	0	0%	3	3
China	1	1%	88	89
Cook Islands	0	0%	2	2
DPR Korea	0	0%	2	2
Fiji	1	50%	1	2
French Polynesia	0	0%	1	1
Guam	0	0%	1	1
Hong Kong, China	1	100%	0	1
India	20	54%	17	37
Indonesia	23	70%	10	33
Japan	0	0%	36	36
Kiribati	0	0%	2	2
Lao PDR	0	0%	4	4
Macao, China	1	100%	0	1
Malaysia	18	95%	1	19
Maldives	1	20%	4	5
Marshall Islands	0	0%	1	1
Micronesia	0	0%	4	4
Mongolia	1	33%	2	3
Myanmar	3	100%	0	3
Nauru	0	0%	1	1
Nepal	1	33%	2	3
New Caledonia	0	0%	1	1
New Zealand	0	0%	6	6
Niue	0	0%	1	1
N. Mariana Is.	0	0%	3	3
Pakistan	9	90%	1	10
Palau	0	0%	1	1
Papua New Guinea	0	0%	1	1

States	Number of Aerodromes that Established RST	% Established	No information or Not Established	Total Aerodromes
Philippines	7	78%	2	9
Rep. of Korea	0	0%	8	8
Samoa	0	0%	2	2
Singapore	2	100%	0	2
Solomon Islands	0	0%	2	2
Sri Lanka	1	33%	2	3
Thailand	10	100%	0	10
Timor Leste	0	0%	2	2
Tonga	0	0%	2	2
Tuvalu	0	0%	1	1
Vanuatu	0	0%	3	3
Viet Nam	1	10%	9	10
Wallis et Futuma	0	0%	1	1
Total	106	28.65%	264	370

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

[Endorsed and Updated by APANPIRG/35]

Updated on 16 Dec. 2020

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Afghanistan</u>							
	Herat International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	Kabul International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	Kandahar International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	Mazar-e-Sharif Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
Annex 14 Volume I PANS- Aerodromes PANS-AIM	AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 12 June 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Bangladesh</u> Hazrat Shahjalal International Airport, Dhaka	Runway/ Taxiway	ICAO mission April 2009	Runway strip width insufficient (280m strip not available for the full length of runway);	runway strip in accordance with Annex 14, Volume I will be provided	CAABD	Runway strip width 280m available for the full length of runway (Mitigation measures for storm water drain on the western side strip, is being replaced with concrete hollow pipes into graded surface. Construction work has been completed for around 1000m out of the 3200m length of the runway and the total work will be completed by June 2025. No obstructions on graded area).	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 16 Dec. 2020

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Brunei Darussalam</u> Brunei International Airport	Taxiway	ICAO Mission of April 2011	non provision of enhanced taxiway centre line marking in accordance with Para 5.2.8 of Annex 14, Volume I Objects on taxiway strips; vegetation on pavement joints and maintenance of joints	Both Northern Parallel Taxiway and Southern Parallel Taxiway Centre line have been repainted yellow and enhanced with black borders on each side.	Airport Operator (DCA Aerodrome Division)		A
		Apron		non provision of ICAO compliant signage in accordance with section 5.4 Annex 14, Volume I	Airfield signages have always been provided at BIA that follow ICAO standards and measurement. Recent replacement of old and faded labels have also been completed in 2018.	Airport Operator (DCA Aerodrome Division)		A
		Rescue and Fire Fighting (RFF):		non provision of direct access for the rescue and fire fighting vehicles from the fire station into the runway;	Duly noted that there is no direct access for fire fighting vehicles to the runway at the moment, but one will be concluded within the second phase of the Airfield Pavement Rehabilitation Project.	Airport Operator (DCA Aerodrome Division)	4th Qtr. 2022	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
		Wildlife Hazards:		Establishing a national bird control committee in accordance with APANPIRG Conclusion 18/1.	Aerodrome Division headed by Head of Aerodrome to firstly establish an in-house committee and will cooperate with Regulatory Division	Airport Operator (DCA Aerodrome Division)	4th Qtr. 2021	B
	Brunei International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
Annex 14 Volume I PANS- Aerodromes PANS-AIM	AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 25 June 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>China</u>							
	Hualien Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	Taichung Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	Tainan Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 25 June 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14, Volume I	<u>India</u> Mumbai International Airport	Runway	AGA mission January 2009	Runway strip is insufficient 300m strip width is not available for the full length of runway 09/27 in accordance with 3.4.3 of Annex 14, Volume I.	280m strip width for full length of runway 09/27 will be made available	MIAL	<u>31 Dec 2026</u> Land acquisition in progress. MIAL has filed temporary exemption with DGCA for non-compliance. Due to presence of slum in beginning of RWY 09/27 south – RWY strip 280m not available.	A
Annex 14 Volume I	Chandigarh Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified. – Defence Aerodrome				A
Annex 14 Volume I	Goa Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified. – Defence Aerodrome				A
Annex 14 Volume I	Port Blair Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified. – Defence Aerodrome				A
Annex 14 Volume I	Pune Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified. – Defence Aerodrome				A
Annex 14 Volume I	Srinagar Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified. – Defence Aerodrome				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
	<u>India</u>							
Annex 14	GORAKHPUR (VEGK)	Aerodrome Certification	25 June 2024	Aerodrome yet to be certified. – Defence Aerodrome				A
Volume I	HINDAN (VIDX)	Aerodrome Certification	25 June 2024	Aerodrome yet to be certified. – Defence Aerodrome				A
Annex 14	JODHPUR (VIJO)	Aerodrome Certification	25 June 2024	Aerodrome yet to be certified. – Defence Aerodrome				A
Volume I	VISAKHAPATNAM (VOVZ)	Aerodrome Certification	25 June 2024	Aerodrome yet to be certified				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 16 June 2023

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Kiribati</u>							
	Christmas Island Airport, Kiritimati	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	Issued with the Interim Certificate since the Operator is not yet fully complied to the requirements	Airport Kiribati Authority	31 Dec 2023	A
	Bonriki International Airport, Tarawa	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	The Aerodrome Operator is not yet fully complied to the requirements	Airport Kiribati Authority	31 Dec 2023	A
Annex 14 Volume I PANS-Aerodromes PANS-AIM	AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.	The AIP will be amended to include this deficiency	Civil Aviation Authority of Kiribati (CAAK)	15 Oct 2023	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 11 July 2023

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Lao PDR</u>							
	Wattay International Airport	Taxiway	ICAO Mission of March 2011	Provision of stop bars at runway-holding position in accordance with Para 5.3.20 of ICAO Annex 14, Volume I	AOL request exemption to DCAL and proposed to install in Long Term Plan.	Airport of Laos (AOL)	DCA exempt of runway hold position lights in accordance to AOL and mention in the Certification.	A
		Wildlife Hazards:		Establishing a national bird control committee in accordance with APANPIRG conclusion 18/1.	DCAL to propose prime minister decree and establish national committee accordingly.	Department of Civil Aviation of Lao PDR (DCAL)	To be completed in 2024	B
	Luang Prabang International Airport	Taxiway		Provision of runway hold position lights in accordance with Para 5.3.19 of ICAO Annex 14, Volume I on new taxiways	Under consideration by Airports of Laos to purpose for support the budgets and installation	AOL	We have planned budgets and installation during 2021 to 2025	A
		Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.		DCAL and AOL	Aerodrome Certification will be completed in December 2023 (on Process)	A
	Savannakhet International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.		DCAL and AOL	Aerodrome Certification will be completed in December 2024	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
	Pakse International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.		DCAL and AOL	Aerodrome Certification will be completed in December 2024	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on ~~17 July 2024~~ 24 March 2025

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Malaysia</u> Kuantan Haji Ahmad Shah Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	Coordination among Ministry of Transport, Ministry of Defense and Airport Operator are being conducted to get the aerodrome certified	Ministry of Transport and Ministry of Defense	June 2025	A
	Labuan Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	Coordination among Ministry of Transport, Ministry of Defense and Airport Operator are being conducted to get the aerodrome certified	Ministry of Transport and Ministry of Defense	Dec. 2024 Certified on 01 March 2025 [Resolved]	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 16 Dec. 2020

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I PANS- Aerodromes PANS-AIM	<u>Marshall Islands</u> AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 16 Dec. 2020

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Micronesia</u> <u>(Federated</u> <u>States of)</u> Pohnpei International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	FM Chuuk International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	Yap International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
	Kosrae Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.				A
Annex 14 Volume I PANS- Aerodromes PANS-AIM	AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on ~~16 Dec. 2020~~ 17 April 2025

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Nauru</u> Nauru International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	Initiate the aerodrome certification process in accordance with ICAO Annex 14 requirements, including gap analysis, preparation of the Aerodrome Manual, stakeholder coordination, and on-site compliance inspection.	Nauru Civil Aviation Authority	Q4 2027(Subject to ICAO and Donor Support)	A
Annex 14 Volume I PANS-Aerodromes PANS-AIM	AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.	Update and publish the certification status of the aerodrome in AIP section AD 1.5 upon progress or completion of the certification process, as per PANS-AIM guidelines.	Nauru Civil Aviation Authority	Q4 2027(Subject to ICAO and Donor Support)	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 16 Dec. 2020

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I PANS- Aerodromes PANS-AIM	<u>Palau</u> AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.				A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 27 March 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Philippines</u>							
	Kalibo International Airport, Akla	Aerodrome Certification	Effective from 1 Jan 2021	Permanent aerodrome certificate yet to be issued.			Temporary Aerodrome Certificate issued with validity from 2 Jan. 2024 until 30 June 2024 Status of Aerodrome Certification as of 22 Feb. 2024 (As per CAAP Website)	A
	Puerto Princesa International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Permanent aerodrome certificate yet to be issued.			Temporary Aerodrome Certificate issued with validity from 10 Dec. 2023 – 10 Jun. 2024. Status of Aerodrome Certification as of 22 Feb. 2024 published in CAAP Website.	A
	Bohol-Panglao International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Permanent aerodrome certificate yet to be issued.			Temporary Aerodrome Certificate issued with validity from 30 Dec. 2023 – 29 Jun. 2024. Status of Aerodrome Certification as of 22 Feb. 2024 published in CAAP Website.	A
	Diosdado Macapagal International Airport RPLC	Aerodrome Certification	6 March, 2023	Permanent aerodrome certificate yet to be issued.			Temporary Aerodrome Certificate issued with validity from 7 Jan. 2024 until 7 Jul. 2024. Status of Aerodrome Certification as of 22 Feb. 2024 published in CAAP Website.	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 16 Dec. 2020

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Mongolia</u> Buyant-Ukhaa Airport	Taxiway	ICAO Mission of July 2011	provision of runway hold position lights in accordance with Para 5.3.19 of ICAO Annex 14, Volume I.	The runway hold position lights will be provided in accordance with Para 5.3.19 of ICAO Annex 14, Volume I.	Civil Aviation Authority of Mongolia	The RWY hold position marking and mandatory signs were provided to avoid runway incursions on the maneuvering area. Because of the existing International scheduled flights will be transferred to new airport in 2020, the additional runway hold position lights are unrequired to install.	A
		Apron: Airfield signage		Provision of ICAO compliant signage in accordance with section 5.4 Annex 14, Volume I and to cut the vegetation in front of the signs.	The signage will be provided in accordance with section 5.4 Annex 14, Volume I. The vegetation in front of the signs will be cut	Civil Aviation Authority of Mongolia	The work on cutting the vegetation in front of the signs was completed in 2017 within the totally 119560 m ² area including, taxiway strip, glide path antenna and apron area, as per Aerodrome manual of, in scope of Aerodrome maintenance plan. [Note: Partially completed]	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 15 June 2021

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Myanmar</u> Yangon International Airport	Runway/ Taxiway	ICAO mission April 2010	Provision of RESA in accordance with Section 3.5 of Annex 14, Volume I requirements;	RESA will be provided	Yangon Aerodrome Company Limited	(Risk Assessment conducted by the operator submitted on 10 Aug 2018.) RESA for RWY 21 was completed on 15 Nov 2018. Revised date- 31 Dec 2021	A
		Bird Hazard		Establishment of a national bird committee in accordance with APANPIRG Conclusion 18/1.	Establish National Bird Committee	Department of Civil Aviation	Guideline for Wildlife Hazard Management at Aerodromes, DCA-GM-AGA 08 has been developed and published on 29 Oct 2018) Revised date- 30 Nov 2021	B

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 20 June 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14, Volume I	<u>Nepal</u> Tribhuvan International Airport	Runway/ taxiways	ICAO Mission of February 2008	Insufficient runway strip, refer recommendations given in section 3.4 of Annex 14, Volume I.	Provide runway strip as per ICAO recommendations	Air Transport Capacity Enhancement Project (ATCEP) under Civil Aviation Authority of Nepal	Construction works are in progress to improve and provide airside infrastructures in accordance with Ultimate Master Plan of Tribhuvan International Airport, which will provide sufficient runway strip with target complete implementation of the plan by 2026.	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on ~~27 March 2024~~ 16 May 2025

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Samoa</u> Faleolo International Airport	Runway Strip	ICAO Mission of Oct. 2015	Insufficient Runway Strip	A 2013 Rule Exemption based on a comprehensive aeronautical study supports the 150 m runway strip width and the State has therefore accepted the lesser width. The recent changes to ICAO Annex 14 and NZ CAR Part 139 denote that the Faleolo Airport runway strip width meets the requirements for a non-precision instrument approach runway at 150 m overall width.	Civil Aviation Authority Samoa	Complete	A
		Aerodrome Pavements		Lack of maintenance of aerodrome pavements in accordance with Annex 14, 10.2	Faleolo International Airport upgraded its pavement for movement area in 2019 where a PAVÉR (software) training was conducted for the aerodrome operator personnel on the need to have a pavement maintenance plan.	Aerodrome Operator	December 2026	U

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 27 March 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Solomon Islands</u> Honiara International Airport/Hender son Field	Runway Strip	ICAO Mission of Oct. 2015	Insufficient Runway Strip				A
		RESA		RESA at both ends of runway not provided				U
		Aerodrome Pavements		Lack of maintenance of aerodrome pavements in accordance with Annex 14, 10.2				U

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 15 June 2022

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Sri Lanka</u> Bandaranaike International Airport	Runway/ Taxiway	ICAO mission April 2010	Provision of 280m strip width for the full length of precision approach CAT I runway in accordance with the standard 3.4.3, Annex 14, Volume I; remove obstacles from runway strip; flush the strip with the adjacent runway shoulder.	runway strip in accordance with Annex 14, Volume I will be provided, obstacles from strip will be removed and flush strip with adjacent runway shoulder.	CAASL	Statistical analysis submitted by AASL has been accepted in 2021. Request made to submit the improved risk assessment with necessary amendments within 2022.	A
				Establishment of a national bird committee in accordance with APANPIRG Conclusion 18/1.	National Bird Committee will be established.		A meeting to be held with all stakeholders to establish the Committee and to ratify the TOR by end of September 2022.	

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on ~~28 June 2024~~ 24 March 2025

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14, Volume I	<u>Thailand</u> Phuket International Airport	Runway	AGA mission of July 2009	RESA to satisfy Section 3.5 of Annex 14, Volume I requirements.	RESA will be provided at the end of both RWY09 and RWY27 to satisfy Section 3.5 of Annex 14, Volume I requirements. Remark: - Dimension of RESA RWY09 is 150x190 m. - Dimension of RESA RWY27 is 150x120 m.	Airports of Thailand Public Company Limited	The construction is expected to be completed in 2024. Airports of Thailand Public Company Limited already has had the contractor for this construction's project and the safety assurance and project management documentation has been approved by the Civil Aviation Authority of Thailand to ensure that the aerodrome can continue to operate safely during the project. Currently, the construction progress is 81.23%	U
				Runway strip width insufficient (280m runway strip for precision approach runways in accordance with Para 3.4.3 of Annex 14, Volume I.	300m runway strip width will be made available. Except 111.4m length at the beginning of RWY09 (60m strip length before RWY09 threshold plus 51.4m length beyond the threshold), the runway strip width will be extended 150m on the right		The construction is expected to be completed in 2024. Airports of Thailand Public Company Limited already has had the contractor for this construction's project and the safety assurance and project management documentation has been approved by the Civil	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
					side of RWY09 centre line and 90.27m on the left side of the runway centre line (due to the marsh near the runway).		Aviation Authority of Thailand to ensure that the aerodrome can continue to operate safely during the project. Currently, the construction progress is 81.23%	
	Krabi Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	Certify the aerodrome in accordance with aerodrome certification requirements	The Civil Aviation Authority of Thailand and Department of Airports	31 December 2024	A
	Surat Thani Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	Certify the aerodrome in accordance with aerodrome certification requirements	The Civil Aviation Authority of Thailand and Department of Airports	31 December 2024 Certified on 28 December 2025 [Resolved]	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 17 June 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Timor-Leste</u>	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	To be certify for its designed category (3C) the significant safety issue relating to AD strip (local houses and habitants must be relocated!) should be resolved.	Gov. TL and ANATL as AD operator	Estimated date: 31 December 2024	A
	Commander-in- Chief of the FALINTIL – Kay Rala Xanana Gusmão International Airport, Suai				• There is ongoing process of reallocation of the houses and habitants within the AD strip; • There is a process of the establishment of the manuals, SOPs, various Airport committees (ASC- RSCA, ERC) • Currently AD is occasionally in use for domestic general aviation and helicopters only.			

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 27 March 2024

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Tonga</u> Fua'amotu International Airport	Runway Strip	ICAO Mission of Oct. 2015	Insufficient Runway Strip	1. File of difference to ICAO Annex 14 Volume I 3.4.4 through CMA-OLF and the publication of significant difference in the AIP Tonga - CAR 139.C.2.2 details that the strip width for aerodrome reference code number 4, non-precision runway must extend laterally on each side of the centre line of the runway and its extended centre line throughout the length of the strip to the minimum distance of 75m. 2. Provide 240m runway strip width at Fuaámotu International Airport.	CAD Office	1. 28 December 2023 2. 31 December 2030	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

Updated on 1 Nov. 2022

Identification		Deficiencies			Corrective Action			
Requirements	States/facilities	Description	Date first reported	Remarks	Description	Executing body	Target date of completion	Priority for action**
Annex 14 Volume I	<u>Tuvalu</u> Funafuti International Airport	Aerodrome Certification	Effective from 1 Jan 2021	Aerodrome yet to be certified.	Aerodrome yet to be certified.		Part 139 Aerodrome Certification in progress for 2023	A
Annex 14 Volume I PANS- Aerodromes PANS-AIM	AIP	Status of Certification of Aerodromes in AIP	Effective from 1 Jan 2021	Status of certification of aerodromes yet to be published in AIP AD 1.5.	Status of certification of aerodromes yet to be published in AIP AD 1.5.		Update Tuvalu AIP Info	A

AIR NAVIGATION DEFICIENCIES IN AOP FIELD IN THE ASIA/PACIFIC REGION

* Priority for action to remedy the shortcoming is based on the following safety assessments:

“U” priority = Urgent requirements having a direct impact on safety and requiring immediate corrective actions. Urgent requirement consisting of any physical, configuration, material, performance, personnel or procedures specification, the application of which is urgently required for air navigation safety.

“A” priority = Top priority requirements necessary for air navigation safety. Top priority requirement consisting of any physical, configuration, material, performance, personnel or procedures specification, the application of which is considered necessary for air navigation safety.

“B” priority = Intermediate requirements necessary for air navigation regularity and efficiency. Intermediate priority requirement consisting of any physical, configuration, material, performance, personnel or procedures specification, the application of which is considered necessary for air navigation regularity and efficiency.



APANPIRG
AERODROMES OPERATIONS AND PLANNING SUB-GROUP (AOP/SG)

LIST OF AOP FOCAL POINTS [Updated on 30 July 2024]

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
1.	AFGHANISTAN			
	1.	Engineer Najibullah	Head of Aerodrome Standardization Afghanistan Civil Aviation Authority	– najib0107@gmail.com ;
2.	AUSTRALIA			
	2.	Mr. Rodney Evans	ARFF Standards Lead Airservices Australia Eastern Avenue Bilinga Coolangatta Airport PO Box 300 Coolangatta QLD 4225	Tel: +61 7 5599 5909 Fax: +61 7 5590 2718 Rodney.Evans@airservicesaustralia.com ;
3.	BHUTAN			
	3.	Mr. Sangay Wangdi	Head of Aerodrome Bhutan Civil Aviation Authority Paro International Airport, Paro, Bhutan	Tel: +975-8-271 911 Mob: +975-17119277 Fax: +975-8-271 909 swangdi@bcaa.gov.bt ;
4.	BRUNEI DARUSSALAM			
	4.	Mr. Mohamad Fauzi bin Mohamad Sidek	Acting Deputy Director (Regulator) Department of Civil Aviation Brunei Darussalam	Tel: +673 233 0142 Mob: +673 816 8909 ddca.regulatory@dca.gov.bn ;
	5.	Mr. Pg Rasman bin Pg Sulaiman	Aerodrome Inspector Department of Civil Aviation Brunei Darussalam	Tel: +673 233 0142 Mob: +673 885 4714 rasman.sulaiman@dca.gov.bn ;
	6.	Ms. Norhidayah Haji Ismail	Air Traffic Control Officer (ANS Inspector) Department of Civil Aviation Brunei Darussalam	Tel: +673 233 0142 Mob: +673 883 4614 norhidayah.ismail@dca.gov.bn ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
5.	CAMBODIA			
	7.	Mr. Cheav Vin	Director (Chief Aerodrome Inspector) of Department of Airport Standards and Safety, State Secretariat of Civil Aviation #44, Phnom Penh International Airport, Russian Blvd., Phnom Penh	Tel: +855 23 890 198 Mob: +855 12 96 88 76 vincheav@gmail.com ;
	8.	Mr. Eng Samreth	Deputy Director (Senior Aerodrome Inspector) of Department of Airport Standards and Safety, State Secretariat of Civil Aviation #44, Phnom Penh International Airport, Russian Blvd., Phnom Penh	Tel: +855 23 890 198 Mob: +855 98 628 811 engsamreth@gmail.com ;
	9.	Mr. Sok Sithpisey	Chief Bureau (Aerodrome Inspector) of Department of Airport Standards and Safety, State Secretariat of Civil Aviation #44, Phnom Penh International Airport, Russian Blvd., Phnom Penh	Tel: +855 23 890 198 Mob: +855 17 800 297 soksithpisey@gmail.com ;
6.	CHINA			
	10.	Mr. Ma Zhigang	Deputy Director General Department of Airport Civil Aviation Administration of China (CAAC) No.155 Dongsi Xidajie, Dong Cheng Dist., Beijing	Tel: +8610 64091804 Fax: +8610 64019967 zhg_ma@caac.gov.cn ;
	11.	Ms. Lyu Qing	Deputy Assistant Division Chief Civil Aviation Administration of China No. 155, Dongsi Xidajie, Beijing 100710	Tel: +8610 6409 2804 lvqing@caac.gov.cn ;
	12.	Mr. Liang Shixin	Intermediate Engineer CAAC General Station of Quality Supervision of Specialized Engineering No. 6 Yutong East St., Chaoyang Dist., Beijing,	Tel: +86 18801 297577 liangshixin@caac.gov.cn ;

LIST OF AOP FOCAL POINTS

NAME			TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
	13.	Mr. Guo Jingcheng	Deputy Consultant Airport Division, Civil Aviation Administration of China (CAAC), Beijing, China	Tel: +86 010-64092854	guojingcheng@caac.gov.cn ;
	14.	Mr. Yu Yali	Department of Airport Civil Aviation Administration of China	–	yl_yu@caac.gov.cn ;
HONG KONG CHINA					
	15.	Mr. Samuel NG	Assistant Director-General of Civil Aviation (Airport Standards) Civil Aviation Department Civil Aviation Department Headquarters 1 Tung Fai Road, Hong Kong Int'l Airport, Lantau, Hong Kong China	Tel: +852-2910 6010 Fax: +852-2795 8469	sng@cad.gov.hk
	16.	Ms. Rosa YIP	Acting Chief Safety Officer (Airport & Safety Regulation) Civil Aviation Department	Tel: +852-2910 6968 Fax: +852-2795 8469	rmlyip@cad.gov.hk
	17.	Mr. David WAN	Senior Safety Officer (Aerodrome and Safeguarding Regulation) Civil Aviation Department	Tel: +852-2910 6147 Fax: +852-2795 8469	dkdwan@cad.gov.hk
	18.	Miss Boleyn NG	Acting Senior Safety Officer (Airport) Civil Aviation Department	Tel: +852-2910 6973 Fax: +852-2795 8469	pmng@cad.gov.hk
	19.	Miss Carman YEUNG	Acting Senior Safety Officer (Airport) Civil Aviation Department	Tel: +852-2910 6970 Fax: +852-2795 8469	cnmyeung@cad.gov.hk
MACAO CHINA					
	20.	Mr. LAM Tat Ming (Taft)	Director of Airport Infrastructure & Air Navigation Civil Aviation Authority, Macao, China	Tel: +853 2851 1213 +853 8796 4120 Fax: +853 2833 8089	taftlam@aacm.gov.mo ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
7.	COOK ISLANDS			
	21.	Mr. John Hosking	Ministry of Transport PO Box 61 Avarua, Rarotonga, Cook Islands	Tel: +682 28810 john.hosking@cookislands.gov.ck ;
	22.	Mr. Dennis Hoskin	Ministry of Transport PO Box 61 Avarua, Rarotonga, Cook Islands	Tel: +682 28810 dennis.hoskin@cookislands.gov.ck ;
8.	DPR KOREA (1)			
	23.	Mr. Rim Chong Il	Deputy Director of Aerodrome Department General Administration of Civil Aviation DPR of Korea	Tel: +8502 18111 Ext. 8108 Fax: +8502 3814410 Ext. 4625 gaca@silibank.net.kp ;
9.	FIJI (1)			
	24.	Mr. Ratu Maibulu Q. Laliqavoka	Technical Officer Aerodromes, Ground Safety Department Civil Aviation Authority of Fiji Private Mail Bag NAP 0354, Nadi International Airport, Nadi	Tel: +679 672 1555 Mob: +679 992 8949 maibulu.laliqavoka@caaf.org.fj ;
10.	INDIA			
	25.	Mr. Dinesh Chand Sharma	Joint Director General of Civil Aviation Directorate General of Civil Aviation Aerodrome Standards Directorate, DGCA Hqrs., New Delhi 110003	Tel: +91 11 2465 3883 dcsharma.dgca@nic.in ;
	26.	Mr. Amit Srivastava	Deputy Director of Operations Directorate General of Civil Aviation Aerodrome Standards Directorate, DGCA Hqrs., Opp. Safdarjung Airport, New Delhi 110003	Tel: +91 11 2462 2495 amits.dgca@nic.in ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
11.	INDONESIA			
	27.	Ms. Ade Trisetyo Aerodrome Inspector Directorate of Airport - Airport Standardization Directorate General Civil Aviation Medan Merdeka Barat No. 8, Jakarta 10110	Tel: +62 350 6661	adeth_rossi@yahoo.com ;
	28.	Mr. Agung Wibowo Airport Inspector Directorate of Airport Directorate General Civil Aviation Sinath Tower, Jl. Silangit Blok B, Jakarta 10610	Tel: +62 822990 05421	agungwibowost@yahoo.com ;
	29.	Mr. Petrus Hery Tris Cahyono Airport Inspector, Directorate of Airport Directorate General Civil Aviation Sinath Tower, Silangit Blok B, Jakarta 10610	Tel: +62 81213992467	herytris07@gmail.com ;
	30.	Mr. Alexander Aerodrome Inspector Directorate General Civil Aviation Medan Merdeka Barat No. 8, Jakarta 10110	Tel: +62 350 6661	alex.dgca@gmail.com ;
12.	JAPAN			
	31.	Mr. AONO Takanari Director for Airport Operations Safety Planning and Coordination Airport Safety Office, Aviation Safety and Security Planning Division, Japan Civil Aviation Bureau, Ministry of Land, Infrastructure, Transport and Tourism	—	aono-t2ty@mlit.go.jp ;
	32.	Mr. HAYASHIDA Futoshi Chief Coordinator of Airport Safety Information Japan Civil Aviation Bureau 2-1-3 kasumigaseki, Chiyodaku, Tokyo100-8918	—	hayashida-fl17f@mlit.go.jp ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
13.	KIRIBATI			
	33.	Mr. Tiamwa Teaiwa	Civil Aviation Authority Ministry of Information, Communications, Transport and Tourism Development Tarawa, Kiribati	— ans.ai@micttd.gov.ki ;
14.	LAO PDR			
	34.	Mr. Sengsangouane Chanthavong	Deputy Director of Aerodrome Safety and Standards Division, Department of Civil Aviation Ministry of Public Works and Transport	Tel: +85620 2222 8823 ngouane2008@yahoo.com ;
	35.	Ms. Malaythong Phimmasone	Deputy Director of Aerodrome Safety and Standards Division, Department of Civil Aviation Ministry of Public Works and Transport	Tel: +85620 5414 4354 malaythong@dcal.gov.la ; thong.dca@gmail.com ;
	36.	Mr. Komack Keochampa	Officer, Aerodrome Safety Inspector Department of Civil Aviation Ministry of Public Works and Transport	Tel: +85620 2223 9498 komack@dcal.gov.la ; okidkcp@gmail.com ;
15.	MALAYSIA			
	37.	Mr. Mahyuddin Bin Sajuri	Deputy Director, Aerodrome Standards Div. Civil Aviation Authority of Malaysia Block Podium, No. 27 Persiaran Perdana, Precint 4, 62618 Putrajaya	Tel: +603 8871 4042 mahyuddin@caam.gov.my ;
16.	MALDIVES			
	38.	Ms. Fathimath Ramiza	Director Air Navigation and Aerodrome Maldives Civil Aviation Authority Velaanaage, Ameer Ahmed Magu, Male' 20096	Tel: +960 334 2984 Fax: +960 332 3039 ramiza@caa.gov.mv ;
	39.	Ms. Aminath Shiznee	Senior Aerodrome Inspector Maldives Civil Aviation Authority, Velaanage 11 th Floor, Ameer Ahmed Magu, Male' 20096	Tel: +960 3324983 Fax: +960 3323039 civav@caa.gov.mv ; shiznee@caa.gov.mv ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
17.	MARSHALL ISLANDS			
	40.	Mr. Alice John	Principal AVSEC/FAL/AGA Inspector Directorate of Civil Aviation P.O. Box 1114, Majuro, Marshall Islands 96960	Tel: +011(692) 625 6179 Fax: +011(692) 625 6170 alcapelle@yahoo.com ; alcapelle68@gmail.com ;
18.	MICRONESIA (FEDERATED STATES OF)			
	41.	Mr. Ryan L. Donre	Airport Safety Inspector FSM Transportation, Communications & Infrastructure, Division of Civil Aviation	— ryan.donre@tci.gov.fm ;
	42.	Mr. Glenn Harris	Assistant Secretary FSM Transportation, Communications & Infrastructure, Division of Civil Aviation	— glenn.harris@tci.gov.fm ;
19.	MONGOLIA			
	43.	Mr. Munkhbold Ganbold	Aerodrome inspector, Air Navigation Division Safety Regulation Department Civil Aviation Authority of Mongolia Buyant-Ukhaa, Khan-Uul District, Ulaanbaatar	Tel: +976 11 285048 Mob: +976 11 88013779 munkhbold.g@mcaa.gov.mn ;
20.	MYANMAR			
	44.	Mr. Kyaw Soe	Director (Aerodrome Standards & Safety) Department of Civil Aviation Headquarters Building, Airport Road, Mingalardon Tsp., 11021, Yangon, Myanmar	Tel: +951 533002 +951 533013 Fax: +951 533000 kyawsoedca@gmail.com ;
	45.	Mr. Hla Phone Zaw	Deputy Director, Aerodrome Standards & Safety Division Department of Civil Aviation Headquarters Building, Yangon, Myanmar	Tel: +951 533002 +951 533013 Fax: +951 533000 hpzdca28@gmail.com ;

LIST OF AOP FOCAL POINTS

NAME			TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
	46.	Mr. Khin Maung Myint	Adviser, Department of Civil Aviation Headquarters Building, Airport Road, Mingalardon Tsp., 11021, Yangon, Myanmar	Tel: +951 533002 +951 533013 Fax: +951 533000	kmm.dca@gmail.com ;
	47.	Mr. Tin Maung Thein	Deputy Director, Aerodrome Standards & Safety Division Department of Civil Aviation Headquarters Building, Yangon, Myanmar	Tel: +951 533002 +951 533013 Fax: +951 533000	akttaaviation@gmail.com ;
	48.	Mr. Tun Zaw	Executive Engineer, Aerodrome Standards & Safety Division, Department of Civil Aviation Headquarters Building, Yangon, Myanmar	Tel: +951 533002 +951 533013 Fax: +951 533000	tunzawdca@gmail.com ;
21.	NAURU				
	49.	Mr. Dominic Tabuna	Director, Civil Aviation Authority of Nauru 1 st Floor, Nauru International Airport, Yaren, Nauru	Tel: +674 557 3122 Mob: +674 557 3091	djtabuna@gmail.com ;
22.	NEPAL				
	50.	Mr. Deo Chandra Lal Karn	Director, Aerodrome Design and Operations Panel Wildlife Hazard Management Expert Group- Member Civil Aviation Authority of Nepal Head Office, Babarmahal, Kathmandu	Tel: +977 1 426 2324	d_karna@hotmail.com ;
	51.	Mr. Babu Ram Paudel	Director, Aerodrome Safety & Standards Department Civil Aviation Authority of Nepal Head Office, Babarmahal, Kathmandu	Tel: +977 1 448 5787 Mob: +98510 96733	paudelbabu@gmail.com ;
	52.	Mr. Dipendra Shrestha	Manager Civil Aviation Authority of Nepal Head Office, Babarmahal, Kathmandu	Tel: +977 1 426 2387	dpndrs@gmail.com ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
23.	NEW ZEALAND			
	53.	Mr. Sean Rogers	Manager Aeronautical Services Civil Aviation Authority of New Zealand PO Box 3555, Wellington, New Zealand 6140	– aeronautical.services@caa.govt.nz ;
24.	PAKISTAN			
	54.	Engr. Muhammad Asjad	Senior Assistant. Director, Aerodrome Standards Pakistan Civil Aviation Authority	– muhammad.asjad@caapakistan.com.pk ;
25.	PALAU			
	55.	Mr. Richard Alonz	Acting Administrator Palau National Aviation Administration Palau International Airport Compound P.O. Box 6051, Koror, Republic of Palau	– pnaa@palaunet.com ; palaudgca@gmail.com ; pnaa.safety@gmail.com ; richalonz4@gmail.com ;
26.	PAPUA NEW GUINEA			
	56.	Mr Percy Sukbat	Senior Aerodrome Inspector, Civil Aviation Safety Authority	Tel: +675 3027541 Mob: +70306849 psukbat@casapng.gov.pg ;
27.	PHILIPPINES			
	57.	Mr. Arnel F. Borlado	Department Manager III, Aerodromes Development and Management Service Civil Aviation Authority of the Philippines	Tel: +639162193221 arnelfb_67@yahoo.com ;
	58.	Mr. Erwin G. Jamero	Division Chief IV, Aerodromes and Air Navigation Safety Oversight Office Civil Aviation Authority of the Philippines	Tel: +632 944 2286 egjamero@gmail.com ;
28.	REPUBLIC OF KOREA			
	59.	Mr. Jaehong Jung	Assistant Director Ministry of Land Infrastructure & Transportation No.11 Doum 6ro, Sejong self-governing city	Tel: +82 44 201 4343 Fax: +82 44 201 5635 pans2021@korea.kr ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
29.	SAMOA			
	60.	Ms. Venice Roebeck Principal Technical Officer Civil Aviation Division Ministry of Works, Transport and Infrastructure Private Bag, Apia, Samoa	Tel: +685 21 611 ext. 302	venice.roebeck@mwti.gov.ws ;
	61.	Ms. Tamara Michael Fuimaono Operations Officer, Civil Aviation Division Ministry of Works, Transport and Infrastructure Private Bag, Apia, Samoa	Tel: +685 21 611 ext. 306	tamara.michael@mwti.gov.ws
	62.	Ms. Yvonne Tuioti Mariner-Viliamu Director/ACEO Civil Aviation Civil Aviation Division Ministry of Works, Transport and Infrastructure Private Bag, Apia, SAMOA	Tel: +685 23565 direct or +685 21611 ext. 301 Mob: +685 7771463	yvonne.mariner@mwti.gov.ws
30.	SINGAPORE			
	63.	Ms. Wong Qi Wen Deputy Head (Aerodrome Operation Regulation) Civil Aviation Authority of Singapore Singapore Changi Airport, PO Box 1, Singapore	Tel: +65 6541 3037 Fax: +65 6542 3869	wong_qi_wen@caas.gov.sg ;
	64.	Mr. Teo Tian Hong Senior Chief (Aerodrome)/Chief (Changi Tower West) Civil Aviation Authority of Singapore Singapore Changi Airport, PO Box 1, Singapore	Tel: +65 6422 7636	Teo_tian_hong@caas.gov.sg ;
31.	SOLOMON ISLANDS			
	65.	Mr. Rex Alafa Coordinator (Aerodromes) Civil Aviation Authority of Solomon Islands Ministry of Communications and Aviation P.O. Box R25. Honiara, Solomon Islands	–	alafa_r@caasi.com.sb ;
32.	SRI LANKA			
	66.	Ms. Shereena Casseer Director Aerodromes & Facilitation Civil Aviation Authority of Sri Lanka No. 152/1, Minuwangoda Road, Katunayake	Tel: +94112355800	daf@caa.lk ;

LIST OF AOP FOCAL POINTS

NAME		TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
	67.	Mr. H. M. Rangana Samanpriya	Senior Civil Aviation Inspector – Aerodromes Civil Aviation Authority of Sri Lanka No. 152/1, Minuwangoda Road, Katunayake	Tel: +9411 2358844 Fax: +9411 2257166 scaiae@caa.lk ;
33.	THAILAND			
	68.	Mr. Thittaya Sangathai	Head of Aerodrome Standards Division Civil Aviation Authority of Thailand 333/105 Laksi Plaza, Khampheng Phet 6 Rd. Talad Bangkhen, Laksi, Bangkok 10210	Tel: +66 2 568 8827 thittaya.s@caat.or.th ;
	69.	Ms. Angsana Panmongkon	Senior Public Aerodrome Standards Division Officer, Civil Aviation Authority of Thailand	Tel: +66 2 568 8827 angsana.r@caat.or.th ;
34.	TIMOR-LESTE			
	70.	Mr. Armando Da Silva	Civil Aviation Authority of Timor-Leste (AACTL) Ministry of Transports and Telecommunications Caicoli Dili, Timor-Leste	Tel: +670 78572600 asilva@aactl.gov.tl ;
35.	TONGA			
	71.	Mr. Sosaia Maáke	Assistant Secretary Technical Ministry of Infrastructure - Civil Aviation Division, (MOI/CAD) ByPass Rd.Fanga-o-Pilolevu/ Nukualofa/ Tonga	Tel: +676 28024 szmaake@gmail.com
36.	TUVALU			
	72.	Mr. Uinga Paelate	Director of Civil Aviation, Ministry for Communications and Transport Private Mail Bag, Funafuti, Tuvalu	– dca.tuvalu@gmail.com ;
37.	UNITED STATES			
	73.	Mr. Michael Watkins	Senior Air Traffic Representative, Asia Pacific Federal Aviation Administration, Air Traffic Organization, System Operations US Embassy, Singapore	– michael.w.watkins@faa.gov ;

LIST OF AOP FOCAL POINTS

NAME			TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
	74.	Mr. Khalil Elia Kodsi	Sr. Foreign Affairs Specialist Office of Airports, Suite 616 800 Independence, Avenue S.W. Washington D.C. 20591	–	Khalil.kodsi@faa.gov ;
	75.	Ms. Lilian Miller	Foreign Affairs Specialist Office of Airports, Suite 616 800 Independence, Avenue S.W. Washington D.C. 20591	Tel: +202-267-3367	Lillian.Miller@faa.gov ;
38.	VANUATU				
	76.	Ms. Jackie Langati Trief	Director Civil Aviation Authority of Vanuatu Port Vila	–	civav@vanuatu.com.vu ; jlangati.civav@vanuatu.com.vu ;
	77.	Ms. Naiany Karu	Assistant Director / Aerodromes Officer Civil Aviation Authority of Vanuatu Port Vila	–	naiany.civav@vanuatu.com.vu ;
39.	VIET NAM				
	78.	Mr. Nguyen Duong	Deputy Director - Airport Management Dept., Civil Aviation Authority of Vietnam (CAAV) 119 Nguyen Son Str., Long Bien Dist., Ha Noi	Tel: +0913211115	nguyenduong@caa.gov.vn ;
	79.	Mr. Nguyen Huu Duc	Official Civil Aviation Authority of Vietnam 199 Nguyen Son, Long Bien, Ha Noi	Tel: +84 906 528 884	nguyenhuuduc@caa.gov.vn ;
INTERNATIONAL ORGANIZATIONS					
40.	ACI				
	80.	Mr. S. L Wong	Head - Technical Affairs, Safety, Capacity and ATM, Airports Council International	–	sl@aci-asiapac.aero ;

LIST OF AOP FOCAL POINTS

NAME			TITLE/ORGANIZATION	TEL/FAX NUMBER	E-MAIL
	81.	Mr. Ken Lau	Senior Manager – Environment and Airport Information Technology, ACI Asia-Pacific Airports Council International Hong Kong International Airport, Hong Kong	–	ken@aci-asiapac.aero ;
41. COSCAPs					
	82.	Capt. Marie Zubryckyj	Programme Coordinator COSCAP-South Asia Dhaka-1229, Bangladesh	Tel: +880 2 8901497 Fax: +880 2 8901498	mzubryckyj@icao.int ;
	83.	Mr. Sudhir Kumar Singh	Programme Coordinator, COSCAP-South East Asia Bangkok, Thailand	Tel: +6625378197 Fax: +880 2 8901498	sksingh@icao.int
	84.	Ms. Susan	COSCAP-NA Beijing 100600, P.R. China	Tel: +86-10-84001671 Fax: +86-10-84024554	sun.qun.susan@coscap-icao.org ;
42. PACIFIC AVIATION SAFETY OFFICE					
	85.	Mr. Mike Haines	AGA Technical Advisor PASO	Tel: +64 27 240 8657	mhaines@paso.aero ;

Note:-

Representative of DCA, Niue (For reference and communication):

Mr. Bill McGregor

Director, Civil Aviation

Department of Transport, Ministry of Infrastructure

Government of Niue

Alofi, NIUE

E-mail: wkl.macgregor@gmail.com

AP-AA/WG TASK LIST (Updated at AP-AA/WG/7)

	ACTION ITEM/PLANNED ACTIVITIES	RESPONSIBLE PARTY	TIME FRAME	STATUS	REMARKS
1/1	Develop a survey on States which have not completed the implementation of aerodrome certification for all international aerodromes, with an AGA EI below 75% and/or AOP air navigation deficiencies to establish the requirements for assistance	India to lead Bangladesh, Nepal and Thailand to assist	December 2019	Closed	From TOR Conclusion AOP/SG/4-8 agreed to circulate the survey to APAC States / Administrations Circulated through SL AN 3/3 – AP258/20 (AGA) dated 18 December 2020 Interim results presented in AP-AA/WG/3 WP/12 [Continued in Task 3/1]
1/2	Review the status of air navigation deficiencies in the field of AOP (as listed in the APANPIRG air navigation deficiencies database) and assist the concerned State(s) to develop corrective action plans	States COSCAPs to support	Continuous	Open	From TOR
1/3	To assist States which have not completed the implementation of aerodrome certification for all international aerodromes and/or with an AGA EI below 75% in establishing an aerodrome certification	Thailand to lead (c & d) Philippines – item (c) Bangladesh – item (d) India – item (e) & (f) Nepal – item (g) Malaysia (lead), India and Nepal – item (a),	January 2020	Closed – Item (a), (b), (c), (e), (f), (g) & (h) Closed - Item (d) and (h)	From TOR Tasks 1/3 (a), (b), (c) and (g) completed and documents are posted on APAC Website https://www.icao.int/APAC/Pages/eDocs.aspx Agreed by Decision AOP/SG/4-7 SL AN 3/3 – AP257/20 (AGA) dated 18

	ACTION ITEM/PLANNED ACTIVITIES	RESPONSIBLE PARTY	TIME FRAME	STATUS	REMARKS
	process, develop a set of generic documents, such as: (a) specific operating regulations; (b) organization structure of the aerodrome regulatory unit; (c) aerodrome certification procedure manual; (d) generic aerodrome inspector handbook with checklists; (e) generic template of the aerodrome manual; (f) training programme and training plan; (g) procedures for accepting non compliances; and (h) surveillance programme.	(b) & (h) Secretariat to support Request support from TCB/IPAV Thailand – item (d) Malaysia (lead), India and Nepal - item (h)	May 2021 December 2021		December 2020 Task 1/3 (a), (b), (d), (e), & (f) completed and documents are posted on APAC Website https://www.icao.int/APAC/Pages/eDocs.aspx Task 1/3 (h) completed (AP-AA/WG/4 – WP/08) and document will be posted after approval by AOP/SG/6 on APAC Website https://www.icao.int/APAC/Pages/eDocs.aspx
3/1	For the aerodrome assistance survey questionnaire: (a) Recirculate to States / Administration which have yet to respond (b) Conduct analysis and recommend way forward	Secretariat India and Nepal	May 2021 December 2021	Closed	Task 3/1 (a): SL Ref.: AN 3/3 - AP075/21 (AGA), dated 5 May 2021 Task 3/2 (b): AP-AA/WG/4-WP/09 Task 3/1 (a) & (b) completed.

Appendix F to the Report of AP-AA/WG/7

	ACTION ITEM/PLANNED ACTIVITIES	RESPONSIBLE PARTY	TIME FRAME	STATUS	REMARKS
4/1	Develop Generic Enforcement Policy and Procedure Manual	Malaysia (Lead), India	December 2022	Completed	AP-AA/WG/5-WP/09 Task 4/1 completed.
4/2	Develop Generic Exemption Policy and Procedure Manual	Australia (Lead), Nepal	December 2022	Completed	AP-AA/WG/5-WP/10 Task 4/2 completed.
AP-AA/WG/5 [13 – 16 March 2023]					
5/1	Develop a Generic Guidance for the evaluation of Aerodrome SMS	Australia, Maldives, Thailand (Lead)	First draft GM by December 2023	Completed	AP-AA/WG/6-WP/06
AP-AA/WG/6 [02 – 05 April 2024]					
6/1	Share State's experiences of operation and maintenance of aerodromes without runway side stripe marking at AP-AA/WG/7	Lao PDR to share experiences at AP-AA/WG/7	AP-AA/WG/7 AP-AA/WG/8		
6/2	Review and improvise the RST Questionnaire presented through AP-AA/WG/6-WP/07	Thailand (Lead), Pakistan, Philippines, Malaysia, Maldives, India, Cambodia	End of May 2024.	Completed	Incorporated in the Final Report of AP-AA/WG/6 Reminder to States.
6/3	Share State's experiences, and mechanism established to resolve conflicts between Aviation Authorities and Environmental and/or Land Use Authorities.	Pakistan to share its experience for land use vis-à-vis aviation safety at Islamabad Airport. India (TBC)	AP-AA/WG/7	Completed	AP-AA/WG/7 – IP/09 (Pakistan)
6/4	Share State's Challenges and Mechanism established for certification of Military Aerodromes used for international Operations.	India and Malaysia to share its challenges and proposed/possible solution derived for certification of Military	AP-AA/WG/7	Completed	AP-AA/WG/7 – WP/13 (Malaysia) India to share experiences at AP-AA/WG/8

	ACTION ITEM/PLANNED ACTIVITIES	RESPONSIBLE PARTY	TIME FRAME	STATUS	REMARKS
		Aerodromes used for international Operations			
6/5	Share State's Experience, challenges and/or practices for safety oversight of Ground Handling Services.	India, Malaysia and Thailand to share experiences and practices at AP-AA/WG/7	AP-AA/WG/7	Completed	AP-AA/WG/7 – WP/15 (Malaysia) AP-AA/WG/7 – IP/06 (India) AP-AA/WG/7 – IP/12 (Thailand)
AP-AA/WG/7 [27 – 30 May 2025]					
7/1	Develop Regional Guidance on Alternative Acceptable Means of Compliance with Regard to RFF Services for Aerodrome Category 1 and 2.	Fiji (Lead), Maldives, Wellington Airport (New Zealand), Philippines, Solomon Islands, USA (TBC)	By AP-AA/WG/9, Progress update at AP-AA/WG/8		
7/2	Sharing experience on USOAP Preparation	Thailand, Maldives, New Zealand (TBC)	AP-AA/WG/8		
7/3	Aerodrome SMS Workshop to address USOAP CMA PQs related to SSP and SMS in conjunction with AP-AA/WG/8	COSCAP-SEA (Lead), USA, India, Pakistan	AP-AA/WG/8		
7/4	Addressing Issues related to Certification of Military Aerodromes used for international Operations.	Workshop on Civil/Military Cooperation in Aerodrome Operations	In 2026		
7/5	Review Appendix A to AP-AA/WG/7 - WP/18 - Guideline for Runway Classification and amend/update as necessary	India (Lead), Pakistan, Thailand, Philippines	By 15 June 2025 First online Meeting on 5 June 2025 at		

	ACTION ITEM/PLANNED ACTIVITIES	RESPONSIBLE PARTY	TIME FRAME	STATUS	REMARKS
			13:00 BKK Time		
7/6	Pakistan's experience with conduct and acceptance of Task and Resource Analysis (TRA) for Certified Aerodromes	Pakistan	AP-AA/WG/8		

Appendix G to the Report of AP-AA/WG/7

General Information		Identification		Classification		Status		Location		Dimensions		Weight		Material		Notes		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version		Status		Date		Time		User		Version	
---------------------	--	----------------	--	----------------	--	--------	--	----------	--	------------	--	--------	--	----------	--	-------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--	--------	--	------	--	------	--	------	--	---------	--

[illegible]



ICAO

International Civil Aviation Organization

The Seventh Meeting of the Asia/Pacific
Aerodrome Assistance Working Group (AP-AA/WG/7)

Bangkok, Thailand, 27 to 30 May 2025

List of Experts

Asia/Pacific Aerodrome Assistance Working Group (AP-AA WG)

[As of 14 March 2024]

	State/Administration and Name	Organization/Title	E-mail and Telephone Numbers
1.	China		
	1. Mr. DONG Lei	Principal Staff Member of Division of Airport of North China Regional Administration, Civil Aviation Administration of China (CAAC)	jr_yang@caac.gov.cn ;
	2. Mr. LI Qiang	Deputy Director of Division of Airport of Beijing Safety Supervision Bureau, Civil Aviation Administration of China (CAAC)	jr_yang@caac.gov.cn ;
2.	India		
	3. Mr. Amit Srivastava	Deputy Director of Operations, Aerodrome Standards, Directorate General of Civil Aviation	Amits.dgca@nic.in Tel: +91-11-24653883 Mobile+91-8750591592
3.	Nepal		
	4. Mr. Babu Ram Paudel	Director – Aerodrome Spector Aerodrome Safety & Standards Dept. Civil Aviation Authority of Nepal	paudelbabu@gmail.com ;
	5. Mr. Hari Prasad Adhikari	Deputy Director Civil Aviation Authority of Nepal	er.hariadhikari@gmail.com ;
4.	COSCAP-SEA		
	6. Mr. Sudhir Kumar Singh	Programme Coordinator COSCAP-SEA	sksingh@icao.int

—END—