

International Civil Aviation Organization

Thirteenth Meeting of the Air Traffic Management Sub-Group (ATM/SG/13) of APANPIRG

Singapore, 25 - 29 August 2025

Agenda Item 4: Air Navigation Service Deficiencies

ATM AND AIRSPACE SAFETY DEFICIENCIES LIST

(Presented by the Secretariat)

SUMMARY

This paper presents a list of Air Navigation Deficiencies noted by the Thirty-Fifth Meeting of Asia/Pacific Air Navigation Planning and Implementation Regional Group (APANPIRG/35) in the Air Traffic Management (ATM) and Airspace Safety fields, supplemented by proposed Deficiencies identified since APANPIRG/35 for review by the meeting. The list is based on the uniform methodology for the identification, assessment and reporting of such deficiencies as described in Part V of the APANPIRG Procedural Handbook.

1. INTRODUCTION

- 1.1 Under the Terms of Reference of APANPIRG, one of its primary objectives is to identify and address specific deficiencies in the air navigation field. In meeting this objective, APANPIRG facilitates the development and implementation of action plans by States to resolve identified deficiencies, where necessary. Consequently, APANPIRG and its Sub-groups regularly review deficiencies in their respective fields and develop recommendations for remedial actions.
- 1.2 APANPIRG Air Navigation Services (ANS) deficiencies are identified in accordance with the *Uniform Methodology for the Identification, Assessment and Reporting of Air Navigation Deficiencies*, together with the related Asia/Pacific Supplement to the Uniform Methodology, as detailed in the APANPIRG Procedural Handbook.
- 1.3 The Twenty-First Meeting of APANPIRG (APANPIRG/21, September 2010) reviewed the updated list based on information provided by concerned States to ATM/AIS/SAR/SG/20 (July 2010, Singapore). The meeting urged States that had not taken firm corrective action to eliminate the deficiencies and adopted the following Conclusion.

Conclusion APANPIRG21/53 – Elimination of ATM Air Navigation Deficiencies

That, States concerned

- a) be urged to take urgent actions to correct the deficiencies in the ATM/AIS/SAR fields identified in Attachment A to the Report on Agenda Item 4;
- b) notify details of the problems/difficulties to the Regional Office; and
- c) designate a point of contact in each State to deal with deficiencies and provide details to the Regional Office by 22 October 2010.

2. DISCUSSION

APANPIRG Air Navigation Deficiencies in the ATM and Airspace Safety Fields

2.1 The proposed list of APANPIRG Air Navigation Deficiencies in the ATM and Airspace Safety fields (as of 31 July 2025) is provided in **Appendix A** to this paper.

Aeronautical Information Management (AIM) Deficiencies

2.2 The following States have Deficiency recorded for non-implementation of World Geodetic System 1984 (WGS-84):

Afghanistan, Brunei Darussalam, Marshall Islands, Micronesia, Nauru, Palau, Samoa and Vanuatu.

2.3 The following State have Deficiency recorded for non-compliance with Aeronautical Information Publication (AIP) format standards of ICAO Annex 15:

Kiribati.

2.4 The following States have Deficiency recorded for non-implementation of Aeronautical Information Services (AIS) Quality Management System as required in Annex 15, Chapter 3:

Afghanistan, Bangladesh, Bhutan, Brunei Darussalam, Cambodia, Kiribati, Lao PDR, Maldives, Marshall Islands, Micronesia, Myanmar, Nauru, Nepal, Palau, Samoa, Solomon Islands, Timor-Leste and Vanuatu.

2.5 ICAO's analysis of the information provided by Brunei Darussalam and the Maldives is currently under review. Both States continue to make commendable efforts toward the implementation of the QMS and are progressing with the intention of being in a position to, and are anticipated to be able to, report its completion at next year's AAITF.

Aeronautical Data Area of Responsibility Deficiencies

2.6 The following State has Deficiency recorded for non-compliance with the aeronautical data area of responsibility requirements of ICAO Annex 15 Chapter 2:

Bangladesh.

<u>Designation of Restricted Areas Deficiencies</u>

2.7 The following States have Deficiency recorded for non-compliance with ICAO Annex 2 requirements for designation of restricted areas:

Australia* and India.

2.8 With reference to the completion of the corrective actions submitted by the Civil Aviation Safety Authority of Australia (CASA), ICAO Asia/Pacific Regional Office has carefully reviewed the relevant documentation and confirmed that Australia has addressed the corrective actions associated with the APANPIRG ATM and Airspace Safety Deficiency regarding the designation of restricted areas over land and territorial waters. In view of this, it is considered that Australia has fulfilled the necessary corrective actions and it is therefore recommended that the deficiency be withdrawn.

Airspace Classification Deficiencies

2.9 The following States and Administration have Deficiency recorded for non-implementation of airspace classification requirements of ICAO Annex 11 Chapter 2:

China, Macao China, Nauru and the Solomon Islands.

ATS Message Addressing Deficiencies

2.10 The following State has Deficiency recorded for non-compliance with procedures specified in ICAO PANS-ATM Section 11.4:

Maldives.

Search and Rescue (SAR) Deficiencies

2.11 The following States and Administration have Deficiency recorded for non-implementation of the *Asia/Pacific Air Navigation Plan Vol II Part I Section 3 Specific Regional Requirements* for implementation of the *Asia/Pacific SAR Plan*:

Afghanistan, Bangladesh, Bhutan, Brunei Darussalam, Cambodia, Macao China, Cook Islands, DPR Korea, French Polynesia, Kiribati, Lao PDR, Maldives, Marshall Islands, Micronesia, Mongolia, Myanmar, Nauru, Nepal, New Caledonia, Pakistan, Palau, Papua New Guinea, Samoa, Solomon Islands, Sri Lanka, Thailand, Timor-Leste, Tonga, Tuvalu and Vanuatu.

Safety Reporting Deficiencies (RASMAG)

- 2.12 The following State has Deficiency recorded for non-provision of safety-related data: Afghanistan.
- 2.13 The Thirtieth Meeting of the Regional Airspace Safety Monitoring Advisory Group (RASMAG/30) reviewed the APANPIRG ATM and Airspace Safety Deficiency List and agreed to make the recommendation to APANPIRG/36
 - a) add India due to had not verified the Reduced Vertical Separation Minimum (RVSM) approval status of 16 aircraft for over six months (since December 2024) and had not submitted the 2024 annual RVSM approval snapshot; and
 - b) add Nepal due to failure to submit annual TSD on time and in the correct format.
- 2.14 The following States have Deficiency concerning responsibility to comply with the height-keeping monitoring requirements of Annex 6:

Afghanistan, India, Nepal, and the Philippines*.

- 2.15 RASMAG/30 agreed to make the recommendation to APANPIRG/36 to:
 - a) remove Philippines; and
 - b) add DPR Korea and Malaysia due to their remaining monitoring burden was 30% or more.
- 2.16 In addition, RASMAG/30 was informed that the deadline for submission of information (such as on reduction of the remaining monitoring burden or RVSM Approval Status verification) must reach Monitoring Agency of Asia Region (MAAR) and ICAO by 24 October 2025 in order to be processed in time for the final list of recommendations and should accurate updates be provided by the deadline, the Secretariat would exclude such items from the recommendations to APANPIRG/36.

Note. The details would be further informed under Agenda Item 3 (ATM/SG/13 WP/05).

ATS Datalink Deficiencies (RASMAG)

2.17 The following States have a Deficiency recorded for non-compliance with the data link performance monitoring and analysis requirements of Annex 11:

India*.

2.18 India has submitted data link performance report for all the three Flight Information Regions (FIRs), including Mumbai FIR, and completed annual *Survey of the Status of Current and Planned Implementation of Performance-Based Horizontal Separation Minima* form for 2025, hence recommended that the deficiency be withdrawn.

Points of Contact

2.19 The List of Contacts for Deficiencies currently on the ICAO Secure Portal website at https://portal.icao.int/DEF/Pages/default.aspx is at **Appendix B** for review as required.

3. ACTION BY THE MEETING

- 3.1 The meeting is invited to:
 - a) review and update the list of ANS Deficiencies for review by APANPIRG/36;
 - b) if possible, identify actions to be taken to correct the identified deficiencies;
 - c) update the Deficiency Points of Contact List as required; and
 - d) discuss any relevant matters as appropriate.

ATM and Airspace Safety Deficiencies List (Updated 31 July 2025)

		Deficiencies		Corrective Action		
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority **
	WGS-84 Requirements of Paragraph 1.2.1 of Annex 15					
Afghanistan	WGS-84 - Not implemented	24/6/2014		Afghanistan	TBD	A
Brunei Darussalam	WGS-84 - Not implemented	24/6/2014		Brunei Darussalam	31/12/2025	A
Marshall Islands	WGS-84 - Not implemented	24/6/2014		Marshall Islands	TBD	A
Micronesia	WGS-84 - Not implemented	24/6/2014		Micronesia	TBD	A
Nauru	WGS-84 - Not implemented		Conferring with consultant	Nauru	TBD	A
Palau	WGS-84 - Not implemented	24/6/2014		Palau	TBD	A
Samoa	WGS-84 - Not implemented	24/6/2014		Samoa	TBD	A
Vanuatu	WGS-84 – Not implemented	2/7/1999	Implemented at main airports	Vanuatu	1999	A
	AIP Format Requirements of Chapter 5 of Annex 15					
Kiribati	AIP Format - Not implemented	7/7/99	ATM/AIS/SAR/SG/18 (June 2009) was advised AIP in draft stage	Kiribati		A
	AIS Quality Management System Requirements of Paragraph 3.6.1 of Annex 15 Quality Management System - Not implemented					
Afghanistan	AIS Quality Management System - Not implemented	24/6/2014		Afghanistan	TBD	A
Bangladesh	AIS Quality Management System - Not implemented	24/6/2014		Bangladesh	TBD	A

ATM/SG/13 – **WP/09 Rev.2** Appendix A

		Deficiencies		Corre	ective Action	
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority
Bhutan	AIS Quality Management System - Not implemented	24/6/2014		Bhutan	TBD	A
Brunei Darussalam	AIS Quality Management System - Not implemented	24/6/2014		Brunei Darussalam	31/03/2026	A
Cambodia	AIS Quality Management System - Not implemented	24/6/2014		Cambodia	TBD	A
Kiribati	AIS Quality Management System - Not implemented	24/6/2014		Kiribati	TBD	A
Lao PDR	AIS Quality Management System - Not implemented	24/6/2014		Lao PDR	TBD	A
Maldives	AIS Quality Management System - Not implemented	24/6/2014		Maldives	30/09/2024	A
Marshall Islands	AIS Quality Management System - Not implemented	24/6/2014		Maldives	TBD	A
Micronesia	AIS Quality Management System - Not implemented	24/6/2014		Micronesia	TBD	A
Myanmar	AIS Quality Management System - Not implemented	9/6/2016		Myanmar	31/12/2025	A
Nauru	AIS Quality Management System - Not implemented	24/6/2014		Nauru	TBD	A
Nepal	AIS Quality Management System - Not implemented	24/6/2014		Nepal	TBD	A
Palau	AIS Quality Management System - Not implemented	24/6/2014		Palau	TBD	A

		Deficiencies		Corre	ective Action	
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority **
Samoa	AIS Quality Management System - Not implemented	24/6/2014		Samoa	TBD	A
Solomon Islands	AIS Quality Management System - Not implemented	24/6/2014		Solomon Islands	TBD	A
Timor-Leste	AIS Quality Management System - Not implemented	24/6/2014		Timor-Leste	TBD	A
Vanuatu	AIS Quality Management System - Not implemented	24/6/2014		Vanuatu	TBD	A
	Aeronautical Data Area of Responsibility - requirements of Paragraph 2.1.2 of Annex 2 15 to ensure that the provision of aeronautical data and aeronautical information covers its own territory and those areas over the high seas for which it is responsible for the provision of ATS					
Bangladesh	Aeronautical Data Promulgation Within the State's Area of Responsibility - Not implemented	29/03/2019 SAIOACG/9		Bangladesh	TBD	A
	Designation of Restricted Areas - requirements of Annex 2 (Definitions) to ensure that restricted areas are designated above the land areas or territorial waters of a State					

		Deficiencies				
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority
Australia	Designation of Restricted Areas Above the Land Areas or Territorial Waters of a State—Not implemented	29/03/2019 SAIOACG/9	Danger areas within international airspace that is part of a State's responsibility is acceptable Australia has completed the corrective actions concerning the designation of restricted areas over land or territorial waters	Australia	December 2022	A
India	Designation of Restricted Areas Above the Land Areas or Territorial Waters of a State - Not implemented	29/03/2019 SAIOACG/9	Danger areas within international airspace that is part of a State's responsibility is acceptable	India	TBD	A
	Airspace Classification Requirements of Paragraph 2.6 of Annex 11					
China	Airspace Classification - Not implemented	7/7/99	Difference to Annex 11 is published in AIP, China.	China	APANPIRG/1 9 updated, implementatio n planned by end 2010.	A
Macao, China	Airspace Classification - Not implemented	05/09/2018		Macau, China	TBD	A
Nauru	Airspace Classification - Not implemented	7/7/99		Nauru	TBD	A
Solomon Islands	Airspace Classification - Not implemented	7/7/99		Solomon Islands	TBD	A

		Deficiencies		Corre	ctive Action	
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority **
	ATS Message Addressing Requirements of Doc 4444 PANS- ATM Section 11.4 (Message Types and their Application)		Note: the threshold for a Deficiency is 5% or more DEP messages reported to have not been sent, and where the analysed data provided evidence of a systemic (either systems or human factors) failure to send the message			
Maldives	DEP message transmission	09/08/2019	DEP messages inconsistently transmitted Conclusion APANPIRG/27/12 and ICAO correspondence	Maldives	TBD	A
	SAR capability: Requirements of Annex 12 as defined in the Regional Air Navigation Plan Volume II Part I – GENERAL PLANNING ASPECTS Section 3 SPECIFIC REGIONAL REQUIREMENTS, failure to reach 90% or more implementation of the Asia/Pacific SAR Plan					
Afghanistan	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/6 56% APSAR/WG/10 55%	Afghanistan	2019	U
Bangladesh	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/9 65% APSAR/WG/10 66%	Bangladesh	2019	U
Bhutan	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/8 28% APSAR/WG/10 26%	Bhutan	2019	U
Brunei Darussalam	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/4 63% APSAR/WG/10 62%	Brunei	2019	U
Cambodia	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/9 76% APSAR/WG/10 74%	Cambodia	2019	U

ATM/SG/13 – **WP/09 Rev.2** Appendix A

		Deficiencies		Corre	Corrective Action		
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority	
Macao, China	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/9-88% APSAR/WG/10-86%	Macao, China	2019	U	
Cook Islands	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/8 62% APSAR/WG/10 60%	Cook Islands	2019	U	
DPR Korea	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/8 71% APSAR/WG/10 70%	DPR Korea	2019	U	
French Polynesia	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/8 84% APSAR/WG/10 82%	French Polynesia	2019	U	
Kiribati	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4 26% APSAR/WG/10 25%	Kiribati	2019	U	
Lao PDR	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4 57% APSAR/WG/10 56%	Lao PDR	2019	U	
Maldives	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/8 78% APSAR/WG/10 76%	Maldives	2019	U	
Marshall Islands	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/5 17% APSAR/WG/10 17%	Marshall Islands	2019	U	
Micronesia	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/5 17% APSAR/WG/10 17%	Micronesia	2019	U	
Mongolia	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/9 89% APSAR/WG/10 87%	Mongolia	2019	U	
Myanmar	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/9 69% APSAR/WG/10 68%	Myanmar	2019	U	
Nauru	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4-0% APSAR/WG/10-0%	Nauru	2019	U	
Nepal	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/9 66% APSAR/WG/10 50%	Nepal	2019	U	
New Caledonia	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/8 78% APSAR/WG/10 77%	New Caledonia	2019	U	

		Deficiencies			ective Action	
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority **
Pakistan	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/9 89% APSAR/WG/10 89%	Pakistan	2019	U
Palau	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/5 17% APSAR/WG/10 17%	Palau	2019	U
Papua New Guinea	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/7 54% APSAR/WG/10 37%	Papua New Guinea	2019	U
Samoa	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4 0% APSAR/WG/10 0%	Samoa	2019	U
Solomon Islands	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4 0% APSAR/WG/10 0%	Solomon Islands	2019	U
Sri Lanka	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/9 84% APSAR/WG/10 86%	Sri Lanka	2019	U
Thailand	Asia/Pacific SAR Plan	17/05/2019	APSAR/WG/9 85% APSAR/WG/10 87%	Thailand	2025	U
Timor-Leste	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4 0% APSAR/WG/10 0%	Timor-Leste	2019	U
Tonga	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4 70% APSAR/WG/10 68%	Tonga	2019	U
Tuvalu	Asia/Pacific SAR Plan	28/05/2022	APSAR/WG/7-0% APSAR/WG/10-0%	Tuvalu	2024	U
Vanuatu	Asia/Pacific SAR Plan	6/07/2015	APSAR/WG/4 0% APSAR/WG/10 0%	Vanuatu	2019	U

		Deficiencies		Corre	ctive Action	
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority
	Non Provision of Safety-related Data Requirement of Paragraph 3.3.5.1 of Annex 11 (provision of data for monitoring the height-keeping performance of aircraft) and APANPIRG Conclusion 16/6 – Non Provision of safety related data by States					
Afghanistan	Non-provision of safety related data	12/07/2019	Failure to submit Kabul LHD data for January-December 2018 and 2020. Afghanistan had submitted data for the period January to July 2021, but no further LHD reports were received after August 2021.	Afghanistan	TBD	U
India	Non-provision of safety related data	RASMAG/30	India had not verified the RVSM approval status of 16 aircraft for over six months (since December 2024) and had not submitted the 2024 annual RVSM approval snapshot.	India	TBD	U
Nepal	Non-provision of safety related data	RASMAG/30	Failure to submit annual TSD on time and in the correct format	Nepal	TBD	U
	State Responsibility to comply with the Annex 6 Height-Keeping Monitoring Requirement Annex 6 Part I Section 7.2.9 (10 th Ed.) and Part II Section 2.5.2.10 (9 th Ed.)					
Afghanistan	Non-compliance with LTHM requirement (remaining monitoring burden more than 30%)	RASMAG/23	Remaining monitoring burden of 50% (RASMAG/29) MAAR informed ICAO that all known airframes in Afghanistan	Afghanistan	TBD	A

		Deficiencies		Corre	ctive Action	
States/facilities	Description	Date first reported	Remarks	Executing body	Target date	Priority **
			have complied with the monitoring requirement (November 2022). Deficiency retained due to the unknown status of the Afghanistan aeronautical authority responsible for ensuring monitoring is conducted.			
Democratic People's Republic of Korea	Non-compliance with LTHM requirement (remaining monitoring burden more than 30%)	RASMAG/30	Remaining monitoring burden of 100% (RASMAG/30)	DPR Korea	TBD	A
India	Non-compliance with LTHM requirement (remaining monitoring burden more than 30%)	RASMAG/29	Remaining monitoring burden of 46% (RASMAG/30)	India	TBD	A
Malaysia	Non-compliance with LTHM requirement (remaining monitoring burden more than 30%)	RASMAG/30	Remaining monitoring burden of 31% (RASMAG/30)	Malaysia	TBD	A
Nepal	Non-compliance with LTHM requirement (remaining monitoring burden more than 30%)	RASMAG/28	Remaining monitoring burden of 45% (RASMAG/30)	Nepal	TBD	A
Philippines	Non compliance with LTHM requirement (remaining monitoring burden more than 30%)	RASMAG/29	Remaining monitoring burden of 40% (RASMAG/29) Remaining monitoring burden of 22% (RASMAG/30)	Philippines	TBD	A
	Data Link Performance Monitoring and Analysis Requirements of Paragraph 2.28 and/or 3.3.5.2 of Annex 11 not met					

Deficiencies			Correc	tive Action	
Description	Date first reported	Remarks	Executing body	Target date	Priority
Post implementation monitoring not implemented	13/07/2017	Performance monitoring and analysis was reported for the Chennai and Kolkata FIRs, but was not reported for the Mumbai FIR. (FIT-Asia/15): India had submitted the data link performance report for all the three FIRs, including	India	TBD	A
	Description Post implementation monitoring not	Description Date first reported Post implementation monitoring not 13/07/2017	Description Date first reported Post implementation monitoring not implemented 13/07/2017 Performance monitoring and analysis was reported for the Chennai and Kolkata FIRs, but was not reported for the Mumbai FIR. (FIT-Asia/15): India had submitted the data link performance report for all the three FIRs, including	Description Date first reported Post implementation monitoring not implemented 13/07/2017 Performance monitoring and analysis was reported for the Chennai and Kolkata FIRs, but was not reported for the Mumbai FIR. (FIT-Asia/15): India had submitted the data link performance report for	Description Date first reported Remarks Executing body Target date

^{**} Note: In accordance with the APANPIRG Handbook - Asia/Pacific Supplement to the Uniform Methodology for the Identification, Assessment and Reporting of Air Navigation Deficiencies, priority for Air Navigation Deficiencies is guided by the principle that a deficiency with respect to an ICAO Standard is accorded a "U" status, while a non-compliance with a Recommended Practice or a PANS is considered as "A" or "B" subject to additional expert evaluation. The final prioritization of deficiencies is the prerogative of APANPIRG.



LIST OF FOCAL POINT FOR AIR NAVIGATION DEFICIENCIES

Updated: 30 April 2025

STATE/ADMINISTRATION	FOCAL CONTAC	T PERSON
Afghanistan	Name:	Mr. Mohammad Hamid Amiry
	Designation:	Aerodrome Certification Inspector
	Address:	Ministry of Transport & Aviation (MoTA)
	Tel:	+0786888011
	Email:	mhamidamiry@gmail.com;
Australia	Name:	Mr. Chris Kumar
	Designation:	ATS Specialist Lead
	Address:	Airservices Australia
	Tel:	+61 3 8340 8270
	Email:	chris.kumar@airservicesaustralia.com;
Bangladesh	Name:	Ms. Sabera Rahman
	Designation:	Deputy Director (ATM)
	Address:	Civil Aviation Authority of Bangladesh Air Traffic Management Division
	Tel:	-
	Fax:	-
	Email:	sabera_atm@caab.gov.bd;
Bhutan	Name:	Mr. Pema Tashi
	Designation:	Superintendent, ANS
	Address:	Bhutan Civil Aviation Authority
	Tel:	+975 8271912
	Fax:	00975 8 271944
	Email:	ptashi@bcaa.gov.bt;
Alternate	Name:	Ms. Devi Maya Adikari
	Designation:	COM/NAV Officer
	Address:	Department of Air Transport, Paro
	Tel:	+975 8 271511
	Fax:	+975 8 271407
	Email:	dmadhikari@doat.gov.bt;
Brunei Darussalam	Name:	Mr. Mohamad Fauzi bin Mohamad Sidek
	Designation:	Acting Deputy Director of Civil Aviation (Regulator)
	Address:	Department of Civil Aviation, Brunei Darussalam
	Tel:	+673 2330142
	Mob:	+673 8168909
	Email:	fauzi.sidek@dca.gov.bn; ddca.regulatory@dca.gov.bn;



STATE/ADMINISTRATION	FOCAL CONTACT	T PERSON
Brunei Darussalam	Name:	Mr. Pengiran Rasman bin Pengiran Sulaiman
Alternate	Designation:	Aerodrome Inspector
	Address:	Department of Civil Aviation, Brunei Darussalam
	Tel:	+673 2330142
	Mob:	+673 8854714
	Email:	rasman.sulaiman@dca.gov.bn;
	Name:	Ms. Norhidayah Haji Ismail
	Designation:	Air Traffic Control Officer
	Address:	Department of Civil Aviation, Brunei Darussalam
	Tel:	+673 2330142
	Mob:	+673 883 4614
	Email:	norhidayah.ismail@civil-aviation.gov.bn;
Cambodia	Name:	Mr. Oun Makara
	Designation:	Chief of Air Traffic Service Air Navigation Standard and Safety Department
	Address:	State Secretariat of Civil Aviation Cambodia
	Tel:	+855 69 775 161
	Email:	anssd.ssca@gmail.com;
China	Name:	Ms. Zhang Ying
	Designation:	Engineer of AirSpace Management Division
	Address:	Air Traffic Management Bureau, CAAC
	Tel:	+86 (10) 8778 6837
	Fax:	+86 (10) 2778 6830
	Email:	zhangying@atmb.net.cn;
Hong Kong, China	Name:	Ms. Erin YY Siu
	Designation:	Senior Safety Manager
	Address:	2/F, Office Building, Civil Aviation Department Headquarters, 1 Tung Fai Road, Hong Kong International Airport, Lantau, Hong Kong
	Tel:	+852 2910 6442
	Fax:	+852 2910 0186
	Email:	eyysiu@cad.gov.hk;
Macao, China	Name:	_
Alternate	Name:	Mr. Lam Tat Ming
	Designation:	Director of Airport Infrastructure & Air Navigation
	Address:	Civil Aviation Authority of Macao Alameda Dr. Carlos D'Assumpçao, 336-342, Centro Comercial Cheng Feng, 18 Andar, Macao, China
	Tel:	+853 2851 1213
	Fax:	+853 2833 8089
	Email:	taftlam@aacm.gov.mo;



STATE/ADMINISTRATION	FOCAL CONTAC	CT PERSON
Macao, China	Name:	Mr. Lo Veng Tong
Alternate	Designation:	Safety Officer of Airport Infrastructure & Air Navigation
	Address:	Civil Aviation Authority of Macao
	Tel:	+853 8796 4132
	Fax:	+853 2833 8089
	Email:	freemanlo@aacm.gov.mo;
Fiji Islands	Name:	Ms. Alisi Namoro
<i>y</i>	Designation:	Executive Manager Ground Safety
	Address:	Civil Aviation Authority of the Fiji Islands
	Tel:	+679 8923155
	Mob:	+679 9984498
	Email:	emgs@caaf.org.fj;
India	Name:	Mr. Moosa Thudhathifanuge
	Designation:	Executive Director (ATM-Air Space Management)
	Address:	Airports Authority of India Rajiv Gandhi Bhawan Safdarjung Airport New Delhi – 110003
	Tel:	+91 11 20819167
	Fax:	+91 11 24610528
	Mob:	+91 9447166566, +91 8075078714
	Email:	edasm@aai.aero;
Indonesia	Name:	Mr. Wahyudi Nugroho
	Designation:	Head of Standardization of Air Navigation Section
	Address:	Directorate General of Civil Aviation, Ministry of Transportation
	Email:	wahyudinugroho2012@gmail.com;
	Name:	Mr. Tian Kusdinar
	Designation:	Head of Air Traffic Management Section
	Address:	Directorate General of Civil Aviation, Ministry of Transportation
	Email:	tian231182@gmail.com;
Japan	Name:	Ms. Hanae NODA
	Designation:	Special Assistant to the Director
	Address:	Air Traffic International Affairs Office Japan Civil Aviation Bureau Ministry of Land, Infrastructure Transport and Tourism
	Tel:	+81 3 5253 8740
	Fax:	+81 3 5253 1664
	Email:	noda-h46nk@mlit.go.jp;



STATE/ADMINISTRATION	FOCAL CONTACT	T PERSON
Kiribati	Name:	Mr. Tiamwa Teaiwa
	Designation:	Air Navigation and Aerodrome Inspector
	Address:	Civil Aviation Authority of Kiribati
	Tel:	686 74026003
	Email:	ans.ai@mcttd.gov.ki;
Lao PDR	Name:	Mr. Sohnsacksit Khamkeo
	Designation:	Director of Air Navigation Standards Division
	Address:	Department of Civil Aviation of Laos Wattay International Airport, P.O.Box 119, Vientiane
	Mob:	+856 20 22499936
	Email:	sohnsacksit@yahoo.com; saykhamkeo@gmail.com;
Malaysia	Name:	Mr. Raja Amsyar Hillman Bin Raja Badrul Hisham
	Designation:	Deputy Director Air Navigation Services and Aerodrome Division
	Address:	Civil Aviation Authority of Malaysia Level 1-4, Block Podium, 62618 Putrajaya ,Malaysia
	Tel./Mob:	-
	Email:	r.amsyarhillman@caam.gov.my;
Maldives	Name:	Mrs. Fathimath Ramiza
	Designation:	Director, Air Navigation and Aerodromes
	Address:	Maldives Civil Aviation Authority 11th Floor, Velaanaage, Ameeru Ahmed Magu, Male' 20096, Maldives
	Tel:	+960 332 4983
	Fax:	+960 332 3039
	Email:	ramiza@caa.gov.mv;
Mongolia	Name:	Mr. Odgerel Davaadorj
	Designation:	Senior officer of the Air Navigation Services Department
	Address:	Civil Aviation Authority of Mongolia 17120 Buyant Ukhaa, Khan Uul District, Ulaanbaatar
	Tel:	+976 11 282081
	Fax:	+976 7004 9640
	Email:	odgerel@mcaa.gov.mn;
Myanmar	Name:	Mr. Soe Paing
	Designation:	Director (Air Navigation Safety)
	Address:	Department of Civil Aviation Myanmar
	Tel:	+95 1 533008
	Fax:	+95 1 533000
	Email:	soepng1@gmail.com;



STATE/ADMINISTRATION	FOCAL CONTACT	T PERSON
Myanmar	Name:	Mr. Thein Naing
Alternate	Designation:	Deputy Director (ANSD)
	Address:	Department of Civil Aviation
		DCA Headquarters Building, P.O. Box 11021,
	T.1.	Mingaladon, Myanmar
	Tel:	+95 1 533215
	Fax:	+95 1 533016
	Email:	ansd.myanmar@gmail.com; chittwo975.c@gmail.com;
New Zealand	Name:	Mr. Sean Rogers
	Designation:	Manager Aeronautical Services
	Address	Civil Aviation Authority of New Zealand P.O. Box 3555, Wellington 6140
	Tel: / Mob:	+64 (4) 560 9522 / +64 27 807 4875
	Fax:	+64 4 569 2024
	E-mail:	sean.rogers@caa.govt.nz;
Nepal	Name:	Mr. Dinesh Raj Ghimire
	Designation:	Deputy Director, Air Traffic Management Department
	Address	Civil Aviation Authority of Nepal (CAAN) Kathmandu, Nepal
	Tel:	+977 1 4266139
	Fax:	+977 1 4262516
	Mob:	+977 9841216175
	E-mail:	dineshr.ghimire@caanepal.gov.np; dnghimire@gmail.com;
Philippines	Name:	Mr. Arnold R. Balucating
	Designation:	Assistant Director General I, Air Navigation Service
	Address	Civil Aviation Authority of the Philippines
	Tel:	+632 879 9244
	Fax:	+632 879 9189
	E-mail:	arbalucating@caap.gov.ph; arnoldrbalucating@yahoo.com;
Alternate	Name:	Mr. Michael E. Mapanao
	Designation:	Acting Assistant Director General I, Air Navigation Service
	Address	Civil Aviation Authority of the Philippines
	Tel:	+632 879 9129
	E-mail:	mikeecho905@yahoo.com;
	Name:	Mr. Luciano R Macuse
	Designation:	Officer-In-Charge, Aerodrome and Air Navigation Safety Oversight Office
	Address	Civil Aviation Authority of the Philippines
	E-mail:	lrm.aansoo2014@gmail.com;



STATE/ADMINISTRATION	FOCAL CONTAC	T PERSON
Republic of Korea	Name:	Mr. Kyutae Kim
·	Designation:	Assistant Director of Air Traffic Division
	Address	Ministry of Land, Infrastructure and Transportation (MOLIT)
	E-mail:	kimkt23@korea.kr;
Singapore	Name:	Mr. Hermizan Jumari
	Designation:	Deputy Director (Planning), ATS
	Address:	Civil Aviation Authority of Singapore Singapore Changi Airport, P.O. Box 1, Singapore 918141
	E-mail:	hermizan_jumari@caas.gov.sg;
Alternate	Name:	Mr. Roger Lau
	Designation:	Senior Chief (ATM), ATS
	Address:	Civil Aviation Authority of Singapore Singapore Changi Airport, P.O. Box 1, Singapore 918141
	E-mail:	roger_lau@caas.gov.sg;
Sri Lanka	Name:	Mr. Rohan Manukulasooriya
	Designation:	Head of Section - Air Navigation Services
	Address:	Civil Aviation Authority of Sri Lanka No. 64, Galle Road, Colombo 3
	Tel:	+94 (11) 235 8910
	E-mail:	hosans@caa.lk;
Thailand	Name:	Mr. Kajonpat Maklin
	Designation:	Deputy Director General
	Address:	The Civil Aviation Authority of Thailand (CAAT)
	Tel:	+662 568 8800
	E-mail:	kajonpat.m@caat.or.th;
Alternate	Name:	Ms. Tawika Huayhongthong
	Designation:	Manager of Air Navigation Services Standards Department
	Address:	The Civil Aviation Authority of Thailand (CAAT)
	Tel:	+662 568 8824
	E-mail:	tawika.h@caat.or.th;
Timor-Leste	Name:	Mr. Carlito Noronha
	Designation:	-
	Address:	Civil Aviation Authority of Timor-Leste
	E-mail:	manewalun88@gmail.com;
Tonga	Name:	Dr. Vinolia Salesi
	Designation:	Director for Civil Aviation
	Address:	Ministry of Infrastructure - Civil Aviation Division
	Tel:	+ 676 28 024
	E-mail:	vinolia.fifita@gmail.com; vfifita@infrastructure.gov.to;



STATE/ADMINISTRATION	FOCAL CONTACT PERSON	
United States	Name:	Mr. Shayne Campbell
	Designation:	Senior Air Traffic Representative, Asia Pacific
	Address:	Federal Aviation Administration American Embassy Singapore 27 Napier Road, Singapore 258508
	Tel:	+65 8909-1136
	E-mail:	Shayne.A.Campbell@faa.gov;
Viet Nam	Name:	Mr. Nguyen The Hung
	Designation:	Director, Air Navigation Department
	Address:	Civil Aviation Administration of Viet Nam 119 Nguyen Son Street, Gia Thuy Ward Long Bien District, Hanoi 10000
	Tel:	+84 24 38727912
	Fax:	+84 24 3927 4194
	E-mail:	hungand@caa.gov.vn; hungand caav@yahoo.com
Alternate	Name:	Mr. Dao Xuan Hoach
	Designation:	Director, Airport Management Department
	Address:	Civil Aviation Administration of Viet Nam 119 Nguyen Son Street, Gia Thuy Ward Long Bien District, Hanoi 10000
	Tel:	+84-24-38727912
	Fax:	+84-24-38271933
	E-mail:	hoachdx@caa.gov.vn;