EUR Regional Aviation Safety Plan (RASP) 2023-2025, rev 1

Safety Actions - Flight operations - aeroplanes

EUR.SPT.0031 Raise of awareness of the risk posed by icing in-flight and potential mitigations

Help to mitigate the risk of accidents and other occurrences due to icing in-flight by raising awareness of this safety Issue. This should include information on the situations where icing in-flight may occur and how flight crew can recognise some of the factors that might lead to accidents. Information should also be provided on the measures that operators and flight crew specifically can take to mitigate the risk of an accident occurring.

An EASA article on "Icing in Flight" was published on 11/12/2020 and can be consulted via that link: https://www.easa.europa.eu/community/topics/icing-flight. Further social media activity as follow up action is planned for 2021.

Status	ongoing		
Reference(s)	GASP SEIs (industry) – Mitigate contributing factors to LOC-I accidents and incidents		
	https://www.easa.europa.eu/community/topics/icing-flight		
Dependencies	GASP Goal 1		
	EPAS SPT.0109 (completed)		
Affected stakeholders	Aircraft Operators - CAT i.a.w. ICAO Annex 6, Groundhandling Services Providers i.a.w. ICA Annex 9 or Annex 14, Pilots		
Owner	States, ICAO EUR/NAT Regional Office, EASA		
EXPECTED OUTPUT			
Deliverable(s)	Timeline		
Promotional Web Mate	rial and Social Media 2023Q4		
CHANGES SINCE LAST EDITION			

Timeline extended by one year.

MONITORING		
Monitoring activities	Related SPIs	
Monitoring percentage of accidents in this key risk areas	EUR.SPI.1.1.04	