

Safety Recommendation - FRAN 2023-010

ICAO ensure that the inconsistencies between MSAW procedures and phraseology contained in Doc 4444 and Doc 9432 are removed and ensure that these documents are updated so that the urgency of the situation is systematically mentioned and the crew is systematically reminded of the QNH in the controller's message in the event of a MSAW.