ICAO Action

Action on this safety recommendation pertaining to the establishment of standardized markings for paved blast pads in Annex 14 will be contingent upon the outcome of action taken in respect of safety recommendation 01.