

ICAO Action (SR 39/2016)

Regarding safety recommendation SR39/2016, please be advised that the ICAO *Manual of Runway Visual Range Observing and Reporting Practices* (Doc 9328) and the *Guide to Meteorological Instruments and Methods of Observation* (WMO-No. 8) provide detailed guidance relating to appropriate siting of instruments to make the RVR assessment representative of the runway segments in use, as required by Annex 3 — *Meteorological Service for International Air Navigation*. It is considered that the current guidance is comprehensive and would assist to improve the siting of the instruments, where necessary.