

ICAO Action 2

With regard to safety recommendations 1 to 3, ICAO notes the problems experienced to recover the flight recorders and to have the flight recorder data available in support of the investigation. To this effect, the safety recommendations were submitted to the Flight Recorder Specific Working Group (FLIRECSWG) for due consideration during their meeting from 29 September to 2 October 2015. The results of the discussions will be submitted to the Air Navigation Commission (ANC) for due consideration in the first quarter of 2016.