

Safety Recommendation

The investigation commission recommends that ICAO raise Recommended Practice 11.10.6.5 in Amendment 53 to Annex 4 to the status of a Standard and accelerate its entry into force.