

**FLIGHT INFORMATION SERVICES FOR SOMALIA (FISS)**  
AERONAUTICAL INFORMATION SERVICES  
MOGADISHU, SOMALIA

TEL/FAX: 252-1-857-394  
AFS: HCMMYOYX  
Email: [ainformationsservice@fp.icao.int](mailto:ainformationsservice@fp.icao.int)  
<https://www.icao.int/ESAF/FISS>

**AIP SUPPLEMENT**

NO. 65/18, 03/19, 04/19,

*Re-issued on: 01 FEB 2019*

---

**ENR**

**SUP 65/2018 17<sup>TH</sup> SEP 2018/PERM. Mogadishu FIR: Fallback Procedure for HF Radio Communication Failure**

Pilots experiencing HF radio communication failure while operating in Mogadishu FIR are requested to contact Mogadishu FIC on SATCOM using INMARSAT code 466601 on FIC telephone No +2521857390 or +2521857391 or +2521857392 or +2521857393 and/ or comply with normal procedures for Radio Communication Failure in accordance with ICAO provisions as may be applicable.

*AIP SUP 44/2017 is here by replaced.*

**AD**

**SUP 03/2019 17<sup>TH</sup> SEP 2018/PERM. Mogadishu FIR: Direct flights from Aden Adde Intl. Airport to Nairobi/JKIA**

Operators intending to operate direct flights from Aden Adde Intl. Airport to Nairobi/JKIA must request approval from Director General of Somalia Civil Aviation Authority (SCAA) and subsequently file a flight plan. All flights departing from other airfields in Somalia are still required to go through Wajir Airport for security vetting.

*AIP SUP 66/18 is hereby replaced*

**SUP 04/2019 17<sup>TH</sup> SEP 2018/PERM. Mogadishu FIR: Status of Airfields in Somalia**

All operators intending to operate to any airfield in Somalia are advised to verify the status of the airfield to which they intend to operate from local authorities or Flight Information Services for Somalia Tel: +2521857394 Email: [Ainformationsservice@fp.icao.int](mailto:Ainformationsservice@fp.icao.int)

*AIP SUP 67/18 is here by replaced.*