





















NO COUNTRY LEFT BEHIND



6 Proposed GASP Goals

- 1. Achieve continuous reduction of OPS safety risks
- 2. Strengthen States' safety oversight capabilities
- 3. Implement effective State safety programmes
- 4. Increase collaboration at regional level
- 5. Expand the use of industry programmes
- 6. Ensure appropriate infrastructure is available to support safe OPS





