SAR Deficiencies

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Algeria	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Algeria and adjacent States	31/12/09	Α
Angola	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Angola and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Angola	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Angola	31/12/09	Α
Benin	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Benin and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Benin	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Benin	31/12/09	Α
Botswana	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Botswana and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Botswana	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Botswana	31/12/0	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Burkina Faso	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Burkina Faso and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Burkina Faso	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Burkina Faso	31/12/09	Α
Burundi	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency	Establish SAR legislation	Burundi	31/12/09	Α
	Annex 12, 2.4, Annex 12, 3.2.4: AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Coordinate with States concerned.	Burundi and Adjacent States.		
Cameroon	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Cameroon and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Cameroon	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR	Establish SAR legislation	Cameroon	31/12/09	Α
Cape Verde	This State has no deficiency in this field.				efficiency.				
Central African Republic	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	CAR and adjacent States	31/12/09	A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	CAR	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	CAR	31/12/09	Α
Chad	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Chad and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Chad	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Chad	31/12/09	A
Comoros	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Comoros and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Comoros	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Comoros	31/12/09	A
Congo	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Congo and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Congo	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Congo	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Côte d'Ivoire	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Cote d'Ivoire and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Cote d'Ivoire	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Cote d'Ivoire	31/12/09	A
Dem. Rep. of Congo	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	DRC and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	DRC	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	DRC	31/12/09	A
Djibouti	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Djibouti and adjacent States	31/12/09	Α
	Annex 12, 2.4, Annex 12, 3.2.4, AFI/7 Rec. 6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	I) Provide SPOC to ICAO: ii) Implement 406 MHz acft.	Djibouti	31/12/09	А
	Annex 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Djibouti	31/12/09	A

Egypt This State has no deficiency in this field.

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Equatorial Guinea	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Equatorial Guinea and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Equatorial Guinea	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Equatorial Guinea	31/12/09	Α
Eritrea	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	Establish SAR agreements	1995	Delay to conduct SAR OPS	Coordination with States concerned	Eritrea and adjacent States	31/12/09	Α
	Annex 12, 3.1.6, 3.1.7	SAR Legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR	Establish SAR Agreements	Eritrea	31/12/09	Α
Ethiopia	Annex 12, 3.1.5, AFI/7 Conc.6/3.	SAR Agreements	-	1995	Delay to conduct SAR/OPS	Coordinate with States concerned.	Ethiopia and adjacent States	31/12/09	Α
France (Réunion)	This State has no deficiency in this field.								
Gabon	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Gabon and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Gabon	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Gabon	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Gambia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Gambia and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Gambia	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Gambia	31/12/09	Α
Ghana	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Ghana and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Ghana	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Ghana	31/12/09	Α
Guinea	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Guinea and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Guinea	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR	Establish SAR legislation	Guinea	31/12/09	Α
Guinea Bissau	This State has no deficiency in this field.				efficiency.				
Kenya	Annex 12, 2.4, Annex 12, 3.2.4, AFI/7 Rec. 6/1 and 6/2	SARSAT ELT	406 MHz and 121.5 Mhz not implemented	1993	Delay to conduct SAR OPS	121.5 Mhz implemented. 406 MHz not Implemented.	Kenya	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annex 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR Authority	1995	Lack of legal authority could delay SAR efficiency.	Development of draft legislation is on going	Kenya	31/12/09	A
	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1996	Delay to conduct SAR OPS	Signed with EAC States only. To coordinate with other neighbouring States concerned outside EAC.	Kenya and adjacent States	31/12/09	A
Lesotho	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Lesotho and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Lesotho	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Lesotho	31/12/09	Α
Liberia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Liberia and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Liberia	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Liberia	31/12/09	Α
Libya	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Libya and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Libya	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Libya	31/12/09	Α
Madagascar	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Madagascar adjacent States	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Madagascar	31/12/09	Α
Malawi	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Malawi and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Malawi	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Malawi	31/12/09	Α
Mali	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mali and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mali	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mali	31/12/09	Α
Mauritania	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mauritania and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mauritania	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mauritania	31/12/09	Α
Mauritius	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mauritius and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mauritius	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mauritius	31/12/09	A
Morocco	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Morocco and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Morocco	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Morocco	31/12/09	A
Mozambique	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mozambique and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mozambique	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mozambique	31/12/09	A
Namibia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Namibia and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to	Namibia	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	ICAO Establish SAR legislation	Namibia	31/12/09	Α
Niger	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Niger and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Niger	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Niger	31/12/09	A
Nigeria	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Nigeria and adjacent States	31/12/09	Α
Rwanda	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Rwanda and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Rwanda	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Rwanda	31/12/09	A
Sao Tome & Principe	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Sao Tome &Principe and adjacent States	31/12/09	A
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Sao Tome &Pricipe	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Sao Tome &Principe	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Senegal	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Senegal and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Senegal	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Senegal	31/12/09	Α
Seychelles	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Seychelles and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Seychelles	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Seychelles	31/12/09	Α
Sierra Leone	This State has no deficiency in this field.								
Somalia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Somalia and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Somalia	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Somalia	31/12/09	Α
South Africa	This State has no deficiency in this field.				omoroney.				
Spain (Canary Is.)	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Sudan	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Sudan and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Sudan	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Sudan	31/12/09	A
Swaziland	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Swaziland and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Swaziland	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Swaziland	31/12/09	A
Tanzania	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Tanzania and adjacent States	31/12/09	Α
Togo	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Togo and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Togo	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Togo	31/12/09	A

Tunisia This State has no deficiency in this field.

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Uganda	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Uganda and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Uganda	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Uganda	31/12/09	A
Zambia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Zambia adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Zambia	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Zambia	31/12/09	A
Zimbabwe	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Zimbabwe and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Zimbabwe	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Zimbabwe	31/12/09	A