

INTERNATIONAL CIVIL AVIATION ORGANIZATION

AFI PLANNING AND IMPLEMENTATION REGIONAL GROUP FIFTEENTH MEETING (APIRG/15)

(Nairobi, Kenya, 26 – 30 September 2005)

Agenda Item 5: Deficiencies in the Air Navigation Fields

5.2: List of deficiencies in the air navigation field

Deficiencies in the ATS/AIS/SAR fields

(Presented by the Secretariat)

Summary

This paper presents the list of deficiencies in the ATS, AIS and SAR fields as updated by the Eighth Meeting of the ATS/AIS/SAR Sub-Group (Dakar, 10 – 12 August 2005). It incorporates updates from States in response to a State Letter as well as inputs directly received from States through missions and correspondence. In carrying out the updates, the Sub-Group made recommendations for appropriate remedial action and proposed target dates for implementation/elimination.

References:

ATS/AIS/SAR/SG/7 Report.

1. Introduction

1.1 The Sub-Group recalled the concerns of the Air Navigation Commission (ANC) and the Council related to the impact of air navigation deficiencies on safety. The Sub-Group noted the appreciation by the ANC and the Council of the efforts made by the APIRG as well as those of States to identify, assess and report air navigation deficiencies.

2. Discussion

- 2.1 The Sub-Group, using the approved methodology, updated the list of deficiencies in the ATS, SAR and AIS/MAP fields as shown in **Appendices A, B and C** to this paper.
- 2.2 The Sub-Group noted with appreciation that there was a marked improvement in the elimination of the previous deficiencies. In the ATS field 50% of the deficiencies have been rectified, in the AIS field 75% of the deficiencies have also been rectified. In the SAR field, though there were some improvements, issues relating to SAR Legislation and SAR Agreement continue to be prevalent. These are being addressed under the ICAO/AFCAC SAR Project.

2.3 In light of the discussions the meeting formulated draft conclusion **8/30** which is reproduced below:

Draft Conclusion 8/30:

Consideration of specific air navigation planning and implementation problems and the review of air navigation deficiencies in the Region

That considering the negative impact of non implementation of the air navigation plan requirements and the persistence of serious cases of deficiencies in several parts of the AFI region; and

- a) States concerned should take as soon as possible concrete measures to eliminate all deficiencies at Appendix A, B and C to this working paper.
- b) the matter be regularly followed up by the ICAO regional offices; and
- c) results be brought to the attention of APIRG.

3. Action required:

That APIRG:

- a) note the list of deficiencies in ATS, AIS and SAR fields appearing in the **Appendices A, B and C** to this working paper as updated by the Secretariat and the ATS/AIS/SAR Sub-Group.
- b) update the list as appropriate on the basis of **Appendices A, B and C**.
- c) invite ICAO Secretariat to coordinate with the States concerned in order for them to take remedial action in a timely manner.
- d) develop a modified conclusion taking into account the content of the ATS/AIS/SAR/SG/8 draft conclusion **8/30** based on a), b) and c) above.

English ATM Deficiencies

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Algeria	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UR981	Casablanca- Marrakech-BULIS- Gao-Niamey-Lagos.	1995	Aircraft subjected to fly non-economical routes	States concerned to coordinate common implementation date (Route segment implemented in Algeria).	Mali-Mauritania- Morocco-Niger- Nigeria	31/12/04	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UR986	Tunis-Ghadames-In Amenas-Djanet- Kano-Foumban- Yaoundé-France Ville	1995	Aircraft subjected to fly non-economical routes	States concerned to coordinate common implementation date.	Algeria	31/12/04	A
	Annex 11 Appendix 2	Five-letter name code	Route crossings not identified	1998	Difficulties for pilots identifying potential traffic conflicts.	ICAO Regional Office concerned allocate the 5-letter name codes.	Algeria	31/12/04	A
	APIRG/13 Conc.13/43	FIR Algiers	Non-implementation of 10 minutes longitudinal separation.					31/12/04	U
	AFI/7 Rec.5/21	FIR Algiers	Non-implementation of ATC in the upper airspace.					31/12/04	U
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA293	(Ibiza) (KIRLA) Tiaret.	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation date.	Algeria	31/12/04	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM999	Casablanca- Errachidia-El Golea- Zarzaitine-Sebha- Sarir-New Valley- Luxor-Jeddah.	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation date.	Algeria-Egypt- Libya-Morocco- Saudi Arabia.	31/12/04	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UG623	(BALEN) Annaba- Tebessa-Ghardaia.	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Algeria.	31/12/04	A
Angola	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM731	Carbonara- OSMAR- Tunis- Jerba-FARES- Dirkou-N'Djamena- Beriberati-Saurimo- Johannesburg	1996	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Angola- Botswana- Central African Republic- Congo(DRC)- Chad-Libya- Niger –South Africa-Zambia	31/12/04	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM998	Gaborone-Maun- Luena-Kinshasa	1996	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Angola- Botswana-DR. Congo.	31/12/04	A
	AFI/7 Rec.5/21.	Provision of ATC 150 NM concept.	Non-provision of ATC Service 150 NM of Huambo	1998	Steep descent for arrival and steep climb for departure.	Implement as required.	Angola	31/12/04	U
Benin	This State has no deficiency in this field.								
Botswana	AFI/7 Rec.5/21	RNAV UM731	Johannesburg- Saurimo	1990	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Angola- Botswana-So uth Africa- Zambia	31/12/04	A
Burkina Faso	This State has no deficiency in this field.								
Burundi	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Cameroon	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA861	Lagos-Garoua	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Cameroon	31/12/04	Α
Cape Verde	This State has no deficiency in this field.								
Central African Republic	This State has no deficiency in this field.								
Chad	This State has no deficiency in this field.								
Comoros	This State has no deficiency in this field.								
Congo	LIM AFI Rec.10/38	SSR Provision of effective surveillance.	Need for SSR surveillance in extended TMA as expressed in the AFI CNS/ATM Plan.	1998	Traffic density/complexi ty contributing to frequent ATS incidents	Implement SSR at Brazzaville	Congo	31/12/04	U
Côte d'Ivoire	This State has no deficiency in this field.								
Dem. Rep. of Congo	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	UM731	Johannesburg- Saurimo-Berberati	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates. (Need of VHF coverage before implementation)	Angola- Botswana-Co ngo (DRC)	31/12/04	A
	AFI/7 Rec.5/21	FIR Kinshasa	Non-provision of ATC service.	-	-	-	-	31/12/04	U

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	APIRG/13 Conc.13/43	FIR Kinshasa	Non-implementation of 10 minute longitudinal separation.	-	-	-	-	31/12/04	U
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA617	Kinshasa-Windhoek	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation date. (Coordination Meeting with Military Authorities ongoing).	Congo (DRC)	31/12/04	U
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UL612	Goma-El Dhaba(Paleohora)	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Congo (DRC)- Egypt-Sudan	31/12/04	Α
Djibouti	This State has no deficiency in this field.								
Egypt	This State has no deficiency in this field.								
Equatorial Guinea	This State has no deficiency in this field.								
Eritrea	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UB525	Addis Ababa- ALEBA-Luxor	1996	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Eritrea	1/9/2005	Α
Ethiopia	This State has no deficiency in this field.								
France (Réunion)	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Gabon	This State has no deficiency in this field.								
Gambia	This State has no deficiency in this field.								
Ghana	This State has no deficiency in this field.								
Guinea	This State has no deficiency in this field.								
Guinea Bissau	This State has no deficiency in this field.								
Kenya	AFI/7 Rec.5/1 - Airspace management	P2, R10, D20	Prohibited area, restricted area, danger area.	1990	Non-availability of direct routing.	Withdraw these areas.	Kenya	31/12/04	Α
Lesotho	This State has no deficiency in this field.								
Liberia	This State has no deficiency in this field.								
Libya	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM999	Zarzaitine-Sebha- Sarir-New Valley	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Libya	31/12/04	Α
	AFI/7 Rec.5/21	Provision of ATC 150 NM concept	Non-provision of ATC 150 NM of Tripoli.	1990	Delayed descent for arrival and steep climb for departure.	Implement as required.	Libya	31/12/04	U

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA748	(Gozo)-Tripoli- Mizda- Cairo-Sharm Sheikh	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Libya and adjacent States	31/12/04	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UG623	BALEN-Annaba- Tebessa- Ghadames	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Libya	31/12/04	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UG855	Tripoli-Ghadames- B. Omar Driss	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Libya	31/12/04	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UG864	Tunis-Tebessa- Ghardaia- Timmimoun	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Libya	31/12/04	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM994	Monastir-Mitiga- Beni- Walid-ORNAT	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Libya	31/12/04	Α
	AFI/7 Rec.5/1	Airspace Management	Inadequate airspace management between ATS units leading to frequent traffic incidents in the FIR boundaries between Alger, N'djamena, Tripoli and Niamey not responding to existing route structure flows.	1998	Frequent ATS incidents in the area attributed to airspace management.	Need for urgent meeting of the States concerned to address the problem of airspace management and prevalent ATS incidents in the area.	Libya and adjacent States	31/12/04	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA411	Jerba-Tripoli-Beni- W alid-Benina- GERFA- Mersa Matruh-Cairo	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Libya	31/12/04	A
	AFI/7 Rec.5/1	P21-R23-Airspace Management	Prohibited area-Restricted area	1990	Non-availability of direct routing.	State concerned to withdraw these areas.	Libya	31/12/04	A
Madagascar	This State has no deficiency in this field.								
Malawi	This State has no deficiency in this field.								
Mali	This State has no deficiency in this field.								
Mauritania	This State has no deficiency in this field.								
Mauritius	This State has no deficiency in this field.								
Morocco	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UR981	Casablanca- Marrakech-BULIS.	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Morocco	31/12/04	A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Airspace Management	Problems associated with non flight level allocations on ATS routes.	1998	Non-standard flight level allocations contributed to ATS incidents	States concerned to meet and address issues under column 3.	Morocco- Portugal	31/12/04	U
Mozambique	This State has no deficiency in this field.								
Namibia	AFI/7 Rec.5/21	Provision of ATC 150 NM concept	Non-provision of ATC service 150 NM Windhoek	1994	Delayed descent for arrival and steep climb for departure.	To Implement as required.	Namibia	31/12/04	U
Niger	This State has no deficiency in this field.								
Nigeria	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA861	Lagos-Garoua	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Nigeria	31/12/04	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM998	Ngaoundere- Maiduguri-Djanet	1995	Aircraft subjected to fly non-economical routes.	-	Nigeria	31/12/04	A
Rwanda	This State has no deficiency in this field.								
Sao Tome & Principe	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Senegal	This State has no deficiency in this field.								
Seychelles	This State has no deficiency in this field.								
Sierra Leone	This State has no deficiency in this field.								
Somalia	AFI/7 Rec.5/21	Provision of ATC 150 NM concept.	Non-provision of ATC service 150 NM of Mogadishu.	1994	Delayed descent for arrival and steep climb for departure.	No action due to the present situation	Somalia	31/12/04	U
	AFI/7 Rec.5/21	Route UG207	Mogadishu-Karachi	1990	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation date.	Somalia	31/12/04	A
South Africa	This State has no deficiency in this field.								
Spain (Canary Is.)	This State has no deficiency in this field.								
Sudan	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UR400	A. Simbel-Kassala	1994	Aircraft subjected to fly non-economical routes.	Not acceptable now within Khartoum FIR.	Sudan	17/02/05	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UR995	Merowe-Addis Ababa	1994	Aircraft subjected to fly non-economical routes.	To be deleted and replaced by UM665.	Sudan	17/02/05	A

APIRG/15 – WP/12 Appendix A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM665	Addis Ababa- Merowe	1994	Aircraft subjected to fly non-economical routes.	Not acceptable in Khartoum FIR due to military reasons.	Sudan	17/02/05	А
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM220	Lodwar-A.Simbel	1994	Aircraft subjected to fly non	States concerned to coordinate common implementation dates.	Sudan	17/02/05	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UL612	Goma-El Dhaba	1994	Aircraft subjected to fly non	Overlaps UB607 need to review alignment at appropriate forum.	Sudan	17/02/05	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UB607	Goma-El Obeid- New Valley-El Dabha	1994	Aircraft subjected to fly non	States concerned to coordinate common implementation dates.	Sudan	17/02/05	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UB525	Addis Ababa-Luxor	1994	Aircraft subjected to fly non	Not acceptable now in Khartoum FIR.	Sudan	17/02/05	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA618	Bukavu-Malakal	1994	Aircraft subjected to fly non	Not available now in Khartoum FIR.	Sudan	17/02/05	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Provision of ATS	Area control service not provided to most ATS routes in the upper airspace.	1998	Aircraft subjected to fly non	State to expedite implementation process.	Sudan	17/02/05	A
Swaziland	AFI/7 Rec.5/1	P4 - Airspace Management	Prohibited area	1990	Non-availability of direct routings.	Withdraw this area - P4.	Swaziland	31/12/04	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Tanzania	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	UB527	Lubumbashi - Dar- es-Salaam	2001	Aircraft subjected to fly non-economical routes.	Tanzania is coordinating with the States for a common implementation date.	D. R. Congo - Tanzania	31/12/04	A
Togo	This State has no deficiency in this field.								
Tunisia Uganda	This State has no deficiency in this field. This State has no deficiency in this field.								
Western Sahara	This State has no deficiency in this field.								
Zambia	This State has no deficiency in this field.								
Zimbabwe	This State has no deficiency in this field.								

SAR English Deficiencies

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Algeria	This State has no deficiency in this field.								
Angola	This State has no deficiency in this field.								
Benin	This State has no deficiency in this field.								
Botswana	This State has no deficiency in this field.								
Burkina Faso	This State has no deficiency in this field.								
Burundi	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR	Establish SAR legislation	Burundi	31/12/04	Α
	Annex 12, 2.4, Annex 12, 3.2.4: AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Coordinate with States concerned.	Burundi and Adjacent States.		
Cameroon	This State has no deficiency in this field.								
Cape Verde	This State has no deficiency in this field.								

APIRG/15 – WP/12 Appendix B

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Central African Republic	This State has no deficiency in this field.								
Chad	This State has no deficiency in this field.								
Comoros	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Comoros and adjacent States	31/12/04	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Comoros	31/12/04	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Comoros	31/12/04	A
Congo	This State has no deficiency in this field.								
Côte d'Ivoire	This State has no deficiency in this field.								
Dem. Rep. of Congo	This State has no deficiency in this field.								
Djibouti	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Djibouti and adjacent States	31/12/04	A
	Annex 12, 2.4, Annex 12, 3.2.4, AFI/7 Rec. 6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	I) Provide SPOC to ICAO: ii) Implement 406 MHz acft.	Djibouti	31/12/04	A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annex 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Djibouti	31/12/04	Α
Egypt	This State has no deficiency in this field.								
Equatorial Guinea	This State has no deficiency in this field.								
Eritrea	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	Establish SAR agreements	1995	Delay to conduct SAR OPS	Coordination with States concerned	Eritrea and adjacent States	1/3/2005	A
	Annex 12, 3.1.6, 3.1.7	SAR Legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR	Establish SAR Agreements	Eritrea	1/3/2005	A
Ethiopia	Annex 12, 3.1.5, AFI/7 Conc.6/3.	SAR Agreements	-	1995	Delay to conduct SAR/OPS	Coordinate with States concerned.	Ethiopia and adjacent States	31/12/04	A
France (Réunion)	This State has no deficiency in this field.								
Gabon	This State has no deficiency in this field.								
Gambia	This State has no deficiency in this field.								

This State has no deficiency in this field.

Ghana

This State has no deficiency in this field.

This State has no deficiency in this field.

Madagascar

Malawi

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Guinea	This State has no deficiency in this field.								
Guinea Bissau	This State has no deficiency in this field.								
Kenya	Annex 12, 2.4, Annex 12, 3.2.4, AFI/7 Rec. 6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft.	Kenya	31/12/04	A
	Annex 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR Authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Kenya	31/12/04	Α
	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1996	Delay to conduct SAR OPS	Signed with EAC States only. To coordinate with other neighbouring States concerned outside EAC.	Kenya and adjacent States	31/12/04	Α
Lesotho	This State has no deficiency in this field.								
Liberia	This State has no deficiency in this field.								
Libya	This State has no deficiency in this field.								

Executing

Body

Target date for implementation

Priority

Date first reported

Comments on

Deficiency

Description of

corrective

action

State Name	Requirements	Facilities or services	Description of Deficiency
Mali	This State has no deficiency in this field.		
Mauritania	This State has no deficiency in this field.		
Mauritius	This State has no deficiency in this field.		
Morocco	This State has no deficiency in this field.		
Mozambique	This State has no deficiency in this field.		
Namibia	This State has no deficiency in this field.		
Niger	This State has no deficiency in this field.		
Nigeria	This State has no deficiency in this field.		
Rwanda	This State has no deficiency in this field.		
Sao Tome & Principe	This State has no deficiency in this field.		
Senegal	This State has no deficiency in this field.		
Seychelles	This State has no deficiency in this field.		

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Sierra Leone	This State has no deficiency in this field.								
Somalia	AFI/7 Rec.5/21	Route UG207	Mogadishu-Karachi	1990	Aircraft subjected to fly non- economical routes	States concerned to coordinate common implementation date	Somalia	31/12/04	Α
	AFI/7 Rec.5/21	Provision of ATC 150 NM concept	Non-provision of ATC service 150 NM of Mogadishu	1994	Delayed descent for arrival and steep climb for departure	No action due to the present situation	Somalia	31/12/04	U
South Africa	This State has no deficiency in this field.								
Spain (Canary Is.)	This State has no deficiency in this field.								
Sudan	This State has no deficiency in this field.								
Swaziland	This State has no deficiency in this field.								
Tanzania	This State has no deficiency in this field.								
Togo	This State has no deficiency in this field.								
Tunisia	This State has no deficiency in this field.								
Uganda	This State has no deficiency in this field.								

APIRG/15 - WP/12
Appendix B

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Western Sahara	This State has no deficiency in this field.								
Zambia	This State has no deficiency in this field.								
Zimbabwe	This State has no deficiency in this field.								

AIS English Deficiencies

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Algeria	This State has no deficiency in this field.								
Angola	Annex 4, 3.2 and 13.2 AFI/7 Rec. 12/31	ICAO Mandatory Charts	Non-availability of the ICAO Aerodrome Chart and the ICAO Aerodrome Obstacle Chart - Type A for Huambo and Luanda.	1990	Lack of charts affects safety	Publish these Charts for Luanda and Huambo	Angola	31/12/04	U
Benin	This State has no deficiency in this field.								
Botswana	This State has no deficiency in this field.								
Burkina Faso	This State has no deficiency in this field.								
Burundi	This State has no deficiency in this field.								
Cameroon	Annex 4, 3.2 and 13.2 AFI/7 Rec.12/31 and 12/32 AFI/7	ICAO Mandatory Charts	Non-availability of the ICAO Aerodrome Chart and the ICAO Aerodrome Obstacle Chart - Type A for Yaoundé.	1990	Lack of charts affects safety	Publish these charts for Yaounde	Cameroon	31/12/04	U
Cape Verde	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Central African Republic	This State has no deficiency in this field.								
Chad	This State has no deficiency in this field.								
Comoros	Annex 4, 3.2 and AFI/7 Rec.12/31	ICAO Mandatory Charts	Non-availability of the ICAO Aerodrome Obstacle Chart - Type A for Dzaoudzi and Moroni	1990	Lack of this chart affects safety	Publish this Chart for Moroni and Dzaoudzi	Comoros	31/12/04	U
Congo	This State has no deficiency in this field.								
Côte d'Ivoire	This State has no deficiency in this field.								
Dem. Rep. of Congo	Annex 4, 13.2 and AFI/7, Rec.12/31	ICAO Mandatory Charts	Aerodrome Charts outdated	1990	Non-updated charts affects safety	Publish new charts. IAC and VAC charts published.	Congo (DRC)	31/12/04	U
Djibouti	Annex 15, 3.3	Integrated AIS package	Irregular distribution of AIS package	01/01/98	Non-availability of latest status of information affects safety	Distribute regularly	Djibouti	31/12/04	U
	Annex 15, 3.6.4	Coordinates WGS84	Accuracy of coordinates in accordance with Annexes 11 and 14	01/01/98	Delay in introduction of GNSS	Implement WGS- 84 coordinates	Djibouti	31/12/04	U
Egypt	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Equatorial Guinea	This State has no deficiency in this field.								
Eritrea	This State has no deficiency in this field.								
Ethiopia	This State has no deficiency in this field.								
France (Réunion)	This State has no deficiency in this field.								
Gabon	This State has no deficiency in this field.								
Ghana	Annex 15, 3.3	Integrated AIS package		01/01/98	Non-availability of latest status of information.	Distribute regularly	Gambia	31/12/04	U
Gambia	This State has no deficiency in this field.								
Guinea	Annex 15, 3.3	Integrated AIS package.	Irregular distribution of AIS package	01/01/98	Non-availability of latest status of information.	Distribute regularly	Guinea	31/12/04	U
Guinea Bissau	Annex 15, 3.6.4	Coordinates WGS-84	Accuracy of coordinates in accordance with Annexes 11 and 14.	01/01/98	Delay in introduction of GNSS	Implementation of WGS-84 coordinates	Guinea- Bissau	31/12/04	U
Kenya	This State has no deficiency in this field.								
Lesotho	Annex 15, 4.1	Lack of new AIP format	Irregular distribution of AIS package	01/01/96	Non-availability of AIP affects safety	Implement and publish new AIP	Lesotho	31/12/04	U

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Liberia	Situation unknown	Robertsfield							
Libya	This State has no deficiency in this field.								
Madagascar	This State has no deficiency in this field.								
Malawi	This State has no deficiency in this field.								
Mali	This State has no deficiency in this field.								
Mauritania	This State has no deficiency in this field.								
Mauritius	This State has no deficiency in this field.								
Morocco	Annex 15, 4.1	New AIP format	Irregular distribution of AIS package.	1/1/96	Non-availability of AIP affects safety	Implement and publish new AIP	Morocco	31/12/04	U
Mozambique	Annex 15, 4.1	AIP in new format	Non-availability of up-to- date information	01/01/96	Use of outdated information may affect safety	Implement and publish new AIP format.	Mozambique	31/12/04	U
Namibia	Annex 4, 13.2 and AFI/7 Rec.12/31	ICAO Mandatory Charts	Non-availability of ICAO Aerodrome Chart for Keetmanshoop and Windhoek/Hosea Kotako.	1979	Lack of these charts affects	Publish the required charts	Namibia	31/12/04	U
Niger	This State has no deficiency in this field.								
Nigeria	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Rwanda	Annex 4, 3.2 and 13.2 Rec.12/31 AFI/7.	ICAO Mandatory Charts.	Non-availability of ICAO Aerodrome Chart and Aerodrome Obstacle Chart - Type A for Kigali.	1979	Lack of these charts affects safety.	Publish the two charts for Kigali.	Rwanda	31/12/04	U
Sao Tome & Principe	Annex 15, 5.1	NOTAM	Irregular Publication of NOTAM.	1991	Lack of NOTAM affects safety.	Publish regularly.	Sao Tome (Brazzaville FIR)	31/12/04	U
Senegal	This State has no deficiency in this field.								
Seychelles	This State has no deficiency in this field.								
Sierra Leone	Annex 15, 5.1	NOTAM	Irregular Publication of NOTAM Publication of reported points.	1991	Lack of NOTAM affects safety	Publish regularly	Sierra Leone (Roberts FIR)	31/12/04	U
Somalia	Annex 4, 3.2, 11.2 and 13.2, AFI/7 Rec.12/31	ICAO Aerodrome Chart and the ICAO Aerodrome Obstacle Chart - Type A.	Non-availability of ICAO Aerodrome Chart, ICAO Aerodrome Obstacle Chart type A and ICAO Instrument Approach Chart for Hargeisa, Kismayu, Mogadishu.	1990	Lack of these charts affects safety.	Publish the three Charts as required	Somalia	31/12/04	U
	Annex 15, 3.6.4	Coordinates WGS84	Accuracy of coordinates to be established in accordance with Annexes 11 and 14.	01/01/98	Delay in introduction of GNSS	Implementation of WGS-84 coordinates	Somalia	31/12/04	U
South Africa	This State has no deficiency in this field.								

This State has no deficiency in this field.

Spain (Canary Is.)

Priority

U

U

APIRG/15 – WP/12 Appendix C

This State has no deficiency in this field.

This State has no deficiency in this field.

Zambia

Zimbabwe

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation
Sudan	Annex 4, 13.2 15, 8.1	ICAO Mandatory Charts.	Non-availability of ICAO Aerodrome Chart for Khartoum.	1990	Lack of this chart affects safety.	Publish the required chart	Sudan	31/12/04
Swaziland	Annex 4, para 3.2 and Rec.12/31 AFI/7	Non-availability of ICAO Aerodrome Chart and the ICAO Aerodrome Obstacle Chart - Type A.	Non-availability of ICAO Aerodrome Obstacle Chart type A for Matsapha.	1991	Lack of this chart affects safety.	Publish the required chart.	Swaziland	31/12/04
Tanzania	This State has no deficiency in this field.							
Togo	This State has no deficiency in this field.							
Tunisia	This State has no deficiency in this field.							
Uganda	This State has no deficiency in this field.							
Western Sahara	This State has no deficiency in this field.							