ATM Deficiencies

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Algeria	AFI/7 Rec.5/21	FIR Algiers	Non-implementation of ATC in the upper airspace in the South area (prevision of implementation in 2006).					31/12/09	A U
Angola	APIRG/13 Conclusion 13/43	Luanda FIR	Non-provision of 10 minutes longitudinal separation	1998			Angola	31/12/09	
Benin	This State has no deficiency in this field.								
Botswana	This State has no deficiency in this field.								
Burkina Faso	This State has no deficiency in this field.								
Burundi	This State has no deficiency in this field.								
Cameroon	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Cape Verde	This State has no deficiency in this field.								
Central African Republic	This State has no deficiency in this field.								
Chad	This State has no deficiency in this field.								
Comoros	This State has no deficiency in this field.								
Congo	LIM AFI Rec.10/38	SSR Provision of effective surveillance.	Need for SSR surveillance in extended TMA as expressed in the AFI CNS/ATM Plan.	1998	Traffic density/complexity contributing to frequent ATS incidents	Implement SSR at Brazzaville	Congo	31/12/09	U
Côte d'Ivoire	This State has no deficiency in this field.								
Dem. Rep. of Congo	AFI/7 Rec.5/21	FIR Kinshasa	Non-provision of ATC service.	-	-	-	-	31/12/09	U
	APIRG/13 Conc.13/43	FIR Kinshasa	Non-implementation of 10 minute longitudinal separation.	-	-	-	-	31/12/09	U

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UL612	Goma-EL Dhaba (Paleohora)	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Congo (DRC)- Egypt - Sudan	31/12/09	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UL612	Goma-El Dhaba (Paleohora)	1995	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Congo (DRC)- Egypt-Sudan	31/12/09	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	UB 527	Lubunbashi – Daras Salam	2001	Aircraft subjected to fly non-economical routes.	States concerned to coordinate a common implementation date.	D. R. Congo - Tanzania	31/12/09	
Djibouti	This State has no deficiency in this field.								
Egypt	This State has no deficiency in this field.								
Equatorial Guinea	This State has no deficiency in this field.								

Eritrea

This State has no deficiency in

State Name	Requirements this field.	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Ethiopia	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UB525	Addis Ababa- ALEBA-Luxor	1996	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Eritrea	1/9/2009	А
France (Réunion)	This State has no deficiency in this field.								
Gabon	This State has no deficiency in this field.								
Gambia	This State has no deficiency in this field.								
Ghana	This State has no deficiency in this field.								
Guinea	This State has no deficiency in this field.								
Guinea Bissau	This State has no deficiency in this field.								
Kenya	AFI/7 Rec.5/1 - Airspace management	P2, R10, D20	Prohibited area, restricted area, danger area.	1990	Non-availability of direct routing.	Withdraw these areas.	Kenya	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Lesotho	This State has no deficiency in this field.								
Liberia	This State has no deficiency in this field.								
Libya	This State has no deficiency in this field.								
Madagascar	This State has no deficiency in this field.								
Malawi	This State has no deficiency in this field.								
Mali	This State has no deficiency in this field.								
Mauritania	This State has no deficiency in								

State Name	Requirements this field.	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Mauritius	This State has no deficiency in this field.								
Morocco	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Airspace Management	Problems associated with non flight level allocations on ATS routes.	1998	Non-standard flight level allocations contributed to ATS incidents	States concerned to meet and address issues under column 3.	Morocco- Portugal	31/12/09	U
Mozambique	This State has no deficiency in this field.								
Namibia	This State has no deficiency in this field								
Niger	This State has no deficiency in this field.								
Nigeria	This State has no deficiency in this field								
Rwanda	This State has no deficiency in this field.								
Sao Tome & Principe	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Senegal	This State has no deficiency in this field.								
Seychelles	This State has no deficiency in this field.								
Sierra Leone	This State has no deficiency in this field.								
Somalia	AFI/7 Rec.5/21	Provision of ATC 150 NM concept.	Non-provision of ATC service 150 NM of Mogadishu.	1994	Delayed descent for arrival and steep climb for	No action due to the present situation	Somalia	31/12/09	U
South Africa	This State has no deficiency in this field.				departure.				
Spain (Canary Is.)	This State has no deficiency in this field.								
Sudan	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UR400	A. Simbel-Kassala	1994	Aircraft subjected to fly non-economical routes.	Not acceptable now within Khartoum FIR.	Sudan	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UM665	Addis Ababa- Merowe	1994	Aircraft subjected to fly non-economical routes.	Not acceptable in Khartoum FIR due to military reasons.	Sudan	17/02/09	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	RNAV UL612	Goma-El Dhaba	1994	Aircraft subjected to fly non-economical routes.	Overlaps UB607 need to review alignment at appropriate forum.	Sudan	17/02/09	Α
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UB607	Goma-El Obeid- New Valley-El Dabha	1994	Aircraft subjected to fly non-economical routes.	States concerned to coordinate common implementation dates.	Sudan	17/02/09	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UB525	Addis Ababa-Luxor	1994	Aircraft subjected to fly non-economical routes.	Not acceptable now in Khartoum FIR.	Sudan	17/02/09	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Route UA618	Bukavu-Malakal	1994	Aircraft subjected to fly non-economical routes.	Not available now in Khartoum FIR.	Sudan	17/02/09	A
	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	Provision of ATS	Area control service not provided to most ATS routes in the upper airspace.	1998	Aircraft subjected to fly non-economical routes.	State to expedite implementation process.	Sudan	17/02/09	A
Swaziland	AFI/7 Rec.5/1	P4 - Airspace Management	Prohibited area	1990	Non-availability of direct routings.	Withdraw this area - P4.	Swaziland	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Tanzania	AFI/7 Rec.5/8 and Table ATS 1 AFI ANP Doc.7474.	UB527	Lubumbashi - Dar- es-Salaam	2001	Aircraft subjected to fly non-economical routes.	Tanzania is coordinating with the States for a common implementation date.	D. R. Congo - Tanzania	31/12/09	A
Togo	This State has no deficiency in this field.								
Tunisia	This State has no deficiency in this field.								
Uganda	This State has no deficiency in this field.								
Zambia	This State has no deficiency in this field.								
Zimbabwe	This State has no deficiency in this field.								

AIS Deficiencies

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Algeria	This State has no deficiency in this field.								
Angola	This State has no deficiency in this field.								
Benin	This State has no deficiency in this field.								
Botswana	This State has no deficiency in this field.								
Burkina Faso	This State has no deficiency in this field.								
Burundi	This State has no deficiency in this field.								
Cameroon	This State has no deficiency in this field.								
Cape Verde	This State has no deficiency in this field.								
Central African Republic	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Chad	This State has no deficiency in this field.								
Comoros	This State has no deficiency in this field.								
Congo	This State has no deficiency in this field.								
Côte d'Ivoire	This State has no deficiency in this field.								
Dem. Rep. of Congo	Annex 4, 13.2 and AFI/7, Rec.12/31	ICAO Mandatory Charts	Aerodrome Charts outdated	1990	Non-updated charts affects safety	Publish new charts. IAC and VAC charts published.	Congo (DRC)	31/12/07	U
Djibouti	This State has no deficiency in this field.								
Egypt	This State has no deficiency in this field.								
Equatorial Guinea	This State has no deficiency in this field.								
Eritrea	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Ethiopia	This State has no deficiency in this field.								
France (Réunion)	This State has no deficiency in this field.								
Gabon	This State has no deficiency in this field.								
Ghana	Annex 15, 3.3	Integrated AIS package		01/01/98	Non-availability of latest status of information.	Distribute regularly	Gambia	31/12/04	U
Gambia	This State has no deficiency in this field.								
Guinea	This State has no deficiency in this field.								
Guinea Bissau	This State has no deficiency in this field.								
Kenya	This State has no deficiency in this field.								
Lesotho	This State has no deficiency in this field.								
Liberia Libya	Situation unknown This State has no deficiency in this field.								
Madagascar	This State has no deficiency in this field.								
Malawi	This State has no								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	deficiency in this field.								
Mali	This State has no deficiency in this field.								
Mauritania	This State has no deficiency in this field.								
Mauritius	This State has no deficiency in this field.								
Morocco	This State has no deficiency in this field.								
Mozambique	This State has no deficiency in this field.								
Namibia	This State has no deficiency in this field.								
Niger	This State has no deficiency in this field.								
Nigeria	This State has no deficiency in this field.								
Rwanda	This State has no deficiency in this field.								
Sao Tome & Principe	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Senegal	This State has no deficiency in this field.								
Seychelles	This State has no deficiency in this field.								
Sierra Leone	This State has no deficiency in this field.								
Somalia	Annex 4, 3.2, 11.2 and 13.2, AFI/7 Rec.12/31	ICAO Aerodrome Chart and the ICAO Aerodrome Obstacle Chart - Type A.	Non-availability of ICAO Aerodrome Chart, ICAO Aerodrome Obstacle Chart type A and ICAO Instrument Approach Chart for Hargeisa, Kismayu, Mogadishu.	1990	Lack of these charts affects safety.	Publish the three Charts as required	Somalia	31/12/07	U
	Annex 15, 3.6.4	Coordinates WGS84	Accuracy of coordinates to be established in accordance with Annexes 11 and 14.	01/01/98	Delay in introduction of GNSS	Implementation of WGS-84 coordinates	Somalia	31/12/07	U
South Africa	This State has no deficiency in this field.								
Spain (Canary Is.)	This State has no deficiency in this field.								
Sudan	This State has no deficiency in this field.								
Swaziland	This State has no deficiency in this field.								
Tanzania	This State has no deficiency in this field.								

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Togo	This State has no deficiency in this field.								
Tunisia	This State has no deficiency in this field.								
Uganda	This State has no deficiency in this field.								
Zambia	This State has no deficiency in this field.								
Zimbabwe	This State has no deficiency in this field.								

SAR Deficiencies

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Algeria	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Algeria and adjacent States	31/12/09	Α
Angola	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Angola and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Angola	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Angola	31/12/09	Α
Benin	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Benin and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Benin	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Benin	31/12/09	Α
Botswana	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Botswana and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Botswana	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework	1995	Lack of legal	Establish SAR	Botswana	31/12/0	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
			for the SAR authority		authority could delay SAR efficiency.	legislation			
Burkina Faso	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Burkina Faso and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Burkina Faso	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Burkina Faso	31/12/09	Α
Burundi	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency	Establish SAR legislation	Burundi	31/12/09	A
	Annex 12, 2.4, Annex 12, 3.2.4: AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Coordinate with States concerned.	Burundi and Adjacent States.		
Cameroon	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Cameroon and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to	Cameroon	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Cape Verde	Annexe 12, 3.1.6, 3.1.7 This State has no deficiency in this field.	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	ICAO Establish SAR legislation	Cameroon	31/12/09	Α
Central African Republic	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	CAR and adjacent States	31/12/09	A
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	CAR	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	CAR	31/12/09	А
Chad	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Chad and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Chad	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Chad	31/12/09	Α
Comoros	Annex 12, 3.1.5, AFI/7	SAR Agreements	-	1991	Delay to conduct	Coordinate with	Comoros	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Conc.6/3				SAR OPS	States concerned	and adjacent States		
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Comoros	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Comoros	31/12/09	A
Congo	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Congo and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Congo	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Congo	31/12/09	Α
Côte d'Ivoire	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Cote d'Ivoire and adjacent States	31/12/09	Α
	Annexe 12, 2.4,	SARSAT ELT	406 MHz	1993	Delay to conduct	Implement 406	Cote d'Ivoire	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2				SAR OPS	MHz in acft. – Provide SPOC to ICAO			
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Cote d'Ivoire	31/12/09	Α
Dem. Rep. of Congo	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	DRC and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	DRC	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	DRC	31/12/09	Α
Djibouti	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Djibouti and adjacent States	31/12/09	A
	Annex 12, 2.4, Annex 12, 3.2.4, AFI/7 Rec. 6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	I) Provide SPOC to ICAO: ii) Implement 406 MHz acft.	Djibouti	31/12/09	A
	Annex 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Djibouti	31/12/09	A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Egypt	This State has no deficiency in this field.								
Equatorial Guinea	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Equatorial Guinea and adjacent States	31/12/09	A
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Equatorial Guinea	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Equatorial Guinea	31/12/09	Α
Eritrea	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	Establish SAR agreements	1995	Delay to conduct SAR OPS	Coordination with States concerned	Eritrea and adjacent States	31/12/09	Α
	Annex 12, 3.1.6, 3.1.7	SAR Legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR	Establish SAR Agreements	Eritrea	31/12/09	Α
Ethiopia	Annex 12, 3.1.5, AFI/7 Conc.6/3.	SAR Agreements	-	1995	Delay to conduct SAR/OPS	Coordinate with States concerned.	Ethiopia and adjacent States	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
France (Réunion)	This State has no deficiency in this field.								
Gabon	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Gabon and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Gabon	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Gabon	31/12/09	Α
Gambia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Gambia and adjacent States	31/12/09	A
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Gambia	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Gambia	31/12/09	Α
Ghana	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Ghana and adjacent States	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Ghana	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Ghana	31/12/09	A
Guinea	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Guinea and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Guinea	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Guinea	31/12/09	Α
Guinea Bissau	This State has no deficiency in this field.				enicionay.				
Kenya	Annex 12, 2.4, Annex 12, 3.2.4, AFI/7 Rec. 6/1 and 6/2	SARSAT ELT	406 MHz and 121.5 Mhz not implemented	1993	Delay to conduct SAR OPS	121.5 Mhz implemented. 406 MHz not Implemented.	Kenya	31/12/09	A
	Annex 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework	1995	Lack of legal	Development of	Kenya	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
			for the SAR Authority		authority could delay SAR efficiency.	draft legislation is on going			
	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1996	Delay to conduct SAR OPS	Signed with EAC States only. To coordinate with other neighbouring States concerned outside EAC.	Kenya and adjacent States	31/12/09	Α
Lesotho	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Lesotho and adjacent States	31/12/09	A
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Lesotho	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Lesotho	31/12/09	Α
Liberia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Liberia and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Liberia	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Liberia	31/12/09	Α
Libya	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Libya and adjacent	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	States Libya	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Libya	31/12/09	Α
Madagascar	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Madagascar adjacent States	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Madagascar	31/12/09	Α
Malawi	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Malawi and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Malawi	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Malawi	31/12/09	Α
Mali	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mali and adjacent States	31/12/09	А

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mali	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mali	31/12/09	Α
Mauritania	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mauritania and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mauritania	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mauritania	31/12/09	Α
Mauritius	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mauritius and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mauritius	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mauritius	31/12/09	Α
Morocco	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Morocco and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Morocco	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR	Establish SAR legislation	Morocco	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
					efficiency.				
Mozambique	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Mozambique and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Mozambique	31/12/09	A
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Mozambique	31/12/09	Α
Namibia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Namibia and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Namibia	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Namibia	31/12/09	Α
Niger	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Niger and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Niger	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework	1995	Lack of legal	Establish SAR	Niger	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
			for the SAR authority		authority could delay SAR efficiency.	legislation			
Nigeria	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Nigeria and adjacent States	31/12/09	Α
Rwanda	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Rwanda and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Rwanda	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Rwanda	31/12/09	Α
Sao Tome & Principe	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Sao Tome &Principe and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Sao Tome &Pricipe	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Sao Tome &Principe	31/12/09	A
Senegal	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Senegal and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Senegal	31/12/09	A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Senegal	31/12/09	A
Seychelles	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Seychelles and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Seychelles	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Seychelles	31/12/09	Α
Sierra Leone	This State has no deficiency in this field.				,				
Somalia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Somalia and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Somalia	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Somalia	31/12/09	A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
South Africa	This State has no deficiency in this field.								
Spain (Canary Is.)	This State has no deficiency in this field.								
Sudan	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Sudan and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Sudan	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Sudan	31/12/09	Α
Swaziland	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Swaziland and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Swaziland	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Swaziland	31/12/09	Α
Tanzania	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Tanzania and adjacent States	31/12/09	Α
Togo	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Togo and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Togo	31/12/09	Α

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Togo	31/12/09	A
Tunisia	This State has no deficiency in this field.								
Uganda	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Uganda and adjacent States	31/12/09	А
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Uganda	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Uganda	31/12/09	Α
Zambia	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Zambia adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Zambia	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Zambia	31/12/09	A

State Name	Requirements	Facilities or services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of corrective action	Executing Body	Target date for implementation	Priority
Zimbabwe	Annex 12, 3.1.5, AFI/7 Conc.6/3	SAR Agreements	-	1991	Delay to conduct SAR OPS	Coordinate with States concerned	Zimbabwe and adjacent States	31/12/09	Α
	Annexe 12, 2.4, Annexe 12, 3.2.4, AFI/7 Rec.6/1 and 6/2	SARSAT ELT	406 MHz	1993	Delay to conduct SAR OPS	Implement 406 MHz in acft. – Provide SPOC to ICAO	Zimbabwe	31/12/09	Α
	Annexe 12, 3.1.6, 3.1.7	SAR legislation	Provide legal framework for the SAR authority	1995	Lack of legal authority could delay SAR efficiency.	Establish SAR legislation	Zimbabwe	31/12/09	Α

_ _ _ _ _ _