

#### INTERNATIONAL CIVIL AVIATION ORGANIZATION

# Third Meeting of the APIRG Communications, Navigation and Surveillance Sub-Group Nairobi, 26-30 April 2010)

**Agenda Item 6:** 

Review of the implementation status and performance of the Aeronautical Radio Navigation Service (ARNS), and identification of deficiencies and remedial action for their elimination.

(Presented by the Secretariat)

#### **SUMMARY**

This paper examines the status of implementation of ARNS facilities in the AFI Region and identifies deficiencies and corrective measures for their elimination.

Action to be taken is at paragraph 3

**REFERENCE:** APIRG/16 Report, CNS/SG/2 report and

SP AFI RAN Report

#### 1. INTRODUCTION

1.1 ICAO has launched a new evolution of performance based navigation system. The ultimate goal is a transition to GNSS that would eliminate the requirement for ground-based aids. However, in order to have a gradual transition, all pending navigational systems must be implemented according to AFI ANP.

## 2 DISCUSSION

VOR/DME and ILS should be operational until 2015 when if any will be decommissioned. No new navigational aids have been implemented since CNS/SG/2 meeting and SP AFI RAN. **Attachment A** to this working paper is the outstanding deficiencies in Radio Navigational field.

## 3. ACTION TO BE TAKEN BY THE MEETING

- **3.1** The meeting is invited to:
  - a) take note of the above information;
  - b) update the meeting on the attached deficiencies; and
  - c) Angola and Madagascar who have along outstanding list should be urged to implement the facilities.

-----

CNS/SG3 - WP/10

# LIST OF DEFICIENCIES IN THE AIR NAVIGATION FIELDS NAVAIDS

1

State Name	Requirements	Facilities or Services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of Corrective action	Executing Body	Target date for implementation	Priority
Angola	Navaids AFI/7, Rec. 10/4	Huambo	VOR/DME	1998	Not implemented	Implement facility	ENANA		A
	Navaids AFI/7, Rec. 10/4	Kuito	VOR/DME	1998	Not implemented	Implement facility	ENANA		A
	Navaids AFI/7, Rec. 10/4	Luena	VOR/DME	1998	Not implemented	Implement facility	ENANA		U
	Navaids AFI/7, Rec. 10/4	Saurimo	VOR/DME	1998	Not implemented	Implement facility	ENANA		U
Cameroon	Navaids AFI/7, Rec. 10/4	Maroua	VOR	1998	Not implemented	Implement facility	Cameroon		A
Congo D.R.C.	Navaids AFI/7, Rec. 10/4	Kindu	VOR	1998	Unserviceable	New equipment to be installed	DR Congo	2005	U
congo 2 vinco	Navaids AFI/7, Rec. 10/4	Kisangani	VOR/DME	1998	Unserviceable	New equipment being installed	DR Congo	2005	A
Guinea	Navaids, AFI/7 Rec. 10/4	Kankan	VOR	1998	Not implemented	Implement facility	Guinea		A
	Navaids AFI/7 Rec.	Labe	VOR	1998	Not implemented	Implement facility	Guinea		A
	Navaids AFI/7 Rec. 10/4	Nzerekore	VOR	1998	Not implemented	Implement facility	Guinea		A
Kenya	Navaids AFI/7 Rec. 10/4	Mandera	VOR/DME	1998	Not implemented	Implement facility	Kenya		U
Lesotho	Navaids AFI/7 Rec. 10/4	Maseru	VOR/DME	2002	Not implemented	To implement	Lesotho		U
Liberia	Navaids AFI/7 Rec. 10/4	Robertsfield	ILS 04	1998	Not implemented	Implement facility	Liberia		U
Libya	Navaids AFI/7 Rec. 10/4	Sarir	VOR/DME	1998	Not implemented	Implement facility	Libya		U
Madagascar	Navaids AFI/7 Rec.	Antsiranana	VOR	1998	Not implemented	Implement facility	Madagascar		U
	Navaids AFI/7 Rec.	Maintirano	VOR	2002	Not implemented	Implement facility	Madagascar		U
	Navaids AFI/7 Rec.	Morondava	VOR	1998	Not implemented	Implement facility	Madagascar		U
	Navaids AFI/7 Rec. 10/4	Sainte Marie	VOR	1998	Not implemented	Implement facility	Madagascar		A

2 CNS/SG3 – WP/10

State Name	Requirements	Facilities or Services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of Corrective action	Executing Body	Target date for implementation	Priority
	Navaids AFI/7 Rec. 10/4	Toliara	VOR	1998	Not implemented	Implement facility	Madagascar		U
Sao Tome & Principe	Navaids AFI/7 Rec. 10/4	Sao Tome	ILS 11	1998	Not implemented	Implement facility	Sao Tome & Principe		A
Sierra Leone	Navaids AFI/7 Rec. 10/4	Freetown/ Lungi	ILS 30	1999	Unserviceable	To repair	Sierra Leone		U
	Navaids AFI/7 Rec. 10/4	Freetown/ Lungi	VOR/DME	1999	Unserviceable	To repair	Sierra Leone		U
Somalia	Navaids AFI/7 Rec. 10/4	Hargeisa	VOR/DME	1998	Not implemented	Implement facility	Somalia		U
	Navaids AFI/7 Rec. 10/4	Mogadishu	VOR/DME	1998	Not implemented	Implement facility	Somalia		U
Sudan	Navaids AFI/7 Rec. 10/4	Geneina	VOR	1998	Not implemented	Implement facility	Sudan		U
	Navaids AFI/7 Rec. 10/4	Juba	ILS 13	1998	Not implemented	Implement facility	Sudan		A
	Navaids AFI/7 Rec. 10/4	Karina	VOR/DME	1998	Not implemented	Implement facility	Sudan		U
Tanzania	Navaids AFI/7 Rec. 10/4	Dodoma	VOR/DME	1998	Not implemented	Implement facility	Tanzania	31/12/2005	U
	Navaids AFI/7 Rec. 10/4	Mbeya	VOR/DME	1998	Not implemented	Implement facility	Tanzania	June 2006	U
	Navaids AFI/7 Rec. 10/4	Mwanza	DME	1998	Not implemented	Implement facility	Tanzania	June 2005	U
Zambia	Navaids AFI/7 Rec. 10/4	Mongu	VOR	1998	Not implemented	Under installation	Zambia	30/12/2005	U
	Navaids AFI/7 Rec. 10/4	Solwezi	VOR	1998	Not implemented	Sourcing for funds	Zambia	Dec.w 2006	U