



SAFE SKIES.
**SUSTAINABLE
FUTURE.**



| ICAO



Serious Incident in Paris CDG May 2022

Transmission of incorrect altimeter setting (QNH)

Raphael GUILLET

Chief of the ICAO APAC RSO Beijing

rguillet@icao.int

Transmission of incorrect altimeter setting (QNH)

Context :

Transmission of incorrect altimeter setting (QNH) by air traffic service, near-collision with ground during satellite approach procedure with barometric vertical guidance

Paris CDG airport in May 2022

Available attachments :

- BEA SAFETY INVESTIGATION REPORT
https://bea.aero/fileadmin/uploads/9HEMU/9H-EMU_EN.pdf
- Presentation of France at the SBAS GBAS workshop in Bengaluru India Oct 2025
- DGAC Analysis in QHN inconsistencies in approach

Transmission of incorrect altimeter setting (QNH)

Questions raised by this serious incident during an APV Baro VNAV :

- Could this situation also occur in the APAC region?
- How to ensure correct transmission of QNH ?
- Should we need to increase minima of RNP APCH (with LNAV VNAV minima) ?
-

Serious Incident in Paris CDG May 2022

5

Transmission of incorrect altimeter setting (QNH)

Action by Meeting

The meeting is invited to:

1. note the information presented; and take action, as appropriate.

Thank You

